

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHD 4923U

DATE 24/6/2019 15:36

MAKE :

MODEL : HYUNDAI i40

Lke

AXA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover ✓			\$ 544.50
	Front Bumper Grille (LH) ✓			\$ 41.60
	Front Bumper Bracket Top (LH) ?			\$ 22.40
	Front Bumper Bracket (LH) ?			\$ 24.60
	Headlamp (LH) ✓			\$ 1,388.00
	Front Fender (LH) X repair			\$ 663.00
	Front Bumper X repair			
	SUB TOTAL			\$ 2,684.10
	LESS 20%			\$ 536.82
	DISCOUNTED TOTAL			\$ 2,147.28
	Front Fender Advertisement Logo (LH) ✓			\$ 100.00
				\$ 100.00
	Labour Charge			
	Panel Beating (Bonnet)			\$ 500.00 300
	Spray Painting Charge			\$ 750.00 600
	Tuff Kote			\$ 50.00 20
	TOTAL LABOUR			\$ 1,300.00
	ESTIMATE TOTAL			\$ 3,547.28
Ka hua 1 (LH) 25/6/19 11:58h 3 Bz 4/5 After Repair p Lk				
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

Nett