

ASS. REC. BY:

REF: CS/FCI 19011225/K1sd3

n2

Special Instruction:

Surveyor: Kalvin

ASSIGNMENT (Office)

CWS

From (Person):

Sithara

of

FCI

Date/Time:

3pm @ 25/6/19

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHB 8036P

Insured:

SHA 0943D

at Workshop m/s

Premier Automotive

Tel:

6544 6689

of

28 'Chengji' South Ave 2 #01-02

Policy No:

Claim No:

D19004108MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A

21/06/2019

CA / REV / REP. / REV 24 HRS

lup

H.O.D. Endorsement:

Date/Time:

3:17pm @ 25/6/19

Person Contacted:

Vincent

Vehicle IN OUT

Date/Time

Action/Instruction

Sithara / ✓

SHA 943D: CS/FCI 18014955/Ricd3e2 D.O.A: 12/08/2018

SHB8036P: CC3/CTI16006921/H1yg3g2 D.O.A: 14/04/2016

27/6/19

@ 16:56 pm revised PA to Sithara via email.

MOTOR SURVEY ASSIGNMENT

Date	24-06-2019	Our Ref No. D19004108MFSH
Accident Date	21-06-2019	Claim Type. Third Party
Insured Vehicle	SHA0943D	Third Party Vehicle. SHB8036P
Survey Location	23 CHANGI SOUTH AVENUE 2 #01-02	
Contact Person.	GOH WEE DEK	
Contact No.	62148880/ 65446682	Fax No. 62141511
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PREMIER AUTOMOTIVE SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Text size + -

Enquire Transaction History**Transaction History Details**

Log Date/Time:	08 Jan 2016 / 08:41:29	Receipt No.:	AACCK001-AX239-160108-000010
Asset Type:	Vehicle	Transaction Amount:	\$68,750.00
Asset ID:	SHB8036P	Channel:	AA Counterless - CYCLE & CARRIAGE KIA PTE LTD
Transaction Type:	01.02 Register New Vehicle (AA)		
Business Transaction Reference No.:	20160108084129854253		
Vehicle No.:	SHB8036P		
Vehicle Type:	H10 - Public Transport Taxi (Motor Car)		
Vehicle Attachment 1:	Air-Con (Taxi)		
Vehicle Attachment 2:	-		
Vehicle Attachment 3:	-		
Vehicle Scheme:	Taxi (Company)		
First Registration Date:	08 Jan 2016		
Original Registration Date:	08 Jan 2016		
Vehicle Make:	KIA		
Vehicle Model:	OPTIMA 1.7(A) DIESEL		
Chassis No.:	KNAGM414MF5656197		
Engine No.:	D4DFDH314424		
Motor No.:	-		
Trailer Chassis No.:	-		
Propellant:	Diesel		
Passenger Capacity:	4		
Engine Capacity:	1685		
Power Rating:	-		
Unladen Weight:	1584		
Maximum Laden Weight:	2050		
Primary Color:	Silver		
Secondary Color:	-		
Manufacturing Year:	2015		
Open Market Value:	\$22,359.00		
Minimum PARF Benefit:	\$13,981.00		
PARF Eligibility:	Y		
No. of Transfer:	0		
Effective Ownership Date/Time:	08 Jan 2016 08:41:29		
COE No.:	2016010801003469H		
COE Expiry Date:	07 Jan 2024		
COE Bid Category:	-		
Actual QP/PQP Paid Amount:	\$45,307.00		
Lifespan Expiry Date:	07 Jan 2024		

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

24-Jun-19

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8036 P

1 pc	Rear bumper	\$	696.00
1 pc	Rear bumper lower cover	\$	206.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00	\$	58.00
1 pc	Rear bumper inner sponge	\$	114.00
1 pc	Rear bumper reinforcement	\$	607.00
2 pcs	Rear bumper reflector n/s & o/s @ \$46.00	\$	92.00
2 pcs	Rear bumper stay o/s & n/s @ \$53.00	\$	108.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00	\$	36.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00	\$	36.00
			\$ 1,953.00
Less 10%			\$ 195.30
			\$ 1,757.70

S/NETT

1 set	Rear bumper clips	\$	48.00
1 set	End panel inner garnish clips	\$	30.00
1 set	Bootlid lower garnish clips	\$	60.00
1 set	Bootlid stickers	\$	100.00
1 set	Reverse sensor	\$	280.00 200
1 pc	Rear bumper top protector	\$	80.00 50
Sundry To dismantle / replace reverse sensor to new bumper and reset to the same To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs. To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the end panel etc To putty and spray painting on bootlid lower garnish, rear bumper, end panel To apply rustproofing on the repaired and replaced panels.			
			\$ 50.00
			\$ 120.00
			\$ 180.00
			\$ 750.00
			\$ 600.00
			\$ 120.00
			\$ 4,175.70

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE
ANY UNFORESEEN DAMAGES.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19011225/K1sd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 02-07-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 943D	Veh. Inspected	SHB 8036P	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19004108MFSH	Excess (\$)	0.00	
Assign From	SITHARA	Assign Date	25/06/2019	
2. Vehicle Particulars & Condition				
Make & Model	KIA OPTIMA	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	KNAGM414MF5658197	Colour	SILVER	
Odometer	334448	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/65 R16	MAXXIS	7 mm	
L/H Front Tyre	205/65 R16	MAXXIS	7 mm	
R/H Rear Tyre	205/65 R16	MAXXIS	7 mm	
L/H Rear Tyre	205/65 R16	MAXXIS	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	21/06/2019	Inspection Date	25/06/2019	
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 8036P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DEFORMED	696.00	696.00
1	REAR BUMPER LOWER COVER	CUT	206.00	206.00
2	REAR BUMPER SIDE BRACKET O/S & N/S @\$29.00	N/S CRACKED / O/S SERVICEABLE	58.00	29.00
1	REAR BUMPER INNER SPONGE	SERVICEABLE	114.00	-
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	607.00	-
2	REAR BUMPER REFLECTOR N/S & O/S @\$46.00	N/S CRACKED / O/S SERVICEABLE	92.00	46.00
2	REAR BUMPER STAY O/S & N/S	SERVICEABLE	108.00	-
2	REAR BUMPER REINFORCEMENT UPPER BRACKET @\$18.00	SERVICEABLE	36.00	-
2	REAR BUMPER REINFORCEMENT LOWER BRACKET @\$18.00	SERVICEABLE	36.00	-
	LESS 10% DISCOUNT		-195.30	-97.70
			1,757.70	879.30
SPECIAL NETT ITEMS				
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	48.00	48.00
1	SET END PANEL INNER GARNISH CLIPS (SN)	NOT NECESSARY	30.00	-
1	SET BOOTLID LOWER GARNISH CLIPS (SN)	NOT NECESSARY	60.00	-
1	SET BOOTLID STICKERS (SN)	NECESSARY	100.00	100.00
1	SET REVERSE SENSOR (SN)	SHORTED	280.00	200.00
1	REAR BUMPER TOP PROTECTOR (SN)	NECESSARY	80.00	50.00
1	SUNDRY (SN)	NECESSARY	50.00	20.00
			648.00	418.00
LABOUR				
	TO DISMANTLE/REPLACE REVERSE SENSOR TO NEW BUMPER AND RESET TO THE SAME.		120.00	30.00
	TO DISMANTLE/REFIT THE INNER GARNISHES, INNER LININGS, INNER TRIMS, CUSHION SEAT, CARPET, ETC TO FACILITATE REPAIRS.	NOT NECESSARY	180.00	-
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS. INCLUDING KNOCK-OUT, STRAIGHTEN, REPAIR, RESHAPE AND ADJUST TO		750.00	200.00

Report Ref No. CS/FC19011225/K1sd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PUTTY AND SPRAY PAINTING ON BOOTLID LOWER GARNISH,REAR BUMPER,END PANEL.	NOT NECESSARY	600.00	360.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.		120.00	-
			1,770.00	590.00
GRAND TOTAL			4,175.70	1,887.30
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,500.00

Report Ref No. CS/FCI19011225/K1sd3n2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.