


ASS. REC. BY: Refuel REF: CS3/LPC18017729/RIN: ⁿ²-11
 Surveyor: Gerald Poh ASSIGNMENT (Office)
 From (Person): Gerald Poh of LPC Date/Time: 24.6.2019
 Estimated Cost: _____ Bill to: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS
 To Inspect Vehicle No: SDT 8209K Insured: SJR 2439S
 at Workshop n/o: TME Automotive Tel: 6898 1533
 of: 7 Soon Lee St # 01-34
 Policy No: _____ Claim No: 18/18/18/VPOS/020953
 Item Insured: _____ Excess: _____
 Make of Veh: _____ D.O.A. 27.4.2016
 (Client's Record) 02/10/18 @ Morning
 CA / REV / REP. / REV 24 HRS ^{'up'} H.O.D. Endorsement: _____
 Date/Time: 2:43pm @ 11/10/18 Person Contacted: Ah Kau Vehicle: IN OUT

Date/Time	Action/Instruction (x) Estimate
	<u>SDT 8209K - NA/INC 11/01/18 1/1</u>
	<u>SJR 2439S - X</u>
	<u>Repairer agreed survey on 2/10/18</u>
	<u>Taukik - 4/10/18, 8/10/18</u>

10/10/18 Submit PPS report
2/7/19 Submit LS \$750 (Red 5400, 4370),
 10 days


1/7/2019

RECEIVED 2 JUL 2019

2/9/19 Mr. Lau have checked
2/9/19 To re-open amend LS \$750, (Red 4900, 3990) Celine 3/9/19
 Pls pass to typist.
4/9/19 reopens not only, 1st ver 3/7/19 ↓

From **Phone**
 PLS call Repetier before going
 02/10/18

1224
 COE XPRY: 2428/SEP

ASSIGNMENT
 SDT 8209K 1990 APR
 M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer /
 Make: **MERCEDES Benz 200E A** 1996
 Colour: **Black** Insured / Std / NI / NA
 No. Holding: **720641** Insured / Std / NI / NA
 Engine: **WDB1240 212 B 214 585**
 Gen. Cond: Good / ☒ Fair / Poor / Burnt
 Steering: ☒ Jammed / Leaked / Burnt /
 Brake: ☒ Jammed / Leaked / Burnt /
 Mod: **NR** / STD A/Rim /
 Tyre Size: **F 195/65R15**
 BS / DUN / EXNOVA / GY / FS / LZA / MIC / OHTSU / PR / SUM /
 TOYO / YOKO / **FRANK**
 Front: **6** Rear: **6**
 R.R. **6** L.R. **6**
 D.O.A. **27/09/18** O.O. **02/10/18 12.11 pm**
 Survey held at: **TMF**
 Date of Damages: **FR / Rear / O/S / N/S / MIC / Rantrop /**
Rene M/s
 The MIC / Chassis frame / Body Structure affected by fire/misuse

SDT 8209K
 TMF Automotive
 7 Soon Lee Street # 01-34

Morning
 Ah Kaw @ 6898 1533
 9739 0213

The veh had commenced its repair at the time of inspection.

CA / REV / REP. / 24HRS (up)
 Date / Time: Action / Instructions

RECEIVED

2018

☐ Prob. Report
☐ Final Report

Days Of Repair:
 Resurvey No. of Trip:

Specimen - For Reference

Report Format
 Lump Sum / LB /

Add Fee: ☐ Day Shop - \$
☐ Inspection - \$
☐ Tyre - \$
☐ Wash - \$

Survey Fee
 Insurance

450

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 1222H

Vehicle Details

Vehicle No: SDT8209K

Vehicle to be Exported: No

Intended Deregistration Date: 04 Oct 2018

Vehicle Make: MERCEDES BENZ

Vehicle Model: 200E AUTO

Primary Colour: Blue

Manufacturing Year: 1990

Engine No: 10296322016866

Chassis No: WD81240212B214985

Maximum Power Output: -

Open Market Value: \$42,753.00

Original Registration Date: 28 Apr 1990

First Registration Date: 28 Apr 1990

Transfer Count: 4

Actual ARF Paid: \$74,818.00

Actual ARF Paid:

Intended PARF Rebate Details

PARF Eligibility: Forfeited

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 30 Sep 2028

COE Category: B - Car (1601cc & above)

COE Period(Years): 10

PQP Paid: \$33,377.00

COE Rebate Amount: \$33,339.00

Total Rebate Amount: \$33,339.00

The information contained herein is correct as at 04 Oct 2018

OK

42K

天
馬
福



TME AUTOMOTIVE PTE LTD

7 Soon Lee Street, #01-34 I-space Building, Singapore 627608

Tel : 6898 1533 Fax : 6268 1968

GST Reg. No. : 201619883C

30 May 2019

PAUL KENNY LIM KOON YEW
C/O 7 Soon Lee Street #01-34
I-Space Building Singapore 627608

REPAIR BILL FOR VEHICLE NO. SDT 8209 K

Total Repair Cost \$12,650.00

Add 7% GST \$ 885.50

Total: \$13,535.50

PRECISION APPRAISAL SERVICES

Insurance Loss Assessors/ Adjusters Cargo Surveyors & Licensed Appraisers

17 Simei St 4 #06-42 Singapore 520227 Fax: 64444886 Company Registration No. 53139926E



AUTOMOBILE INSPECTION REPORT

To:

PAUL KENNY LIM KOON YEW
C/O 7 Soon Lee Street #01-34 I-space
Building Singapore 627608

INSURANCE DETAILS

Insured : -
Policy No. / Claim No. : -
Sum Insured : -
Excess Clause : -
Windscreen Coverage : -
Type of Claims : Third Party Claims
Third Party Insurer : -
Third Party Policy No. : -

REFERENCE

Assigned By : As above
Accident Date : 27 September 2018
Assignment Date : 28 September 2018
Inspection Date : 28 September 2018
Our Reference No. : PAS/TMF/190511/TP

Inspection Report Date : 30 May 2019

Workshop Name :

TMF AUTOMOTIVE PTE LTD

Inspection Address :

7 Soon Lee Street #01-34 I-space Building
Singapore 627608

PARTICULARS OF VEHICLE

Registration No. : SOT 8209 K
Make/Model : MERCEDES BENZ 200E AUTO
Yr of Manuf/Regn : 1990
Carrying Capacity : 4 Seater
Chassis No. : WDB1240212B214985
Engine No. : 10296322016866
Colour : Metallic Black
Class : Passenger (Private)

Mileage : 720641 Km/h
Radio/Cassette : Fitted
CD Disc Player : Fitted
Air Conditioner : Fitted
Clock : Fitted
Seat Belt : Fitted
Wing Mirror Other : Fitted
Accessories : Fitted

PRE-ACCIDENT CONDITION (Static Check Only)

Body Work : Good
Paint Work : Good
Handbrake : Serviceable
Footbrake : Serviceable
Steering : Serviceable
Any Apparent : None
Eng Modifications

VEHICLE VALUE

Market Value : -
Wreck Value (Part) : -

TYRE SIZE & CONDITION

Front N/s Size : 195/65R15 80 %
Make : FALKEN
Rear N/s size : 195/65R15 80 %
Make : FALKEN
Spare Size : 195/65R15 80 %
Make : FALKEN

Front O/s Size : 195/65R15 80 %
Make : FALKEN
Rear O/s Size : 195/65R15 80 %
Make : FALKEN
Spare Size :
Make :
Jack & Tools : Intact/Missing

Type of Wheel Rims: Alloy

Note: The above percentage % represent the estimated remaining tyre threads.

VEHICLE REGN NO : SDT 8209 K
OUR REFERENCE : PAS/TMF/190511/TP
INSPECTION REPORT DATE: 10-Jun-19

APPRAISEMENT SCHEDULE

CONTINUATION SHEET NO :

S/N	Qty	Parts / Labour Descriptions	Remarks / Condition	Repairer's Estimate Amount	Recommendation / Revised Amount
		PARTS SUPPLY - NETT ITEMS		\$ cts	\$ cts
1	1pc	Bootlid	Badly Dented	1261.00	1261.00
2	1pc	Bootlid centre logo	Necessary	56.00	56.00
3	1pc	Bootlid 'E200' emblem	Necessary	68.00	68.00
4	1pc	Bootlid 'Masterpiece' emblem	Necessary	78.00	78.00
5	1pc	Bootlid upper lock	Bent	185.00	185.00
6	1pc	Bootlid key lock	Dented	225.00	225.00
7	1pc	Bootlid central lock	Dented	488.00	488.00
8	1pc	Bootlid lower lock	Bent	455.00	455.00
9	2pcs	Bootlid hinges @\$145	Bent	290.00	290.00
10	1pc	Boat rubber	Torn	188.00	188.00
11	1 pcs	Tailamp assy @\$502	Cracked LH, RH-NN Δ	1004.00	1004.00
12	1pc	Rear bumper	Badly Dented	1148.00	1148.00
13	1pc	Rear bumper centre mldg	Necessary DIS A	189.00	189.00
14	1 pcs	Rear bumper corner mldg @\$163 ✓	Necessary LH-RHS, RH-NN Δ	326.00	326.00
15	1pc	Rear bumper centre garnish	Badly Dented	398.00	398.00
16	1pc	Rear N/s Fender	Badly Dented	1195.43	1195.43
17	1pc	Rear bumper sponge	Serviceable	171.00	-
18	1set	Rear windscreen mldg	Necessary	241.00	241.00
19	1pc	Rear panel	Badly Dented	578.00	578.00
20	1pc	Rear panel top garnish	Warped	95.00	95.00
21	2pcs	Rear bumper bracket @\$44	N/s Cracked	88.00	44.00
21	1pc	Rear N/s Shock absorber	Bent	176.90	176.90
22	1pc	Rear N/s Control Arm ✓✓	Bent	130.41	130.41
23	1pc	Rear N/s torque arm	Bent	144.20	144.20
24	1pc	Rear N/s lateral arm	Bent	138.90	138.90
25	1pc	Rear N/s thrust arm	Bent	55.95	55.95
26	1pc	Rear N/s knuckle arm ✓✓	Bent	244.82	244.82
27	1pc	Rear N/s torsion bar	Bent	237.54	237.54
28	1pc	Rear N/s stabilizer link	Bent	88.00	88.00
29	1pc	Spare tyre well	Badly Dented	2080.35	2080.35
30	1pc	Spare tyre well cover	Cracked	180.09	180.09
		Less: 10% discount		12204.59	11989.59
		SPECIAL NETT ITEMS		12204.59	10790.63
1	1set	Rear windscreen sealant	Necessary	50.00	50.00
2	1set	Rear bumper sensor	Dented	350.00	250.00
3	1set	Rear panel sealant	Necessary	50.00	50.00
4	1set	Bootfloor sealant	Necessary	50.00	50.00
		LABOUR & MISC. CHARGES		12604.59	11090.63
1		Towing - 2Trips		400.00	250.00
2		Remove the necessary affected parts, cut/weld rear panel, spare tyre well, rear n/s fender, straighten both rear chassis rear o/s fender, rear n/s door and replace parts			
3		Putty and spraypaint on all affected parts			
4		Check electrical			
5		Tuff Kote			
6		Remove and refit rear windscreen			
7		Remove and refit rear bumper sensors			
8		Remove and refit rear n/s suspension ✓			
9		Rewire rear portion			
10		Reset Wheel Alignment - Before Repaired ✓			
11		Reset Wheel Alignment - After Repaired ✓			
12		Remove and refit fuel tank			
13		Remove and repair rear suspension crossmember & rear axle components			
14		Remove and refit bootlid components ✓			
		Note: Recommended lump sum repair at \$12,650.00nett.			
		SUB / GRAND TOTAL		18704.59	15810.53

PRECISION APPRAISAL SERVICES



PRECISION APPRAISAL SERVICES

Insurance Loss Assessors / Adjusters Cargo Surveyors & Licensed Appraisers

VEHICLE REGISTRATION NO. : SGH 9687 J


APPENDIX A



POINT OF IMPACT

Direction of impact/damage marked (→) (X)

The vehicle sustained impact on its Rear Portion. (see Diagram D)



GENERAL DESCRIPTION OF DAMAGES

Parts damaged were :

The bootlid, rear bumper and panel, both rear chassis and fenders, spare tyre well, rear n/s door were dented.

ADJUSTMENTS & RECOMMENDATIONS

A static inspection was carried out on 28/09/2018 & our report is here with enclosed for your perusal. The Repairs Estimate submitted by M/s TMF AUTOMOTIVE PTE LTD as per attached Appraisalment Schedule have been revised and scrutinised thoroughly by us & in our opinion, we consider it to be fair and reasonable. The repairer has agreed to effect repairs to the owners satisfaction & to roadworthy condition on in agreed Lump Sum Repair Basis of \$ 12,650.00 after deducting the Policy Excess Clause of \$ NA. As instructed, we have not authorised any of the repairs on your behalf.

	Repairer's		Our	
	Estimate	Amount	Revised	Amount
Repares Parts	12604	59	11090	63
owing Charges	400	00	250	00
'B Labour Charges	2000	00	1600	00
Others Misc Charges	1700	00	1270	00
aintwork	2000	00	1600	00
otal	\$ 18704	59	\$ 15810	63

Under normal circumstances, the duration of repairs should not exceed Sixteen (16) days excluding Pre - Repair Inspection (PRI) / Pre - Repair Survey (PRS) waiting time frame.

Attached photographs taken during inspection One Hundred & Seventy - Five (175) Photographs.

SPECIAL REMARKS

1. The inspection was conducted on a 'without prejudice' basis
2. On 03/10/2018, we examined the extent of damages
3. On 12/11/2018, we examined the repaired vehicle.

Yours Faithfully,



TFNG PHILIP FOO
ACII CAE, AMIMI
AIAME, AMSAE-A
Licensed Appraiser/Adjuster

Inspection Report Date: 30 May 2019















LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD			Ref : CS3/LPC18017729/R1vd3n2-1	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Date : 05-09-2019	
			Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SJR 2439S	Veh. Inspected	SDT 8209K
	Policy No.	Z18VP05017506	Coverage (\$)	0.00
	Claim No.	18/18/18/VP05/020953	Excess (\$)	0.00
	Assign From	GERALD	Assign Date	24/06/2019
2. Vehicle Particulars & Condition				
	Make & Model	MERCEDES BENZ 200E A	c.c	1996
	Engine No.	HIDDEN	Year of Reg.	1990
	Chassis No.	WDB1240212B214985	Colour	BLACK
	Odometer	720641	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/65 R15	FALKEN	6 mm
	L/H Front Tyre	195/65 R15	FALKEN	6 mm
	R/H Rear Tyre	195/65 R15	FALKEN	6 mm
	L/H Rear Tyre	195/65 R15	FALKEN	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	27/09/2018	Inspection Date	02/10/2018
	Survey held at	TMF AUTOMOTIVE PTE LTD 7 SOON LEE STREET #01-34 ISPACE SINGAPORE 627608		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		10 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDT 8209K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BOOTLID (N)	BADLY DENTED	1,261.00	1,261.00
1	BOOTLID CENTRE LOGO (N)	NECESSARY	56.00	56.00
1	BOOTLID "E200" EMBLEM (N)	NECESSARY	68.00	68.00
1	BOOTLID "MASTERPIECE" EMBLEM (N)	NOT FITTED	78.00	-
1	BOOTLID UPPER LOCK (N)	BENT	185.00	185.00
1	BOOTLID KEY LOCK (N)	DENTED	225.00	225.00
1	BOOTLID CENTRAL LOCK (N)	SERVICEABLE	488.00	-
1	BOOTLID LOWER LOCK (N)	SERVICEABLE	455.00	-
2	BOOTLID HINGES @\$145.00 (N)	SERVICEABLE	290.00	-
1	BOOT RUBBER (N)	TORN	188.00	188.00
2	TAILLAMP ASSY @\$502.00 (N)	N/S SCRATCHED / O/S NOT NECESSARY	1,004.00	502.00
1	REAR BUMPER (N)	BADLY DENTED	1,148.00	1,148.00
1	REAR BUMPER CENTRE MLDG (N)	DISTORTED	189.00	189.00
2	REAR BUMPER CORNER MLDG @\$163.00 (N)	N/S DISTORTED / O/S NOT NECESSARY	326.00	163.00
1	REAR BUMPER CENTRE GARNISH (N)	BADLY DENTED	398.00	398.00
1	REAR N/S FENDER (N)	BADLY DENTED	1,195.43	1,195.43
1	REAR BUMPER SPONGE (N)	SERVICEABLE	171.00	-
1	SET REAR WINDSCREEN MLDG (N)	NECESSARY	241.00	241.00
1	REAR PANEL (N)	BADLY DENTED	578.00	578.00
1	REAR PANEL TOP GARNISH (N)	WARPED	95.00	95.00
2	REAR BUMPER BRACKET @\$44.00 (N)	N/S CRACKED	88.00	44.00
1	REAR N/S SHOCK ABSORBER (N)	NOT NECESSARY	176.90	-
1	REAR N/S CONTROL ARM (N)	BENT	130.41	130.41
1	REAR N/S TORQUE ARM (N)	NOT NECESSARY	144.20	-
1	REAR N/S LATERAL ARM (N)	NOT NECESSARY	138.90	-
1	REAR N/S THRUST ARM (N)	NOT NECESSARY	55.95	-
1	REAR N/S KNUCKLE ARM (N)	BENT	244.82	244.82
1	REAR N/S TORSION BAR (N)	NOT NECESSARY	237.54	-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR N/S STABILIZER LINK (N)	NOT NECESSARY	88.00	-
1	SPARE TYRE WELL (N)	TO REPAIR SEE LABOUR	2,080.35	-
1	SPARE TYRE WELL COVER (N)	CRACKED	180.09	180.09
	LESS 10% DISCOUNT		-	-709.18
			12,204.59	6,382.57
	SPECIAL NETT ITEMS			
1	SET REAR WINDSCREEN SEALANT (SN)	NECESSARY	50.00	50.00
1	SET REAR BUMPER SENSOR (SN)	DENTED	350.00	200.00
1	SET REAR PANEL SEALANT (SN)	NECESSARY	50.00	50.00
1	SET BOOTFLOOR SEALANT (SN)	NOT NECESSARY	50.00	-
			500.00	300.00
	LABOUR			
	TOWING-2 TRIPS.		400.00	90.00
	REMOVE THE NECESSARY AFFECTED PARTS,CUT/WELD REAR PANEL,SPARE TYRE WELL,REAR N/S FENDER,STRAIGHTEN BOTH REAR CHASSIS,REAR O/S FENDER,REAR N/S DOOR AND REPLACE PARTS.		2,000.00	1,200.00
	PUTTY AND SPRAYPAINT ON ALL AFFECTED PARTS.		2,000.00	1,200.00
	CHECK ELECTRICAL.		100.00	30.00
	TUFF KOTE.		100.00	60.00
	REMOVE AND REFIT REAR WINDSCREEN.		150.00	120.00
	REMOVE AND REFIT REAR BUMPER SENSORS.		100.00	60.00
	REMOVE AND REFIT REAR N/S SUSPENSION.		400.00	100.00
	REWIRE REAR PORTION.	NOT NECESSARY	50.00	-
	RESET WHEEL ALIGNMENT-BEFORE REPAIRED.)		100.00	80.00
	RESET WHEEL ALIGNMENT-AFTER REPAIRED.)		100.00	-
	REMOVE AND REFIT FUEL TANK.	NOT NECESSARY	100.00	-
	REMOVE AND REPAIR REAR SUSPENSION CROSSMEMBER & REAR AXLE COMPONENTS.	NOT NECESSARY	400.00	-
	REMOVE AND REFIT BOOTLID COMPONENTS.		100.00	80.00
			6,100.00	3,020.00
	GRAND TOTAL		18,804.59	9,702.57

Report Ref No. CS3/LPC18017729/R1vd3n2-1



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			7,750.00
---	--	--	----------

Report Ref No. CS3/LPC18017729/R1vd3n2-1

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.