

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG19011301/R1TD3E2

Date: 02/06/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

**Claimant Vehicle No :** XE2357Y

**Insured Vehicle No :** SMG6395E

Date of Loss: 22/05/2019

Nature of Claim: TP

Claim No: 2899564180SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **XE2357Y**

Make &amp; Model: DAF CF85.410, 12.9 D FT (M)

Engine No: A251651

Reg. Date: 25/10/2016 (Man. Year: 2016)

Chassis No: XL RTE85MC0G113379

Colour: Red

Odometer: 99903 km

Engine Capacity: 12902 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 315/80 R22.5

Rear Tyre Size: 315/80 R22.5 (D)

Front Left Side: AGATE 8 mm

Rear Left Side: AGATE 8/8 mm

Front Right Side: AGATE 8 mm

Rear Right Side: AGATE 8/8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,204.40	2,883.96	320.44	10.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,040.00	750.00	290.00	27.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>4,244.40</b>	<b>3,633.96</b>	<b>610.44</b>	<b>14.38</b>
<b>+ GST 7.00/7.00% (S\$)</b>	297.11	254.38	42.73	14.38
<b>Nett Amount (S\$)</b>	<b>4,541.51</b>	<b>3,888.34</b>	<b>653.17</b>	<b>14.38</b>

### INSPECTION

Date of Assignment: 24/06/2019

Date Inspected: 26/06/2019 Inspected At:

Choon Heng Logistics Pte Ltd (HQ)

1 TUAS AVENUE 20

Singapore 638832

Estimated Period of Repair: 3.0 days

**Adjuster:** MOHD RASUL**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*GRILLE	Cracked	827.00 F	*827.00 FL
2	1		*BUMPER BRACKET	Cracked	1,949.10 F	*1,949.10 FL
3	1		*LAMP BRACKET	Cracked	428.30 F	*428.30 FL
					<b>Sub Total (S\$)</b>	<b>3,204.40</b>
					<b>- List Item Discount on L Items 0.00/10.00% (S\$)</b>	<b>320.44</b>
					<b>Total Parts (S\$)</b>	<b>2,883.96</b>

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	FRONT BUMPER ASSY WILL KNOCK AND USE BACK (NPA)	New	0.00	0.00
2	REMOVAL AND REPLACEMENT OF NEW GRILLE. PANEL BEATING AND SPRAY PAINTING OF BUMPER AND RHD HEADLAMP COVER PANEL. DISMANTLE AND FIX BACK FOR ALL ACCIDENT PARTS	New	1,040.00	750.00
<b>Gross Labour Cost (S\$)</b>			<b>1,040.00</b>	<b>750.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >