

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19011332/UBA3Q2

Date: 12/08/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800109780

Claimant
Vehicle No : FU7121G **Insured Vehicle No :** SME4948J

Date of Loss: 19/03/2019 Nature of Claim: TP Claim No: 8738115060SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FU7121G		
Make & Model:	HONDA CB400 S, 399cc (M)	Engine No:	NC23E2031156
Reg. Date:	28/03/2002 (Man. Year: 2002)	Chassis No:	NC391031115
Colour:	White	Odometer:	0 km
Engine Capacity:	399 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	120-60-17	Rear Tyre Size:	160-60-17
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,729.00	7,414.10	2,314.90	23.79
Miscellaneous Items	0.00	0.00	0.00	
Labour	960.00	335.00	625.00	65.10
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,689.00	7,749.10	2,939.90	27.50
Approved Total (Overridden) (S\$)		6,000.00		
Nett Amount (S\$)	10,689.00	6,000.00	4,689.00	43.87
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 26/06/2019

Date Inspected: 26/06/2019 Inspected At:

Erofia Motor Trading Pte Ltd - (kaki Bukit) (HQ)
1 Kaki Bukit Avenue 6, #02-62
AutoBay @ Kaki Bukit
Singapore 417883

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA

Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TOP COWLING	Cracked	220.00 FL	*220.00 FL
2	1		*FRONT FENDER	Broken	196.00 FL	*196.00 FL
3	1		*HEADLAMP	Cracked	380.00 FL	*380.00 FL
4	1		*HEADLAMP BRACKET	Cracked	65.00 FL	*65.00 FL
5	1		*HEADLAMP REAR BRACKET	Bent	85.00 FL	*85.00 FL
6	2		*FORK INNER TUBES	Bent	620.00 FL	*620.00 FL
7	2		*FORK OUTER TUBES	Bent	640.00 FL	*640.00 FL
8	1		*FORK UNDER BRACKET	Bent	335.00 FL	*285.00 FL
9	2		*FRONT BRAKE DISCS	Bent	910.00 FL	*910.00 FL
10	1		*FRONT RIM SHAFT	Bent	68.00 FL	*68.00 FL
11	1		*FRONT SPORT RIM	Bent	850.00 FL	*850.00 FL
12	1		*METER	Cut	880.00 FL	*880.00 FL
13	1		*HANDLE -BAR	Bent	145.00 FL	*145.00 FL
14	1		*SET HANDLE-GRIP	Necessary	90.00 FL	*90.00 FL
15	2		*SIDE MIRRORS	Broken	190.00 FL	*190.00 FL
16	1		*CLUTCH LEVER	Not Necessary	58.00 FL	*- FL
17	1		*BRAKE LEVER	Scratched	65.00 FL	*65.00 FL
18	2		*FRONT SIGNALS	Broken	170.00 FL	*170.00 FL
19	1		*FUEK TANK	Repair	950.00 FL	*- FL
20	1		*FRONT FOOTREST -R/H	Cut	75.00 FL	*75.00 FL
21	1		*FRONT FOOTREST BRACKET	Bent	245.00 FL	*245.00 FL
22	1		*BRAKE PEDAL	Not Necessary	98.00 FL	*- FL
23	1		*REAR FOOTREST -R/H	Cut	70.00 FL	*70.00 FL
24	1		*EXHAUST PIPE	Dented	865.00 FL	*865.00 FL
25	1		*EXHAUST PIPE PROTECTOR	Scratched	55.00 FL	*55.00 FL
26	1		*REAR SIGNAL -R/H	Cut	85.00 FL	*85.00 FL
27	1		*REAR TAILBOARD	Repair	335.00 FL	*- FL
28	1		*REAR FENDER	Cracked	95.00 FL	*95.00 FL
29	1		*REAR TAILLAMP	Cracked	280.00 FL	*280.00 FL
30	1		*HORN	Dented	80.00 FL	*80.00 FL
31	1		*SET NUMBER PLATE	Bent	28.00 FS	*10.00 FS
32	2		*FORK OILS	Necessary	30.00 FS	*30.00 FS
33	2		*FORK OIL SEALS	Necessary	56.00 FS	*56.00 FS
34	1		*SET STEERING CONE	Necessary	80.00 FS	*80.00 FS
35	1		*STEERING PAMPER	Not fitted	480.00 FS	*- FS
36	1		*E.R.P IU	Not Necessary	175.00 FS	*- FS
37	1		*FRONT TYRE	Serviceable	300.00 FS	*- FS
38	1		*SET CRASH BAR	Bent	300.00 FS	*300.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	10,649.00	8,185.00
- List Item Discount on L Items 10.00/10.00% (\$)	920.00	770.90
Total Parts (\$)	9,729.00	7,414.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PROVIDE TOWING SERVICE	New	50.00	35.00
2	TO PROVIDE LABOUR	New	480.00	300.00
3	TO REPAIR BODY FRAME	New	350.00	0.00
4	TO CHECK WIRING AND RESET HEADLAMP FOCUSING	New	80.00	0.00
Gross Labour Cost (\$\$)			960.00	335.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >