

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLM 3077Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER (CONSISTENT)	BUCKLED / DENTED	497.50	497.50
10	REAR BUMPER CLIP (CONSISTENT)	NECESSARY	40.00	40.00
1	REAR BUMPER SIDE RETAINER LH (CONSISTENT)	SERVICEABLE	112.70	-
1	REAR BUMPER SIDE RETAINER RH (CONSISTENT)	SERVICEABLE	112.70	-
1	REAR BUMPER REINFORCEMENT (CONSISTENT)	TO REPAIR SEE LABOUR	398.90	-
1	REAR BUMPER LOWER GARNISH CENTRE (CONSISTENT)	DENTED / CUT	582.60	582.60
1	REAR BUMPER LOWER GARNISH RH (CONSISTENT)	BUCKLED / MTG CRACKED	149.70	149.70
1	REAR BUMPER TOW COVER (CONSISTENT)	SERVICEABLE	31.70	-
1	REAR BUMPER UNDER COVER RH (CONSISTENT)	SERVICEABLE	187.60	-
4	REAR BUMPER UNDER COVER CLIP (CONSISTENT)	NOT NECESSARY	14.00	-
1	TAIL LAMP RH -LOWER (CONSISTENT)	NOT NECESSARY	511.60	-
	LESS 25% DISCOUNT		-659.75	-317.45
			1,979.25	952.35
	SPECIAL NETT ITEMS			
1	REVERSE SENSOR (SN) (CONSISTENT)	SERVICEABLE	200.00	-
			200.00	-
	<u>LABOUR</u>			
	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (REAR BUMPER ,END PANEL,RHR FENDER).INCLUSIVE OF THE REPAIR OF REAR BUMPER REINFORCEMENT.		600.00	200.00
	TO PUTTY ,RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA.(REAR BUMPER ,END PANEL,RHR FENDER).		600.00	300.00
	TO CHECK WIRING		50.00	15.00
	TO REMOVE & REFIT REVERSE SENSOR .		120.00	50.00
	TO TUFF COAT.	NOT NECESSARY	100.00	
			1,470.00	565.00
	GRAND TOTAL		3,649.25	1,517.35

Report Ref No. CC4/ASM19011337/Kps3q2





Report Ref No. CC4/ASM19011337/Kps3q2

KONG SENG CHEONG

Licensed Appraiser