

ASS. REC. BY:

REF: CS/FCI19011375/Dvd3n2 Special Instruction:

Quoted by: Bryan

ASSIGNMENT (Office)

CWS

From (Person): Eileen Ke

of FCI

Date/Time: 26/6/19 @ 5.25pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHA 5859G

Insured: SH7268G

at Workshop m/s

Chunni Motor

Tel: 65425119

of

AMK Autopoint #01-05/06

Policy No:

Claim No: D19004174MFS#

Sum Insured:

Excess:

Make of Velt:

(Client's Record)

D.O.A. 25/6/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 9.17am @ 27/6/19

Person Contacted:

Jynn

Vehicle IN/OUT

Date/Time

Action/Instruction

I thought /

SH7268G: CS/FCI18003694/Dvd3n2 D.O.A. 19/02/2018

SHA5859G: NA/AG16001904/r3 D.O.A. 29/01/2016

27/6/19

Email preli revised to FCI

ASSIGNMENT

COE July 2025
2017 July

Date:
 Estimated Cost:
 OD / TP / WS / TP RES / OD RES / EVA / HV / MV
 To inspect Vehicle No:
 at Workshop No:
 at:
 Insured:
 Policy No:
 Claims No:
 Claim Insured:
 (Client's Record)
 Make of Veh:


(Policy Conditions)
 Remark: The veh had commenced its repair at the time of inspection.

Est. or Market Value:
 RAC Accident Report: Consistent? Yes or No
 GLA / PRT Cover: Consistent? Yes or No
 Est. Repair: 10 days Res: Yes or No
 Lump Sum: 20 % A Val: Yes or No
 GA / REV / REP. / 24 HRS

Date: Person Contacted: Vehicle IN / OUT

Veh No: SHA 5859 G
 Type: M Car / M Cycle / Bus / Van / Lorry / Prime Mover /
 Truck / Trailer or
 Make: Toyota Prius 1798
 Colour: Blue
 Cap Reading: 194202
 Emp No: 22R3060371
 C/A: JTDKB3F4X03562968
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: Nil / STD / STD ABKin or
 Tyre Size: F: 195/65 R 15
 R: 11

BS / DUN / EXNOVA / GY / ES / LIZA / MIC / OHSU / PIR / SUMI /
 TOYO / YOKO or Goodyear
 Front: R/Ral S mm
 L/Ral S mm
 D.O.A: 25/06/2019
 Survey held at Chunnir AMK
 Des. of Damages: Frt / Rear / O/S / N/S / U/G / Rooftop or
 Rmt y Rev
 The U/G / Chassis frame / Body Structure affected due to collision



Date / Time: Action / Instruction
 First Capital SH 7268 G
 24/07/19 Jnanpr 2/2 20 000/- with 10 days 7 (Red 11,007.86, 36%)

RECEIVED 24 JUL 2019

Date/Time, File Pass to?
 ☐ : Preli. Report
 ☐ : Final Report

24/7- typist

Report Format: CWS
 Lump Sum / L.B.E: 20,000/-

Days Of Repair:
 Resurvey No. of Trip:

Add Fee:
 ☐ Site Insp (\$
 ☐ Interview (\$
 ☐ Tech. Inv. (\$
 ☐ Weekend (\$

27X15=405
 170+405 21X15=315
 Survey Fee: 170+315
 Transportation: 50
 50+50
 238
 873
 963



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D19004174MFSH

Our ref: CS/FCI19011375/Dvd3

Date: 27/6/2019

The Motor Claims Department
MS FIRST CAPITAL INSURANCE LTD

Without Prejudice

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO SHA 5859G


We thank you for your instruction on 26/6/2019

Please be informed that we had conducted the inspection of the above mentioned vehicle on 26/6/2019 at the premises of M/s CHUNNI MOTOR WORK PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$31,027.86
Revised Estimate Amount	: S\$22,322.54
"Check" Items Amount	: S\$
Book Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the front and rear portion



Comments/Present Status:

Damages Consistent

Yours faithfully,

Bryan Ang
Automotive Assessor / Investigator

MOTOR SURVEY ASSIGNMENT

Date	26-06-2019	Our Ref No. D19004174MFSH
Accident Date	25-06-2019	Claim Type. Third Party
Insured Vehicle	SH7268G	Third Party Vehicle. SHA5859G
Survey Location	AMK AUTOPOINT, SOON HOCK MOTOR, #01-05/06	
Contact Person.	LYNN OR IRENE - 65421726	
Contact No.	65427162/ 0	Fax No. 65426039
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CHUNNI MOTOR WORK PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	EILEEN LEE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
 This is a computer generated letter, no signature required.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 27 June 2019 12:20 PM
To: 'CWS Motor Claims'
Cc: 'Eileen Lee'; SUR
Subject: RE: SURVEY ASSESSMENT - D19004174MFSH/1, SHA 5859G
Attachments: SHA 5859G PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SHA 5859G
Date of survey: 26/6/2019
Number of days : 9 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Thursday, 27 June 2019 7:49 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Eileen Lee' <EileenLee@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19004174MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 26 June 2019 5:24 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Eileen Lee <EileenLee@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19004174MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

CHUNNI MOTOR WORK PTE LTD**REPAIR ESTIMATE**

VEHICLE NO: SHA 5859G

DATE : 25.06.2019

MAKE :

TEL NO : 6542 5119

MODEL : TOYOTA PRIUS

FAX NO : 6542 6039

First Capital

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT
LAMP ASSY, FOG, RH NH			\$ 920.00 X
LAMP ASSY, FOG, LH NH			\$ 920.00 X
UNIT ASSY, HEADLAMP, RH (LED) <i>monty broken</i>			\$ 3,455.00 ✓
UNIT ASSY, HEADLAMP, LH (LED) <i>monty broken</i>			\$ 3,455.00 ✓
		6910.00	\$ 8,750.00
SUB TOTAL			\$ 8,750.00
LESS 20% 25%		5182.50	\$ 1,750.00
DISCOUNTED TOTAL			\$ 7,000.00
LABOUR CHARGE			
Panel Beating			\$ 350.00 200/-
Spray Painting Charge			\$ 250.00 200/-
Wiring Charge		430.00	\$ 50.00 30/-
TOTAL LABOUR			\$ 650.00

SHA 5859G

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT
REAR TRUNK LID COVER <i>fine</i>			\$ 1,126.60
REAR TRUNK LID LOCK <i>Don</i>			\$ 457.90
REAR TRUNK LID COVER TRIM BOARD <i>mainly broken</i>			\$ 254.40
REAR TRUNK LID RUBBER <i>deformed</i>			\$ 365.20
REAR TRUNK LID GLASS (BLACK COLOR) <i>broken</i>			\$ 1,569.70
GARNISH SUB-ASSY, BACK DOOR, OUTSIDE <i>dislodged / broken</i>			\$ 889.70
REAR TRUNK LID LOGO(PRIUS) <i>the</i>			\$ 52.90
REAR TRUNK LID LOGO(HYBRID) <i>the</i>			\$ 52.90
REAR TRUNK LID LOGO(TOYOTA STAR) <i>the</i>			\$ 47.00
MOTOR & PUMP ASSY, REAR WASHER <i>NH</i>			\$ 240.80
MOTOR ASSY, REAR WIPER <i>NH</i>			\$ 734.60
REAR BUMPER <i>broken</i>			\$ 458.60
REAR BUMPER RE-INFORCEMENT <i>fine</i>			\$ 318.80
REAR BUMPER UNDER COVER <i>dislodged</i>			\$ 552.60
REAR BUMPER SIDE RETAINER, LH <i>NH</i>			\$ 112.70
REAR BUMPER UNDER SIDE COVER (LH) <i>bt</i>			\$ 232.00
REAR BUMPER UNDER SIDE CENTRE COVER <i>dislodged</i>			\$ 552.60
REAR BUMPER TOWING COVER <i>dislodged</i>			\$ 82.70
REAR BUMPER CLIPS <i>the</i>			\$ 22.00
ARM SUB-ASSY, REAR BUMPER, RH <i>NH</i>			\$ 139.60
ARM SUB-ASSY, REAR BUMPER, LH <i>NH</i>			\$ 139.60
SEAL, REAR BUMPER SIDE, LH <i>dislodged</i>			\$ 148.40
TAIL LAMP ASSY (UPPER) (LH/RH) <i>broken / crack</i>		\$ 557.90	\$ 1,115.80
TAIL LAMP ASSY (LOWER) (LH/RH) <i>broken / crack</i>		\$ 548.40	\$ 1,096.80
REAR END PANEL <i>fine</i>			\$ 602.10
REAR END PANEL GARNISH <i>bt</i>			\$ 165.80
REAR SPARE TYRE PANEL <i>fine</i>			\$ 667.70
REAR FIBER TOOLS BOX TRAY <i>broken</i>			\$ 450.00
REAR EXHAUST PIPE <i>Dental</i>			\$ 1,163.40
REAR EXHAUST PIPE HANGER <i>NH</i>			\$ 40.70
REAR EXHAUST PIPE INSULATOR <i>bt</i>			\$ 314.60
REAR FENDER, LH <i>Dental</i>			\$ 836.70
REAR FENDER, RH <i>NH</i>			\$ 836.70
REAR FENDER PANEL, ROOF SIDE OUTER, LH <i>rev</i>			\$ 311.00
REAR FENDER PANEL, ROOF SIDE OUTER, RH <i>rev</i>			\$ 311.00
REAR FENDER SHEILD (LH) <i>NH</i>			\$ 134.20
REAR FENDER AIR DUCT, LH <i>deformed</i>			\$ 165.10
REAR CHASSIS MEMBER <i>NH</i>			\$ 1,180.80
REAR FLOOR BOARD (LH) <i>fine</i>			\$ 301.00
REAR WINDSCREEN GLASS WITH MOULDING <i>NH</i>			\$ 1,778.30
SPOILER SUB-ASSY, REAR <i>NH</i>			\$ 953.70
		15841.30	
		11880.97	
SUB TOTAL			\$ 20,976.70
LESS 20% <i>25%</i>			\$ 4,195.34
DISCOUNTED TOTAL			\$ 16,781.36

SHA 5859G

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT	
REAR NO. PLATE WITH TRIM COVER <i>vt</i>			\$ 45/100.00	NETT ✓
REAR TRUNK LID APPS STICKER <i>hlc</i>			\$ 40.00	NETT ✓
REAR TRUNK LID COMFORT & TEL NO. STICKER <i>hlc</i>			\$ 60.00	NETT ✓
REAR BUMPER REVERSE SENSOR <i>Dew</i>			\$ 135.70	NETT ✓
REAR BUMPER RUBBER MAT <i>dislodged</i>			\$ 50.00	NETT ✓
REAR WINDSCREEN SEALANT <i>hlc</i>		376.70	\$ 46.00	NETT ✓
			\$ 431.70	
LABOUR CHARGE				
Panel Beating			\$ 2,200.00	1200/-
Spray Painting Charge			\$ 1,500.00	1000/-
Wiring Charge			\$ 50.00	30/-
Tuff Kote			\$ 100.00	40/-
Rear Chassis Alignment Charge			\$ 400.00	110/-
Remove/Refix Cushion & Upholstery Rear		2530.00	\$ 150.00	80/-
Remove/Refix Rear Windscreen Glass			\$ 120.00	80/-
Remove/Refix Reverse Sensor			\$ 80.00	40/-
Remove/Refix Fuel Tank			\$ 150.00	110/-
Remove/Refix Exhaust Pipe			\$ 150.00	60/-
Diagnosis & Resetting To Erase Fault Code			\$ 480.00	110/-
			\$ 5,380.00	
TOTAL LABOUR				
ESTIMATE TOTAL		20400.17	\$ 30,243.06	
26/06/2019 @ 1015hrs		Supp 5076.75	31,027.86	
HA Antura		25476.92	1/520000/-	
4/5mth 9 days				
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: _____ Date: _____				

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

CHUNNI MOTOR WORK PTE LTD**REPAIR ESTIMATE**

VEHICLE NO: SHA 5859G (Supplementary)

DATE : 26.06.2019

MAKE :

TEL NO : 6542 5119

MODEL : TOYOTA PRIUS

FAX NO : 6542 6039

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT
TAIL LAMP QUARTER PANEL, LH <i>Replaced</i>			\$ 99.00 ✓
TAIL LAMP QUARTER PANEL INNER, LH <i>Replaced</i>			\$ 69.00 ✓
REAR FENDER TRIMBOARD (LH) <i>B7</i>			\$ 725.00 ✓
REAR SPARE TYRE NUT <i>broken / B7</i>			\$ 88.00 ✓
SUB TOTAL			\$ 981.00
LESS 20% <i>25%</i>			\$ 196.20
DISCOUNTED TOTAL			\$ 784.80
<i>26/06/2019</i> <i>[Signature]</i> <i>2KK And</i> <i>[Signature]</i>			<i>735.75</i>

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19011375/Dvd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 25-07-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 7268G	Veh. Inspected	SHA 5859G	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19004174MFSH	Excess (\$)	0.00	
Assign From	EILEEN LEE	Assign Date	26/06/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JTDKB3FUX03562968	Colour	BLUE	
Odometer	194202	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	GOODYEAR	5 mm	
L/H Front Tyre	195/65 R15	GOODYEAR	5 mm	
R/H Rear Tyre	195/65 R15	GOODYEAR	5 mm	
L/H Rear Tyre	195/65 R15	GOODYEAR	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	25/06/2019	Inspection Date	26/06/2019	
Survey held at	CHUNNI MOTOR WORK PTE LTD BLK 10 ANG MO KIO IND. PARK 2A, #03-19 AMK AUTOPOINT SINGAPORE 568047.			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			10 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 5859G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	LAMP ASSY,FOG,RH	NOT NECESSARY	920.00	-
1	LAMP ASSY,FOG,LH	NOT NECESSARY	920.00	-
1	UNIT ASSY,HEADLAMP,RH (LED)	MOUNTING BROKEN	3,455.00	3,455.00
1	UNIT ASSY,HEADLAMP,LH (LED)	MOUNTING BROKEN	3,455.00	3,455.00
1	REAR TRUNK LID COVER	BUCKLED	1,126.60	1,126.60
1	REAR TRUNK LID LOCK	DAMAGED	457.90	457.90
1	REAR TRUNK LID COVER TRIM BOARD	MOUNTING BROKEN	254.40	254.40
1	REAR TRUNK LID RUBBER	DEFORMED	365.20	365.20
1	REAR TRUNK LID GLASS (BLACK COLOR)	BROKEN	1,569.70	1,569.70
1	GARNISH SUB-ASSY,BACK DOOR,OUTSIDE	DISLODGE / BROKEN	889.70	889.70
1	REAR TRUNK LID LOGO (PRIUS)	NECESSARY	52.90	52.90
1	REAR TRUNK LID LOGO (HYBRID)	NECESSARY	52.90	52.90
1	REAR TRUNK LID LOGO (TOYOTA STAR)	NECESSARY	47.00	47.00
1	MOTOR & PUMP ASSY,REAR WASHER	NOT NECESSARY	240.80	-
1	MOTOR ASSY,REAR WIPER	NOT NECESSARY	734.60	-
1	REAR BUMPER	BROKEN	458.60	458.60
1	REAR BUMPER RE-INFORCEMENT	BUCKLED	318.80	318.80
1	REAR BUMPER UNDER COVER	DISLODGE	552.60	552.60
1	REAR BUMPER SIDE RETAINER,LH	NOT NECESSARY	112.70	-
1	REAR BUMPER UNDER SIDE COVER (LH)	BENT	232.00	232.00
1	REAR BUMPER UNDER SIDE CENTRE COVER	DISLODGE	552.60	552.60
1	REAR BUMPER TOWING COVER	DISLODGE	82.70	82.70
10	REAR BUMPER CLIPS	NECESSARY	22.00	22.00
1	ARM SUB-ASSY,REAR BUMPER,RH	NOT NECESSARY	139.60	-
1	ARM SUB-ASSY,REAR BUMPER,LH	NOT NECESSARY	139.60	-
1	SEAL,REAR BUMPER SIDE,LH	DISLODGE	148.40	148.40
2	TAIL LAMP ASSY (UPPER)(LH/RH) @\$557.90	BROKEN / CRACKED	1,115.80	1,115.80

Report Ref No. CS/FCI19011375/Dvd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	TAIL LAMP ASSY (LOWER)(LH/RH) @\$548.40	BROKEN / CRACKED	1,096.80	1,096.80
1	REAR END PANEL	BUCKLED	602.10	602.10
1	REAR END PANEL GARNISH	BENT	165.80	165.80
1	REAR SPARE TYRE PANEL	BUCKLED	667.70	667.70
1	REAR FIBER TOOLS BOX TRAY	BROKEN	450.00	450.00
1	REAR EXHAUST PIPE	DENTED	1,163.40	1,163.40
1	REAR EXHAUST PIPE HANGER	NOT NECESSARY	40.70	-
1	REAR EXHAUST PIPE INSULATOR	BENT	314.60	314.60
1	REAR FENDER,LH	DENTED	836.70	836.70
1	REAR FENDER,RH	NOT NECESSARY	836.70	-
1	REAR FENDER PANEL,ROOF SIDE OUTER,LH	TO REPAIR SEE LABOUR	311.00	-
1	REAR FENDER PANEL,ROOF SIDE OUTER,RH	TO REPAIR SEE LABOUR	311.00	-
1	REAR FENDER SHIELD (LH)	NOT NECESSARY	134.20	-
1	REAR FENDER AIR DUCT,LH	DEFORMED	165.10	165.10
1	REAR CHASSIS MEMBER	NOT NECESSARY	1,180.80	-
1	REAR FLOOR BOARD (LH)	BUCKLED	301.00	301.00
1	REAR WINDSCREEN GLASS WITH MOULDING	NECESSARY	1,778.30	1,778.30
1	SPOILER SUB-ASSY,REAR	NOT NECESSARY	953.70	-
1	REAR TYRE RIM,LH (ADDITIONAL)	NOT NECESSARY	1,555.00	-
1	REAR WHEEL HUB CAP,LH (ADDITIONAL)	NOT NECESSARY	177.70	-
1	REAR WHEEL BEARING ING & HUB,LH (ADDITIONAL)	DAMAGED	610.20	610.20
1	REAR CROSS MEMBER (ADDITIONAL)	BENT	2,200.40	2,200.40
1	REAR SHOCK ABSORBER,LH (ADDITIONAL)	DISTORTED / BENT	118.30	118.30
1	REAR SHOCK ABSORBER MOUNTING,LH (ADDITIONAL)	NOT NECESSARY	125.30	-
1	REAR LOWER ARM,LH (ADDITIONAL)	DISTORTED	497.50	497.50
1	REAR UPPER ARM,LH (ADDITIONAL)	DISTORTED	356.80	356.80
1	REAR KNUCKLE ARM,LH (ADDITIONAL)	DISTORTED	810.60	405.30
1	REAR STABILIZER BAR (ADDITIONAL)	DISTORTED	311.50	311.50
1	REAR STABILIZER LINK,LH (ADDITIONAL)	DISTORTED	151.60	151.60
1	REAR TRAILING ARM,LH (ADDITIONAL)	DISTORTED	314.20	314.20
1	REAR ASSIST ARM,LH (ADDITIONAL)	DISTORTED	342.20	342.20

Report Ref No. CS/FCI19011375/Dvd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	TAIL LAMP QUARTER PANEL,LH (ADDITIONAL)	DENTED	99.00	99.00
1	TAIL LAMP QUARTER PANEL INNER,LH (ADDITIONAL)	DENTED	69.00	69.00
1	REAR FENDER TRIMBOARD (LH)(ADDITIONAL)	BENT	725.00	725.00
1	REAR SPARE TYRE NUT (ADDITIONAL)	BROKEN / BENT	88.00	88.00
	LESS 20% DISCOUNT		-7,655.80	-
	LESS 25% DISCOUNT		-	-7,260.08
			30,623.20	21,780.22
	SPECIAL NETT ITEMS			
1	REAR NO PLATE WITH TRIM COVER (SN)	BENT	100.00	45.00
1	REAR TRUNK LID APPS STICKER (SN)	NECESSARY	40.00	40.00
1	REAR TRUNK LID COMFORT & TEL NO STICKER (SN)	NECESSARY	60.00	60.00
1	REAR BUMPER REVERSE SENSOR (SN)	DAMAGED	135.70	135.70
1	REAR BUMPER RUBBER MAT (SN)	DISLODGE	50.00	50.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	46.00	46.00
1	REAR TYRE,LH (ADDITIONAL)(SN)	NOT NECESSARY	216.00	-
			647.70	376.70
	LABOUR			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR FENDER PANEL,ROOF SIDE OUTER,LH AND REAR FENDER PANEL,ROOF SIDE OUTER,RH.		2,550.00	1,400.00
	SPRAY PAINTING CHARGE.		1,750.00	1,200.00
	WIRING CHARGE.		100.00	60.00
	TUFF KOTE.		100.00	40.00
	REAR CHASSIS ALIGNMENT CHARGE.	NOT NECESSARY	400.00	-
	REMOVE/REFIX CUSHION & UPHOLSTERY REAR.		150.00	80.00
	REMOVE/REFIX REAR WINDSCREEN GLASS.		120.00	80.00
	REMOVE/REFIX REVERSE SENSOR.		80.00	40.00
	REMOVE/REFIX FUEL TANK.	NOT NECESSARY	150.00	-
	REMOVE/REFIX EXHAUST PIPE.		150.00	60.00
	DIAGNOSIS & RESETTING TO ERASE FAULT CODE.	NOT NECESSARY	480.00	-
	REMOVE/REFIX UNDERCARRIAGE (RR)(ADDITIONAL).		200.00	150.00
	REAR WHEEL ALIGNMENT (ADDITIONAL).		80.00	60.00

Report Ref No. CS/FCI19011375/Dvd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	RE-SET ABS SYSTEM (ADDITIONAL).		200.00	150.00
			6,510.00	3,320.00
GRAND TOTAL			37,780.90	25,476.92
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				20,000.00

Report Ref No. CS/FCI19011375/Dvd3n2

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.