

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793J . Tel: 6741-1730 / 731 . Fax: 6744-5746. Email: liusbros@gmail.com

Invoice/Ref No: YP522E190620

Estimate**Customer**

Name: AIG Asia Pacific Insurance Pte Ltd

Date: 26-06-19

Address Motor Claims Department

Vehicle No: YP522E

78 Shenton Way #07-16

Model/Make: Mitsubishi

AIG Building

Singapore 079120

Canter FEB21ER3SDEB (CBU)

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear Tail Lamp	\$ 225.30	
2	Tail Lamp Bracket	\$ 185.00	
3	Cargo Box Rear Door	\$ 1,200.00	SN
4	Cargo Box Rear Door "Corporate Advertisement & Artwork"	\$ 680.00	SN 650 S.W
5	Cargo Box Lower Wooden	\$ 800.00	SN 680 S.W
6	Step Wooden	\$ 320.00	SN
7	Safety Bumper	\$ 950.00	SN
8	Number Plate "Metal"	\$ 28.00	SN
9	Number Plate Bracket	\$ 95.00	SN
	To check all wiring & electrical component for proper function	\$ 50.00	20
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 800.00	600
	To putty & spray painting & including touch up paint on accident affected area	\$ 900.00	600
	To apply Rust Proofing, reseal tuff-coating treatment on accident area	\$ 80.00	11X

Total Parts & Labour of estimate for damaged vehicle

\$ 6,313.30

Total amount in Lump Sum Basis for repaired vehicle

SDLS:



M/s Liu's Brother Auto Engrg Wks

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P- 410.30
 252
 1- 307.72
 S.W 2864.00
 10km - 1220.00
 439772
 3513

not added
 2/5 \$3500
 4 day