

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19011412/KKA3Q2

Date: 28/04/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100431394

Claimant Vehicle No : SJK6776D **Insured Vehicle No :** SKV7836M

Date of Loss: 25/06/2019 Nature of Claim: TP Claim No: 8886335901SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJK6776D**

Make & Model: NISSAN ALMERA, 1.5 4AT ABS AIRBAG 2WD 4DR (A) Engine No: HR15926135D

Reg. Date: 13/05/2016 (Man. Year: 2016) Chassis No: MNTBBAN17Z0005582

Colour: Metallic Grey Odometer: 80857 km

Engine Capacity: 1498 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/65 R15 Rear Tyre Size: 185/65 R15

Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,004.33	978.05	26.28	2.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	950.00	780.00	170.00	17.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,954.33	1,758.05	196.28	10.04
+ GST 7.00/7.00% (S\$)	136.80	123.06	13.74	10.04
Nett Amount (S\$)	2,091.13	1,881.11	210.02	10.04
+ Loss of Use (3.0 x S\$100.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		8.00		
Nett Liability (S\$)		2,189.11		

INSPECTION

Date of Assignment: 09/09/2019

Date Inspected: 09/09/2019 Inspected At: Cheng Hoe Motor Pte Ltd (Yishun)
Blk 1019 #01-374/382, Yishun
Industrial Park A
Singapore 768761

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG

Manager: Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	545.10 FN	*545.10 FN
2	1		*REAR BUMPER RH SIDE RETAINER	Not Necessary	29.20 FN	*- FN
3	6		*REAR BUMPER CLIPS	Necessary	27.00 FN	*27.00 FN
4	1		*RH TAIL LAMP	Cracked	292.40 FN	*292.40 FN
5	1		*REVERSE SENSOR	Necessary	200.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$\$)	1,093.70	1,064.50
- Nett Item Discount on N Items 10.00/10.00% (\$\$)	89.37	86.45

Total Parts (\$\$)	1,004.33	978.05
---------------------------	-----------------	---------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	400.00	300.00
2	PUTTY AND RESPRAY ON REAR PORTION	New	550.00	480.00
Gross Labour Cost (\$)			950.00	780.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >