

ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Klo, Ind Park 2 #01-251/ 259, 569536. Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperl.com.sg

tepair Estimates	SME 5685 K		IV of Mathoria
	Finalised		A.
a) Cost / List Price Items	\$ 4470-76 6,020.16		Not Nothern Repair
Plus/Less 25%	\$ 1242 69 1,505.04		77
Total of Cost / List	\$3773 07 4,515.12		
b) Nett Price Items		-	
Less			8
Total of Nett Item			
c) Special Nett Items	\$ 240.00 295.00		
ts Cost	\$3968-07 4,810.12		
	\$ 1990-00 3,430.00		
	77-2 03-	102.	
	\$ 3436 7 8,240.12	2060-20	
∍ total will be subjected to 7	\$ 5956 8,240.12 % G.S.T.	5820-30	
∍ total will be subjected to 7			
∍ total will be subjected to 7			
		Kennerh	
of Surveyor		Kennerh LKIe 28/8/19 at	
of Surveyor iny		Kennerh LKIe	
of Surveyor iny conducted on ks By Surveyor	% G.S.T.	Kennerh LKle 28/6/19 at	
of Surveyor iny conducted on ks By Surveyor ie repair of this vehicle is ay	% G.S.T. : :	Kennerh LKle 28/6/19 at	
of Surveyor iny conducted on ks By Surveyor ie repair of this vehicle is au	% G.S.T. : :	Kennerh LICIe 28/8/19 at antil further notice. 26 day(s)	
of Surveyor iny conducted on ks By Surveyor	% G.S.T. : throughout firms and the state of the	Kennerh LICIe 28/8/19 at antil further notice. 26 day(s)	



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536. Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : Make & Model :

Chassis No

SME 5685 K

TOYOTA PRIUS ALPHA ZVW400030095 Submit By

Year Manufacture

Engine No.

JENNY 2018

Cost / List

S/No.	Part Description		Qty	Unit Price	Price	Disposition by Surveyor
1	Rear windscreen moulding	Na	1	\$70.20		
2	Rear windscreen sealant	Ne	1	\$50.00	S.N	Para
3	Reverse sensor	ne	1	\$200.00	S,N	-
4	Rear number plate	Sz.	. 1	\$45.00	S.N	X
(5)	Rear bumper	Ry	1	\$459.20		
6	Rear bumper clip	n	10	\$38.90		-
7	Rear bumper side retainer LH	pri	1	\$121.70		
8	Rear bumper side retainer RH	0,3	1	\$121.70		_
9	Rear bumper reinforcement		1	N/A		
10	Rear bumper reflector LH	Sh	1	\$58.70		X
-11	Rear bumper reflector RH	54	1	\$58.70		X
(12)	Tail door	B	1	\$1,022.50		
13	Tail door lock	ne	1 1	\$391.60		-
14	Tail door plate garnish	Si	1	\$498.30		Х
15	Tail door emblem	na	1	\$67.10		_
16	Wording "PRIUSCX"	Na	1	\$72.66		_
17	Tail door trim	In	1	\$433.70		7
18	Tail end panel	A	1	\$678.10		3
19	Tail end panel garnish	Re	1	\$154.60		
20	Tail end panel garnish clip	n	10	\$39.20		
21	Boot weatherstrip	Dd IR	11	\$342.70		7
22	Tail lamp LH 561-35	cm	1	\$653.20		2
23	Tail Lamp RH 561-35	cm	1	\$653.20		1

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge

will be charged accordingly under supplementary.

Blk 5033 Ang Mo Kio Industrial Park 2 #01-259 Singapore 569536 Tel: 64841221 Fax: 64847829 Company Reg No. 200005485N / GST No. 20-0005485-N

488656

240 SN

Spare	Pari	ts
-------	------	----

Vehic	le	No.	:
Make	8	Model	4 +

Chassis No :

SME 5685 K

TOYOTA PRIUS ALPHA

ZVW400030095

Submit By

Year Manufacture

Carmen Lim

2018

Engine No. Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition b
24	Tail lamp clip	2			Surveyor
25			\$84.20		
26					
27					
28					
29					
30					
31					
32					
33					
34					
35					
36					
37		-			
38					
39					
40					
41		-			
42		-			
43					
44					
45					
46		-			

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Klo, Ind Park 2 #01-251/ 259, 569536. Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperl.com.sg

Labour

Vehicle No.

SME 5685 K

Submit By

Carmen Lim

Make & Model

TOYOTA PRIUS ALPHA

Year of Manufacture:

2018

Labour Description	Esimated	Adjusted
TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT	Frice	Price
REPAIR AREA. (TAIL DOOR, REAR BUMPER, END PANEL		
SPARE TYRE WELL PANEL)	\$1,200.00	7001
TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT		
REPAIR AREA. (TAIL DOOR, REAR BUMPER END PANEL		
SPARE TYRE WELL PANEL)	\$1,400.00	8801
To check wiring	\$50.00	201
To remove & refit reverse sensor	\$120.00	501
To remove & refit spare tyre, spare tyre board, carpet trim	\$150.00	801
to assist work load,	7.00.00	
To remove & refit rear windscreen	\$120.00	~
To tuff coat	\$150.00	601
To transfer boot mechanism to new boot	\$120.00	601
o conduct water leakage tests to ensure proper air and	\$120.00	201
ealing	7.20.00	
	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (TAIL DOOR, REAR BUMPER, END PANEL, SPARE TYRE WELL PANEL) TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (TAIL DOOR, REAR BUMPER, END PANEL, SPARE TYRE WELL PANEL) To check wiring To remove & refit reverse sensor To remove & refit spare tyre, spare tyre board, carpet trim to assist work load. To remove & refit rear windscreen To tuff coat To transfer boot mechanism to new boot To conduct water leakage tests to ensure proper air and	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (TAIL DOOR,REAR BUMPER,END PANEL, SPARE TYRE WELL PANEL) TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (TAIL DOOR,REAR BUMPER,END PANEL, SPARE TYRE WELL PANEL) To check wiring \$1,400.00 To remove & refit reverse sensor \$120.00 To remove & refit spare tyre, spare tyre board, carpet trim to assist work load. To remove & refit rear windscreen \$150.00 To tuff coat \$150.00 To transfer boot mechanism to new boot \$120.00 To conduct water leakage tests to ensure proper air and

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.