

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/III19011431/KPS3Q2

**Date:** 24/06/2020

### REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D19MCV0002409
<b>Claimant Vehicle No :</b>	GW7786R	<b>Insured Vehicle No :</b>	GBD600Z
Date of Loss:	22/06/2019	Nature of Claim:	TP
		Claim No:	MCV2019D0000669

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GW7786R	Engine No:	QD32183398
Make & Model:	NISSAN CABSTAR, 2.0 (M)	Chassis No:	JN1SF4F23Z0851185
Reg. Date:	29/10/2003 (Man. Year: 2003)	Odometer:	626032 km
Colour:	Metallic Gold		
Engine Capacity:	3153 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	195R15X8	Rear Tyre Size:	155 R12X8 (D)
Front Left Side:	OHTSU 7 mm	Rear Left Side:	Falken 1/1 mm
Front Right Side:	OHTSU 7 mm	Rear Right Side:	Falken 1/1 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,774.43	2,964.57	-190.14	-6.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,180.00	950.00	230.00	19.49
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>3,954.43</b>	<b>3,914.57</b>	<b>39.86</b>	<b>1.01</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,100.00</b>		
<b>Nett Amount (S\$)</b>	<b>3,954.43</b>	<b>3,100.00</b>	<b>854.43</b>	<b>21.61</b>
<b>+ Loss of Use (4.0 x S\$60.00/day) (S\$)</b>		240.00		
		<b>(S\$)</b>		
		3,340.00		
<b>Liabe Amount (50.00%) (S\$)</b>		<b>1,670.00</b>		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>1,677.45</b>		
<b>Global Sum Settlement (S\$)</b>		<b>1,670.00</b>		

### INSPECTION

Date of Assignment: 26/06/2019

Date Inspected: 03/07/2019 Inspected At:

Kay Motor (HQ)  
BLK 9 SIN MING INDUSTRIAL

ESTATE #01-46  
Singapore 565744

Estimated Period of Repair: 4.0 days

---

**Adjuster:** KENNETH KONG

**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 02 Jan 2020)	
<b>Parts:</b>	N/A	NISSAN CABSTAR 2.0 (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GW7786R)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*O/S FRONT DOOR	Bent	1,882.79 FL	*1,696.20 FL
2	1		*O/S FRONT DOOR VIEW MIRROR	Serviceable	149.00 FL	*- FL
3	1		*O/S FRONT STEP BOARD	Dented / Cut	256.35 FL	*256.35 FL
4	1		*O/S FRONT CORNER PANEL	Bent	486.00 FL	*428.90 FL
5	1		*O/S FRONT SIDE LAMP	Broken	214.80 FL	*214.80 FL
6	1		*FRONT BUMPER	Dented / Cut	903.10 FL	*675.50 FL
7	1		*LETTERING	Necessary	50.00 FS	*20.00 FS
					<b>Sub Total (\$\$)</b>	<b>3,942.04</b>
					<b>- List Item Discount on L Items 30.00/10.00% (\$\$)</b>	<b>1,167.61</b>
					<b>Total Parts (\$\$)</b>	<b>2,774.43</b>
						<b>2,964.57</b>

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & REFIT O/S DOOR GLASS & MECHANISM	New	50.00	50.00
2	TO PUTTY & SPRAY PAINTING	New	550.00	450.00
3	TO REPAIR & PANELBEAT O/S DOOR PILLAR ,DISMANTLE & FIT THE ABOVE PARTS	New	580.00	450.00
<b>Gross Labour Cost (S\$)</b>			<b>1,180.00</b>	<b>950.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >