

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19011434/KKA3Q2

Date: 30/12/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994335
Claimant
Vehicle No : SMG2016B **Insured Vehicle No :** SJS3641L
Date of Loss: 23/06/2019 **Nature of Claim:** TP **Claim No:** 9591822258SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMG2016B
Make & Model: TOYOTA NOAH HYBRID, 1.8 (A) **Engine No:** 2ZR0B67840
Reg. Date: 10/12/2018 (Man. Year: 2018) **Chassis No:** ZWR800324338
Colour: Metallic Pearl White **Odometer:** 74300 km
Engine Capacity: 1797 cc
Market Value/New Car Price: N/A
Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes **Footbrake (Serviceable):** Yes
Handbrake (Serviceable): Yes **Engine Modification:** No **Pre-accident Condition:**

CONDITION OF TYRES

Front Tyre Size: 195/60 R15 **Rear Tyre Size:** 195/60 R15
Front Left Side: Michelin 8 mm **Rear Left Side:** Michelin 8 mm
Front Right Side: Michelin 8 mm **Rear Right Side:** Michelin 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,606.54	1,456.54	150.00	9.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,980.00	1,270.00	710.00	35.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	3,586.54	2,726.54	860.00	23.98
+ GST 7.00/7.00% (\$\$)	251.06	190.86	60.20	23.98
Nett Amount (\$\$)	3,837.60	2,917.40	920.20	23.98
Global Sum Settlement (\$\$)		0.00		

INSPECTION

Date of Assignment: 01/07/2019
Date Inspected: 01/07/2019 **Inspected At:** 9A SERANGOON NORTH AVE 5
Repaired: Optima Werkz Pte Ltd (HQ)
Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR RH	Bent	1,839.50 FL	*1,839.50 FL
2	1		*REAR DOOR FRAME PROTECTIVE STICKER RH	Necessary	102.55 FL	*102.55 FL
3	1		*FRONT DOOR RH (NPA)	Repair	0.00 FL	*- FL
4	1		*REAR WHEEL ARCH PANEL RH (NPA)	Repair	0.00 FL	*- FL
5	1		*FRONT DOOR PROTECTIVE RUBBER RH	*Check	150.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	2,092.05	1,942.05
- List Item Discount on L Items 25.00/25.00% (\$)	485.51	485.51

Total Parts (\$)	1,606.54	1,456.54
-------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR CHARGES TO REMOVE ,REPAIR ,REPLACE ,READJUST ,ALL ACCIDENT AREAS & ETC	New	800.00	500.00
2	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIAL AT FRONT DOOR RH ,SLIDING DOOR RH ,REAR WHEEL ARCH PANEL & ETC	New	900.00	660.00
3	TO DISMANTLE & REINSTALL SLIDING DOOR INNER MECHANISM & ETC BACK TO ORIGINAL OPERATION	New	120.00	60.00
4	TO CHECK WIRING & DOOR CENTRAL LOCKING SYSTEM & ETC	New	80.00	20.00
5	TO UNDERSEAL MATERIALS	New	80.00	30.00
Gross Labour Cost (\$\$)			1,980.00	1,270.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >