

ASS. REC. BY:

REF: C83/MSG19000127/TIV d352-1

From (Person):

Tan Kah Leh
Katherine Wong

ASSIGNMENT (Office)

MSIG

24/6/2019

Date/Time: 3/11/19 @ 2:39pm

Estimated Cost

Bill to

OD (12) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SMA 9819L

Insured:

SG2 8393T

at Workshop no:

Kok Wong Car Grooming

Tel:

9183 9633

of

No.1 Soon Lee Strt # 06-40 Pioneer

Policy No:

A804 2337 4AMX

Claim No:

580660

Sum Insured:

Excess:

Make of Veh:

D.O.A.

25/12/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS ^{1up}

H.O.D. Endorsement:

07/01/2019

Date/Time:

2:59pm @ 3/11/19

Person Contacted:

Mr. Kok

Vehicle:

INT/OUT

Date/Time	Action/Instruction (X) Estimate
	SMA 9819L - NA / EQI 18019284 / 24
	SG2 8393T - X
	Over never turn up on 07/01/19. Repenter arrange on 8/1/19
	Disassemble: 10/1/2019.
12/1/19	Submit LS \$ 1700 (Red 1750, 5170)

459/1700; 4 days

Do Not Finalise

RECEIVED 15 JUL 2019


10/7/2019

REF: MS1G

ASSIGNMENT

CoE 2023 May
2019, Jan

From: Date: 07/01/19

Estimated Cost

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMA9819L

at Workshop m/s: Kok Wong Car Grooming

of No. 1 Soon Lee St. #06-40

Insured

Policy No

Claims No

Sum Insured


Excess

(Client's Record)

Make of Veh.

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Est. or Market Value:

IDAC Accident Rpt. Consistent? Yes or No

GIA / PR Seen: Consistent? Yes or No

Est. Repairs: 4 days Res: Yes or No

Lump Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS^{1up}

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SMA9819L

Type: M / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota 911's

C.C. 1598

Colour

Silver

A/C

Insured / Std / NI / NA

Sp. Reading

14.291

T/Radio

Insured / Std / NI / NA

Eng/No:

C/N:

MR053 ZEE12611358

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: N/A / Rim / STD A/Rim or

195/65R15

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

8/1/170/172

Survey held at

Kok Wong

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear m/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

- Estimated repair range \$2000 - \$2,500

14/1/2019

Date/Time, File Pass to?

☐

: Prol. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip: 1

Survey Fee:

Transportation

) G + RS. \$

) Photos

) Others

TOTAL

Report Format: PRS

Lump Sum / I.B.E. (\$)

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$



**ABSOLUTE APPRAISAL SERVICES PTE LTD
LOSS ADJUSTERS & MOTOR APPRAISERS**

160 Sin Ming Drive #05-16 Sin Ming AutoCity (S) 575722

Mobile: 9688-0413 Fax: 6266-7396

Email: absolute.app.svcs@gmail.com

Vehicle Inspection Report

To: Fei Siong (F&B) Holdings Pte Ltd
C/o: 1 Soon Lee Street #06-40 Pioneer Centre
Singapore 627605

Date of report: 26.01.2019
Date of request: 08.01.2019
Date of inspection: 08.01.2019
Date of accident: 25.12.2018
Claim type: Third Party Claim

Report No: AAS/2019/011

Particulars of affected vehicle:

Registration no:	SMA9819L	Odometer:	142091 km
Make/Model:	Toyota Corolla Altis 1.6 (A)	Engine Capacity:	1598 cc
Year of registration:	2008	Engine no:	3ZZ4769743
Colour:	Metallic Blue	Chassis no:	MR053ZEE106111358

Condition of tires:

Front Left:	5mm	Front Right:	5mm
Make:	Dunlop	Make:	Dunlop
Rear Left:	6m	Rear Right:	6m
Make:	Dunlop	Make:	Dunlop

Type of road wheel: Alloy (The above represent the remaining life of the tire thread)

Pre-accident condition (Static tests only)

General Bodywork	: Good
Paintwork	: Good
Handbrake	: In order
Footbrake	: In order
Steering	: In order
Apparent engine modification	: Nil

The Assignment

The inspection was conduct at M/s. Kok Wang Car Grooming
1 Soon Lee Street #06-40 Pioneer Centre
Singapore 627605

(Subsequent inspection was conducted)

Assessment

Repairer's estimate:	\$ 6,201.92
Revised estimate:	\$ 4,286.60
Recommended reserve:	\$ 3,450.00 (Lump sum)

Estimated normal duration of repairs : 7 Working days



**ABSOLUTE APPRAISAL SERVICES PTE LTD
LOSS ADJUSTERS & MOTOR APPRAISERS**

160 Sin Ming Drive #05-16 Sin Ming AutoCity (S) 575722

Mobile: 9688-0413 Fax: 6266-7396

Email: absolute.app.svcs@gmail.com

Vehicle No: SMA9819L

Report No: AAS/2019/011

W/O PREJUDICE

Point of impact

At the LHR portion.

General description of damages

The rear bumper, LH tail lamp, rear end panel, LHR fender, etc.

Other parts were also found damaged. (See schedule for details)

Recommendation

The estimate cost of repair submitted by M/s Kok Wang Car Grooming as per schedule attached have been revise and scrutinize. We list the breakdown of our findings and recommendation as per attached.

Our adjusted amount for the cost of repair is SGD \$4,286.60

Conclusion

The repairer has agreed to undertake the repair at a lumpsum of SGD \$3,450.00

Under normal circumstances, the repair of the damaged vehicle should be completed within a reasonable period of 7 working days.

We have **Not Authorised** and/or instruction to the repairer to proceed with the repairs. This inspection was conducted entirely on a '**Without Prejudice**' basis.

We are pleased to advise that the inspection was carried out accordingly and hereby submit our appraisal report which includes 48 photographs.

Your Faithfully
Absolute Appraisal Services Pte Ltd



Nicky Seah
Automobile Appraiser
MSAAA / MSMCTA



ABSOLUTE APPRAISAL SERVICES PTE LTD LOSS ADJUSTERS & MOTOR APPRAISERS

160 Sin Ming Drive #05-16 Sin Ming AutoCity (S) 575722

Mobile: 9688-0413 Fax: 6266-7396

Email: absolute.app.svcs@gmail.com

Vehicle No: SMA9819L

Report No: AAS/2019/011

Appraisal Schedule

S/N	Parts Description	Qty	Condition	Repairer's Est	Revised Est
1	Rear bumper	1	Dented	\$ 559.20	\$ 559.20
2	Rear bumper reflector LH	1	Serviceable	\$ 39.00	-
3	Rear bumper retainer LH	1	Cracked	\$ 103.20	\$ 103.20
4	Rear bumper support LH	1	Cracked	\$ 36.80	\$ 36.80
5	Rear bumper sponge	1	Cracked	\$ 153.40	\$ 153.40
6	Rear bumper arm LH	1	Dented	\$ 87.10	\$ 87.10
7	Rear bumper seal LH	1	Serviceable	\$ 66.70	-
8	Rear end panel	1	Dented/Repair	\$ 683.33	-
9	Rear end panel top trim	1	Cracked	\$ 220.60	\$ 220.60
10	Tail lamp LH	1	Loop Broken	\$ 374.90	\$ 374.90
11	Tail lamp lower bracket LH	1	Cracked	\$ 69.80	\$ 69.80
12	LHR fender	1	Dented/Distorted	\$ 1,094.70	Rx \$ 1,094.70
13	LHR fender inner trim	1	Serviceable	\$ 351.40	-
14	LHR fender ventilator	1	Cracked	\$ 130.40	\$ 130.40
15	Rear glass moulding	1	Necessary	\$ 98.70	10x \$ 98.70
Total:				\$ 4,069.23	\$ 2,928.80
-25%				\$ 1,017.31	\$ 732.20
List total:				\$ 3,051.92	\$ 2,196.60
1	Rear windscreen sealant	1	Necessary	\$ 60.00	17x \$ 40.00
2	Rear bumper clips	1set	Necessary	\$ 50.00	\$ 30.00
3	Joint sealant	2	1 tube Necessary	\$ 60.00	17x \$ 40.00
Special nett total:				\$ 230.00	\$ 110.00
Parts Total:				\$ 3,281.92	\$ 2,306.60



ABSOLUTE APPRAISAL SERVICES PTE LTD
LOSS ADJUSTERS & MOTOR APPRAISERS

160 Sin Ming Drive #05-16 Sin Ming AutoCity (S) 575722

Mobile: 9688-0418 Fax: 6266-7396

Email: absolute.app.svcs@gmail.com

Vehicle No: SMA9819L

Report No: AAS/2019/011

S/N Labour Description

Repairer's Est ⁿⁿ Revised Est

1	Remove & refit rear glass.	\$ 180.00	X \$ 150.00
2	Remove, reinstall rear trimmings & rear seats	\$ 200.00	\$ 150.00 ⁶⁰
3	Remove & refit fuel tank.	\$ 100.00	X \$ 80.00 ⁿⁿ
4	Remove & transfer reverse sensor.	\$ 80.00	\$ 50.00 ³⁰
5	Rust proofing on rear affected & replacement panels.	\$ 100.00	\$ 30.00
6	To check rear lightings & wirings.	\$ 60.00	\$ 40.00 ³⁰
7	Spray painting on affected & replacement panels.	\$ 1,000.00	\$ 600.00 ⁴⁰⁰
8	Conduct panel beating, straightening, cutting & reforming. Renew damaged parts. Re-align all affected area.	\$ 1,200.00	\$ 880.00 ⁴⁰⁰

Labour Total: \$ 2,920.00 \$ 1,980.00⁹⁵⁰

Grand Total: \$ 6,201.92 \$ 4,286.60

The final adjusted lump sum amount is \$3,450.00

Under normal circumstances, the repair should be completed within a reasonable period of 7 working days.

48 Photographs were taken at the time of inspection.

2183.75
259/1700
4 days

...CLAIM SUBFOLDER...(Pending for Survey Report)

Paper Survey

CLAIM SUBFOLDER TRACKING

Case	Notified	Est. Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Jan 2019		03 Jan 2019 14:39 Edit Adj Rpt	S\$1,700.00 Edit Estimates	S\$1,700.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	GOH SWEE POH PATRICK, ID: S0214955I, Tel: +6596750247, Email: SPGOHP@GMAIL.COM		
Main Claimant:	FEI SIONG (F&B) HOLDINGS PTE. LTD., Co. Reg. No.: 200513686W		
Vehicle Reg. No.:	SMA9819L	Date of Loss:	25/12/2018 13:00 - :59 [126 Months From LTA Reg Date (Man Yr)]
Claim Type:	TP / 580660	Policy/Cover Note No.:	A80423374QMX (Comprehensive) Coverage: 12/04/2018 - 11/04/2019
Vehicle Reg. No. (Insured):	SGZ8393T	Policy No. (Claimant):	
		Excess:	
Repairer:	Kok Wang Car Grooming - Pioneer (HQ) No. 1 Soon Lee Street, #06-40 Pioneer Centre, 627603 Pioneer - Tel: 91839633		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong - 6594 2544]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 26/06/2019]		
Driver/Custodian (Insured):	GOH SWEE POH PATRICK (69 / Male), NRIC: S0214955I, Tel: +6596750247 Email: SPGOHP@GMAIL.COM		
Adj Asg. Remarks:	Liability 0%. TP disagree with our SJE list. Proceed to appoint LKK as the SJE. Contact Person: Mr Kok / 9183 9633.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- MSIG_SG (24/06/2019): Report Send Back Alerts - SMA9819L (TP)

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?

No results.

Claim Documents

***SMA9819L (580660)**
[SGZ8393T]

TP

FEI SIONG (F&B) HOLDINGS PTE. LTD.

Dec 25 2018 1:00PM

[GOH SWEE POH PATRICK]

Kok Wang Car Grooming - Pioneer

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View [View in Browser](#) ▼

Video

No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	1 per page ▼	Thumbnail	Print
1	03/01/19 09:44	Video - Accident From: SC - Reg. No: SGZ8393T, Claimant: GOH SWEE POH PATRICK		Load MP4	

Assessment Reports

No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	1 per page ▼	Thumbnail	Print
1	03/01/19 09:44	Accident Statement From: SC - Reg. No: SGZ8393T, Claimant: GOH SWEE POH PATRICK		Load HTM	
2	03/01/19 09:44	Addendum Sheet From: SC - Reg. No: SGZ8393T, Claimant: GOH SWEE POH PATRICK		Load TIF	
3	03/01/19 09:44	Accident Statement Addm. #1 From: SC - Reg. No: SGZ8393T, Claimant: GOH SWEE POH PATRICK		Load HTM	

Photos/Images

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	3 per page ▼	Thumbnail	Print
1	11/01/19 11:57	General View		Load JPG	
2	11/01/19 11:57	General View		Load JPG	
3	11/01/19 11:57	General View		Load JPG	
4	11/01/19 11:57	General View		Load JPG	
5	11/01/19 11:57	General View		Load JPG	
6	11/01/19 11:57	General View		Load JPG	
7	11/01/19 11:57	General View		Load JPG	
8	11/01/19 11:57	General View		Load JPG	
9	11/01/19 11:57	General View		Load JPG	
10	11/01/19 11:57	General View		Load JPG	
11	11/01/19 11:57	General View		Load JPG	
12	11/01/19 11:57	General View		Load JPG	
13	11/01/19 11:57	General View		Load JPG	
14	11/01/19 11:58	Photographs of Damaged Parts		Load JPG	
15	11/01/19 11:58	Photographs of Damaged Parts		Load JPG	
16	11/01/19 11:58	Photographs of Damaged Parts		Load JPG	
17	11/01/19 11:58	Photographs of Damaged Parts		Load JPG	
18	11/01/19 11:58	Photographs of Damaged Parts		Load JPG	
19	11/01/19 11:58	Photographs of Damaged Parts		Load JPG	
20	11/01/19 11:58	Photographs of Damaged Parts		Load JPG	
21	11/01/19 11:58	Photographs of Damaged Parts		Load JPG	
22	11/01/19 11:58	Photographs of Damaged Parts		Load JPG	
23	11/01/19 11:58	Photographs of Damaged Parts		Load JPG	
24	11/01/19 11:58	Photographs of Damaged Parts		Load JPG	
25	11/01/19 11:58	Photographs of Damaged Parts		Load JPG	

Video			1 per page ▼	✓
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
26	11/01/19 11:58	Photographs of Damaged Parts	Load JPG	✓
27	11/01/19 11:58	Photographs of Damaged Parts	Load JPG	✓
28	11/01/19 11:58	Photographs of Damaged Parts	Load JPG	✓
29	11/01/19 11:58	Photographs of Damaged Parts	Load JPG	✓
30	11/01/19 11:58	Photographs of Damaged Parts	Load JPG	✓
31	11/01/19 11:58	Photographs of Damaged Parts	Load JPG	✓
32	11/01/19 11:58	Photographs of Damaged Parts	Load JPG	✓
Documentation			1 per page ▼	✓
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	03/01/19 09:44	SMA9819L GIA Rpt From: SC - Reg. No: SGZ8393T, Claimant: GOH SWEE POH PATRICK	Load PDF	
2	03/01/19 09:47	PRI	Load PDF	
3	24/06/19 15:26	survey report	Load PDF	
4	24/06/19 15:27	Survey photo	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	15/07/19 16:24	PRS INVOICE	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG19000127/T1VD3S2-1

Date: 15/07/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A80423374QMX

Claimant Vehicle No : SMA9819L

Insured Vehicle No : SGZ8393T

Date of Loss: 25/12/2018

Nature of Claim: TP

Claim No: 580660

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMA9819L

Make & Model: TOYOTA COROLLA ALTIS, 1.6 (A)

Engine No: 3ZZ4769743

Reg. Date: 25/06/2008 (Man. Year: 2008)

Chassis No: MR053ZEE106111358

Colour: Silver

Odometer: 142091 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65R15

Rear Tyre Size:

195/65R15

Front Left Side: Dunlop 6 mm

Rear Left Side:

Dunlop 6 mm

Front Right Side: Dunlop 6 mm

Rear Right Side:

Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,281.92	1,233.75	2,048.17	62.41
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,920.00	950.00	1,970.00	67.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,201.92	2,183.75	4,018.17	64.79
Approved Total (Overridden) (S\$)		1,700.00		
Nett Amount (S\$)	6,201.92	1,700.00	4,501.92	72.59

INSPECTION

Date of Assignment: 03/01/2019

Date Inspected: 08/01/2019 Inspected At:

Kok Wang Car Grooming - Pioneer (HQ)
No. 1 Soon Lee Street, #06-40 Pioneer Centre
Singapore 627603

Estimated Period of Repair: 4.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 Jul 2019)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMA9819L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	559.20 FL	*559.20 FL
2	1		*REAR BUMPER REFLECTOR LH	Serviceable	39.00 FL	*- FL
3	1		*REAR BUMPER RETAINER LH	Cracked	103.20 FL	*103.20 FL
4	1		*REAR BUMPER SUPPORT LH	Cracked	36.80 FL	*36.80 FL
5	1		*REAR BUMPER SPONGE	Cracked	153.40 FL	*153.40 FL
6	1		*REAR BUMPER ARM LH	Dented	87.10 FL	*87.10 FL
7	1		*REAR BUMPER SEAL LH	Serviceable	66.70 FL	*- FL
8	1		*REAR END PANEL	Repair	683.33 FL	*- FL
9	1		*REAR END PANEL TOP TRIM	Cracked	220.60 FL	*220.60 FL
10	1		*TAIL LAMP LH	Loop Broken	374.90 FL	*374.90 FL
11	1		*TAIL LAMP LOWER BRACKET LH	Cracked	69.80 FL	*69.80 FL
12	1		*LHR FENDER	Repair	1,094.70 FL	*- FL
13	1		*LHR FENDER INNER TRIM	Serviceable	351.40 FL	*- FL
14	1		*LHR FENDER VENTILATOR	Not Necessary	130.40 FL	*- FL
15	1		*REAR GLASS MOULDING	Not Necessary	98.70 FL	*- FL
16	1		*REAR WINDSCREEN SEALANT	Not Necessary	60.00 FS	*- FS
17	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
18	2		*JOINT SEALANT	Not Necessary	120.00 FS	*- FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (\$\$)	4,299.23	1,635.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,017.31	401.25
Total Parts (\$\$)	3,281.92	1,233.75

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REFIT REAR GLASS.	New	180.00	0.00
2	REMOVE, REINSTALL REAR TRIMMINGS & REAR SEATS.	New	200.00	60.00
3	REMOVE & REFIT FUEL TANK.	New	100.00	0.00
4	REMOVE & TRANSFER REVERSE SENSOR.	New	80.00	30.00
5	RUST PROOFING ON REAR AFFECTED & REPLACEMENT PANELS.	New	100.00	30.00
6	TO CHECK REAR LIGHTING & WIRINGS.	New	60.00	30.00
7	SPRAY PAINTING ON AFFECTED & REPLACEMENT PANELS.	New	1,000.00	400.00
8	CONDUCT PANEL BEATING, STRAIGHTENING, CUTTING & REFORMING. RENEW DAMAGED PARTS. RE-ALIGN ALL AFFECTED AREA.	New	1,200.00	400.00
Gross Labour Cost (S\$)			2,920.00	950.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >