

22/03/2002

ASS. REC. BY:

REF: CSMG 170089741 Utd302-1

Special Instruction:

Survivor: Marcus

ASSIGNMENT (Office)

27/6/2019

From (Person): Chhiet Myat Aii

of MSG

Date/Time: 14.5.19 9.56am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SGR 92215

Insured: SLG 6235x

at Workshop m/s U E motor

Tel: 82238601

of 3006 vb road 1

Policy No: 29034026QMY

Claim No:

Sum Insured:

Excess:

Make of Veh:

D.O.A 11.5.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 14.5.19 10.34am

Person Contacted: MR NG

Vehicle: IN/OUT

Date/Time	Action/Instruction (X) Estimate
	SGR 92215 - NA / MSG 170089741 / h4 DUA - 11/07/2019
	SLG 6235x - NA / MSG 170089741 / h4 DUA - 11/07/2019
	Diamondette: 15/5/2019
	Water repair: 21/5/2019

2/7/19 Sumat 4/5 @ 5300 SLG Red (\$4600) 46%

RECEIVED 04 JUL 2019

*[Signature]*  
4/7/2019

09/11/13 wef

ASS. REC. BY: Marcus

REF:

# MS161 ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

Consistent? : Yes or No

Consistent? : Yes or No

days Res.: Yes or No

% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Date / Time

Action / Instruction

Vehicle: IN / OUT

Veh No:

Type: M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond. Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Yr Regn:

2, 07

C.O 1584

A/C: Insured / Std / NI / NA

T/Radio: Insured / Std / NI / NA

JM4STC53A74007522

195/60R15

Rear 6 mm

L/Bal. 6 mm

D.O.A 11/5/19

D.O.A 4/5/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prel. Report

☐

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

) \$ + RS \$

) Photos

) Others

)

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

PRE

120

11

131

## Celine Fong (LKKAUTO)

---

**From:** Chhia Nyuk Pui <NyukPui\_Chhia@sg.msig-asia.com>  
**Sent:** Thursday, 27 June 2019 4:04 PM  
**To:** SUR  
**Subject:** FW: Your ref: L19.0598.CYN. Our ref: 593215 (OIV: SLG6235X)  
**Attachments:** 27062019150900.pdf

Hi LKK Team

Please do paper survey.  
Thanks.

Chhia Nyuk Pui  
Senior Executive, Claims Services  
Direct line +65 6594 2521 | Direct fax +65 6643 1349 | [nyukpui\\_chhia@sg.msig-asia.com](mailto:nyukpui_chhia@sg.msig-asia.com)



MSIG Insurance (Singapore) Pte. Ltd. 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | Tel +65 6220 9644 | Fax +65 6225 6371 | Co. Reg. No. 200412212G | [www.msig.com.sg](http://www.msig.com.sg) | Follow us on  [@MSIG\\_SG](https://twitter.com/MSIG_SG)

A member of **MS&AD** INSURANCE GROUP

---

**From:** Kuru & Co [mailto:[kurulegal@yahoo.com.sg](mailto:kurulegal@yahoo.com.sg)]  
**Sent:** Thursday, 27 June, 2019 3:11 PM  
**To:** Chhia Nyuk Pui <NyukPui\_Chhia@sg.msig-asia.com>  
**Subject:** Re: Your ref: L19.0598.CYN. Our ref: 593215 (OIV: SLG6235X)

EXTERNAL EMAIL: Be careful when you click any links or open any attachment(s).

---

Dear Ms Chhia

Your email of even date refers.

Our survey report and colored photos enclosed for your perusal.

Kindly let us have your offer soonest possible.

Thank you and best regards  
Anne

Kuru & Co  
150 South Bridge Road  
#04-06 Fook Hai Building  
Singapore 058727

# KURU & CO

Advocates & Solicitors  
UEN / GST Registration No: 53130937A


CNP

Ref: S93215

150 South Bridge Road  
#04-06 Fook Hai Building  
Singapore 058727

Kurubalan s/o Manickam Rengaraju  
Jan Chua Peck Kiang

Tel: 65322 009 (5 lines)  
Fax: 65322 007 (Our fax no. is not for service of court documents)



Our ref: **L.19.0598.CYN**  
(Please quote our reference when replying)

13 June 2019

## BY CERTIFICATE OF POSTING

Tee Chee Siong  
130 Lorong Ah Soo  
#05-388  
Singapore 530130

(Yr ref: SLG 6235X)

## BY HAND ONLY

MSIG Insurance (Singapore) Pte Ltd  
16 Raffles Quay  
#24-01 Hong Leong Building  
Singapore 048581

(Yr ref: SLG 6235X)

Dear Sirs,

### ACCIDENT INVOLVING SGR 9221S & **SLG 6235X** ON 11.05.2019 AT/ALONG JUNCTION OF RIVERVALE DRIVE

We act for **Ang Kim Hock**, owner of vehicle registration number **SGR 9221S**.

We are instructed to claim for damages against you in connection with the above-captioned road traffic accident involving our client's vehicle and your vehicle registration number **SLG 6235X**.

We are instructed that the accident was caused by your/your driver's/your insured's negligent driving and/or management of your/your insured's vehicle. As a result of the accident, our client's vehicle was damaged and our client had been put to loss and expense, particulars of which are as follows:

Cost of repairs	\$ 9,900.00
Loss of use	\$ 880.00
Survey fee	\$ 648.00
LTA fee/s	\$ 7.49
Incidentals (Inclusive of GST)	\$ 53.50
Cost at this stage (Inclusive of GST)	\$ 963.00

Enclosed are the supporting documents for your perusal:

Pre-repair Notification letter

Our client's SAS report

Your insured's LTA searches

Repair Bill

Survey report, invoice and **61 colored photographs** (on your undertaking to return the same within 03 days upon demand)

File not found.  
Options of file any

ACL 7  
AC ✓



Our ref: **L.19.0598.CYN**  
(Please quote our reference when replying)

13 June 2019

**ACCIDENT INVOLVING SGR 9221S & SLG 6235X ON 11.05.2019  
AT/ALONG JUNCTION OF RIVERVALE DRIVE**

We have on 13.05.19 notified your insurer of the accident and a pre-repair inspection of our client's vehicle was carried out by your insurer on 14.05.19.

Should you have a counterclaim against our client arising out of the accident, you are required to send us a letter giving full particulars of the counterclaim with all relevant supporting documents within 8 weeks from your receipt of this letter.

Please also note that you or your insurer should send us an acknowledgement of receipt of this letter within 14 days of your receipt of this letter, failing which our client will have no alternative but to commence proceedings without further notice to you or your insurer.

Yours faithfully,



Encl.

**N.B. Supporting documents are forwarded only to your insurer BY HAND**

**Cc. NTUC Income Insurance Co-Operative Limited (Mutual client – SGR 9221S) /  
BY FAX: 6338 1500**

Please do not prejudice our mutual client's claim in whatsoever way. Meanwhile, we would be obliged if you could let us have a complete set of third party's SAS/police report if you have received a copy of same for our attention.

**Cc. Client**



L19.0598.cj // ACCIDENT INVOLVING SGR9221S & SLG6235X  
ON 11.5.19 JUNCTION OF RIVERVALE DRIVE NOTIFICATION OF  
ACCIDENT AND PRE-REPAIR SURVEY

From: Kuru & Co (kurulegal@yahoo.com.sg)

To: motorsurvey@sg.msig-asia.com; venessa\_chan@sg.msig-asia.com

Date: Monday, 13 May 2019, 10:31 am SGT

Dear sirs

ACCIDENT INVOLVING SGR9221S & SLG6235X ON 11.5.19  
JUNCTION OF RIVERVALE DRIVE  
NOTIFICATION OF ACCIDENT AND PRE-REPAIR SURVEY

We act for **Ang Kim Hock**, whose vehicle registration number **SGR9221S** was damaged in the above accident.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within **2 working days** of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle.

A copy of our client's SAS report is enclosed.

If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Regards

Irene

Kuru & Co

150 South Bridge Road

#04-06 Fook Hai Building

Singapore 058727

Tel: 6532 2009

Fax: 6532 2007

img-513102154.pdf  
147.3kB





## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report 11/05/2019 15:05  
Date Of Accident 11/05/2019 12:05  
Exact Location Of Accident JUNCTION OF RIVERVALE DRIVE/SENGKANG EAST WAY  
Country/State Of Loss SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number SGR9221S  
Insured/Policyholder  
Name Of Registered Owner ANG KIM HOCK  
NRIC No S1329229I  
Email Address ANG.KIMHOCK@YAHOO.COM.SG  
Mobile Phone No (LOCAL) +65-91172166  
Alternative Phone No OTHERS-91172166  
Vehicle Particulars  
Manufacturer MITSUBISHI  
Model LANCER-1.6 (A)  
Exact Purpose for which vehicle was being used at time of accident PRIVATE USE  
Are you claiming under your own insurance policy for repair to your vehicle? NO  
If No, Please state action to be taken THIRD PARTY  
Vehicle Category PRIVATE CAR  
Insurance Company  
Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD.  
Type Of Coverage THIRD PARTY FIRE AND/OR THEFT  
Fleet Policy NO  
Policy Number 5078810031-03  
Cover Note Number  
Driver  
Name of Driver ANG KIM HOCK  
NRIC No S1329229I  
Date Of Birth 10/11/1958  
Occupation INDOOR  
Date Of Driving Pass 19/12/1979  
Driving Experience 39 YEARS AND 4 MONTHS  
Gender MALE  
Mobile Number (LOCAL) +65-91172166  
Fax Number  
Contact Number OTHERS-91172166  
Email Address ANG.KIMHOCK@YAHOO.COM.SG

Address BLK 123 RIVERVALE DRIVE  
#07-147  
Postcode 542123  
Was driver an employee of the Insured's Company NO  
If No, Relationship of the Driver with the Insured OWNER  
Vehicle Registration Number of Driver's Own Vehicle  
Insurance Company of Driver's Own Vehicle

#### General Information of the Accident

Type Of Accident COLLISION - CROSS JUNCTION

Weather Conditions AFTER RAIN

Road Surface WET

#### Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) involved in the accident 2

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (including Driver) 1

#### Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

#### Circumstances of Accident

PLEASE REFER TO SKETCH PLAN

#### Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? YES

Was there any audio recorded? NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLG6235X  
Vehicle Make/Model/Colour TOYOTA HARRIER  
Details Of Properties  
Vehicle Category PRIVATE CAR  
Name of Driver TEE CHEE SIONG  
NRIC/Passport Number 57176923B  
Contact Number 88090637  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (including Driver)

## Accident Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurers to discontinue or rescind policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance company.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the logging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be situated outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

11/05/2018  
Reporting Centre Person's Signature  
Name: R. S. L. Wong  
TELEPHONE No.:

# Accident Sketch Plan

SKETCH PLAN

A) 1/1/2019

B) 1/1/2019

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

KIRK VALL 2019

ON 11/05/2019 AT ABOUT 12:05 HRS I WAS AT RIVERVALE  
DRIVE I WANTED TO TURN RIGHT TO GOA KING EAST WAY  
THE TRAFFIC LIGHT WAS GREEN & THE OPPOSITE DIRECTION  
A CAR SL 625X DID NOT STOP ON THE RED LIGHT &  
HAD AN COLLISION WITH MY CAR SGR 99215

VIDEO FOOTAGE ATTACH.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Person's Signature  
Date & Time

Driver's Signature  
(If driver is not the policyholder)  
Date & Time

Reporting Centre Person's Signature  
Name:  
Reporting No:

11/05/2019

1/1/2019

## Enquire Vehicle & Owner Information ( Vehicle No. SLG6235X As At 11 May 2019 / 12:05:00 )

### Law Firm Search Details

Search Reason: Insurance claim in relation to traffic accident

Law Firm Case No.: L19.0598.CJ

### Current Owner Details

Owner ID Type: Singapore NRIC

Owner ID: S7176923B

Owner Name: TEE CHEE SIONG

Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes

Registered Block/House No.: 130

Registered Street Name: LORONG AH SOO

Registered Unit No.: # 05 - 388

Registered Building Name:-

Registered Postal Code: 530130

### Current Vehicle Details

Vehicle No.: SLG6235X

Make Description/Model: TOYOTA / HARRIER PREMIUM 2.0 A

Insurance Company Name:MSIG INSURANCE (SINGAPORE) PTE LTD

ROC NO. 43880900M  
**U E MOTOR**  
BLK 3005 UBI ROAD 1 #01-334  
SINGAPORE 408700  
TEL: 6744 1995 FAX: 6741 6225

**OFFICIAL RECEIPT**

No.: 1342

Date: 21/5/19

茲收到  
Received from Ang Kim Hock

支付大銀  
the sum of Dollars Nine Thousand Nine Hundred only -

系还  
in payment of SGR9221S

\$9900/xx  
xx

Cash / Cheque No.:

  
.....  
**U E MOTOR**

Besform

# U E MOTOR

Blk 3006, Ubi Road 1, #01-334

Singapore 408700

Tel: 67441995 Fax: 67416225

Email: uemotor@hotmail.com

Ang Kim Hock

c/o UE Motor

Blk 3006, Ubi Road 1,

#01-334 Singapore 408700

Date: 21/5/2019

Our reference: 19-5-8270

Accident Date: 11/5/2019

## FINAL BILL TO VEHICLE SGR9221S MITSUBISHI LANCER

AS PER SURVEY

\$ 9,900.00

TOTAL AMOUNT:

-----  
\$ 9,900.00  
=====

  
.....  
U E MOTOR



Our reference: 19-5-8270

Date: 21/5/2019

**INVOICE NO. 8270**

Ang Kim Hock  
c/o UE Motor  
Blk 3006, Ubi Road 1,  
#01-334 Singapore 408700

Registration No. **SGR9221S**

We enclose our fee note for your kind attention, which remains payable irrespective of the outcome of this case.

S/No.	Description of Services Provided	Qty	Amount
1	Being vehicle damage assessment report, inspection, photographs, transport and miscellaneous.	1	\$ 648.00
Total amount			<u>\$ 648.00</u>

Please kindly cross all cheques made payable to "Impact Analysis Consultant".

We thank you in anticipation for your prompt payment.

**L. L. Tan (Ms)**  
Principal Consultant

*Subsidiaries of Impact Analysis Consultant:*

• Impact Analysis Consulting Pte Ltd • Impact Analysis Academy Pte Ltd • IA Racking Solutions Pte Ltd  
• IA Accounting & Consultancy Pte Ltd • Infoknights International Services (Philippines) • IABN Pte Ltd  
[www.iaconsultingsg.com](http://www.iaconsultingsg.com)

Our reference: 19-5-8270

Date: 21/5/2019

c/o UE Motor  
Blk 3006, Ubi Road 1,  
#01-334 Singapore 408700

Dear Sirs

RE: Road Traffic Accident on 11/5/2019  
Ang Kim Hock

In accordance with your instructions received in this office on 13/5/2019, we made arrangements to examine the vehicle on 13/5/2019 at above-mentioned address. The following data was recorded:


#### Vehicle details

Make	Mitsubishi	Registration	SGR9221S
Model	Lancer	Chassis	JMYSTCS3A7U007522
Colour	Gold	Gearbox	Auto
Odometer	234587km	Paintwork	Good
Steering	In order	Brakes	In order
Condition	Good		

#### Tyre Depths

Front left	195/60R15	85% Michelin
Front right	195/60R15	85% Michelin
Rear left	195/60R15	85% Michelin
Rear right	195/60R15	85% Michelin

#### Impact Direction & Area of Damage:



Status	REPAIRABLE
Magnitude	Medium
Legal status	Unroadworthy

Following our examination of the accident damage, we have calculated repair times and method, which are detailed on page 2 & 3. We would recommend a sum of \$9,900.00 and 9 working days for repair, which is sufficiently lower than the pre accident value to render the vehicle an economically and physically reliable proposition.

#### Subsidiaries of Impact Analysis Consultant:

• Impact Analysis Consulting Pte Ltd • Impact Analysis Academy Pte Ltd • IA Racking Solutions Pte Ltd  
• IA Accounting & Consultancy Pte Ltd • Infoknights International Services (Philippines) • IABN Pte Ltd  
www.iaconsultingsg.com

Our reference 19-5-8270

Date 21/5/2019

Page 2

## Section A: Damaged Parts Assessment

Part's Description	Qty	Condition As Inspected	Repairer's Estimate	Our Adjustment
--------------------	-----	------------------------	---------------------	----------------

### List Items:

Bonnet (19009138) 617	1	buckled 617	758.90	SUC 758.90 ✓
Bonnet lock	1	damaged	58.90	Ref 58.90 ✓
Bonnet hinge @\$55.00	2	bent	110.00	Ref 110.00 ✓
Front number plate garnish	1	damaged	65.80	Ref 65.80 ✓
Front bumper 64003301HD	1	deformed 737	758.90	Ref 758.90 ✓
Front bumper beam c/w support.	1	bent	151.00	151.00 X
Front bumper lower grille	1	deformed	85.90	Ref 85.90 ✓
Front bumper side bracket @\$17.00	2	bent	34.00	Ref 34.00 ✓
Front bumper fog lamp cover @\$35.00	2	lh deformed rh reuse	70.00	11 35.00 X
Front radiator grille	1	damaged	335.70	Ref 335.70 ✓
Front radiator grille logo	1	necessary	45.00	Ref 45.00 ✓
N126713 Front head lamp @\$632.00 515X2	2	= cracked 1030	1264.00	Ref 1264.00 ✓
Front support panel MN 150618	1	bent 569	698.70	Ref 698.70 ✓
Front aircon condenser	1	bent 597	1089.00	Ref 1089.00 ✓
Front aircon fan assy (no dye)	1	damaged	787.00	11 787.00 X
Front radiator	1	bent	719.00	Ref 719.00 ✓
Front radiator fan motor	1	ceased	301.00	11 301.00 X
Front radiator fan blade (no dye)	1	damaged	86.90	17 86.90 X
Front radiator fan cowling	1	damaged	110.00	17 110.00 X
Front air cleaner air duct	1	deformed	91.00	11 91.00 X
Wiper garnish lh	1	damaged	35.60	Ref 35.60 ✓
Front engine mounting @\$125.00	2	damaged	250.00	Ref 250.00 1PC 125
Front Intercooler	1	damaged NF	1225.50	1225.50 X
Front cross member	1	bent 230	712.45	Ref 712.45 ✓
<b>Sub- Total costs</b>			9844.25	9809.25
Percentage discount : 10%			984.43	980.93
<b>Sub-Total costs for parts</b>			8859.83	8828.33

5394.9  
102  
4813.41

### Subsidiaries of Impact Analysis Consultant:

• Impact Analysis Consulting Pte Ltd • Impact Analysis Academy Pte Ltd • IA Racking Solutions Pte Ltd  
• IA Accounting & Consultancy Pte Ltd • Infoknights International Services (Philippines) • IABN Pte Ltd  
www.iaconsultingsg.com

Our reference 19-5-8270

Date 21/5/2019

**Special Nett Items:**

Front number plate	1	bent	50.00	50.00	40
Front radiator grille clip @\$4.00	4	necessary	16.00	16.00	✓
Front horn (Air) Set	1	damaged	150.00	150.00	60p
Front bumper clip @\$5.90	10	necessary	59.00	59.00	50
<b>Sub-Total costs for parts</b>			<b>275.00</b>	<b>275.00</b>	

**Parts Repair**

*	*	*	0.00	0.00	
<b>Sub- Total costs</b>			<b>0.00</b>	<b>0.00</b>	
<b>Total costs for parts</b>			<b>9134.83</b>	<b>9103.33</b>	

**Subsidiaries of Impact Analysis Consultant:**

• Impact Analysis Consulting Pte Ltd • Impact Analysis Academy Pte Ltd • IA Racking Solutions Pte Ltd  
• IA Accounting & Consultancy Pte Ltd • Infoknights International Services (Philippines) • IABN Pte Ltd  
[www.iaconsulting.sg](http://www.iaconsulting.sg)

Our reference 19-5-8270

Date 21/5/2019

Page 3

### Section B: Labour Cost Calculation

	Hourly rate	Manhr. Req.	Total
To dismantle, replace, cut, weld, knock out dents to straighten accident parts as-mentioned on the 'Parts Repair' column inclusive of replacement parts.	\$ 45.00	29	\$ 1,305.00
Putty & Spray painting to adjacent panels. Job allowance. Paint / material.	Sub-contract work.		\$ 900.00
Apply rust proofing on the adjacent panels.	Sub-contract work.		\$ 50.00
Wiring and bulb checking	\$ 45.00	0.5	\$ 22.50
Remove / replace aircon condenser and refill aircon gas	\$ 45.00	3	\$ 135.00
Remove and replace front engine mounting	\$ 45.00	5	\$ 225.00
<b>Total labour cost</b>			<b>\$ 2,637.50</b>

Manhour rate and the number of manhours required for each repairing task are formulated based on individual workshop's operating cost and In-house@ IA Research Guidelines respectively.

6631.41

6631.41

11772.33

*Subsidiaries of Impact Analysis Consultant:*

• Impact Analysis Consulting Pte Ltd • Impact Analysis Academy Pte Ltd • IA Racking Solutions Pte Ltd  
• IA Accounting & Consultancy Pte Ltd • Infoknights International Services (Philippines) • IABN Pte Ltd  
[www.iaconsulting.sg.com](http://www.iaconsulting.sg.com)

Our reference 19-5-8270

Date 21/5/2019

### Section C: Summary Table of Total Repair Cost

Description		Cost	
<b>Damaged Parts Assessment</b> (See section A)		\$9,103.33	
		\$1,820.67	
Further discount	20%		
Recommended cost of parts		\$7,282.66	(1)
<b>Labour Cost Calculation</b> (See section B)		\$2,637.50	(2)
<b>Total Repair Cost</b> (Round off to hundred)		\$9,900.00	(1) + (2)

We would recommend a sum of \$9,900.00 and 9 working days for repair.  
No further items will be approved without our expressed written agreement. Any significant additional items will be subject to a supplementary report.

Mechanical Engineer, Accident Expert Witness, Licensed Appraiser (Automobile)  
B.Eng. (Hons, NUS)  
Diploma.Mechanical Engineering  
NTC-2 Automotive Technology  
Sr.MIES, Institution of Engineers, Singapore (#20100091)  
MATAI, Maryland Association of Traffic Accident Investigators  
IAARS, International Association of Accident Reconstruction Specialists  
PMC of Singapore Business Advisors & Consultants Council  
ACTA Certified Trainer, Singapore

#### Subsidiaries of Impact Analysis Consultant:

• Impact Analysis Consulting Pte Ltd • Impact Analysis Academy Pte Ltd • IA Racking Solutions Pte Ltd  
• IA Accounting & Consultancy Pte Ltd • Infoknights International Services (Philippines) • IABN Pte Ltd  
www.iaconsulting.sg.com



## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 May 2019 15:07		14 May 2019 09:58 <a href="#">Edit Adj Rpt</a>	<b>S\$5,300.00</b> <a href="#">Edit Estimates</a>	<b>S\$5,300.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>



















































Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;"><a href="#">[Created by insurer]</a></span>									
Insured:	<b>TEE CHEE SIONG</b> , ID: S7176923B								
Main Claimant:	<b>ANG KIM HOCK</b> , ID: S13292291								
Vehicle Reg. No.:	<b>SGR9221S</b>	Date of Loss:	11/05/2019 12:00 - :59 <b>[146 Months and 15 Days From LTA Reg Date (Man Yr)]</b>						
Claim Type:	<b>TP / 593215</b>	Policy/Cover Note No.:	A29034026QMX (Comprehensive) Coverage: 06/10/2018 - 05/10/2019						
Vehicle Reg. No. (Insured):	<b>SLG6235X</b>	Policy No. (Claimant):							
		Excess:							
Repairer:	<b>U E MOTOR (HQ)</b> 3006, Ubi Road 1, #01-334, 408700 Ubi - Tel:								
Handling Insurer:	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Chhia Nyuk Pul</b> - 6594 2521]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MARCUS CHUA</b> ] ... <b>[Final Rpt due 01/07/2019]</b>								
Driver/Custodian (Insured):	TEE CHEE SIONG (), NRIC: S7176923B Email:								
Adj Asg. Remarks:	SURVEY DISAGREE ON SJE - ASSIGN LKK. LIABILITY: 100% CONTACT: MR NG 8223 8601								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
<ul style="list-style-type: none"> <li>MSIG_SG (27/06/2019): Report Send Back Alerts - SGR9221S (TP)</li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									







































































## Claim Documents

\*SGR9221S (593215)  
[SLG6235X]  
TP  
ANG KIM HOCK  
May 11 2019 12:00PM  
[TEE CHEE SIONG]  
U E MOTOR

Upload Documents		Upload Photos		Compose New Letter		View		View in Browser	
Photos/Images							3 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail	Print	
1	15/05/19 08:20	Odometer Reading						<input checked="" type="checkbox"/>	
2	15/05/19 08:20	Chassis Number						<input checked="" type="checkbox"/>	
3	15/05/19 08:21	General View						<input checked="" type="checkbox"/>	
4	15/05/19 08:21	General View						<input checked="" type="checkbox"/>	
5	15/05/19 08:21	General View						<input checked="" type="checkbox"/>	
6	15/05/19 08:21	General View						<input checked="" type="checkbox"/>	
7	15/05/19 08:21	General View						<input checked="" type="checkbox"/>	
8	15/05/19 08:21	General View						<input checked="" type="checkbox"/>	
9	15/05/19 08:21	General View						<input checked="" type="checkbox"/>	
10	15/05/19 08:21	General View						<input checked="" type="checkbox"/>	
11	15/05/19 08:21	General View						<input checked="" type="checkbox"/>	
12	15/05/19 08:21	General View						<input checked="" type="checkbox"/>	
13	15/05/19 08:21	General View						<input checked="" type="checkbox"/>	
14	15/05/19 08:21	General View						<input checked="" type="checkbox"/>	
15	15/05/19 08:21	General View						<input checked="" type="checkbox"/>	
16	15/05/19 08:21	General View						<input checked="" type="checkbox"/>	
17	15/05/19 08:21	General View						<input checked="" type="checkbox"/>	
18	15/05/19 08:21	General View						<input checked="" type="checkbox"/>	
19	15/05/19 08:21	General View						<input checked="" type="checkbox"/>	
20	15/05/19 08:21	General View						<input checked="" type="checkbox"/>	
21	15/05/19 08:21	General View						<input checked="" type="checkbox"/>	
22	15/05/19 08:21	General View						<input checked="" type="checkbox"/>	
23	15/05/19 08:21	General View						<input checked="" type="checkbox"/>	
24	15/05/19 08:21	General View						<input checked="" type="checkbox"/>	
25	15/05/19 08:21	General View						<input checked="" type="checkbox"/>	
26	15/05/19 08:21	General View						<input checked="" type="checkbox"/>	
27	15/05/19 08:21	General View						<input checked="" type="checkbox"/>	
28	15/05/19 08:21	General View						<input checked="" type="checkbox"/>	
29	15/05/19 08:21	General View						<input checked="" type="checkbox"/>	
30	15/05/19 08:21	General View						<input checked="" type="checkbox"/>	
31	15/05/19 08:21	General View						<input checked="" type="checkbox"/>	
32	15/05/19 08:21	General View						<input checked="" type="checkbox"/>	
33	15/05/19 08:21	General View						<input checked="" type="checkbox"/>	
34	15/05/19 08:21	General View						<input checked="" type="checkbox"/>	
35	15/05/19 08:21	General View						<input checked="" type="checkbox"/>	
36	15/05/19 08:21	General View						<input checked="" type="checkbox"/>	
37	15/05/19 08:21	General View						<input checked="" type="checkbox"/>	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	15/05/19 08:21	General View	 Load JPG	<input checked="" type="checkbox"/>
39	15/05/19 08:21	General View	 Load JPG	<input checked="" type="checkbox"/>
40	15/05/19 08:21	General View	 Load JPG	<input checked="" type="checkbox"/>
41	15/05/19 08:21	General View	 Load JPG	<input checked="" type="checkbox"/>
42	15/05/19 08:21	General View	 Load JPG	<input checked="" type="checkbox"/>
43	15/05/19 08:21	General View	 Load JPG	<input checked="" type="checkbox"/>
44	15/05/19 08:21	General View	 Load JPG	<input checked="" type="checkbox"/>
45	15/05/19 08:21	General View	 Load JPG	<input checked="" type="checkbox"/>
46	15/05/19 08:21	General View	 Load JPG	<input checked="" type="checkbox"/>
47	15/05/19 08:21	General View	 Load JPG	<input checked="" type="checkbox"/>
48	15/05/19 08:21	General View	 Load JPG	<input checked="" type="checkbox"/>
49	15/05/19 08:21	General View	 Load JPG	<input checked="" type="checkbox"/>
50	15/05/19 08:21	General View	 Load JPG	<input checked="" type="checkbox"/>
51	15/05/19 08:21	General View	 Load JPG	<input checked="" type="checkbox"/>
52	15/05/19 08:21	General View	 Load JPG	<input checked="" type="checkbox"/>
53	15/05/19 08:21	General View	 Load JPG	<input checked="" type="checkbox"/>
54	15/05/19 08:21	General View	 Load JPG	<input checked="" type="checkbox"/>
55	15/05/19 08:21	General View	 Load JPG	<input checked="" type="checkbox"/>
56	15/05/19 08:21	General View	 Load JPG	<input checked="" type="checkbox"/>
57	15/05/19 08:21	General View	 Load JPG	<input checked="" type="checkbox"/>
58	15/05/19 08:21	General View	 Load JPG	<input checked="" type="checkbox"/>
59	15/05/19 08:21	General View	 Load JPG	<input checked="" type="checkbox"/>
60	15/05/19 08:21	General View	 Load JPG	<input checked="" type="checkbox"/>
61	15/05/19 08:21	General View	 Load JPG	<input checked="" type="checkbox"/>
62	15/05/19 08:21	General View	 Load JPG	<input checked="" type="checkbox"/>
63	15/05/19 08:21	General View	 Load JPG	<input checked="" type="checkbox"/>
64	15/05/19 08:21	General View	 Load JPG	<input checked="" type="checkbox"/>
65	15/05/19 08:21	General View	 Load JPG	<input checked="" type="checkbox"/>
66	15/05/19 16:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	15/05/19 16:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	15/05/19 16:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	15/05/19 16:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	15/05/19 16:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	15/05/19 16:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	15/05/19 16:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	15/05/19 16:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	15/05/19 16:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	15/05/19 16:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	15/05/19 16:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	15/05/19 16:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	15/05/19 16:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	15/05/19 16:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	15/05/19 16:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
81	15/05/19 16:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	15/05/19 16:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	15/05/19 16:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
84	15/05/19 16:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	15/05/19 16:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	15/05/19 16:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	15/05/19 16:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	15/05/19 16:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	15/05/19 16:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	15/05/19 16:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
91	15/05/19 16:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
92	15/05/19 16:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
93	15/05/19 16:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
94	15/05/19 16:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
95	15/05/19 16:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
96	15/05/19 16:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
97	15/05/19 16:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
98	15/05/19 16:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
99	15/05/19 16:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
100	15/05/19 16:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
101	15/05/19 16:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
102	15/05/19 16:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
103	15/05/19 16:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
104	15/05/19 16:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
105	15/05/19 16:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
106	15/05/19 16:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
107	21/05/19 14:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
108	21/05/19 14:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
109	21/05/19 14:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
110	21/05/19 14:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
111	21/05/19 14:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
112	21/05/19 14:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
113	21/05/19 14:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
114	21/05/19 14:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
115	21/05/19 14:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
116	21/05/19 14:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
117	21/05/19 14:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
118	21/05/19 14:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
119	21/05/19 14:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
120	21/05/19 14:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
121	21/05/19 14:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
122	21/05/19 14:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
123	21/05/19 14:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
124	21/05/19 14:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
125	21/05/19 14:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
126	21/05/19 14:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
127	21/05/19 14:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
128	21/05/19 14:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
129	21/05/19 14:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
130	21/05/19 14:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
131	21/05/19 14:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
132	21/05/19 14:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
133	21/05/19 14:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
134	21/05/19 14:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
135	21/05/19 14:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
136	21/05/19 14:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
137	21/05/19 14:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
138	21/05/19 14:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
139	21/05/19 14:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
140	21/05/19 14:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
141	21/05/19 14:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
142	21/05/19 14:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
143	21/05/19 14:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
144	21/05/19 14:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	13/05/19 15:10	SLG6235X GIA Rpt	 Load PDF	
2	13/05/19 15:11	SGR9221S GIA Rpt	 Load PDF	
3	13/05/19 16:09	TP LIST OF SURVEYORS	 Load PDF	
4	13/05/19 16:09	SURVEY DISAGREE ON SJE - ASSIGN LKK.	 Load PDF	
5	13/05/19 16:48	EMAIL FROM TP ON WORKSHOP DETAIL	 Load PDF	
6	27/06/19 15:06	LOD	 Load PDF	
7	27/06/19 15:12	Survey Report 1	 Load PDF	
8	27/06/19 15:13	Survey Report 2	 Load PDF	
9	27/06/19 16:05	Email LKK to do Paper Re	 Load HTM	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	05/07/19 08:37	PRS Invoice	 Load PDF	
2	05/07/19 08:37	Colour Photo	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG19008474/UTD3E2-1

Date: 05/07/2019

## REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A29034026QMX

Claimant Vehicle No : SGR9221S

Insured Vehicle No : SLG6235X

Date of Loss: 11/05/2019

Nature of Claim: TP

Claim No: 593215

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SGR9221S

Make &amp; Model: MITSUBISHI LANCER, 1.6 (A)

Engine No: 4G18HT6433

Reg. Date: 26/02/2007 (Man. Year: 2006)

Chassis No: JMYSTCS3A7U007522

Colour: Beige

Odometer: 234587 km

Engine Capacity: 1584 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 195/60 R15

Rear Tyre Size:

195/60 R15

Front Left Side: Michelin 6 mm

Rear Left Side:

Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side:

Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,134.82	5,021.41	4,113.41	45.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,637.50	1,610.00	1,027.50	38.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>11,772.32</b>	<b>6,631.41</b>	<b>5,140.91</b>	<b>43.67</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>5,300.00</b>		
<b>Nett Amount (S\$)</b>	<b>11,772.32</b>	<b>5,300.00</b>	<b>6,472.32</b>	<b>54.98</b>

## INSPECTION

Date of Assignment: 14/05/2019

Date Inspected: 14/05/2019

Inspected At:

U E MOTOR (HQ)  
3006, Ubi Road 1, #01-334  
Singapore 408700

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b> MRM-SG		Version: 1.0 (Last Synchronised: 05 Jul 2019)
<b>Parts:</b>	143	MITSUBISHI LANCER 1.6 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SGR9221S)		
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *		

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Buckled	758.90 FL	*617.00 FL
2	1		*BONNET LOCK	Bent	58.90 FL	*58.90 FL
3	2		*BONNET HINGE	Bent	110.00 FL	*110.00 FL
4	1		*FRONT NUMBER PLATE GARNISH	Deformed	65.80 FL	*65.80 FL
5	1		*FRONT BUMPER	Distorted	758.90 FL	*737.00 FL
6	1		*FRONT BUMPER LOWER GRILLE	Deformed	85.90 FL	*85.90 FL
7	2		*FRONT BUMPER SIDE BRACKET	Bent	34.00 FL	*34.00 FL
8	2		*FRONT BUMPER FOG LAMP COVER	Not Necessary	70.00 FL	*- FL
9	1		*FRONT RADIATOR GRILLE	Deformed	335.70 FL	*335.70 FL
10	1		*FRONT RADIATOR GRILLE LOGO	Necessary	45.00 FL	*45.00 FL
11	2		*FRONT HEAD LAMP	Cracked	1,264.00 FL	*1,030.00 FL
12	1		*FRONT SUPPORT PANEL )	Bent	698.70 FL	*569.00 FL
13	1		*FRONT BUMPER BEAM )		151.00 FL	*- FL
14	1		*FRONT AIRCON CONDENSER	Bent	1,089.00 FL	*597.00 FL
15	1		*FRONT AIRCON FAN ASSY	Not Necessary	787.00 FL	*- FL
16	1		*FRONT RADIATOR	Bent	719.00 FL	*719.00 FL
17	1		*FRONT RADIATOR FAN MOTOR	Not Necessary	301.00 FL	*- FL
18	1		*FRONT RADIATOR FAN BLADE	Not Necessary	86.90 FL	*- FL
19	1		*FRONT RADIATOR FAN COWLING	Not Necessary	110.00 FL	*- FL
20	1		*FRONT AIR CLEANER AIR DUCT	Not Necessary	91.00 FL	*- FL
21	1		*WIPER GARNISH LH	Cut	35.60 FL	*35.60 FL
22	1		*FRONT ENGINE MOUNTING	Front Twisted	250.00 FL	*125.00 FL
23	1		*FRONT INTERCOOLER	Not fitted	1,225.50 FL	*- FL
24	1		*FRONT CROSS MEMBER	Bent	712.45 FL	*230.00 FL
25	1		*FRONT NUMBER PLATE	Bent	50.00 FS	*40.00 FS
26	4		*FRONT RADIATOR GRILLE CLIP	Necessary	16.00 FS	*16.00 FS
27	1		*SET FRONT HORN (AIR)	Damaged	150.00 FS	*60.00 FS
28	10		*FRONT BUMPER CLIP	Necessary	59.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>10,119.25</b>	<b>5,560.90</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	<b>984.43</b>	<b>539.49</b>
<b>Total Parts (\$\$)</b>	<b>9,134.82</b>	<b>5,021.41</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO DISMANTLE, REPLACE, CUT, WELD, KNOCK OUT DENTS TO STRAIGHTEN ACCIDENT PARTS AS-MENTIONED ON THE PARTS REPAIR COLUMN INCLUSIVE OF REPLACEMENT PARTS	New	1,305.00	600.00
2	APPLY RUST PROOFING ON THE ADJACENT PANELS	New	50.00	50.00
3	WIRING AND BULB CHECKING	New	22.50	20.00
4	REMOVE / REPLACE AIRCON CONDENSER AND REFILL AIRCON GAS	New	135.00	100.00
5	REMOVE AND REPLACE FRONT ENGINE MOUNTING	New	225.00	40.00
6	PUTTY & SPRAY PAINTING TO ADJACENT PANELS. JOB ALLOWANCE. PAINT / MATERIAL	New	900.00	800.00
<b>Gross Labour Cost (S\$)</b>			<b>2,637.50</b>	<b>1,610.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >