

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKN 6688Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER (SN) (CONSISTENT)	TO REPAIR SEE LABOUR	2,343.00	-
4	REAR BUMPER STICKY PAD (SN) (CONSISTENT)	NOT NECESSARY	21.00	-
1	REAR BUMPER FIXING PARTS (SN) (CONSISTENT)	NOT NECESSARY	249.00	-
1	REAR BUMPER SPOILER (SN) (CONSISTENT)	NOT NECESSARY	316.00	-
1	REAR BUMPER SEAL RING (SN) (CONSISTENT)	NOT NECESSARY	5.00	-
1	SUNDRIES (SN) (CONSISTENT)	NOT NECESSARY	300.00	-
			3,234.00	-
	LABOUR			
	TO REMOVE AND TRANSFER REAR PARKING AID AN REAR LID KICK SENSOR ASSY ,CHECK FUNCTION .		360.00	360.00
	TO DISMANTLE AND RENEW REAR BUMPER ASSY .RE- ORGANISE REAR CRASH MANAGEMENT COMPONENTS .REINSTALL ALL PARTS REMOVED.INCLUSIVE OF THE REPAIR OF REAR BUMPER.		1,200.00	800.00
	TO RESPRAY REAR BUMPER .		1,000.00	800.00
	TO CARRY OUT DIAGNOSTIC CHECK .		192.00	192.00
			2,752.00	2,152.00
	GRAND TOTAL		5,986.00	2,152.00

RECOMMENDED COST OF REPAIRS			2,152.00
-----------------------------	--	--	----------

Report Ref No. CC4/ASM19011531/Apa3q2



ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.