

Lampac



# ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.  
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

## Repair Estimates

SLP 4804 U

Not Authorized  
Resurvey Required

Parts	(a) Cost / List Price Items	\$	5,245.43
	Plus/Less 25%	\$	1,311.36
	<b>Total of Cost / List</b>	<b>\$</b>	<b>3,934.07</b>
	(b) Nett Price Items		
	Less		
	<b>Total of Nett Item</b>		
	(c) Special Nett Items	\$	350.00
<b>Total Parts Cost</b>		<b>\$</b>	<b>4,284.07</b>
<b>Labour</b>		<b>\$</b>	<b>2,770.00</b>
<b>Total</b>		<b>\$</b>	<b>7,054.07</b>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary item must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kennerly  
Company : CLK  
Survey conducted on : 28/8/18 at \_\_\_\_\_

### Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : 07 day(s)

(c) Resurvey : Required / ~~Not Required~~

(d) Excess : \$ \_\_\_\_\_

(e) Signature of surveyor : Le Date: 28/8/18



# ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.  
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

## Spare Parts

Vehicle No. : SLP 4804 U  
Make & Model : TOYOTA PRIUS  
Chassis No. : \_\_\_\_\_

Submit By : Carmen Lim  
Year Manufacture : \_\_\_\_\_  
Engine No. : \_\_\_\_\_

## Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	LH rear door	1	\$1,211.40		✓
2	LH rear door hinge top	1	\$78.34		X
3	LH rear door hinge bottom	1	\$78.34		X
4	LH rear door weatherstrip	1	\$198.70		?
5	LHR door glass outer moulding	1	\$107.80		X
6	LHR power window motor	1	\$187.90		?
7	LHR power window regulator	1	\$570.60		?
8	LH rear fender	1	\$883.60		✓
9	LH rear fender undershield	1	\$92.30		?
10	LH rear fender undershield clip	10	\$30.00		?
11	LH rear fender air duct	1	\$115.60		?
12	LH rear tyre	1	\$350.00	S.N	?
13	LH rear hub cap	1	\$195.65		✓
14	Rear bumper	1	\$497.50		✓
15	Rear bumper clip	10	\$40.00		✓
16	Rear bumper side retainer LH	1	\$112.70		✓
17	Rear bumper side retainer RH	1	\$112.70		X
18	Rear bumper lower garnish centre	1	\$582.60		X
19	Rear bumper lower garnish LH	1	\$149.70		X
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



## ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.

Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

### Labour

Vehicle No. : **SLP 4804 U** Submit By : **Carmen Lim**  
Make & Model : **TOYOTA PRIUS** Year of Manufacture : **0**

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (LHF DOOR, LHR DOOR, LHR FENDER, REAR BUMPER)	\$1,000.00	800
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (LHF DOOR, LHR DOOR, LHR FENDER, REAR BUMPER)	\$1,000.00	800
3	TO Check wiring	\$50.00	20
4	To do wheel alignment.	\$120.00	60
5	To remove & refit Door trim, door glass, window regulator, door lock to assist work load.	\$150.00	60
6	To tuff coat.	\$150.00	60
7	To remove & refit inner seat & upholstery to assist work load.	\$150.00	100
8	To remove & refit petrol tank to assist work load.	\$150.00	60

*Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.*