

Ryder

Auto Pte Ltd

2 Kaki Bukit Ave 2, #02-19 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

wheel arch inner garnish cat ✓
wheel arch inner garnish bracket at ✓
XE3807J Pg 1/1

ESTIMATE OF REPAIR

Veh # : XE3807J Model : UD TRUCKS (13/12/2017)

Date Of Accident : 11/3/2019 3P : XE853U (AIG)

Location : ALONG PIONEER RD HEADING TOWARDS JLN BUROH RD

S/Nos.	Qty	Description	Surveyor Remarks	Surveyor Adj	Amount \$	
		<u>Special Nett Items</u>				
1	1 pc	Front wheel guard <i>cm</i> ✓			619.10	
2	1 pc	Front wheel arch <i>at</i> ✓			531.00	
3	1 pc	Front wheel arch step garnish <i>sun</i> ✓			331.00	
		Sub-Total			1,481.10	
		<u>Labour</u>				
1		To remove and replace front damage parts			400.00	150
2		To spray painting.			300.00	150
		Sub-Total			700.00	
		Total			2,181.10	
		After -20%			1,744.88	

Chan
Chan San Choon
Director
DipEng, AAE MIMI,MSAE(Aust)

Rasul
Hp 90016568

2 days

4/3

01/07/19 @ 1400 hrs

Resy after repair

email: rasul@lkkauto.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



Authorised Workshop
Authorised Reporting Centre

AC 8778 1999
24 hr accident call

Mobil 1

bizSAFE₁