

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG19011601/AEA3Q2

**Date:** 26/08/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100498950-02

**Claimant**  
**Vehicle No :** SJV8054H **Insured Vehicle No :** SLK7017G

**Date of Loss:** 27/06/2019 **Nature of Claim:** TP **Claim No:** 7277406549SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SJV8054H</b>		
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Engine No:	3ZZ4975113
Reg. Date:	09/02/2010 (Man. Year: 2010)	Chassis No:	MR053ZEE106167777
Colour:	Grey	Odometer:	78170 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,790.81	1,740.12	2,050.69	54.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,550.00	1,630.00	920.00	36.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>6,340.81</b>	<b>3,370.12</b>	<b>2,970.69</b>	<b>46.85</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>2,700.00</b>		
<b>(\$\$)</b>	6,340.81	2,700.00	3,640.81	57.42
<b>+ GST 7.00/7.00% (\$\$)</b>	443.86	189.00	254.86	57.42
<b>Nett Amount (\$\$)</b>	<b>6,784.67</b>	<b>2,889.00</b>	<b>3,895.67</b>	<b>57.42</b>
<b>+ Car Rental (7.0 x S\$100.00/day) (\$\$)</b>		700.00		
<b>+ Doc/Search Fee (\$\$)</b>		8.00		
<b>Nett Liability (\$\$)</b>		<b>3,597.00</b>		

### INSPECTION

Date of Assignment: 01/07/2019

Date Inspected: 01/07/2019 Inspected At:

Precise Auto Service (HQ)  
No 1 Kaki Bukit Ave 6, #02-34/36  
Singapore 417883

Estimated Period of Repair: 6.0 days

---

**Adjuster:** ADRIAN LING**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	372.85 FL	*372.85 FL
2	2		*REAR BUMPER SIDE RETAINER -LH & RH	Necessary	264.50 FL	*124.00 FL
3	2		*REAR BUMPER SIDE ATTACHMENT -LH & RH	Not Necessary	282.80 FL	*- FL
4	2		*REAR BUMPER REFLECTOR -LH & RH	Not Necessary	363.80 FL	*- FL
5	10		*REAR BUMPER CLIPS	Necessary	129.00 FL	*30.00 FL
6	1		*REAR BUMPER SPONGE	Cracked	182.60 FL	*182.60 FL
7	1		*REAR BUMPER BEAM	Not Necessary	372.25 FL	*- FL
8	1		*REAR BUMPER STAY -LH & RH	N/S Dented	282.80 FL	*85.60 FL
9	1		*BOOT LID	Repair	781.75 FL	*- FL
10	1		*BOOT LID WEATHERSTRIPE	Not Necessary	182.25 FL	*- FL
11	1		*BOOT LID RUBBER STOPPER	Not Necessary	43.10 FL	*- FL
12	1		*BOOT LID EMBLEM 1.6	Necessary	41.90 FL	*41.90 FL
13	1		*BOOT LID EMBLEM COROLLA	Necessary	41.35 FL	*41.35 FL
14	1		*BOOT LID EMBLEM ALTIS	Necessary	43.10 FL	*43.10 FL
15	1		*BOOT LID BADGE	Necessary	41.10 FL	*41.10 FL
16	1		*REAR END PANEL	Dented	781.10 FL	*781.10 FL
17	1		*REAR END PANEL TOP TRIM	Deformed	289.90 FL	*289.90 FL
18	4		*REAR END PANEL TOP TRIM CLIPS	Necessary	51.60 FL	*20.00 FL
19	1		*REVERSE SENSOR WITH CONTROL UNIT	Damaged	380.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>4,927.75</b>	<b>2,253.50</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$)</b>	<b>1,136.94</b>	<b>513.38</b>
<b>Total Parts (\$)</b>	<b>3,790.81</b>	<b>1,740.12</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO CHECK WIRING SYSTEM	New	50.00	30.00
2	TO TUFF COAT AFFECTED AREAS	New	180.00	60.00
3	TO REMOVE & REFIX INTERIOR UPHOLSTERY	New	120.00	80.00
4	TO REMOVE & REFIX REVERSE SENSOR	New	120.00	60.00
5	TO REMOVE & REFIX BOOT LID MECHANISM	New	180.00	0.00
6	TO RESPRAY AFFECTED AREAS	New	1,000.00	800.00
7	TO RENEW DAMAGES PARTS ,STRAIGHTEN & REPAIR & ALIGNED ALL PARTS	New	900.00	600.00
<b>Gross Labour Cost (S\$)</b>			<b>2,550.00</b>	<b>1,630.00</b>

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**