

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19011604/AEA3Q2

Date: 23/06/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant
Vehicle No : SLF8640B **Insured Vehicle No :** SML2765X

Date of Loss: 23/06/2019 Nature of Claim: TP Claim No: 6146313650SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLF8640B	Engine No:	F16D4161100093
Make & Model:	CHEVROLET CRUZE, 1.6 (A)	Chassis No:	KL1JA69E9GK346913
Reg. Date:	14/09/2016 (Man. Year: 2016)	Odometer:	22444 km
Colour:	Blue		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Kumho 6 mm	Rear Left Side:	Kumho 6 mm
Front Right Side:	Kumho 6 mm	Rear Right Side:	Kumho 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,769.30	15,653.80	4,115.50	20.82
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,380.00	3,150.00	3,230.00	50.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	26,149.30	18,803.80	7,345.50	28.09
Approved Total (Overridden) (S\$)		14,000.00		
Nett Amount (S\$)	26,149.30	14,000.00	12,149.30	46.46
+ Car Rental (12.0 x S\$100.00/day) (S\$)		1,200.00		
+ Doc/Search Fee (S\$)		7.45		
+ Other Costs (S\$)		90.00		
Nett Liability (S\$)		15,297.45		
Global Sum Settlement (S\$)		15,200.00		

INSPECTION

Date of Assignment: 26/06/2019

Date Inspected: 26/06/2019 Inspected At:

Xin Hua Workshop Pte Ltd (HQ)
23 Kaki Bukit Ave 4 #04-01
Singapore 415933

Estimated Period of Repair: 12.0 days

Adjuster: ADRIAN LING

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RR FENDER LH	Buckled	2,196.00 FL	*2,196.00 FL
2	1		*RR FENDER GUTTER PANEL LH	Buckled	184.00 FL	*184.00 FL
3	1		*RR FENDER EXTENSION LOW PANEL LH	Dented	278.00 FL	*278.00 FL
4	1		*RR FENDER AIR DUCT LH	Cracked	164.00 FL	*164.00 FL
5	1		*RR TAILLAMP PANEL LH	Dented	322.00 FL	*322.00 FL
6	1		*RR TAILLAMP PANEL RH	Dented	322.00 FL	*322.00 FL
7	1		*RR FENDER INNER SHIELD LH	Not Necessary	193.00 FL	*- FL
8	1		*RR FENDER INNER SHIELD RH	Not Necessary	193.00 FL	*- FL
9	1		*RR FENDER INNER TRIM LH	Deformed	388.00 FL	*388.00 FL
10	1		*RR FENDER INNER TRIM RH	Torn	388.00 FL	*388.00 FL
11	1		*RR WINDSCREEN MLDG	Necessary	118.00 FL	*118.00 FL
12	1		*RR FENDER QUARTER GARNISH LH	Not Necessary	140.00 FL	*- FL
13	1		*RR DOOR LH	Not Necessary	1,603.00 FL	*- FL
14	1		*RR BUMPER	Distorted	1,456.00 FL	*1,456.00 FL
15	1		*RR BUMPER CHROME MLDG RH	Distorted	152.00 FL	*152.00 FL
16	1		*RR BUMPER CHROME MLDG LH	Distorted	152.00 FL	*152.00 FL
17	1		*RR BUMPER CHROME MLDG CENTRE	Distorted	205.00 FL	*205.00 FL
18	1		*RR BUMPER REINFORCEMENT	Bent	736.00 FL	*736.00 FL
19	1		*RR BUMPER SIDE RETAINER LH (INNER)	Necessary	116.00 FL	*116.00 FL
20	1		*RR BUMPER SIDE RETAINER LH (OUTER)	Necessary	116.00 FL	*116.00 FL
21	1		*RR BUMPER SIDE RETAINER RH (INNER)	Necessary	116.00 FL	*116.00 FL
22	1		*RR BUMPER SIDE RETAINER RH (OUTER)	Necessary	116.00 FL	*116.00 FL
23	1		*RR BUMPER CENTRE RETAINER	Cracked	130.00 FL	*130.00 FL
24	4		*RR BUMPER REVERSE SENSOR	Damaged (3 PCS ONLY)	860.00 FL	*645.00 FL
25	4		*RR BUMPER REVERSE SENSOR RUBBER SEAL	Necessary	52.00 FL	*52.00 FL
26	1		*RR BUMPER REVERSE WIRE HARNESS	Snapped	336.00 FL	*336.00 FL
27	1		*RR BUMPER TOW COVER	Not Necessary	96.00 FL	*- FL
28	1		*RR REVERSE CAMERA	Damaged	361.00 FL	*361.00 FL
29	2		*RR NUMBER PLATE LAMP	Cracked	150.00 FL	*150.00 FL
30	1		*RR BOOTLID	Distorted	1,973.00 FL	*1,973.00 FL
31	1		*RR BOOTLID WEATHERSTRIP	Cut	214.00 FL	*214.00 FL
32	1		*RR BOOTLID STOPED	Not Necessary	12.00 FL	*- FL
33	1		*RR BOOTLID INSULATOR	Deformed	288.00 FL	*288.00 FL
34	1		*RR BOOTLID LOGO	Necessary	165.00 FL	*165.00 FL
35	1		*RR BOOTLID EMBLEM CHEVROLET	Necessary	82.00 FL	*82.00 FL
36	1		*RR BOOTLID EMBLEM CRUZE LS	Necessary	80.00 FL	*80.00 FL
37	1		*RR BOOTLID LOCK	Damaged	286.00 FL	*286.00 FL
38	1		*RR BOOTLID LOCK COVER	Missing	38.00 FL	*38.00 FL
39	1		*RR BOOTLID LOCK KEYLESS SENSOR	Cracked	167.00 FL	*167.00 FL
40	1		*RR BOOTLID HINGE RH	Bent	176.00 FL	*176.00 FL
41	1		*RR BOOTLID HINGE LH	Bent	176.00 FL	*176.00 FL
42	1		*RR BOOTLID LAMP RH	Cracked	401.00 FL	*401.00 FL
43	1		*RR BOOTLID LAMP LH	Cracked	401.00 FL	*401.00 FL
44	1		*RR TAILLAMP LH	Cut	850.00 FL	*850.00 FL
45	1		*RR TAILLAMP RH	Cut	850.00 FL	*850.00 FL
46	1		*RR END PANEL	Dented	996.00 FL	*996.00 FL
47	1		*RR END PANEL TOP GARNISH	Deformed	267.00 FL	*267.00 FL
48	1		*RR SPARE TYRE PANEL	Repair	1,439.00 FL	*- FL
49	1		*RR SPARE TYRE PANEL BOARD	Deformed	473.00 FL	*473.00 FL
50	1		*RR EXHAUST SILENCER BOX	Not Necessary	559.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
51	1		*RR EXHAUST SILENCER BOX MOUNTING	Not Necessary	45.00 FL	*- FL
52	10		*RR BUMPER CLIP	Necessary	40.00 FS	*40.00 FS
53	10		*RR BOOTLID INNER TRIM CLIP	Necessary	40.00 FS	*40.00 FS
54	10		*RR FENDER INNER TRIM CLIP	Necessary	40.00 FS	*40.00 FS
55	10		*RR FENDER INNER SHIELD CLIP	Not Necessary	40.00 FS	*- FS
56	5		*RR END PANEL TOP GARNISH CLIP	Necessary	20.00 FS	*20.00 FS
57	1		*RR WINDSCREEN SEALANT	Necessary	65.00 FS	*45.00 FS
58	1		*RR WINDSCREEN INNER SEAL	Necessary	40.00 FS	*30.00 FS
59	1		*RR NUMBER PLATE	Cracked	65.00 FS	*65.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	21,927.00	17,362.00
- List Item Discount on L Items 10.00/10.00% (S\$)	2,157.70	1,708.20
Total Parts (S\$)	19,769.30	15,653.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE/RENEW THE ACCIDENT DAMAGED PORTION ,TO PANEL BEATING ,RESHAPE ,STRAIGHTEN ,ORIENTATE AND ALIGN REPAIR /REPLACEMENT PARTS	New	2,400.00	1,400.00
2	CARRY OUT SPRAY PAINTING ON AFFECTED AREA ,RR BUMPER ,RR BOOTLID ,RR END PANEL ,RR SPARE TYRE PANEL ,RR FENDER LH ,RR FENDER RH,RR DOOR LH	New	2,000.00	1,300.00
3	TO DISCONNECT FRONT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS ,RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR	New	160.00	30.00
4	REMOVE AND REFIX SEAT CUSHION/UPHOLSTERY & ROOF LINING TO FACILITATE REPAIRS	New	300.00	100.00
5	TO REMOVE AND REFIX REVERSE SENSOR AND CONDUCT TEST	New	120.00	60.00
6	TO CONDUCT TRANSFER OF PARTS FROM OLD BOOTLID TO NEW BOOTLID	New	180.00	80.00
7	TO REMOVE AND REPLACE EXHAUST PIPE	New	180.00	0.00
8	TO REMOVE AND REFIX REAR WINDSCREEN	New	200.00	120.00
9	TO CONDUCT ANTI RUST OF UNDER CARRIAGE TUFF COAT	New	100.00	60.00
10	TO CONDUCT WATER LEAKAGE TEST AFTER REPAIRS OF VEHICLE	New	60.00	0.00
11	REMOVE AND REPLACE LHR UNDER CARRIAGE PARTS	New	300.00	0.00
12	TO CONDUCT 4 WHEEL ALIGNMENT	New	180.00	0.00
13	TO CONDUCT RESET OF ENGINE LIGHT ON	New	200.00	0.00
Gross Labour Cost (\$\$)			6,380.00	3,150.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >