

ASS. REC. BY:

REF:

CS/SPF19011606/Evd302

Special Instruction:

Survivor: Steve

ASSIGNMENT (Office)

From (Person): KIM PANG CHAY

of SPF

Date/Time: 01/07/2019

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MY/CS

To Inspect Vehicle No: QX 1018R

Insured:

at Workshop m/s SMRT

Tel:

of 60 woodlands IND PK E4

Policy No:

Claim No: MHASPF0300000113

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. -

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	QX 1018R : CS/SPF18019148/KS002 D.O.A.: 05/10/2018
27/7/19	Email report to Kim Pang
22/7/19	Submit report man-HR- 31 HR

Do Not Finalise

ASSIGNMENT

Form _____ Date: _____

Estimated Cost _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No. _____

at Workshop No. _____

of _____

Insured _____

Policy No. _____

Claim No. _____

Sum Insured _____ Excess: _____

(Client's Record)

Make of Veh. _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:				
IDAC Accident Report:			Consistent? : Yes or No	
GIA / PR Seen:			Consistent? : Yes or No	
Est. Repairs:	days:		Res.: Yes or No	
Lump Sum:	%		3 Val.: Yes or No	

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No QX 1018 R In Regn. 2014
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Hyundai Elantra C.V. 1591
 Colour White A/C Insured / Std
 Sp. Reading N/A T/R (L/R) Insured / Std
 Eng/No:
 C/Nr: KMH0H4KM E4 Q8S202
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyro Size: F: 205/55R16
 R:
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SU
 TOYO / YOKO or Falken
 Front Rear
 R/Bal. 6 R/Bal. 6
 L/Bal. 6 L/Bal. 6
 D.O.A. D.O.L. 1/7/19
SMRT
 Survey held at
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop
 The UIC / Chassis frame / Body Structure affected due

Date / Time	Action / Instruction
-------------	----------------------

RECEIVED 23 JUL 2019

4) ☐ : Prel. Report
☐ : Final Report

Date/Time File Return to?

2) 22/7 - typist

Report Format :
Lump Sum / I.B.I. (%)

Days Of Repair: _____
Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$
☐ : Interview (\$
☐ : Tech Invs (\$
☐ : Weekend (\$

Survey Fee: 180
Transportation

-) $G = R^2$ G
-) Phenol
-) $\text{C}_6\text{H}_5\text{OH}$
-) $\text{C}_6\text{H}_5\text{O}$

180

Nivitha (LKK Auto)

From: Kim Pang CHAY (SPF) <CHAY_Kim_Pang@spf.gov.sg>
Sent: Monday, 1 July 2019 11:48 AM
To: Denise Tay (LKKAuto)
Cc: Perry HE (SPF); Kwee Huat TAN (SPF); Admin-D (LKKAuto); assignments
Subject: Appraisal Services for SPF vehicle at SMRT - QX1018R

Hi Denise,

Please provide Appraisal Service (Parts and Labour-man hours) for the following SPF vehicle at SMRT, with new contract rate.

Ref: MHASPF0300000113

Vehicle: QX1018R

Parts		
	Description	Qty
1.1	Front Bumper	1
1.2	Front RH Bumper Retainer	1
1.3	Front LH Bumper Retainer	1
1.4	Front Bumper Centre Grill	1
1.5	Front Bumper Lower Lip	1
1.6	Radiator Grill	1
1.7	Front Number Plate	1
1.8	Front Bumper Sponge	1
1.9	Front Bumper Reinforcement	1
1.10	Front Bumper Lower Beam	1
1.11	Front Support Panel	1
1.12	RHS Head Lamp	1
1.13	RHS Head Lamp Lower Bracket	1
1.14	LHS Head Lamp	1
1.15	LHS Head Lamp Lower Bracket	1
1.16	Radiator	1
1.17	Radiator Top Hose	1
1.18	Radiator Upper Hose	1
1.19	Radiator Lower Hose	1
1.20	Radiator Neck	1
1.21	Radiator Fan Assy	1
1.22	Air Con Condenser	1
1.23	Air Con Condenser Discharge Hose	1
1.24	Air Con Condenser Liquid & Suction Hose	1
1.25	Bonnet Cover	1
1.26	RHS Bonnet Cover Hinge	1
1.27	LHS Bonnet Cover Hinge	1
1.28	Bonnet Cover Lock Assy	1

	Labour	Man Hour
--	--------	----------

1.1	Replace & Spray Paint (2 colours) for Front Bumper including replacing both side Front Bumper Retainers, Centre Grill, Radiator Grill, Lower Lip, Front Bumper Sponge & Front Number Plate.	7.5
1.2	Replace Front Bumper Reinforcement	2.5
1.3	Replace Front Bumper Lower Beam	1.5
1.4	Replace Front Support Panel	4
1.5	Replace & Wiring for RHS Head Lamp including replacing RHS Head Lamp Lower Bracket	1.5
1.6	Replace & Wiring for LHS Head Lamp including replacing LHS Head Lamp Lower Bracket	1.5
1.7	Replace Radiator including replacing Radiator Top, Upper, Lower Hose & Radiator Neck	3.5
1.8	Replace Air Con Condenser including replacing Air Con Condenser Discharge Hose & Air Con Condenser Liquid & Suction Hose	8
1.9	Replace & Spray Paint for Bonnet Cover (2 colours) including replacing both side Bonnet Cover Hinges, Bonnet Cover Lock Assy & Replacing 'POLICE' Wording Sticker on Bonnet Cover	5
SUB-TOTAL		35

Thank You

Regards

Chay Kim Pang
Senior Contract Management Engineer (Vehicle Maintenance)
Automotive Engineering & Management Division
Police Logistics Department
Singapore Police Force
DID: (65) 6478 4827



WARNING "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

Veron Chen (LKKAuto)

From: Kim Pang CHAY (SPF) <CHAY_Kim_Pang@spf.gov.sg>
Sent: Monday, 22 July 2019 3:31 PM
To: Veron Chen (LKKAuto)
Cc: Perry HE (SPF); Kwee Huat TAN (SPF); SUR
Subject: RE: Appraisal Services for SPF vehicle at SMRT - QX1018R

OK, thanks.

Regards

Chay Kim Pang
Senior Contract Management Engineer (Vehicle Maintenance)
Automotive Engineering & Management Division
Police Logistics Department
Singapore Police Force
DID: (65) 6478 4827



WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

From: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Sent: Monday, 22 July 2019 2:06 PM
To: Kim Pang CHAY (SPF) <CHAY_Kim_Pang@spf.gov.sg>
Cc: Perry HE (SPF) <Perry_HE@spf.gov.sg>; Kwee Huat TAN (SPF) <TAN_Kwee_Huat@spf.gov.sg>; SUR <sur@lkkauto.com>
Subject: FW: Appraisal Services for SPF vehicle at SMRT - QX1018R

Dear Kim Pang,

Can we submit our report?

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)
Sent: Thursday, 18 July 2019 9:21 AM
To: Kim Pang CHAY (SPF) <CHAY_Kim_Pang@spf.gov.sg>
Cc: Perry HE (SPF) <Perry_HE@spf.gov.sg>; Kwee Huat TAN (SPF) <TAN_Kwee_Huat@spf.gov.sg>; SUR <sur@lkkauto.com>
Subject: RE: Appraisal Services for SPF vehicle at SMRT - QX1018R

Dear Kim Pang,

Item 1.7 and 1.8 included in the Scope of work.

Refer amend report attached.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)

Sent: Wednesday, 17 July 2019 2:02 PM

To: Kim Pang CHAY (SPF) <CHAY_Kim_Pang@spf.gov.sg>

Cc: Perry HE (SPF) <Perry_HE@spf.gov.sg>; Kwee Huat TAN (SPF) <TAN_Kwee_Huat@spf.gov.sg>; SUR <sur@lkkauto.com>

Subject: RE: Appraisal Services for SPF vehicle at SMRT - QX1018R

Dear Kim Pang,

We will check and revert.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Kim Pang CHAY (SPF) <CHAY_Kim_Pang@spf.gov.sg>

Sent: Wednesday, 17 July 2019 1:42 PM

To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>

Cc: Perry HE (SPF) <Perry_HE@spf.gov.sg>; Kwee Huat TAN (SPF) <TAN_Kwee_Huat@spf.gov.sg>; SUR <sur@lkkauto.com>

Subject: RE: Appraisal Services for SPF vehicle at SMRT - QX1018R

Hi, Veron

Item 1.7 and 1.8 are stated as Unconfirm therefore should these 2 jobs be included in the Scope of work?

1.7	Replace Radiator including replacing Radaitor Top, Upper, Lower Hose & Radiator Neck	Unconfirm			3.5
1.8	Condenser Discharge Hose & Air Con Condenser Liquid & Suction Hose	Unconfirm			8

Regards

Chay Kim Pang
Senior Contract Management Engineer (Vehicle Maintenance)
Automotive Engineering & Management Division
Police Logistics Department
Singapore Police Force
DID: (65) 6478 4827



HOME TEAM
TRANSFORMATION 2025
One Home, One Team
Building Our Future Together

WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

From: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Sent: Tuesday, 16 July 2019 2:21 PM
To: Kim Pang CHAY (SPF) <CHAY_Kim_Pang@spf.gov.sg>
Cc: Perry HE (SPF) <Perry_HE@spf.gov.sg>; Kwee Huat TAN (SPF) <TAN_Kwee_Huat@spf.gov.sg>; SUR <sur@lkkauto.com>
Subject: FW: Appraisal Services for SPF vehicle at SMRT - QX1018R

Dear Kim Pang,

Can we submit our report?

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)
Sent: Tuesday, 2 July 2019 2:35 PM
To: SUR <sur@lkkauto.com>; Kim Pang CHAY (SPF) (CHAY_Kim_Pang@spf.gov.sg) <CHAY_Kim_Pang@spf.gov.sg>
Cc: Perry HE (SPF) <Perry_HE@spf.gov.sg>; Kwee Huat TAN (SPF) (TAN_Kwee_Huat@spf.gov.sg) <TAN_Kwee_Huat@spf.gov.sg>
Subject: RE: Appraisal Services for SPF vehicle at SMRT - QX1018R

Dear Kim Pang,

Enclosed herewith report.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Kim Pang CHAY (SPF) [mailto:CHAY Kim Pang@spf.gov.sg]

Sent: Monday, 1 July, 2019 11:48 AM

To: Denise Tay (LKKAUTO) <denisetay@lkkauto.com>

Cc: Perry HE (SPF) <Perry HE@spf.gov.sg>; Kwee Huat TAN (SPF) <TAN Kwee Huat@spf.gov.sg>; Admin-D (LKKAUTO) <admin-d@lkkauto.com>; assignments <assignments@lkkauto.com>

Subject: Appraisal Services for SPF vehicle at SMRT - QX1018R

Hi Denise,

Please provide Appraisal Service (Parts and Labour-man hours) for the following SPF vehicle at SMRT, with new contract rate.

Ref: MHASPF0300000113

Vehicle: QX1018R

Parts		
	Description	Qty
1.1	Front Bumper	1
1.2	Front RH Bumper Retainer	1
1.3	Front LH Bumper Retainer	1
1.4	Front Bumper Centre Grill	1
1.5	Front Bumper Lower Lip	1
1.6	Radiator Grill	1
1.7	Front Number Plate	1
1.8	Front Bumper Sponge	1
1.9	Front Bumper Reinforcement	1
1.10	Front Bumper Lower Beam	1
1.11	Front Support Panel	1
1.12	RHS Head Lamp	1
1.13	RHS Head Lamp Lower Bracket	1
1.14	LHS Head Lamp	1
1.15	LHS Head Lamp Lower Bracket	1
1.16	Radiator	1
1.17	Radiator Top Hose	1
1.18	Radiator Upper Hose	1
1.19	Radiator Lower Hose	1
1.20	Radiator Neck	1
1.21	Radiator Fan Assy	1
1.22	Air Con Condenser	1
1.23	Air Con Condenser Discharge Hose	1
1.24	Air Con Condenser Liquid & Suction Hose	1
1.25	Bonnet Cover	1
1.26	RHS Bonnet Cover Hinge	1
1.27	LHS Bonnet Cover Hinge	1
1.28	Bonnet Cover Lock Assy	1

	Labour	Man Hour
--	--------	----------

1.1	Replace & Spray Paint (2 colours) for Front Bumper including replacing both side Front Bumper Retainers, Centre Grill, Radiator Grill, Lower Lip, Front Bumper Sponge & Front Number Plate.	7.5
1.2	Replace Front Bumper Reinforcement	2.5
1.3	Replace Front Bumper Lower Beam	1.5
1.4	Replace Front Support Panel	4
1.5	Replace & Wiring for RHS Head Lamp including replacing RHS Head Lamp Lower Bracket	1.5
1.6	Replace & Wiring for LHS Head Lamp including replacing LHS Head Lamp Lower Bracket	1.5
1.7	Replace Radiator including replacing Radiator Top, Upper, Lower Hose & Radiator Neck	3.5
1.8	Replace Air Con Condenser including replacing Air Con Condenser Discharge Hose & Air Con Condenser Liquid & Suction Hose	8
1.9	Replace & Spray Paint for Bonnet Cover (2 colours) including replacing both side Bonnet Cover Hinges, Bonnet Cover Lock Assy & Replacing 'POLICE' Wording Sticker on Bonnet Cover	5
SUB-TOTAL		35

Thank You

Regards

Chay Kim Pang
Senior Contract Management Engineer (Vehicle Maintenance)
Automotive Engineering & Management Division
Police Logistics Department
Singapore Police Force
DID: (65) 6478 4827



WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

Registration No. QX 1018R

S/N	ITEM DESCRIPTION	PARTS				MAN-HOUR QTY
		PARTS QTY	Condition	PARTS COST PER UNIT (\$) AFTER MARK UP	TOTAL PARTS COST (\$) AFTER MARK UP	
1	MATERIALS					
1.1	Front Bumper	1	Broken			
1.2	Front RH Bumper Retainer	1	Broken			
1.3	Front LH Bumper Retainer	1	Broken			
1.4	Front Bumper Centre Grill	1	Broken			
1.5	Front Bumper Lower Lip	1	Crushed			
1.6	Radiator Grill	1	Broken			
1.7	Front Number Plate	1	Bent			
1.8	Front Bumper Sponge	1	Broken			
1.9	Front Bumper Reinforcement	1	Dented			
1.10	Front Bumper Lower Beam	1	Not Necessary			
1.11	Front Support Panel	1	Dented			
1.12	RHS Head Lamp	1	Broken			
1.13	RHS Head Lamp Lower Bracket	1	Bent			
1.14	LHS Head Lamp	1	Broken			
1.15	LHS Head Lamp Lower Bracket	1	Bent			
1.16	Radiator	1	Cracked			
1.17	Radiator Top Hose	1	Not Necessary			
1.18	Radiator Upper Hose	1	Not Necessary			
1.19	Radiator Lower Hose	1	Not Necessary			
1.20	Radiator Neck	1	Not Necessary			
1.21	Radiator Fan Assy	1	Not Necessary			
1.22	Air Con Condenser	1	Twisted			

1.23	Air Con Condenser Discharge Hose	1	Not Necessary			
1.24	Air Con Condenser Liquid & Suction hose	1	Not Necessary			
1.25	Bonnet Cover	1	Crushed			
1.26	RHS Bonnet Cover Hinge	1	Missing			
1.27	LHS Bonnet Cover Hinge	1	Not Necessary			
1.28	Bonnet Cover Lock Assy	1	Bent			
1	LABOUR DESCRIPTION					
1.1	Replace & Spray Paint (2 colours) for Front Bumper including replacing both side Front Bumper Retainers, Centre Grill, Radiator Grill Lower Lip, Front Bumper Sponge & Front Number Plate.					6
1.2	Replace Front Bumper Reinforcement					1.5
1.3	Replace Front Bumper Lower Beam					1
1.4	Replace Front Support Panel					4
1.5	Replace & Wiring for RHS Head Lamp including replacing RHS Head Lamp Lower Bracket					1
1.6	Replace & Wiring for LHS Head Lamp including replacing LHS Head Lamp Lower Bracket					1
1.7	Replace Radiator including replacing Radiator Top, Upper, Lower Hose & Radiator Neck					3.5
1.8	Condenser Discharge Hose & Air Con Condenser Liquid & Suction Hose					8
1.9	replacing both side Bonnet Cover Hinges, Bonnet Cover Lock Assy & Replacing 'POLICE' Wordings Sticker on Bonnet Cover					5
COSTING		TOTAL PARTS COST			TOTAL MAN-HOUR	
					31	

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Tuesday, 16 July 2019 2:21 PM
To: Kim Pang CHAY (SPF) (CHAY_Kim_Pang@spf.gov.sg)
Cc: Perry HE (SPF); Kwee Huat TAN (SPF) (TAN_Kwee_Huat@spf.gov.sg); SUR
Subject: FW: Appraisal Services for SPF vehicle at SMRT - QX1018R
Attachments: PHOTOS.pdf; QX 1018R.pdf

Dear Kim Pang,

Can we submit our report?

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)
Sent: Tuesday, 2 July 2019 2:35 PM
To: SUR <sur@lkkauto.com>; Kim Pang CHAY (SPF) (CHAY_Kim_Pang@spf.gov.sg) <CHAY_Kim_Pang@spf.gov.sg>
Cc: Perry HE (SPF) <Perry_HE@spf.gov.sg>; Kwee Huat TAN (SPF) (TAN_Kwee_Huat@spf.gov.sg) <TAN_Kwee_Huat@spf.gov.sg>
Subject: RE: Appraisal Services for SPF vehicle at SMRT - QX1018R

Dear Kim Pang,

Enclosed herewith report.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Kim Pang CHAY (SPF) [mailto:CHAY_Kim_Pang@spf.gov.sg]
Sent: Monday, 1 July, 2019 11:48 AM
To: Denise Tay (LKKAuto) <denisetay@lkkauto.com>
Cc: Perry HE (SPF) <Perry_HE@spf.gov.sg>; Kwee Huat TAN (SPF) <TAN_Kwee_Huat@spf.gov.sg>; Admin-D (LKKAuto) <admin-d@lkkauto.com>; assignments <assignments@lkkauto.com>
Subject: Appraisal Services for SPF vehicle at SMRT - QX1018R

Hi Denise,

Please provide Appraisal Service (Parts and Labour-man hours) for the following SPF vehicle at SMRT, with new contract rate.

Ref: MHASPF0300000113

Vehicle: QX1018R

Parts		
	Description	Qty
1.1	Front Bumper	1
1.2	Front RH Bumper Retainer	1
1.3	Front LH Bumper Retainer	1
1.4	Front Bumper Centre Grill	1
1.5	Front Bumper Lower Lip	1
1.6	Radiator Grill	1
1.7	Front Number Plate	1
1.8	Front Bumper Sponge	1
1.9	Front Bumper Reinforcement	1
1.10	Front Bumper Lower Beam	1
1.11	Front Support Panel	1
1.12	RHS Head Lamp	1
1.13	RHS Head Lamp Lower Bracket	1
1.14	LHS Head Lamp	1
1.15	LHS Head Lamp Lower Bracket	1
1.16	Radiator	1
1.17	Radiator Top Hose	1
1.18	Radiator Upper Hose	1
1.19	Radiator Lower Hose	1
1.20	Radiator Neck	1
1.21	Radiator Fan Assy	1
1.22	Air Con Condenser	1
1.23	Air Con Condenser Discharge Hose	1
1.24	Air Con Condenser Liquid & Suction Hose	1
1.25	Bonnet Cover	1
1.26	RHS Bonnet Cover Hinge	1
1.27	LHS Bonnet Cover Hinge	1
1.28	Bonnet Cover Lock Assy	1

	Labour	Man Hour
1.1	Replace & Spray Paint (2 colours) for Front Bumper including replacing both side Front Bumper Retainers, Centre Grill, Radiator Grill, Lower Lip, Front Bumper Sponge & Front Number Plate.	7.5
1.2	Replace Front Bumper Reinforcement	2.5
1.3	Replace Front Bumper Lower Beam	1.5
1.4	Replace Front Support Panel	4
1.5	Replace & Wiring for RHS Head Lamp including replacing RHS Head Lamp Lower Bracket	1.5
1.6	Replace & Wiring for LHS Head Lamp including replacing LHS Head Lamp Lower Bracket	1.5

1.7	Replace Radiator including replacing Radaitor Top, Upper, Lower Hose & Radiator Neck	3.5
1.8	Replace Air Con Condenser including replacing Air Con Condenser Discharge Hose & Air Con Condenser Liquid & Suction Hose	8
1.9	Replace & Spray Paint for Bonnet Cover (2 colours) including replacing both side Bonnet Cover Hinges, Bonnet Cover Lock Assy & Replacing 'POLICE' Wording Sticker on Bonnet Cover	5
SUB-TOTAL		35

Thank You

Regards

Chay Kim Pang
Senior Contract Management Engineer (Vehicle Maintenance)
Automotive Engineering & Management Division
Police Logistics Department
Singapore Police Force
DID: (65) 6478 4827



WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

Registration No. QX 1018R

S/N	ITEM DESCRIPTION	PARTS				MAN-HOUR QTY
		PARTS QTY	Condition	PARTS COST PER UNIT (\$) AFTER MARK UP	TOTAL PARTS COST (\$) AFTER MARK UP	
1	MATERIALS					
1.1	Front Bumper	1	Broken			
1.2	Front RH Bumper Retainer	1	Broken			
1.3	Front LH Bumper Retainer	1	Broken			
1.4	Front Bumper Centre Grill	1	Broken			
1.5	Front Bumper Lower Lip	1	Crushed			
1.6	Radiator Grill	1	Broken			
1.7	Front Number Plate	1	Bent			
1.8	Front Bumper Sponge	1	Broken			
1.9	Front Bumper Reinforcement	1	Dented			
1.10	Front Bumper Lower Beam	1	Not Necessary			
1.11	Front Support Panel	1	Dented			
1.12	RHS Head Lamp	1	Broken			
1.13	RHS Head Lamp Lower Bracket	1	Bent			
1.14	LHS Head Lamp	1	Broken			
1.15	LHS Head Lamp Lower Bracket	1	Bent			
1.16	Radiator	1	Unconfirm			
1.17	Radiator Top Hose	1	Not Necessary			
1.18	Radiator Upper Hose	1	Not Necessary			
1.19	Radiator Lower Hose	1	Not Necessary			
1.20	Radiator Neck	1	Not Necessary			
1.21	Radiator Fan Assy	1	Unconfirm			
1.22	Air Con Condenser	1	Unconfirm			

1.23	Air Con Condenser Discharge Hose	1	Not Necessary			
1.24	Air Con Condenser Liquid & Suction hose	1	Not Necessary			
1.25	Bonnet Cover	1	Crushed			
1.26	RHS Bonnet Cover Hinge	1	Missing			
1.27	LHS Bonnet Cover Hinge	1	Not Necessary			
1.28	Bonnet Cover Lock Assy	1	Bent			
1	LABOUR DESCRIPTION					
1.1	Replace & Spray Paint (2 colours) for Front Bumper including replacing both side Front Bumper Retainers, Centre Grill, Radiator Grill Lower Lip, Front Bumper Sponge & Front Number Plate.					6
1.2	Replace Front Bumper Reinforcement					1.5
1.3	Replace Front Bumper Lower Beam					1
1.4	Replace Front Support Panel					4
1.5	Replace & Wiring for RHS Head Lamp including replacing RHS Head Lamp Lower Bracket					1
1.6	Replace & Wiring for LHS Head Lamp including replacing LHS Head Lamp Lower Bracket					1
1.7	Replace Radiator including replacing Radiator Top, Upper, Lower Hose & Radiator Neck		Unconfirm			3.5
1.8	Condenser Discharge Hose & Air Con Condenser Liquid & Suction Hose		Unconfirm			8
1.9	replacing both side Bonnet Cover Hinges, Bonnet Cover Lock Assy & Replacing 'POLICE' Wording Sticker on Bonnet Cover					5
COSTING		TOTAL PARTS COST				
		TOTAL MAN-HOUR				31

3/19

12 days

Reference No.	1018/SPF/4W/19/05/26
iLMS No.	1100024281

LKK Auto Consultants hence notify	0.00	0.00
The Repairer of the following	0.00	0.00
• To restore before/after spray painting	0.00	0.00
• To dispo damaged part(s) during resurvey	0.00	0.00
• Parts prices are subject to confirmation	0.00	0.00
• Third party survey is on a "Without Prejudice" basis	0.00	0.00
• No illegal modification(s) is allowed	0.00	0.00
• Supplementary item(s) must be resurveyed and	0.00	0.00
is subject to final approval from Insurance Company	0.00	0.00
Acknowledged by Repairer	0.00	0.00
Signature:	0.00	0.00
Date:	0.00	0.00

S/N	LABOUR DESCRIPTION	Man-Hour Rate (\$)	Man-Hour Qty	Total Man-Hour Cost (\$)
1	Scope Of Repairs			
1.1	Replace & Spray Paint (2 colours) for Front Bumper including replacing both side Front Bumper Retainers, Centre Grill, Radiator Grill, Lower Lip, Front Bumper Sponge & Front Number Plate.		7.5 6	0.00
1.2	Replace Front Bumper Reinforcement		2.5 1.5	0.00
1.3	Replace Front Bumper Lower Beam		1.5 1	0.00
1.4	Replace Front Support Panel		4 /	0.00
1.5	Replace & Wiring for RHS Head Lamp including replacing RHS Head Lamp Lower Bracket		1.5 1	0.00
1.6	Replace & Wiring for LHS Head Lamp including replacing LHS Head Lamp Lower Bracket		1.5 1	0.00
1.7	Replace Radiator including replacing Radaitor Top, Upper, Lower Hose & Radiator Neck		3.5 3 /	0.00
1.8	Replace Air Con Condenser including replacing Air Con Condenser Discharge Hose & Air Con Condenser Liquid & Suction Hose		8 /	0.00
1.9	Replace & Spray Paint for Bonnet Cover (2 colours) including replacing both side Bonnet Cover Hinges, Bonnet Cover Lock Assy & Replacing 'POLICE' Wordng Sticker on Bonnet Cover		5 /	0.00
SUB-TOTAL			35	0.00
2	Additional Services			
2.1	Towing Service From Station to Workshop (SOR 10)	176.80 /	0	0.00
2.2	Return Service From Workshop to Station (SOR 9)	61.20 /	0	0.00
SUB-TOTAL			0	0.00
Labour Total:			S	-
GRAND TOTAL :			S	-
Total sum billed under SOR only :			S	-
Total sum billed under CVR only :			S	-
Contractor shall complete the entire repair within 30 working days upon approval date . (Include parts awaiting time)				



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTOMOTIVE ENGINEERING & MGT DIVISION		Ref : CS/SPF19011606/Evd3e2		
CONTRACT MANAGEMENT SECTION(SPORE POLICE FORCE) 1 MOUNT PLEASANT ROAD BLK 8 OLD POLICE ACADEMYSINGAPORE 298333		Date : 26-07-2019		
ATTN : KIM PANG CHAY		Code : SPF3		
1. Policy Particulars :- OWN DAMAGE				
Insured Veh.		Veh. Inspected QX 1018R		
Policy No.		Coverage (\$) 0.00		
Claim No. MHASPF0300000113		Excess (\$) 0.00		
Assign From KIM PANG CHAY		Assign Date 01/07/2019		
2. Vehicle Particulars & Condition				
Make & Model HYUNDAI ELANTRA		c.c 1591		
Engine No. HIDDEN		Year of Reg. 2014		
Chassis No. KMHDH41CMEU085202		Colour WHITE		
Odometer -		Steering IN ORDER		
Brakes IN ORDER		Modification SPORTS RIM		
General GOOD				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	FALKEN	6 mm	
L/H Front Tyre	205/55 R16	FALKEN	6 mm	
R/H Rear Tyre	205/55 R16	FALKEN	6 mm	
L/H Rear Tyre	205/55 R16	FALKEN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date		Inspection Date 01/07/2019		
Survey held at		SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		
5a. Remarks				



Registration No. QX 1018R

S/N	ITEM DESCRIPTION	PARTS				MAN- HOUR QTY
		PARTS QTY	Condition	PARTS COST PER UNIT (\$) AFTER MARK UP	TOTAL PARTS COST (\$) AFTER MARK UP	
1	MATERIALS					
1.1	Front Bumper	1	Broken			
1.2	Front RH Bumper Retainer	1	Broken			
1.3	Front LH Bumper Retainer	1	Broken			
1.4	Front Bumper Centre Grill	1	Broken			
1.5	Front Bumper Lower Lip	1	Crushed			
1.6	Radiator Grill	1	Broken			
1.7	Front Number Plate	1	Bent			
1.8	Front Bumper Sponge	1	Broken			
1.9	Front Bumper Reinforcement	1	Dented			
1.10	Front Bumper Lower Beam	1	Not Necessary			
1.11	Front Support Panel	1	Dented			
1.12	RHS Head Lamp	1	Broken			
1.13	RHS Head Lamp Lower Bracket	1	Bent			
1.14	LHS Head Lamp	1	Broken			
1.15	LHS Head Lamp Lower Bracket	1	Bent			
1.16	Radiator	1	Cracked			
1.17	Radiator Top Hose	1	Not Necessary			
1.18	Radiator Upper Hose	1	Not Necessary			
1.19	Radiator Lower Hose	1	Not Necessary			
1.20	Radiator Neck	1	Not Necessary			
1.21	Radiator Fan Assy	1	Not Necessary			
1.22	Air Con Condenser	1	Twisted			
1.23	Air Con Condenser Discharge Hose	1	Not Necessary			
1.24	Air Con Condenser Liquid & Suction hose	1	Not Necessary			
1.25	Bonnet Cover	1	Crushed			
1.26	RHS Bonnet Cover Hinge	1	Missing			
1.27	LHS Bonnet Cover Hinge	1	Not Necessary			

1.28	Bonnet Cover Lock Assy	1	Bent			
1	LABOUR DESCRIPTION					
1.1	Replace & Spray Paint (2 colours) for Front Bumper including replacing both side Front Bumper Retainers, Centre Grill, Radiator Grill Lower Lip, Front Bumper Sponge & Front Number Plate.					6
1.2	Replace Front Bumper Reinforcement					1.5
1.3	Replace Front Bumper Lower Beam					1
1.4	Replace Front Support Panel					4
1.5	Replace & Wiring for RHS Head Lamp including replacing RHS Head Lamp Lower Bracket					1
1.6	Replace & Wiring for LHS Head Lamp including replacing LHS Head Lamp Lower Bracket					1
1.7	Replace Radiator including replacing Radaitor Top, Upper, Lower Hose & Radiator Neck					3.5
1.8	Replace Air Con Condenser including replacing Air Con Condenser Discharge Hose & Air Con Condenser Liquid & Suction Hose					8
1.9	Replace & Spray Paint for Bonnet Cover (2 colours) including replacing both side Bonnet Cover Hinges, Bonnet Cover Lock Assy & Replacing 'POLICE' Wording Sticker on Bonnet Cover					5
COSTING		TOTAL PARTS COST				
		TOTAL MAN-HOUR				31

Registration No. QX 1018R

Vehicle Inspected By

CHEN TSUE YEE
Automotive Assessor

ADRIAN LING WAI PING
B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.