

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse
Singapore 199555

Our File No: CS/LPC19011631/KVD3E2

Date: 29/08/2019

REFERENCE

Insured/Claimant:	DONALD KOH	Policy No:	Z19VP05021779
Date of Loss:	03/06/2019	Nature of Claim:	OD
		Claim No:	19/19/19/VP05/021883

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLR9428D		
Make & Model:	INFINITI Q30, 1.5 D PREMIUM DCT (A)	Engine No:	K9KG481D003032
Reg. Date:	31/08/2017 (Man. Year: 2017)	Chassis No:	SJKDAAH15U1035348
Colour:	Metallic Pearl White	Odometer:	38091 km
Engine Capacity:	1461 cc		
Market Value/New Car Price:	S\$95,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R17	Rear Tyre Size:	215/60 R17
Front Left Side:	Continental 7 mm	Rear Left Side:	Continental 7 mm
Front Right Side:	Continental 7 mm	Rear Right Side:	Continental 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,925.80	5,936.30	1,989.50	25.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,400.00	990.00	410.00	29.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,325.80	6,926.30	2,399.50	25.73
- Excess (S\$)	0.00	1,000.00	-1,000.00	
(S\$)	9,325.80	5,926.30	3,399.50	36.45
+ GST 7.00/7.00% (S\$)	652.81	414.84	237.97	36.45
Nett Amount (S\$)	9,978.61	6,341.14	3,637.47	36.45

INSPECTION

Date of Assignment:	01/07/2019	
Date Inspected:	02/07/2019	Inspected At: AMK Autopoint #01-04
		Repairer : Cheng Hoe Motor Pte Ltd
Estimated Period of Repair:	4.0 days	

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 29 Aug 2019)	
Parts:	N/A	INFINITI Q30 1.5 D PREMIUM DCT (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLR9428D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*1 pc front bumper (WCP)	Bent	1,000.00 F	*1,000.00 F
2	1		*1 pc front bumper sponge (WCP)	Cracked	320.00 F	*320.00 F
3	1		*1 pc front bumper reinforcement (WCP)	Repair	600.00 F	*- F
4	1		*1 pc front bumper lower centre grille (WCP)	Cracked	280.00 F	*280.00 F
5	1		*1 pc front bumper lower centre grille outer garnish (WCP)	Distorted	190.00 F	*190.00 F
6	1		*1 pc front bumper RH side retainer (WCP)	Distorted	30.00 F	*30.00 F
7	1		*1 pc front bumper RH side garnish (WCP)	Dented / Cut	210.00 F	*210.00 F
8	1		*1 pc front bumper lower centre garnish (WCP)	Cracked	210.00 F	*210.00 F
9	1		*6 pcs front bumper clips @ \$1.50/pc (WCP)	Necessary	9.00 F	*9.00 F
10	1		*1 pc front grille assy (WCP)	Serviceable	520.00 F	*- F
11	1		*1 pc front grille logo (WCP)	Serviceable	100.00 F	*- F
12	1		*1 pc front RH fender inner shield (WCP)	Cracked	195.00 F	*195.00 F
13	1		*6 pcs front RH fender inner shield clips @ \$3/pc (WCP)	Necessary	18.00 F	*18.00 F
14	1		*1 pc front RH fender wheel arch garnish (WCP)	Serviceable	190.00 F	*- F
15	1		*1 pc RH headlamp (WCP)	Cracked	2,700.00 F	*2,700.00 F
16	1		*1 pc front engine lower engine cover (WCP)	Serviceable	320.00 F	*- F

F=Franchise part.

Sub Total (\$\$)	6,892.00	5,162.00
+ Margin on L,N Items 15.00/15.00% (\$\$)	1,033.80	774.30
Total Parts (\$\$)	7,925.80	5,936.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	Remove & refix front bumper,grille,headlamp,wheel arch garnish;knocking & repair frt panel & realign front RH fender the same	New	600.00	400.00
2	Putty & respray front bumper,front RH fender,front panel & all affected areas	New	600.00	440.00
3	To check & reprogramme,clear SRS fault code	New	200.00	150.00
Gross Labour Cost (S\$)			1,400.00	990.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >