

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19011647/AKA3Q2

Date: 09/09/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700056957

Claimant
Vehicle No : SLA556R **Insured Vehicle No :** SDM8858Z

Date of Loss: 30/06/2019 Nature of Claim: TP Claim No: 1952843125SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLA556R		
Make & Model:	HYUNDAI ELANTRA, 1.6 ABS D/AB 2WD 4DR (A)	Engine No:	G4FGFU060457
Reg. Date:	22/02/2016 (Man. Year: 2015)	Chassis No:	KMHDH41CMGU653731
Colour:	Grey	Odometer:	32744 km
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,434.24	4,440.08	6,994.16	61.17
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,280.00	2,000.00	3,280.00	62.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,714.24	6,440.08	10,274.16	61.47
Approved Total (Overridden) (S\$)		5,150.00		
Nett Amount (S\$)	16,714.24	5,150.00	11,564.24	69.19
+ Loss of Use (8.0 x S\$40.00/day) (S\$)		320.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		5,477.45		
Global Sum Settlement (S\$)		5,390.00		

INSPECTION

Date of Assignment: 02/07/2019

Date Inspected: 02/07/2019 Inspected At:

Cas Garage Pte Ltd (HQ)
No.1, Kaki Bukit Ave 6, #02-22
Autobay
Singapore 417883

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING**Manager:** Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Dented	1,023.90 FL	*1,023.90 FL
2	1		*BOOTLID SMART KEY ANTENNA	Not Necessary	236.70 FL	*- FL
3	1		*BOOTLID BOOT RELEASE ANTENNA	Cracked	236.70 FL	*236.70 FL
4	1		*BOOTLID INNER TRIM	Not Necessary	326.70 FL	*- FL
5	2		*BOOTLID REFLECTORS	Not Necessary	1,577.20 FL	*- FL
6	1		*BOOTLID EMBLEM ELANTRA	Necessary	90.30 FL	*90.30 FL
7	1		*BOOTLID LOGO	Necessary	75.80 FL	*75.80 FL
8	1		*BOOTLID OUTER HANDLE	Not Necessary	189.80 FL	*- FL
9	1		*BOOTLID ELITE EMBLEM	Necessary	75.60 FL	*75.60 FL
10	1		*BOOTLID TOP LOCK	Damaged	283.10 FL	*283.10 FL
11	1		*BOOTLID LOWER LATCH	Not Necessary	45.20 FL	*- FL
12	1		*BOOTLID WEATHERSTRIP	Not Necessary	301.20 FL	*- FL
13	1		*BOOTLID REFLECTORS	N/s Cut	805.20 FL	*402.60 FL
14	1		*BOOTLID WEATHERSTRIP	Cut	187.90 FL	*187.90 FL
15	2		*BOOTLID HINGES	Not Necessary	173.40 FL	*- FL
16	1		*REAR BUMPER	Deformed	605.70 FL	*605.70 FL
17	2		*REAR BUMPER REFLECTORS	Cut	195.20 FL	*195.20 FL
18	2		*REAR BUMPER RETAINERS	Necessary	137.80 FL	*137.80 FL
19	1		*REAR BUMPER BOTTOM	Deformed	365.70 FL	*365.70 FL
20	1		*REAR BUMPER REINFORCEMENT	Cracked	488.90 FL	*328.00 FL
21	2		*REAR REINFORCEMENT BRACKETS	Not Necessary	139.40 FL	*- FL
22	2		*REAR MUDGUARDS	Not Necessary	179.60 FL	*- FL
23	2		*REAR BUMPER COVERS	Not Necessary	291.60 FL	*- FL
24	1		*TAILLAMPS	N/s Cut	995.20 FL	*497.60 FL
25	2		*TAILLAMPS PANELS	Repair	997.00 FL	*- FL
26	2		*REAR FENDER INNER COWLING	Not Necessary	279.60 FL	*- FL
27	1		*REAR END PANEL	Dented	523.40 FL	*523.40 FL
28	1		*REAR END PANEL TOP GARNISH	Cracked	145.80 FL	*145.80 FL
29	1		*REAR SILENCER BOX	Not Necessary	862.20 FL	*- FL
30	2		*REAR SILENCER BOX MOUNTING	Not Necessary	170.60 FL	*- FL
31	1		*REAR FLOOR PANEL	Repair	1,055.30 FL	*- FL
32	1		*REAR FLOOR PANEL TOP BOARD	Not Necessary	356.10 FL	*- FL
33	1		*SET REAR NUMBER PLATE WITH CASING	Not Necessary	50.00 FS	*- FS
34	1		*SET REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
35	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	30.00 FS	*10.00 FS
36	1		*SET REVERSE SENSOR	Damaged	250.00 FS	*200.00 FS
37	2		*SET REAR FENDER INNER COWLING	Not Necessary	60.00 FS	*- FS
38	1		*SET EMERGENCY SIGN KIT	Not Necessary	200.00 FS	*- FS
39	2		*END PANEL INSULATOR SEAL	Necessary	80.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 14,117.80 5,475.10
- List Item Discount on L Items 20.00/20.00% (\$\$) 2,683.56 1,035.02

Total Parts (\$\$) 11,434.24 4,440.08

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO TUFFCOAT AFFECTED AREA	New	200.00	60.00
2	TO REMOVE/REFIT INTERIOR UPHOLSTERY	New	150.00	60.00
3	TO APPLY SEALANT AND UNDERCOATING TO THE AFFECTED AREAS	New	350.00	60.00
4	TO APPLY BREAK SEAL AND RESEAL WEENKEND CAR PLATE SEAL	New	120.00	80.00
5	TO REMOVE/REFIT WIRING CHECKS ON TAILLAMPS AND REFLECTORS	New	120.00	30.00
6	TO CONDUCT WATER LEAKAGE TEST	New	150.00	0.00
7	TO REMOVE/REPLACE REAR SILENCER BOX	New	120.00	0.00
8	TO REMOVE/REPLACE REVERSE SENSOR AND DISTANCE SETTLING	New	150.00	50.00
9	TO REMOVE AND REPLACE BOOTLID MECHANISM	New	120.00	60.00
10	TO RENEW DAMAGED PARTS,REPLACE,BEAT,WELD,REALIGN AND ALIGNE ALL PARTS	New	2,000.00	800.00
11	TO RESPRAY AFFECTED AREAS	New	1,800.00	800.00
Gross Labour Cost (\$\$)			5,280.00	2,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >