ASSIGNMENT

From Date:	Veh No: SH 8 742 L	Yr Regn: 5	11/15
Estimated Cost:	Type: M.Car / M.Cycle / Bus / Van / Lo		
OD / TP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or		
To Inspect Vehicle No:	Make: Toyoth Pilus	G;(1798
at Workshop mis	Colour MG/097	A/C: Insured	d/Std/NI/NA
of	Sp.Reading 4235/6	T/Radio: Insure	d / Std / NI / NA
Insured: SHD 2877H	Eng/No:		
Policy No. 506804573704(A/10/2018 - >	C/No:	10575 5397	
Claims No. MT 1051637-002	Gen. Cond: Good) Fair / Poor / Burnt		
Sum insured: Excess:	Steering Inorder / Jammed / Leaked /	Burnt or	
(Client's Record)	Brake: Inorder/ Jammed / Leaked /	Burnt or	
Make of Veh:	Modi: Nil /(S/Rim) / STD A/Rim or		,"
	Tyre Size: F: 19	5/GRIS	
(Policy Condition)	R:	11	
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA /	MIC / OHTSU / PIF	R/SUMI/
repair at the time of inspection.	TOYOTYOKO or Falken		
Ball or Market Value:	Front	Rear	
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. 6 mm	R/Bal. 6	mm
GIA PR Seen: Consistent? : Yes or No	L/Bal. 6 mm	L/Bal. 6	mm
Est. Rapairs: days Res.: Yes or No	D.O.A. 28/6/19	D.O.I. //	7/19
Lum Sum: % 3 Val.: Yes or No	Survey held at SMRT		
CA / REV / REP. / 24 HRS	Des. of Damages (Frt) (Rear / O/S /	N/S / U/C / Roo	ftop or
Vehicle: IN / OUT			
Date Person Contacted:	The U/C / Chassis frame / Body	Structure affected	d due to collision.
Date Time Action / Instruction		00	119/2106
SHD 2877H - X	2.2		TM 2748
10/7/19 SHB 742L : CG3 CTI16022028/Syc	led \$ 12718.05, 67%)	C.	IN 1877H
with the total the total of	and the state of t	-11/	10 201111
	2010		
RECEIVED	1 1 2 JUL 2019		
Date File Pass 107 : Preli. Report	Days Of Repair:		
1) [M3 Mwist : Final Report	Resurvey No. of Trip:	Survey Fee:	160
Date/Time, File Return to?		Transportation	
Add Fee	: Site Insp (\$) _3+RS,E	
7.	: Interview (\$) Photos	
Report Format :	. Tech. Invs (\$) Others	
Lump Sum 18.1: (\$ 6300)	: Weekend (\$)	
		TOTAL	160

Shiau Chan (LKKAuto)

From:

MTCL@income.com.sg

Sent:

Thursday, 11 July 2019 5:26 PM

To:

Shiau Chan (LKKAuto)

Subject:

FW: REQUEST CLAIM NUMBER

Hi,

Claim created.

With Regards

Samsia

Senior Admin Assistant, Motor Insurance www.income.com.sg













At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify. Find out more at income.com.sg/careers



From: Shiau Chan (LKKAuto) [mailto:siewsc@lkkauto.com]

Sent: Thursday, 11 July 2019 11:54 AM

To: MTCL@income.com.sg

Subject: REQUEST CLAIM NUMBER

Dear Sir/Madam,

Please refer to the below:

TP Claims against NTUC Income: Follow-Through Survey

Date:

11/07/2019

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	С
1	MT/1051637-002	SMRT TAXIS PTE LTD	SHB 742L	SHD 2877H	

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

eBao Tech									G	ieneralC	laim
Hello, NAC_PAYA_UBI_80	00601						· Change L	anguage	· Change Pa	assword •	Log Out
My Desktop	Polic	y Query									
Notice of Loss	Policy N	0.				Date of	Accident	28/0	6/2019 09:15	5.	
	Vehicle	No.(For Motor)	SHD287	7H		Certifica	te Number				
					Se	arch					
	Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
	0	5068045737- 04		PRIME CAR RENTAL & TAXI SERVICES PTE. LTD.	199606293Z	GFT	Third Party, Fire & Theft	SHD2877H	SHD2877H	09/10/2018	
					Col	ntinue					

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID: Vehicle Details	5369K
Vehicle No.:	SHB742L
Vehicle to be Exported:	No
Intended Deregistration Date:	01 Jul 2019
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS TAXI (SMRT)
Primary Colour:	Maroon
Manufacturing Year:	2014
Engine No.:	2ZR6257419
Chassis No.:	JTDKN36U005755397
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$32,920.00
Original Registration Date:	05 Jan 2015
First Registration Date:	05 Jan 2015
Transfer Count:	0
Actual ARF Paid: Intended PARF Rebate Details	\$8,088.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	04 Jan 2023
PARF Rebate Amount: ntended COE Rebate Details	\$6,066.00
COE Expiry Date:	04 Jan 2023
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$52,486.00
COE Rebate Amount:	\$23,015.00
Total Rebate Amount: Message	\$29,081.00

The information contained herein is correct as at 01 Jul 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies. 5. Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

	ACCIDENT STATEMENT
Date Of Report	28/06/2019 15:10
Date Of Accident	28/06/2019 14:05
Exact Location Of Accident	PIE TOWARDS TUAS NEAR KALLANG BAHRU EXIT
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SHB742L
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000
Vehicle Particulars	
Manufacturer	ТОУОТА
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
f No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-19093197MFSH
Cover Note Number	A CONTRACTOR OF THE CONTRACTOR
Driver	
Jame of Driver	

Name of Driver MOHAMED NAZEER AMIN @NASH A DECRUZ

NRIC No S76427871 Date Of Birth 29/12/1976 Occupation OUTDOOR Date Of Driving Pass 03/09/1999

Driving Experience 19 YEARS AND 9 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-80000000

Fax Number Contact Number

EMail Address NOEMAIL Address

766

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OTHER - HIRER

Vehicle Registration Number of Driver's Own

Vehicle

.

Insurance Company of Driver's Own Vehicle

-

General Information of the Accident

Type Of Accident

CHAIN COLLISION

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

Number of vehicles (including own vehicle)

3

involved in the accident

3

Was any body injured in the Accident?

YES

Was any injured conveyed to hospital by ambulance?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

2

Passenger 1

NAME:

: CHEN XIAOQI

GENDER:

: FEMALE

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

I WAS TRAVELLING ALONG PIE AT THE RIGHT MOST LANE WITH A PASSENGER ON BOARD WHEN THE FRONT VEHICLE SJM274P SUDDENLY STOPPED. I APPLIED MY BRAKE AND ABLE TO STOP IN TIME. HOWEVER, THE VEHICLE SHD2877H FROM BEHIND FAILED TO STOP AND COLLIDED ONTO THE REAR PORTION OF MY TAXI. DUE TO THE GREAT IMPACT, MY TAXI WAS PUSHED FORWARD AND HIT ONTO THE REAR OF THE VEHICLE SJM274P.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Remarks/ Reasons:

FILE TOO BIG

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SHD2877H

Vehicle Make/Model/Colour

PRIME

Details Of Properties

Vehicle Category

TAXI

Name of Driver

HOK SWEE KWAN

NRIC/Passport Number

S1742909D

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SJM274P

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

CHRIS NG SZE HOW

NRIC/Passport Number

S7939624I

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

MOHAMED NAZEER AMIN @NASH A DECRUZ

Approximate Age Injuries Sustain

Injured person in which vehicle?

SHB742L

Were seat belts worn?

Was this injured conveyed to hospital by

ambulance?

NO

Address Postcode

DETAILS OF INJURED PERSON 2

Name

CHEN XIAOQI

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SHB742L

Were seat belts worn?

Was this injured conveyed to hospital by

ambulance?

NO

Address

Postcode

Sketch Plan Pg. 1

	RALLAND EX	111	1111	
			12	
	4		C	C-SJM 274P
	8		南	A- CHO
			A	018 743L
	P1E > TURS			C-SJM 274P A-SHB 742L B-SHD 2877 H
	2/6		B	0 17 7
DESCRIBE CIRCUMSTANCE	S OF THE ACCIDENT		SHOULD HOLD IN	
	O THE ACCIDENT			
CLARATION PTE				
CLARATION PTE				
e declare the foregoing partic	ulars are true in every rgsp	ect.		
e declare the foregoing partic	V			1 11
e declare the foregoing partic	V			nh 28/1/1
de declare the foregoing partic				ch 28/1/1
e declare the foregoing partic	V	Υ.	Reporting (La 28/11/

Sketch Plan Pg. 2

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful</u> and <u>accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
 Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
 interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident (all insurers') and the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) Investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the malling of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

(ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time:

Driver's Signature (If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature Name:

NRIC/FIN No .:

de 28/19



Case Details

Case Reference Number: TAX/06/19/2106

Type of Repair : Accident Repair

Vehicle Registration Number: SHB742L

Company Type: SMRT Taxis Pte Ltd

Estimation ID: EST-7505-ID

Assigned By : Taxi Claims Manager Team

Insurance Company Name ATUC Income

Insurance Co-operative Ltd

Accident Date and Time: 28/06/2019 06:05

AM

Vehicle Age(In Months): 53

Documents / Photographs

View Documents / Photographs

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

229200	100000000000000000000000000000000000000			SMRT Recon	imend	ation						Survey	or Approval
BOM Type		Portion	Material Number	Part Name	Qty	Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace
One Time Key In	Main		6505517	BUMPER FRT	1	482.00	482.00	25.00	361.50	Replace	1	361.5	Replace •
One Time Key In	Main			BUMPER CLIPS	10	1.61	16.10	25.00	12.08	Replace	10	12.08	Replace •
One Time Key In	Main		6505518	BUMPER ENERGY ABSORBER FRT	1	78.80	78.80	25.00	59.10	Replace	0	0	Check • X
One Time Key In	Main		6505539	BUMPER REINFORCEMENT FRT	1	498.40	498.40	25.00	373.80	Replace	0	0	Check • X
One Time Key In	Main			ARM SUB-ASSY,FR BUMPER LH	1	250.40	250.40	25.00	187.80	Replace	0	0	Not Give + X
One Time Key In	Main			ARM SUB-ASSY,FR BUMPER RH	1	250.40	250.40	25.00	187.80	Replace	0	0	Not Give • X
One Time Key In	Main			BRACKET, FR BUMPER	1	110.40	110.40	25.00	82.80	Replace	0	0	Not Give + X
One Time Key In	Main			NUMBER PLATE FRAME	1	15.00	15.00	0.00	15.00	Replace	1	15.00	Replace v
One Time Key In	Main			NUMBER PLATE	1	12.00	12.00	0.00	12.00	Replace	1	12.00	Replace v /
One Time Key In	Main			BUMPER GRILLE SUB- ASSY,LOWER	1	311.10	311.10	25.00	233.33	Replace	0	0	Not Give • X
One Time Key In	Main	1	6550638	EMBLEM FRONT	1	86.50	86.50	25.00	64.88	Replace	1	64.88	Replace + //

2111.10

Total Spare Part Cost 13,244.67

Lump Sum Discount (%) 20.00

Surveyor Total 5,575.10

Lump Sum Dis (%)

20

* Type		Portion	Material Number	Part Name	Qty	Price Per Unit(\$)	List Price(\$)	Dis(%) Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace
One Time Key In	Main			HOOD END PANEL SEAL	1	35.50	35.50	25.00	26.63	Replace	0	0	Check · y /
One Time Key In	Main		6505573	GRILLE, RADIATOR	1	310.60	310.60	25.00	232.95	Replace	0	0	Check • X M
One Time Key In	Main		6505548	BUMPER REAR	1	458.60	458.60	25.00	343.95	Replace	1	343.9	Replace • / 0
One Time Key In	Main			BUMPER CLIPS	10	1.61	16.10	25.00	12.08	Replace	10	12.08	Replace • / //
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.0	Replace • / /
One Time Key In	Main			BUMPER REINFORCEMENT REAR	1	205.70	205.70	25.00	154.27	Replace	1	154.2	Replace • / 0
One Time Key In	Main			ARM SUB-ASSY, RR BUMPER LH	1	139.60	139.60	25.00	104.70	Replace	0	0	Check • X
One Time Cey	Main			ARM SUB-ASSY, RR BUMPER RH	1	139.60	139.60	25.00	104.70	Replace	0	0	Check • X A
ne ime ey	Main			ANTENNA, ELECTRICAL LOWER REAR	1	157.40	157.40	10.00	141.66	Replace	1	141.6	Replace • / [
ine ime ey	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	1	180.0	Replace + ///
me me	Main			BUMPER SIDE RETAINER RR/LH	1	94.80	94.80	25.00	71.10	Replace	1	71.10	Replace + / 13K
ne me ay	Main			BUMPER SIDE RETAINER RR/RH	1	94.80	94.80	25.00	71.10	Replace	1	71.10	Replace • < fj/
ne me ey	Main		1	BUMPER SEAL, RR LH	1	88.90	88,90	25.00	66.68	Replace	0	0	Not Give + X
ne ne y	Main		E	BUMPER SEAL, RR RH	1	65.70	65.70	25.00	49.28	Replace	0	0	Not Give + X ///
ne y	Main			BUMPER LIP COVER RR/LH	1	72.20	72.20	25.00	54.15	Replace	0	0	Check + X M
ne y	Main			BUMPER LIP COVER	1	118.10	118.10	25.00	88.57	Replace	0	0	Check • X //
e I	Main		В	UMPER LIP REAR	1	228.90	228.90	25.00	171.68	Replace	1	171.6	Replace • / (

Тур	M Costing e Type	Portion	Material Number	Part Name	Qty	Price Per Unit(\$	List Price(S	Dis(%) Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace
One Time Key In				UNDER COVER SUB- ASSY, RR FLOOR	1	514.50	514.50	25.00	385.88	Replace	0	0	Check • X MM
One Time Key In	Main			END PANEL	1	602,10	602.10	25.00	451.58	Replace	1	451.5	Replace • /00
One Time Key In	Main			END PANEL COVER, DECK TRIM HOLE	1	46.10	46.10	25.00	34.58	Replace	1	34.58	Replace • / CRV
One Time Key In	Main			END PANEL COVER, DECK TRIM, RR	1	121.10	121.10	25.00	90.83	Replace	1	90.82	Replace •/Cf4
One Time Key In	Main			SEALANT SIKAFLEX	1	37.00	37.00	0.00	37.00	Replace	1	37.00	Replace • ///
One Time Key In	Main			BOX, DECK FLOOR, RE	1	649.70	649.70	25.00	487.28	Replace	0	0	Check • // ////
One Time Key In	Main			BOX, RR FLOOR, BOARD	1	679.60	679.60	25.00	509.70	Replace	0	0	Check • X /////
One Time Key In	Main			SPARE TYRE PANEL	1	667.70	667.70	25.00	500.78	Replace	0	0	Check • 1/////
One Time Key In	Main			CUSHION, SPARE WHEEL	1	230.80	230.80	25.00	173.10	Replace	0	0	Check • X M
One Time Key In	Main			CARRIER, SPARE	1	19.70	19.70	25,00	14.77	Replace	0	0	Check • X ///
One Time Key In	Main		1	PROTECTOR, SPARE	1	143.70	143.70	25.00	107.77	Replace	0	0	Check • X ////
One Time Key In	Main			MEMBER SUB-ASSY, RR LH	1	174.10	174.10	25.00	130.57	Replace	0	0	Check • X ////
One Time Key In	Main		F	LOOR PANEL RR/LH	1	102.00	102.00	25.00	76.50	Replace	0	0	Check · X ////
One Time Key In	Main		F	REINFORCEMENT, RR	2	34.60	69.20	25.00	51.90	Replace	2	51.90	Replace • / //
One Time Key In	Main		т	AILGATE ASY	1	1,007.90	1,007.90	25.00	755.92	Replace	1	755.9	Replace • / DD
One Time Key In	Main			AILGATE DOOR LASS MOULDING, RH	1	29.40	29.40	25.00	22.05	Replace	1	22.05	Replace • / PPC
	Main			AILGATE DOOR LASS MOULDING, LH	1	29.40	29.40	25.00	22.05	Replace	1	22.05	Replace • / //

Total Spare Part Cost 13,244.67

Surveyor Total 5,575.10

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

	е Туре	Portion	Material Number	Part Name	Qty	Price Per Unit(\$	List Price(S	Dis(%) Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace
One Tim Key In	е			MOULDING BACK WINDOW, LOWER NO.1	1	29.40	29.40	25.00	22.05	Replace	1	22.05	Replace * //
One Tim Key In	е			TAILGATE LOWER WINDOW GLASS	1	721.30	721.30	25.00	540.98 540.97	Replace	1	540.9	Replace • /
One Tim Key In				SEALANT W/SCREEN	3	37.00	111.00	0.00	111.00	Replace	3	111.0	Replace • ///
One Time Key In				TAILGATE DOOR HINGE LH/RH	2	58.30	116.60	25.00	87.45	Replace	0	0	Not Give • X
One Time Key In	Main			TAILGATE DOOR STAY LH	1	241.50	241.50	25.00	181.13	Replace	0	0	Not Give • y /
One Time Key In	Main			TAILGATE DOOR STAY	1	241.50	241.50	25.00	181.13	Replace	0	0	Not Give • X
One Time Key In	Main			TAILGATE DOOR LOCK	1	444.10	444.10	25.00	333.08	Replace	1	333.0	Replace v
One Time Key In	Main			TAILGATE LOCK, COVER	1	15.70	15.70	25.00	11.77	Replace	0	0	Not Give • X A
One Time Key In	Main			STRIKER, BACK DOOR	1	48.90	48.90	25.00	36.67	Replace	0	0	Not Give • X
One Time Key In	Main			TAILGATE DOOR WEATHER STRIP	1	353.40	353.40	25.00	265.05	Replace	1	265.0	Replace + / (
One Time Key In	Main			TAILGATE TRIM, LOWER	1	180.70	180.70	25.00	135.52	Replace	0	0	Check • X
One Time Key In	Main			TAILGATE, BAORD ASSY	1	246.90	246.90	25.00	185.18	Replace	0	0	Check · X
One Time Key In	Main			FAILGATE OUTSIDE GARNISH	1	504,90	504.90	25.00	378.67	Replace	1	378,6	Replace • /C
One Time Key In	Main		E	EMBLEM REAR	1	60.30	60.30	25.00	45.22 45.22	Replace	1	45.22	Replace • ///
One Time Key	Main		L	ICENSE PLATE LAMP	2	35.70	71.40	10.00	64.26	Replace	0	0	Check • ////
One Time Key	Main			AMERA ASSY, ELEVISION, RR	1 1	1,436.60	1,436.60		1,292.94	Replace	0	0	Check • Y ///
One Time	Main		N	AME PLATE (HYBRID)	1 5	1.90	51.90		38.92	Replace	1	38.92	Replace • /poc

Total Spare Part Cost 13,244.67

Surveyor Total 5,575.10

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Ту		Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%) Final Price(S)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	r Repair/Replace
On Tin Ke	те			NAME PLATE (PRUIS)	1	60.80	60.80	25.00	45.60	Replace	1	45.60	Replace *
On Tin Key In	ie			NAME PLATE (TOYOTA)	1	51.90	51.90	25.00	38.92	Replace	1	38.92	Replace *
One Tim Key In	e			NUMBER PLATE	1	15.00	15.00	0.00	15.00	Replace	1	15.00	Replace •
One Tim Key In	е			NUMBER PLATE FRAME	1	12.00	12.00	0.00	12.00	Replace	1	12.00	Replace */
One Tim Key In	e			STICKER DECAL SMRT	1	7.80	7.80	0.00	7.80	Replace	1	7.80	Replace *
One Time Key In				STICKER DECAL 6555 8888	1	21.60	21.60	0.00	21.60	Replace	1	21.60	Replace *
One Time Key In				SPOILER REAR	1	953.70	953.70	25.00	715.28	Replace	0	0	Not Give •
One Time Key In	Main			TAIL LAMP BRACKET, RH	1	30.70	30.70	25.00	23.02	Replace	0	0	Not Give +
One Time Key In	Main			TAIL LAMP RH	1	557.80	557.80	10.00	502.02	Replace	1	502.0	Replace •
One Time Key In	Main			TAIL LAMP BRACKET, LH	1	30.70	30.70	25.00	23.02	Replace	0	0	Not Give *
One Time Key In	Main			TAIL LAMP LH	1	548.40	548.40	10.00	493.56	Replace	0	0	Not Give •
						To	tal Spare Pa	rt Cost	13,244.67		Surve	yor Total	5,575.10
						Lump	Sum Disco	unt (%)	20.00		Lump Sur	n Dis (%)	20
						Fin	al Spare Pa	rt Cost	10,595.74		Final	Sur Total	4.460.08

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor		Rema
1	Main	TO REPAIR FRONT PORTION	338.00	200	/	
2	Main	TO REPAIR REAR PORTION	1,352.00	900	/	
Total:			1,690.00	1,100.00		

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(S)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPSRAY FRONT BUMPER	378.00	200.00	

			necommendation(3)	Aujustment(\$)
, 2	Main	TO SPRAY FRONT BUMPER LOWER SUB GRILLE	180.00	0
3	Main	TO RESPRAY REAR BUMPER	378.00	200.00
4	Main	TO RESPRAY BUMPER BEAM	180.00	0
5	Main	TO RESPRAY REAR PANEL	180.00	100 /
6	Main	TO RESPRAY REAR SPARE TYRE PANEL	180.00	0
7	Main	TO RESPRAY REAR MEMBER, LH	180.00	0
8	Main	TO RESPRAY TAIL GATE	378.00	200 /
9	Main	TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	100 /
10	Main	TO RESPRAY SPOILER	180.00	0
Total:			2,394.00	800.00

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20 /	
2	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	20 /	
3	Main	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	30.00 /	
4	Main	TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	30 /	
5	Main	TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	125.00	125.00	
6	Main	TO ALIGN CHASSIS	350.00	0.00	
7	Main	TO TRANSFER REAR TAILGATE MECHANISM	120.00	30 /	
8	Main	TO REMOVE AND REFIX REAR WINDSCREEN	240.00	100	
9	Main	TO WASH AND VACUUM	60.00	0.00	
10	Main	TO REPLACE SUNDRY PARTS	100.00	30 /	(9018.75
Total:			1,435.00	385.00	(9018-1

Summary

724UZ . 10

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	10,595.74	4,460.08
Total Labour Cost	1,690.00	1,100.00

Total Spray Painting	2,394.00	800.00
Other	1,435.00	385.00
Overall Total	16,114.74	6,745.08
Lump Sum Repair Option	2	
Lump Sum Total	16,100.00	6,750.00
Surveyor Approved Amount		6,750.00
No of Repair Days*	11	7
Remarks	~	L/S repair, take after spray. Finalize sent to stevechen@tkkauto.com
Surveyor Name		STEVE CHEN
Signature		- months
		3/1/8

Survey Date

01/07/2019

P- 5575.18

1190800
385

7860-18

L/5-6288-14

-6300

LKY Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Save

Clear



SMRT Automotive Services Pto Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number: 63085592
Estimator Telephone Number: 68652623
Accident Reporting Number: 68652672

Date Generated : 10/07/2019 User ID : PohSuan

Registration Number	SHB742L
Case Reference Number	TAX/06/19/2106
Registration Date	5/1/2015
Company Type	SMRT Taxis Pte Ltd
Make	тоуота
Model	PRIUS
Name of Driver	MOHAMED NAZEER AMIN @ NASH A DECRUZ
Type of Accident	Head to Rear
Accident Date and Time	28/6/2019 2:05 PM
Accident Reported Date and Time	28/6/2019 3:10 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24102204
Special Instruction to ARC, if any	TSS
Prepared Date and Time	30/6/2019 11:02 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Summary of Repair Estimate	•	
Contracting the second	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,690.00	\$1,100.00
Total Spray Cost	\$2,394.00	\$800.00
Total Spare Part Cost	\$13,244.67	\$5,575.18
Total Other Cost	\$1,435.00	(\$1,175.18)
TOTAL COST	\$18,763.67	\$6,300.00 (L/S)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	11.0	7.0
Prepared / Adjusted By	Kim Ming Chin	STEVE CHEN (LKK) / NTUC
ARC / Surveyor Sign Off Date	01/07/2019 5:41 PM	01/07/2019 4:20 PM
Signature	9	
Remarks		L/S repair, take after spray. Finalize sent



SMRT Automotive Services Pte Ltd 50 Woodlands Industrial Park E4 Singapore 757705 FAX Number : 63065592 Estimator Telephone Number : 68652623 Accident Reporting Number : 68652672

Date Generated : 18/07/2019 User ID : PohSuan

Section C - Quotation and Accident Invoice Details							
Quotation Number	QN-1907-0178	Invoice Number					
Quotation Date	10.07.2019	Invoice Date					
Invoice Amount		Prepared Date					

Section	on D - Details of Repair Estimates	
Part 1 - Labour Works		
Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT PORTION	\$338.00	\$200.00
TO REPAIR REAR PORTION	\$1,352.00	\$900.00
Total Labour	\$1,690.00	\$1,100.00

Job Scope	Quotation from ARC	Adjusted by Surveyor if
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00
TO SPRAY FRONT BUMPER LOWER SUB GRILLE	\$180.00	\$0.00
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY BUMPER BEAM	\$180.00	\$0.00
TO RESPRAY REAR PANEL	\$180.00	\$100.00
TO RESPRAY REAR SPARE TYRE PANEL	\$180.00	\$0.00
TO RESPRAY REAR MEMBER,LH	\$180.00	\$0.00
TO RESPRAY TAIL GATE	\$378.00	\$200.00
TO RESPRAY TAILGATE OUTSIDE GARNISH	\$180.00	\$100.00
TO RESPRAY SPOILER	\$180.00	\$0,00
Total Spray Painting & Panel Beating	\$2,394.00	\$800.00

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Lump Sum Adjustment by Surveyor	\$0.00	(\$1,560.18)
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$20.00
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	\$120.00	\$30.00
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	\$120.00	\$30.00
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	\$125.00	\$125.00
TO ALIGN CHASSIS	\$350.00	\$0.00
TO TRANSFER REAR TAILGATE MECHANISM	\$120.00	\$30.00
TO REMOVE AND REFIX REAR WINDSCREEN	\$240.00	\$100.00
TO WASH AND VACUUM	\$60,00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$30.00
Total Other Costs	\$1,435.00	(\$1,175.18)



SMRT Automotive Services Ptc Ltd 60 Woodlands Industrial Park E4, Singapore 757705 FAX Number : 63665592 Estimator Telephone Number : 68662623 Accident Reporting Number : 68662672

Date Generated : 10/07/2019

User ID : PohSuan

Part	Portion	Stock	Part Name	Quantity	List Price	Discount	Final Price	Estimator	Surveyor
Number 6505517		Number 52119-	BUMPER FRT	1.00	(\$) \$482.00	25.00	\$361.50	Approved Replace	Replace
		47930 52161-	BUMPER CLIPS	10.00	\$1.61	25.00	\$12.08	Replace	Replace
		16010	BUMPER CLIFS		O TOTAL			The state of	
5505518		52611- 47080	BUMPER ENERGY ABSORBER FRT	0.00	\$78.80	0.00	\$0.00	Replace	Check
505539		52021-	BUMPER	0.00	\$498.40	0.00	\$0.00	Replace	Check
	-	47023 57014-	REINFORCEMENT FRT ARM SUB-ASSY,FR	0.00	\$250.40	0.00	\$0.00	Replace	Not Given
		47030	BUMPER LH				1 12 139 139 139 1		Prising Control State
		57013- 47030	ARM SUB-ASSY,FR BUMPER RH	0.00	\$250.40	0.00	\$0.00	Replace	Not Given
		52114-	BRACKET, FR BUMPER	0.00	\$110.40	0.00	\$0.00	Replace	Not Given
		47140	NUMBER PLATE FRAME	1.00	\$15.00	0.00	\$15.00	Replace	Replace
			NUMBER PLATE	1.00	\$12.00	0.00	\$12.00	Replace	Replace
		50400	A CONTRACTOR OF THE CONTRACTOR	10000	100000	0.00	60.00	2	1
6505541		53102- 47020	BUMPER GRILLE SUB- ASSY,LOWER	0.00	\$311.10	0.00	\$0.00	Replace	Nat Given
6550638		75310- 47010	EMBLEM FRONT	1.00	\$86.50	25.00	\$64.88	Replace	Replace
		53395-	HOOD END PANEL SEAL	0.00	\$35.50	0.00	\$0.00	Replace	Check
6505573		47020 53111-	GRILLE, RADIATOR	0.00	\$310.60	0.00	\$0.00	Replace	Check
6505548	-	47040 52159-	BUMPER REAR	1.00	\$458.60	25.00	\$343.95	Replace	Replace
5505546		47905						A	Kepiace
		52161- 16010	BUMPER CLIPS	10.00	\$1.61	25.00	\$12.08	Replace	Replace
			PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace
		52023-	BUMPER	1.00	\$205.70	25.00	\$154.28	Replace	Replace
	-	12240 52016-	REINFORCEMENT REAR ARM SUB-ASSY. RR	0.00	\$139.60	0.00	\$0.00	Replace	Check
		47030	BUMPER LH	0.0000	DOMESTIC STREET	1000	I Passes	Charles Control	X
		52015- 47050	ARM SUB-ASSY, RR BUMPER RH	0.00	\$139.60	0.00	\$0.00	Replace	Check >
		89997- 30070	ANTENNA, ELECTRICAL	1.00	\$157.40	10.00	\$141.66	Replace	Replace
		30070	SENSOR REVERSE	1.00	\$180.00	0.00	\$180.00	Replace	Replace
		52576-	BUMPER SIDE RETAINER	1.00	\$94.80	25.00	\$71.10	Replace	Replace
		47020 52575-	RR/LH BUMPER SIDE RETAINER	1.00	\$94.80	25.00	\$71,10	Replace	Replace
		47020	RR/RH	(Inches	\$34.00	F-1000A	76-0000-9	Replace	Replace
		52592- 47021	BUMPER SEAL, RR LH	0.00	\$88.90	0.00	\$0.00	Replace	Not Given
		52591-	BUMPER SEAL, RR RH	0.00	\$65.70	0.00	\$0.00	Replace	Not Given
	-	47021 76088-	BUMPER LIP COVER	0.00	\$72.20	0.00	\$0.00	Replace	Check
		47020	RR/LH	.01222	i in the same	100.00		SOCI-MINISOLI	X
		76087- 47020	BUMPER LIP COVER RR/RH	0.00	\$118.10	0.00	\$0.00	Replace	Check
		76891-	BUMPER LIP REAR	1.00	\$228.90	25.00	\$171.68	Replace	Replace
		47020 58308-	UNDER COVER SUB-ASSY,	0.00	\$514.50	0.00	\$0.00	Replace	Check y
		47011 58307-	RR FLOOR END PANEL	1.00	\$602.10	25.00	\$451.58	Replace	Replace
		47060		1.1.1.17					-
		64718- 47031B0	END PANEL COVER, DECK TRIM HOLE	1.00	\$46.10	25.00	\$34.58	Replace	Replace
		64716-	END PANEL COVER, DECK	1.00	\$121.10	25.00	\$90.83	Replace	Replace
		47031B0	TRIM, RR SEALANT SIKAFLEX	1,00	\$37.00	0.00	\$37.00	Replace	Replace
		64993-	BOX, DECK FLOOR, RR	0.00	\$649.70	0.00	\$0.00	Replace	Check
		47020		1000	10000000	2030	7(33)	TWO COMES	<i>y</i>
		58416- 47030B3	BOX, RR FLOOR, BOARD	0.00	\$679.60	0.00	\$0.00	Replace	Check
		58311-	SPARE TYRE PANEL	0.00	\$667.70	0.00	\$0.00	Replace	Check
		47071 64777-	CUSHION, SPARE WHEEL	0.00	\$230.80	0.00	\$0.00	Replace	Check
		47090 51931-	CARRIER, SPARE	0.00	\$19.70	0.00	\$0.00	Replace	/
		47020				10000	TO TO SERVICE OF THE PARTY OF T	replace	Check
		64778- 47050	PROTECTOR, SPARE	0.00	\$143.70	0.00	\$0.00	Replace	Check y



SMRT Automotive Services Pte L1d

60 Woodlands incustrial Park E4, Singapora 757705

FAX Number : 63685592

Estimator Telephona Number : 68662623

Accident Risporting Number : 68662672

Date Generated: 10/07/2019 User ID : PohSuan

Part Number Total	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Check	
			ge After Surveyor Signed off		1.			lanca	16	
otal		1,110			\$16,636.52		\$5,575.18			
		47010 81561- 47170	TAIL LAMP LH	0.00	\$548.40	0.00	\$0.00	Replace	Not Given X	
		47180 52563-	TAIL LAMP BRACKET, LH	0.00	\$30.70	0.00	\$0.00	Replace	Not Given X	
		47010 81551-	TAIL LAMP RH	1.00	\$557.80	10.00	\$502.02	Replace	Replace	
		47910 52562-	TAIL LAMP BRACKET, RH	0.00	\$30.70	0.00	\$0.00	Replace	Not Given ×	
		76085-	SPOILER REAR	0.00	\$953.70	0.00	\$0.00	Replace	Not Given X	
			STICKER DECAL 6555 8888	1.00	\$21.60	0.00	\$21.60	Replace	Replace	
			STICKER DECAL SMRT	1.00	\$7.80	0.00	\$7.80	Replace	Replace	5 400
			NUMBER PLATE FRAME	1.00	\$12.00	0.00	\$12.00	Replace	Replace	s\$63
		47030	NUMBER PLATE	1.00	\$15.00	0.00	\$15.00	Replace	Replace	
		47030 75443-	NAME PLATE (TOYOTA)	1.00	\$51.90	25.00	\$38.93	Replace	Replace	
		47051 75442-	NAME PLATE (PRUIS)	1.00	\$60.80	25.00	\$45.60	Replace	Replace	288.
		47040 75374-	TELEVISION, RR NAME PLATE (HYBRID)	1.00	\$51.90	25.00	\$38.93	Replace	Replace	-
		86790-	CAMERA ASSY,	0.00	\$1,436.60	0.00	\$0.00	Replace	Check X	
		81271- 53011	LICENSE PLATE LAMP	0.00	\$35.70	0.00	\$0.00	Replace	Check	200
		75310- 47020	EMBLEM REAR	1.00	\$60.30	25.00	\$45.23	Replace	Replace	V
		76801- 47070-B0	TAILGATE OUTSIDE GARNISH	1.00	\$504.90	25.00	\$378.68	Replace	Replace	360
		67750- 47071C0	TAILGATE, BAORD ASSY	0.00	\$246.90	0.00	\$0.00	Replace	Check X	100
		67751- 47040C0	TAILGATE TRIM, LOWER	0.00	\$180.70	0.00	\$0.00	Replace	Check X +	10-
		67881- 47022	TAILGATE DOOR WEATHER STRIP	1.00	\$353.40	25.00	\$265.05	Replace	1 1	125.0
		69431- 47010	STRIKER, BACK DOOR	0.00	\$48.90	0.00	Samesas	Replace	Penlace +	575.
		69415- 47020	TAILGATE LOCK, COVER	55555	Its 1720cs		\$0.00	35	Not Given V	,,,,,
		47030		0.00	\$15.70	0.00	\$0.00	Replace	Not Given	575
		0W542 69350-	TAILGATE DOOR LOCK	1.00	\$444.10	25.00	\$333.08	Replace	Replace	
		0W532 68950-	TAILGATE DOOR STAY RH		\$241.50	0.00	\$0.00	Replace	Not Given _	
		47010 68960-	LH/RH TAILGATE DOOR STAY LH	0.00	\$241.50	0.00	\$0.00	Replace	Not Given Y	
		68810-	TAILGATE DOOR HINGE	0.00	\$58.30	0.00	\$0.00	Replace	Not Given	
		47030	SEALANT W/SCREEN	3.00	\$37.00	0.00	\$111.00	Replace	Replace	
		47030 64821-	WINDOW, LOWER NO.1 TAILGATE LOWER	1.00	\$721.30	25.00	\$540.98	Replace	Replace	
		75575 -	MOULDING BACK	1.00	\$29.40	25.00	\$22.05	Replace	Replace	
		75574- 47020	TAILGATE DOOR GLASS MOULDING, LH	1.00	\$29.40	25.00	\$22.05	Replace	Replace	
		75573- 47080	TAILGATE DOOR GLASS MOULDING, RH	1.00	\$29.40	25.00	\$22.05	Replace	Replace	
		67005- 47241	TAILGATE ASY	1.00	\$1,007.90	25.00	\$755.93	2/23/1/22/22	Replace	
		58336- 12090	REINFORCEMENT, RR	2.00	\$34.60	25.00	*			
		47301					\$51.90	11100 F 1725 STEELS	Replace	
		47030 58303-	LH FLOOR PANEL RR/LH	0.00	\$102.00	0.00	\$0.00	Replace	Check X	



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD			Ref:	NS/INC19011652/Eqd3e2			
		D UNION HOUSESINGAPORE	Date:	15-07-2019 INC4			
1.		Policy Particulars	:- THIR	PARTY CLAIM			
300.0	Insured Veh.	SHD 2877H	T	spected	SHB 742L		
	Policy No.	5068045737-04	Cover	age (\$)	0.00		
	Claim No.	MT/1051637-002	Exces	s (\$)	0.00		
	Assign From		Assig	n Date	01/07/2019		
2.	TO PROPERTY OF	Vehicle Parti	culars &	Condition			
	Make & Model	TOYOTA PRIUS	c.c		1798		
	Engine No.	HIDDEN	Year o	f Reg.	2015		
	Chassis No.	JTDKN36U005755397	Colou	r	MAROON		
	Odometer	423516	Steering		IN ORDER		
	Brakes	IN ORDER	Modifi	cation	SPORTS RIM		
	General	GOOD					
3.		Conditi	ions of	Tyres			
		Size	Make		Balance		
	R/H Front Tyre	195/65 R15	FALKE	N	6 mm		
	L/H Front Tyre	195/65 R15	FALKE	N	6 mm		
	R/H Rear Tyre	195/65 R15	FALKE	N	6 mm		
	L/H Rear Tyre	195/65 R15	FALKE	N	6 mm		
4.		Descripti	on of Da	amages			
	THE VEHICLE SU	STAINED DAMAGES AT THE FR	ONT AN	REAR PORTION.			
	DAMAGES SEE DETAILS.						
5.	FIRST SHEET .	Genera	Inform	ation			
	Accident Date	28/06/2019	Inspec	tion Date	01/07/2019		
	Survey held at	SMRT AUTOMOTIVE SERVICE	S PTE L	TD			
		60 WOODLANDS INDUSTRIAL	PARK E	4 SINGAPORE 7577	705		
5a.	DESERTED AND ADDRESS.	R	emarks				
		ON WAS CONDUCTED ON A"WIT CE TO YOUR INSTRUCTIONS, W					
5b.		Estimate	4 10 10 10 10		No. of the second second		
	ESTIMATED NOR	MAL PERIOD FOR REPAIR:		7 Working Days			



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315





ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 742L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BUMPER FRT (DISC 25%)	DENTED	482.00	361.50
10	BUMPER CLIPS @\$1.61 (DISC 25%)	NECESSARY	16.10	12.08
1	EMBLEM FRONT (DISC 25%)	NECESSARY	86.50	64.88
1	BUMPER REAR (DISC 25%)	DENTED	458.60	343.95
10	BUMPER CLIPS @\$1.61 (DISC 25%)	NECESSARY	16.10	12.08
1	BUMPER REINFORCEMENT REAR (DISC 25%)	DENTED	205.70	154.28
1	BUMPER SIDE RETAINER RR/LH (DISC 25%)	BROKEN	94.80	71.10
1	BUMPER SIDE RETAINER RR/RH (DISC 25%)	BROKEN	94.80	71.10
1	BUMPER LIP REAR (DISC 25%)	CRUSHED	228.90	171.68
1	END PANEL (DISC 25%)	DENTED	602.10	451.58
1	END PANEL COVER, DECK TRIM HOLE (DISC 25%)	CRUSHED	46.10	34.58
1	END PANEL COVER, DECK TRIM, RR (DISC 25%)	CRUSHED	121.10	90.83
2	REINFORCEMENT, RR @\$34.60 (DISC 25%)	DENTED	69.20	51.90
1	TAILGATE ASY (DISC 25%)	DENTED	1,007.90	755.93
1	TAILGATE DOOR GLASS MOULDING, RH (DISC 25%)	NECESSARY	29.40	22.05
1	TAILGATE DOOR GLASS MOULDING, LH (DISC 25%)	NECESSARY	29.40	22.05
1	MOULDING BACK WINDOW, LOWER NO.1 (DISC 25%)	NECESSARY	29.40	22.05
1	TAILGATE LOWER WINDOW GLASS (DISC 25%)	BROKEN	721.30	540.98
1	TAILGATE DOOR LOCK (DISC 25%)	BENT	444.10	333.08
1	TAILGATE DOOR WEATHER STRIP (DISC 25%)	CRUSHED	353.40	265.05
1	TAILGATE OUTSIDE GARNISH (DISC 25%)	CRUSHED	504.90	378.68
1	EMBLEM REAR (DISC 25%)	NECESSARY	60.30	45.23
1	NAME PLATE (HYBRID) (DISC 25%)	NECESSARY	51.90	38.93
1	NAME PLATE (PRIUS) (DISC 25%)	NECESSARY	60.80	45.60
1	NAME PLATE (TOYOTA) (DISC 25%)	NECESSARY	51.90	38.93
1	ANTENNA, ELECTRICAL LOWER REAR (DISC 10%)	BROKEN	157.40	141.66
1	TAIL LAMP RH (DISC 10%)	BROKEN	557.80	502.02
1	NUMBER PLATE FRAME (SN)	BROKEN	15.00	15.00
1	NUMBER PLATE (SN)	CUT	12.00	12.00
2	PIXEL STICKER @\$60.00 (SN)	NECESSARY	120.00	120.00

Report Ref No. NS/INC19011652/Eqd3e2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SENSOR REVERSE (SN)	BROKEN	180.00	180.00
1	SEALANT SIKAFLEX (SN)	NECESSARY	37.00	37.00
3	SEALANT W/SCREEN @\$37.00 (SN)	NECESSARY	111.00	111.00
1	NUMBER PLATE (SN)	CUT	15.00	15.00
1	NUMBER PLATE FRAME (SN)	CUT	12.00	12.00
1	STICKER DECAL SMRT (SN)	NECESSARY	7.80	7.80
1	STICKER DECAL 6555 8888 (SN)	NECESSARY	21.60	21.60
1	BUMPER ENERGY ABSORBER FRT	NOT NECESSARY	78.80	-
1	BUMPER REINFORCEMENT FRT	NOT NECESSARY	498.40	-
1	ARM SUB-ASSY, FR BUMPER LH	NOT NECESSARY	250.40	-
1	ARM SUB-ASSY, FR BUMPER RH	NOT NECESSARY	250.40	-
1	BRACKET, FR BUMPER	NOT NECESSARY	110.40	-
1	BUMPER GRILLE SUB-ASSY, LOWER	NOT NECESSARY	311.10	
1	HOOD END PANEL SEAL	NOT NECESSARY	35.50	-
1	GRILLE, RADIATOR	NOT NECESSARY	310.60	-
1	ARM SUB-ASSY, RR BUMPER LH	NOT NECESSARY	139.60	-
1	ARM SUB-ASSY, RR BUMPER RH	NOT NECESSARY	139.60	
1	BUMPER SEAL, RR LH	NOT NECESSARY	88.90	8
1	BUMPER SEAL, RR RH	NOT NECESSARY	65.70	-
1	BUMPER LIP COVER RR/LH	NOT NECESSARY	72.20	-
1	BUMPER LIP COVER RR/RH	NOT NECESSARY	118.10	-
1	UNDER COVER SUB-ASSY, RR FLOOR	NOT NECESSARY	514.50	8
1	BOX, DECK FLOOR, RR	NOT NECESSARY	649.70	-
1	BOX, RR FLOOR, BOARD	NOT NECESSARY	679.60	-
1	SPARE TYRE PANEL	NOT NECESSARY	667.70	-
1	CUSHION, SPARE WHEEL	NOT NECESSARY	230.80	-
1	CARRIER, SPARE	NOT NECESSARY	19.70	-
1	PROTECTOR, SPARE	NOT NECESSARY	143.70	-
1	MEMBER SUB-ASSY, RR LH	NOT NECESSARY	174.10	-
1	FLOOR PANEL RR/LH	NOT NECESSARY	102.00	-
2	TAILGATE DOOR HINGE LH / RH @\$58.30	NOT NECESSARY	116.60	3
1	TAILGATE DOOR STAY LH	NOT NECESSARY	241.50	-
1	TAILGATE DOOR STAY RH	NOT NECESSARY	241.50	-

Report Ref No. NS/INC19011652/Eqd3e2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	TAILGATE LOCK, COVER	NOT NECESSARY	15.70	
1	STRIKER, BACK DOOR	NOT NECESSARY	48.90	2
1	TAILGATE TRIM, LOWER	NOT NECESSARY	180.70	-
1	TAILGATE, BOARD ASSY	NOT NECESSARY	246.90	
2	LICENSE PLATE LAMP @\$35.70	NOT NECESSARY	71.40	
1	CAMERA ASSY, TELEVISION, RR	NOT NECESSARY	1,436.60	-
1	SPOILER REAR	NOT NECESSARY	953.70	-
1	TAIL LAMP BRACKET, RH	NOT NECESSARY	30.70	-
1	TAIL LAMP BRACKET, LH	NOT NECESSARY	30.70	-
1	TAIL LAMP LH	NOT NECESSARY	548.40	
			16,928.10	5,575.18
	LABOUR			
	PANEL BEATING & BODY WORK.		1,690.00	1,100.00
	SPRAY PAINT.		2,394.00	800.00
	TO CHECK WIRING AND SYSTEM FUNCTION.		80.00	20.00
	TO TEST AND REFIX REVERSE SENSOR SYSTEM.		120.00	20.00
	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.		120.00	30.00
	TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE.		120.00	30.00
	TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM.		125.00	125.00
	TO ALIGN CHASSIS.	NOT NECESSARY	350.00	2
	TO TRANSFER REAR TAILGATE MECHANISM.		120.00	30.00
	TO REMOVE AND REFIX REAR WINDSCREEN.		240.00	100.00
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
	TO REPLACE SUNDRY PARTS.		100.00	30.00
			-	-
			-	
			-	
			5,519.00	2,285.00
	GRAND TOTAL		22,447.10	7,860.18

Report Ref No. NS/INC19011652/Eqd3e2





6,300.00 RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)

Report Ref No. NS/INC19011652/Eqd3e2

CHEN TSUE YEE

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.