

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III19011685/UGA3N2

Date: 20/07/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	M495128/02
Claimant		
Vehicle No : SJC4060R	Insured Vehicle No :	SKT6135U
Date of Loss: 14/06/2019	Nature of Claim: TP	Claim No: MCA190147

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJC4060R		
Make & Model:	SUBARU IMPREZA, 1.6 (M)	Engine No:	EJ16D138547
Reg. Date:	18/02/2008 (Man. Year: 2007)	Chassis No:	JF1GD5KJ37G072295
Colour:	Grey	Odometer:	158236 km
Engine Capacity:	1597 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,339.36	1,301.44	3,037.92	70.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,740.00	1,500.00	1,240.00	45.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	7,079.36	2,801.44	4,277.92	60.43
Approved Total (Overridden) (\$\$)		2,200.00		
(\$\$)	7,079.36	2,200.00	4,879.36	68.92
+ GST 7.00/7.00% (\$\$)	495.56	154.00	341.56	68.92
Nett Amount (\$\$)	7,574.92	2,354.00	5,220.92	68.92
+ Car Rental (4.0 x S\$100.00/day) (\$\$)		400.00		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		2,761.45		
Global Sum Settlement (\$\$)		2,760.00		

INSPECTION

Date of Assignment: 11/07/2019

Date Inspected: 11/07/2019 Inspected At:

Hock Wah Motor Workshop Pte Ltd
(Bedok)
Blk 3011, Bedok Industrial Park E.,
#01-2008/2010/2012
Singapore 489977

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Jul 2020)
Parts:	143	SUBARU IMPREZA 1.6 (M) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJC4060R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Repair	654.30 FL	*- FL
2	1		*BOOTLID EMBLEM	Necessary	65.80 FL	*65.80 FL
3	1		*BOOTLID LOGO -SUBARU	Necessary	48.50 FL	*48.50 FL
4	1		*BOOTLID LOGO -IMPREZA	Necessary	48.50 FL	*48.50 FL
5	1		*BOOTLID HINGE RH	Not Necessary	54.50 FL	*- FL
6	1		*BOOTLID HINGE LH	Not Necessary	54.50 FL	*- FL
7	1		*BOOTLID RUBBER	Twisted	90.50 FL	*90.50 FL
8	1		*END PANEL	Repair	528.70 FL	*- FL
9	1		*REAR BUMPER	Dented	588.70 FL	*588.70 FL
10	1		*REAR BUMPER REINFORCEMENT	Not Necessary	110.00 FL	*- FL
11	1		*REAR BUMPER RETAINER RH	Bent	60.30 FL	*60.30 FL
12	1		*REAR BUMPER RETAINER LH	Not Necessary	60.30 FL	*- FL
13	3		*REAR BUMPER CLIP	Necessary	11.70 FL	*11.70 FL
14	1		*REAR NUMBER PLATE LAMP	Not Necessary	38.60 FL	*- FL
15	1		*REAR TAILLAMP O/S	Cracked	421.80 FL	*412.80 FL
16	1		*REAR FENDER RH (NPA)	Repair	0.00 FS	*- FS
17	1		*SPARE TYRE PANEL (NPA)	Repair	0.00 FS	*- FS
18	1		*REAR NUMBER PLATE	Bent	30.00 FS	*20.00 FS
19	1		*REAR NUMBER PLATE HOLDER	Bent	30.00 FS	*20.00 FS
20	1		*SET REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
21	1		*REAR BUMER SPOILER RH	Not Necessary	480.00 FS	*- FS
22	1		*BOOTLID SPOILER	Not Necessary	1,250.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,906.70	1,566.80
- List Item Discount on L Items 20.00/20.00% (\$\$)	567.34	265.36
Total Parts (\$\$)	4,339.36	1,301.44

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR TO REMOVE & REFIT NECESSARY PARTS	New	1,000.00	600.00
2	SPRAY PAINT ON THE AFFECTED AREAS	New	1,200.00	800.00
3	ANTI-RUST COATING	New	350.00	30.00
4	TO REMOVE & REFIT REVERSE SENSOR	New	150.00	50.00
5	WIRING	New	40.00	20.00
Gross Labour Cost (\$\$)			2,740.00	1,500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >