

22/03/2012

ASS. REC. BY:

REF: CS/MSG19011688/0+d372

Special Instruction:

Surveyor: Bryan

ASSIGNMENT (Office)

From (Person): Irene Tan Gek Ing

of MS19

Date/Time: 27.19 13:37p.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHA 8610L

Insured:

SLV 2022

at Workshop m/s Chinni Motor

Tel:

65425119

of BIK10 #01-05/06

Policy No: 28795104 MCX

Claim No:

598448

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A

1.7 2019

3.7 2019

CA / REV / REP. / REV 24 HRS

"up"

H.O.D. Endorsement:

Date/Time: 27.19 3.31p.m

Person Contacted:

Lynn

Vehicle IN/OUT


Date/Time	Action/Instruction (✓) Estimate
	SLV 2022R 'X
	SHA 8610L : CS/FCI19011143/d3 D.O.A: 2016/12/09
	9/7@17:04 - Revised via email preli advise

ASS. REC. BY:

# ASSIGNMENT

CDE May 2024

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_



(Policy Condition)  
 Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 10 days Res.: Yes or No  
 Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SHA 8610 L Yr Regn: 2016, May  
 Type: M.Car / M.Cycle / Bus / Van / Lorry (Taxi) / Prime Mover /  
 Truck / Trailer or  
 Make: Hyundai I40 C.C. 1685  
 Colour: Yellow A/C: Insured / Std / NI / NA  
 Sp. Reading: 370371 T/Radio: Insured / Std / NI / NA  
 Eng/No: D4FDFU609651  
 C/No: KMHLB41UMGU087457  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or  
 Brake: In order / Jammed / Leaked / Burnt or  
 Modi: Nil / S/Rim / STD A/Rim or  
 Tyre Size: F: 205/60 R16  
 R: — 11 —  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or Henkook  
 Front Rear  
 R/Bal. S mm R/Bal. S mm  
 L/Bal. S mm L/Bal. S mm  
 D.O.A. 01/07/2019 D.O.I. 03/07/2019  
 Survey held at Chunni AMK  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
Front y Rear  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	MSIG SLV 2022R
08/08/19	Insure 2/s 17000/- - ite 10 days 7 in (Red: 13470.90/ 52%)
	To submit accordingly

RECEIVED 30 SEP 2019

Date/Time, File Pass to?

1) 30/9 Typist

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: (\$) 17000

Days Of Repair: 10

Resurvey No. of Trip:

Add Fee: ☐ Site Insp (\$)  
☐ Interview (\$)  
☐ Tech. Invs (\$)  
☐ Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

250

11

261

Note: This document has not been finalised.  
**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Irene Tan Gek Ing

Date: 09 Jul 2019

**Preliminary Advice**

Insured Vehicle No	: SLV2022R	Accident Date	: 01/07/2019
TP Vehicle No	: SHA8610L	Assignment Date	: 02/07/2019
Make	: HYUNDAI I40	Est. Duration of Repair	: 10.00
Date of Inspection	: 03/07/2019		
Inspection At	: CHUNNI MOTOR WORK PTE LTD - AMK (HQ) BLK 10 #01-05/06, AMK AUTOPOINT SINGAPORE 568047		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front, rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	35,470.90
Revised Amount	:S\$	21,697.58
Check Items (Estimated)	:S\$	0.00
Total	:S\$	21,697.58

Lump Sum Repair :S\$

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

**Remarks**

- ( ) The vehicle is economical/not economical for repair.
- ( x ) The above survey was conducted on a 'without prejudice' basis.

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 Jul 2019 12:50		02 Jul 2019 13:57 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	SKYWAY MOTOR PTE LTD, Co. Reg. No.: 199904194N		
Main Claimant:	CITYCAB PTE LTD, Co. Reg. No.: 199502839G		
Vehicle Reg. No.:	SHA8610L	Date of Loss:	01/07/2019 10:00 - :59 [37 Months and 19 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP	Policy/Cover Note No.:	28795104MCX (Comprehensive) Coverage: 08/08/2018 - 07/08/2019
Vehicle Reg. No. (Insured):	SLV2022R	Policy No. (Claimant):	
		Excess:	
Repairer:	Chunni Motor Work Pte Ltd - Amk (HQ) Blk 10 #01-05/06, AMK Autopoint, 568047 Ang Mo Kio - Tel: 64836016		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 03/07/2019]		
Adj Asg. Remarks:	on WP. Liab: dispute (OI NR) TP agree on SJE - assign LKK Auto Consultants. Contact: Ms Lynn or Ms Irene at 65425119 or 6542 7162		

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

MCDG19085468 / ComfortDelGro Engineering Pte Ltd - Loyang  
 ENTRY DATE & TIME: 01/07/2019 16:11  
 SUBMITTED BY: Janet Lim Slang Gek

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report 01/07/2019 16:11  
 Date Of Accident 01/07/2019 10:00  
 Exact Location Of Accident PIE TWDS AIRPORT NEAR LAMP POST 266  
 Country/State of Loss SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number SHA8610L  
 Insured/Policyholder  
 Name Of Registered Owner CITYCAB PTE LTD  
 Co Reg No 199502839G  
 Email Address FLEETSAFETY@CDGTAXI.COM.SG  
 Mobile Phone No  
 Alternative Phone No OFFICE-65508768  
**Vehicle Particulars**  
 Manufacturer HYUNDAI  
 Model i40  
 Exact Purpose for which vehicle was being used at time of accident  
 Are you claiming under your own insurance policy for repair to your vehicle? NO  
 If No, Please state action to be taken THIRD PARTY  
 Vehicle Category TAXI  
**Insurance Company**  
 Name of Insurance Company MS FIRST CAPITAL INSURANCE LTD  
 Type Of Coverage THIRD PARTY FIRE AND/OR THEFT  
 Fleet Policy YES  
 Policy Number D-18088937MFSH  
 Cover Note Number  
**Driver**  
 Name of Driver LIM TECK CHIN  
 NRIC No S1422433E  
 Date Of Birth 23/11/1960  
 Occupation OUTDOOR  
 Date Of Driving Pass 08/02/1980  
 Driving Experience 39 YEARS AND 4 MONTHS  
 Gender MALE  
 Mobile Number (LOCAL) +65-96175155  
 Fax Number  
 Contact Number  
 Email Address TECKCHINL@YAHOO.COM

Address	BLK 607 YISHUN STREET 61 #06-287
Postcode	760607
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

**General Information of the Accident**

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

**Other Information**

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (Including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : - GENDER: : MALE

**Details of Police Action**

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

**Circumstances of Accident**

REFER ATTACHED

**Attachment(s)**

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number	SLV2022R
Vehicle Make/Model/Colour	HONDA
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	RAHIM BIN TUMIN
NRIC/Passport Number	
Contact Number	91885008
Address	
Postcode	
Insurance Company Name	

Nature Of Damago

FRONT

No. Of Passenger (Including Driver)

**DETAILS OF OTHER VEHICLE PROPERTY 2**

Vehicle Registration Number

SLQ3149D

Vehicle Make/Model/Colour

TOYOTA

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

POOVALAI THEVAR KATHIRAVANNETHI

NRIC/Passport Number

Contact Number

97992162

Address

Postcode

Insurance Company Name

Nature Of Damage

REAR

No. Of Passenger (Including Driver)

**SKETCH PLAN****IMPORTANT NOTICE**


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

CITYCAB PTE LTD  
CO. REG. NO. 199502839G


Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 01.07.2019@1230hrs

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.: June



## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 01.07.2019 @ 1000hrs I was travelling along PIE TWDS Airport Near Lamp Post 266. with one male passenger onboard.

As I VEH(C) SLQ 3149D slowed down and I followed. Suddenly Veh(B) SLV hit onto my vehicle and caused my vehicle to surge forward and hit onto VEH(C) SLQ 3149D.

As the accident took place too fast I could not take evasive action to prevent the accident.

No injury in this accident.

VEH(B) SLV 2022R MR Rahim Bin Tumin HP:9188 5008

VEH(C) SLQ 3149D MR Poovalai Thevar Kathiravannethi HP: 9799 2162

MALE PASSENGER : MR LIM H/P: 9652 5922.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

CITYCAB PTE LTD

20. REG. NO. 199502B39G

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 01.07.2019@1230hrs

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.: June

**CHUNNI MOTOR WORK PTE LTD****REPAIR ESTIMATE\***

VEHICLE NO : SHA 8610L

DATE : 1.07.2019

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039

MUG

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Radiator Grille <i>broken</i>			\$ 1,110.10	✓
	Radiator Grille H Emblem <i>new</i>			\$ 39.50	✓
	Front Bumper Cover <i>distorted / wandy broken</i>			\$ 1,052.20	✓
	Front Bumper Sponge <i>turn</i>			\$ 99.20	✓
	Front Bumper Reinforcement <i>BT</i>			\$ 402.10	✓
	Front Bumper Bracket Top (LH/RH) <i>NH</i>		\$ 22.40	\$ 44.80	X
	Front Bumper Bracket (LH/RH) <i>NH</i>		\$ 24.60	\$ 49.20	X
	Headlamp Support Top Cover <i>NH</i>			\$ 222.60	X
	Headlamp Support Panel Assy <i>2 Crack</i>			\$ 907.40	✓
	Headlamp (LH/RH) <i>wandy broken</i>		\$ 1,388.00	\$ 2,776.00	✓
	Radiator <i>2 BT / punctured</i>			\$ 698.30	✓
	Radiator Fan Blade, Cowling, Motor Assy <i>NH</i>			\$ 792.95	X
	Radiator Bracket (RH/LH) <i>NH</i>		\$ 6.50	\$ 13.00	X
	Radiator Guard <i>NH</i>		\$ 20.00	\$ 40.00	X
	Horn Unit (LH/RH) <i>Crack</i>		\$ 73.80	\$ 147.60	✓
	Aircon Condenser <i>2 BT</i>			\$ 927.50	✓
	Inter Cooler <i>2 BT</i>			\$ 1,032.50	✓
	Inter Cooler Mounting (2 PCS) <i>NH</i>			\$ 25.90	X
	Hose B To Inter Cooler <i>NH</i>			\$ 229.70	X
	Hose C To Inter Cooler Inlet <i>NH</i>			\$ 294.50	X
	Pipe To Inter Cooler <i>NH</i>			\$ 167.05	X
	Pipe To Inter Cooler Outlet <i>NH</i>			\$ 244.55	X
			9192.40		
			7353.92		
	SUB TOTAL			\$ 11,316.65	
	LESS 20%			\$ 2,263.33	
	DISCOUNTED TOTAL			\$ 9,053.32	
	Front Number Plate <i>Crack</i>			\$ 25.00	Nett ✓
	Front No Plate Trim Cover <i>Crack</i>			\$ 30.00	Nett ✓
			45.00	\$ 55.00	
	Labour Charge				
	Panel Beating			\$ 1,000.00	500/-
	Spray Painting Charge			\$ 250.00	200/-
	Wiring Charge			\$ 50.00	30/-
	Towing Charge			\$ 60.00	NH
	Remove/Refix Aircon & Refill Gas			\$ 150.00	80/-
	Diagnostic & Resetting To Erase Fault Code			\$ 480.00	NH
			810.00		
	TOTAL LABOUR			\$ 1,990.00	

SHA 8610L

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid <i>st</i>			\$ 2,174.90
	Boot Lid Rubber <i>deformed</i>			\$ 96.50
	Boot Lid Hinge (LH/RH) <i>HL</i>	\$	142.30	\$ 284.60
	Boot Lid Hinge Cover (LH/RH) <i>HL</i>	\$	158.00	\$ 316.00
	Boot Lid Lock Upper <i>st</i>			\$ 102.60
	Boot Lid Lock Lower <i>st</i>			\$ 31.70
	Boot Lid 'H' Emblem <i>HL</i>			\$ 28.70
	Boot Lid CRDI Plate <i>HL</i>			\$ 27.90
	Boot Lid Lamp (LH/RH) <i>crack</i>	\$	565.60	\$ 1,131.20
	Boot Lid Trimboard <i>deformed / torn</i>			\$ 116.40
	Boot Lid Trimboard Clips (10pcs) <i>HL</i>			\$ 11.00
	Bootlid Moulding <i>crack / st</i>			\$ 85.00
	Bootlid i40 Emblem <i>HL</i>			\$ 27.90
	Bootlid Lower Garnish <i>st / mostly broken</i>			\$ 227.90
	Rear Bumper <i>Dented</i>			\$ 553.00
	Rear Bumper Reinforcement <i>crack / Dented</i>			\$ 428.40
	Rear Bumper Reinforcement Bracket (LH/RH) <i>st</i>	\$	80.30	\$ 160.60
	Rear Bumper Clip 10 pcs <i>HL</i>			\$ 22.00
	Rear Bumper Bracket <i>HL</i>	\$	35.60	\$ 71.20
	Rear Bumper Sponge <i>torn</i>			\$ 118.40
	Rear Bumper Under Cover <i>dented</i>			\$ 228.00
	Tail Lamp (LH/RH) <i>crack</i>	\$	697.80	\$ 1,395.60
	Tail Lamp Quarter Panel (LH/RH) <i>HL N/S o/s Dented</i>	\$	<u>226.50</u>	\$ 453.00
	Rear Panel <i>Dented</i>			\$ 526.70
	Rear Panel Garnish <i>deformed / mostly</i>			\$ 57.70
	Rear Panel Lower Panel <i>Dented</i>			\$ 495.50
	Spare Tyre Holder <i>st</i>			\$ 223.10
	Spare Tyre Panel <i>Dented</i>			\$ 852.80
	Spare Tyre Panel Cushion <i>HL</i>			\$ 209.05
	Rear Towing Hook <i>HL</i>			\$ 94.60
	Member Assy- Rear Floor Centre <i>HL</i>			\$ 570.40
	Exhaust Pipe Insulator <i>HL</i>	\$	58.55	\$ 117.10
	Exhaust Silencer <i>st</i>	\$	967.70	\$ 1,935.40
	Exhaust Pipe Hanger <i>HL</i>	\$	58.55	\$ 117.10
	Exhaust Pipe Centre <i>HL</i>			\$ 730.10
	Rear Fender With Housing (LH/RH) <i>Dented</i>	\$	4,736.80	\$ 9,473.60
	Rear Fender Inner Lining (RH) <i>HL</i>			\$ 169.30
	Rear Fender Air-Duct <i>HL</i>			\$ 51.60
	Rear Windscreen Moulding <i>HL</i>			\$ 28.30
			13333.70	\$ 23,744.85
			10666.96	\$ 4,748.97
				\$ 18,995.88
	SUB TOTAL			
	LESS 20%			
	DISCOUNTED TOTAL			

SHA 8610L

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Boot Lid Comfort Logo & Tel No. Sticker <i>N/C</i>			\$ 30.00	Nett ✓
	Boot Lid Advertisement Logo <i>N/C</i>			\$ 100.00	Nett ✓
	Rear No. Plate <i>CRANK</i>			\$ 25.00	Nett ✓
	Rear Bumper Reverse Sensor <i>Dam</i>			\$ 135.70	Nett ✓
	Rear Bumper Advertisement Logo <i>N/C</i>			\$ 50.00	Nett ✓
	Rear Bumper Rubber Mat <i>detuned</i>			\$ 50.00	Nett ✓
	Rear Fender Advertisement Logo (LH/RH) <i>N/C</i>		\$ 100.00	\$ 200.00	Nett ✓
	Rear Windscreen Sealant <i>N/C</i>			\$ 46.00	Nett ✓
			636.70	\$ 636.70	
	Labour Charge			\$ 2,000.00	1000/-
	Panel Beating			\$ 1,750.00	900/-
	Spray Painting Charge			\$ 50.00	30/-
	Wiring Charge			\$ 100.00	40/-
	Tuff Kote			\$ 150.00	80/-
	Remove/Refix Cushion & Upholstery Rear			\$ 120.00	80/-
	Remove/Refix Rear Windscreen Glass			\$ 120.00	40/-
	Remove/Refix Reverse Sensor			\$ 150.00	NA
	Remove/Refix Fuel Tank			\$ 300.00	60/-
	Remove/Refix Exhaust Pipe				
			2230.00	\$ 4,740.00	
	<i>[Signature]</i> TOTAL LABOUR			\$ 35,470.90	
	<i>[Signature]</i> ESTIMATE TOTAL				
	03/07/2019 @ 0915hrs			21742.58	
	NA Arthur			4317000/-	
	2/5mm 10 days				
	<i>[Signature]</i> Ryan				
	LKK Auto				
	<i>[Signature]</i>				
	<div>LKK Auto Consultants hence notify the Repairer of the following:<ul style="list-style-type: none"><li>• To resurvey before/after spray painting</li><li>• To display damaged part(s) during resurvey</li><li>• Parts prices are subject to confirmation</li><li>• Third party survey is on a "Without Prejudice" basis</li><li>• No illegal modification(s) is allowed</li><li>• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company</li></ul>Acknowledged by Repairer Signature: Date:</div>				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19011688/DTD3N2

Date: 30/09/2019

## REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	28795104MCX
Claimant Vehicle No :	SHA8610L	Insured Vehicle No :	SLV2022R
Date of Loss:	01/07/2019	Nature of Claim:	TP
		Claim No:	598448

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SHA8610L	Engine No:	D4FDFU609651
Make & Model:	HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A)	Chassis No:	KMHLB41UMGU087457
Reg. Date:	12/05/2016 (Man. Year: 2016)	Odometer:	370371 km
Colour:	Yellow		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	Hankook 5 mm	Rear Left Side:	Hankook 5 mm
Front Right Side:	Hankook 5 mm	Rear Right Side:	Hankook 5 mm

The above values represent the remaining tyre treads depth

## COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	28,740.90	18,702.58	10,038.32	34.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,730.00	3,040.00	3,690.00	54.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>35,470.90</b>	<b>21,742.58</b>	<b>13,728.32</b>	<b>38.70</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>17,000.00</b>		
<b>(S\$)</b>	<b>35,470.90</b>	<b>17,000.00</b>	<b>18,470.90</b>	<b>52.07</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>2,482.96</b>	<b>1,190.00</b>	<b>1,292.96</b>	<b>52.07</b>
<b>Nett Amount (S\$)</b>	<b>37,953.86</b>	<b>18,190.00</b>	<b>19,763.86</b>	<b>52.07</b>

## INSPECTION

Date of Assignment: 02/07/2019

Date Inspected: 03/07/2019 Inspected At:

Chunni Motor Work Pte Ltd - Amk (HQ)  
Blk 10 #01-05/06, AMK Autopoint  
Singapore 568047

Estimated Period of Repair: 10.0 days

Adjuster: BRYAN TANI

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

*knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

## Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 30 Sep 2019)
<b>Parts:</b>	143	HYUNDAI I40 1.7 D CRDI F/L ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHA8610L)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RADIATOR GRILLE	Broken	1,110.10 FL	*1,110.10 FL
2	1		*RADIATOR GRILLE H EMBLEM	Necessary	39.50 FL	*39.50 FL
3	1		*FRONT BUMPER COVER	Distorted/Mounting Broken	1,052.20 FL	*1,052.20 FL
4	1		*FRONT BUMPER SPONGE	Torn	99.20 FL	*99.20 FL
5	1		*FRONT BUMPER REINFORCEMENT	Bent	402.10 FL	*402.10 FL
6	2		*FRONT BUMPER BRACKET TOP (LH/RH)	Not Necessary	44.80 FL	*- FL
7	2		*FRONT BUMPER BRACKET (LH/RH)	Not Necessary	49.20 FL	*- FL
8	1		*HEADLAMP SUPPORT TOP COVER	Not Necessary	222.60 FL	*- FL
9	1		*HEADLAMP SUPPORT PANEL ASSY	Cracked	907.40 FL	*907.40 FL
10	2		*HEADLAMP (LH/RH)	Mounting Broken	2,776.00 FL	*2,776.00 FL
11	1		*RADIATOR	Bent/Punctured	698.30 FL	*698.30 FL
12	1		*RADIATOR FAN BLADE,COWLING,MOTOR ASSY	Not Necessary	792.95 FL	*- FL
13	2		*RADIATOR BRACKET (LH/RH)	Not Necessary	13.00 FL	*- FL
14	2		*RADIATOR GUARD	Not Necessary	40.00 FL	*- FL
15	2		*HORN UNIT (LH/RH)	Cracked	147.60 FL	*147.60 FL
16	1		*AIRCON CONDENSER	Bent	927.50 FL	*927.50 FL
17	1		*INTER COOLER	Bent	1,032.50 FL	*1,032.50 FL
18	1		*INTER COOLER MOUNTING (2 PCS)	Not Necessary	25.90 FL	*- FL
19	1		*HOSE B TO INTER COOLER	Not Necessary	229.70 FL	*- FL
20	1		*HOSE C TO INTER COOLER INLET	Not Necessary	294.50 FL	*- FL
21	1		*PIPE TO INTER COOLER	Not Necessary	167.05 FL	*- FL
22	1		*PIPE TO INTER COOLER OUTLET	Not Necessary	244.55 FL	*- FL
23	1		*BOOT LID	Bent	2,174.90 FL	*2,174.90 FL
24	1		*BOOT LID RUBBER	Deformed	96.50 FL	*96.50 FL
25	2		*BOOT LID HINGE (LH/RH)	Not Necessary	284.60 FL	*- FL
26	2		*BOOT LID HINGE COVER (LH/RH)	Not Necessary	316.00 FL	*- FL
27	1		*BOOT LID LOCK UPPER	Bent	102.60 FL	*102.60 FL
28	1		*BOOT LID LOCK LOWER	Bent	31.70 FL	*31.70 FL
29	1		*BOOT LID H EMBLEM	Necessary	28.70 FL	*28.70 FL
30	1		*BOOT LID CRDI PLATE	Necessary	27.90 FL	*27.90 FL
31	2		*BOOT LID LAMP (LH/RH)	Cracked	1,131.20 FL	*1,131.20 FL
32	1		*BOOT LID TRIMBOARD	Deformed/Torn	116.40 FL	*116.40 FL
33	10		*BOOT LID TRIMBOARD CLIPS	Necessary	11.00 FL	*11.00 FL
34	1		*BOOTLID MOULDING	Cracked/Bent	85.00 FL	*85.00 FL
35	1		*BOOTLID I40 EMBLEM	Necessary	27.90 FL	*27.90 FL
36	1		*BOOTLID LOWER GARNISH	Bent/Mounting Broken	227.90 FL	*227.90 FL
37	1		*REAR BUMPER	Dented	553.00 FL	*553.00 FL
38	1		*REAR BUMPER REINFORCEMENT	Cracked/Dented	428.40 FL	*428.40 FL
39	2		*REAR BUMPER REINFORCEMENT BRACKET (LH/RH)	Bent	160.60 FL	*160.60 FL
40	10		*REAR BUMPER CLIP	Necessary	22.00 FL	*22.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
41	2		*REAR BUMPER BRACKET	Not Necessary	71.20 FL	*- FL
42	1		*REAR BUMPER SPONGE	Torn	118.40 FL	*118.40 FL
43	1		*REAR BUMPER UNDER COVER	Distorted	228.00 FL	*228.00 FL
44	2		*TAIL LAMP (LH/RH)	Cracked	1,395.60 FL	*1,395.60 FL
45	1		*TAIL LAMP QUARTER PANEL (LH/RH)	O/s Dented/N/s Not Necessary	453.00 FL	*226.50 FL
46	1		*REAR PANEL	Dented	526.70 FL	*526.70 FL
47	1		*REAR PANEL GARNISH	Mounting Deformed	57.70 FL	*57.70 FL
48	1		*REAR PANEL LOWER PANEL	Dented	495.50 FL	*495.50 FL
49	1		*SPARE TYRE HOLDER	Bent	223.10 FL	*223.10 FL
50	1		*SPARE TYRE PANEL	Dented	852.80 FL	*852.80 FL
51	1		*SPARE TYRE PANEL CUSHION	Not Necessary	209.05 FL	*- FL
52	1		*REAR TOWING HOOK	Not Necessary	94.60 FL	*- FL
53	1		*MEMBER ASSY-REAR FLOOR CENTRE	Not Necessary	570.40 FL	*- FL
54	2		*EXHAUST PIPE INSULATOR	Not Necessary	117.10 FL	*- FL
55	2		*EXHAUST SILENCER	Bent	1,935.40 FL	*1,935.40 FL
56	2		*EXHAUST PIPE HANGER	Not Necessary	117.10 FL	*- FL
57	1		*EXHAUST PIPE CENTRE	Not Necessary	730.10 FL	*- FL
58	1		*REAR FENDER (LH/RH)	O/s Dented	9,473.60 FL	*2,020.00 FL
59	1		*REAR FENDER INNER LINING (RH)	Not Necessary	169.30 FL	*- FL
60	1		*REAR FENDER AIR-DUCT	Not Necessary	51.60 FL	*- FL
61	1		*REAR WINDSCREEN MOULDING	Necessary	28.30 FL	*28.30 FL
62	1		*FRONT NO PLATE TRIM COVER }	Cracked	30.00 FS	*45.00 FS
63	1		*FRONT NUMBER PLATE }	Cracked	25.00 FS	*- FS
64	1		*BOOT LID COMFORT LOGO & TEL NO STICKER	Necessary	30.00 FS	*30.00 FS
65	1		*BOOT LID ADVERTISEMENT LOGO	Necessary	100.00 FS	*100.00 FS
66	1		*REAR NO PLATE	Cracked	25.00 FS	*25.00 FS
67	1		*REAR BUMPER REVERSE SENSOR	Damaged	135.70 FS	*135.70 FS
68	1		*REAR BUMPER ADVERTISEMENT LOGO	Necessary	50.00 FS	*50.00 FS
69	1		*REAR BUMPER RUBBER MAT	Deformed	50.00 FS	*50.00 FS
70	2		*REAR FENDER ADVERTISEMENT LOGO (LH/RH)	Necessary	200.00 FS	*200.00 FS
71	1		*REAR WINDSCREEN SEALANT	Necessary	46.00 FS	*46.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 35,753.20 23,207.80  
 - List Item Discount on L Items 20.00/20.00% (\$\$) 7,012.30 4,505.22

Total Parts (\$\$) 28,740.90 18,702.58

Report was unsubmitted during this print-out.
---



## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	3,000.00	1,500.00
2	SPRAY PAINTING CHARGE	New	2,000.00	1,100.00
3	WIRING CHARGE	New	100.00	60.00
4	TOWING CHARGE	New	60.00	0.00
5	REMOVE/REFIX AIRCON & REFILL GAS	New	150.00	80.00
6	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE	New	480.00	0.00
7	TUFF KOTE	New	100.00	40.00
8	REMOVE/REFIX CUSHION & UPHOLSTERY REAR	New	150.00	80.00
9	REMOVE/REFIX REAR WINDSCREEN GLASS	New	120.00	80.00
10	REMOVE/REFIX REVERSE SENSOR	New	120.00	40.00
11	REMOVE/REFIX FUEL TANK	New	150.00	0.00
12	REMOVE/REFIX EXHAUST PIPE	New	300.00	60.00
<b>Gross Labour Cost (S\$)</b>			<b>6,730.00</b>	<b>3,040.00</b>

Report was unsubmitted during this print-out.

&lt; END OF ESTIMATES &gt;