Adjuster Report Page 1 of 5

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG19011697/KKA3Q2

Date: 20/04/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100433023

Claimant
Vehicle No: SHD9826J Insured Vehicle No: SKU8522S

Date of Loss: 26/06/2019 Nature of Claim: TP Claim No: 1795777081SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHD9826J

 Make & Model:
 RENAULT LATITUDE, 2.0 L (A)
 Engine No:
 M9R8839C001017

 Reg. Date:
 25/04/2014 (Man. Year: 2013)
 Chassis No:
 VF1ABL15AUC277403

Colour: Metallic White/Red Odometer: 337591 km

Engine Capacity:
Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

1995 сс

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
Front Left Side: Linglong 9 mm Rear Left Side: Giti 8 mm
Front Right Side: Linglong 9 mm Rear Right Side: Giti 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	22,773.78	1,788.57	20,985.21	92.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,890.00	480.00	11,410.00	95.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	34,663.78	2,268.57	32,395.21	93.46
Approved Total (Overridden) (S\$)		1,800.00		
(S\$)	34,663.78	1,800.00	32,863.78	94.81
+ GST 7.00/7.00% (S\$)	2,426.46	126.00	2,300.46	94.81
Nett Amount (S\$)	37,090.24	1,926.00	35,164.24	94.81
+ Loss of Use (2.0 x S\$5	60.00/day) (S\$)	100.00		
+ Car Rental (2.0 x S\$8	31.13/day) (S\$)	162.26		
+ Doc/Se	earch Fee (S\$)	7.49		
Net	t Liability (S\$)	2,195.75		

INSPECTION

Date of Assignment: 01/07/2019

Date Inspected: 01/07/2019 Inspected At: Trans-cab Auto Services Pte Ltd

No 2 Ang Mo Kio Street 63

Singapore 569111

Estimated Period of Repair: 2.0 days

Adjuster Report Page 2 of 5

Adjuster: KENNETH KONG Manager: Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 5

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER REAR	Buckled	1,108.46 FL	*1,108.46 FL
2	1		*BUMPER LOWER REAR	Dented	768.84 FL	*768.84 FL
3	1		*BUMPER BRACKET CTR REAR	Serviceable	113.47 FL	*- FL
4	1		*BUMPER BRACKET SIDE RH REAR	Serviceable	135.97 FL	*- FL
5	1		*BUMPER RETAINER RH REAR	Serviceable	44.99 FL	*- FL
6	1		*BUMPER REFLECTOR RH	Serviceable	43.61 FL	*- FL
7	1		*BUMPER BRACKET SIDE LH REAR	Serviceable	135.97 FL	*- FL
8	1		*BUMPER RETAINER LH REAR	Serviceable	44.99 FL	*- FL
9	1		*BUMPER REFLECTOR LH	Serviceable	43.61 FL	*- FL
10	1		*BUMPER BEAM REAR	Repair	777.52 FL	*- FL
11	1		*BUMPER BEAM BRACKET LH REAR	Repair	225.95 FL	*- FL
12	1		*BUMPER BEAM BRACKET RH REAR	Repair	225.95 FL	*- FL
13	1		*OUTER PANEL REAR (END PANEL)	Repair	1,471.77 FL	*- FL
14	1		*OUTER PANEL REAR (END PANEL)TRIM	Serviceable	404.56 FL	*- FL
15	1		*TAILLAMP RH	Serviceable	552.55 FL	*- FL
16	1		*TAILLAMP PANEL RH	Repair	986.70 FL	*- FL
17	1		*TAILLAMP LH	Serviceable	552.55 FL	*- FL
18	1		*TAILLAMP PANEL LH	Repair	986.70 FL	*- FL
19	1		*BOOT REAR	Repair	2,872.68 FL	*- FL
20	1		*BOOT FINISHER	Serviceable	470.06 FL	*- FL
21	1		*BOOT WEATHERSTRIP	Serviceable	323.05 FL	*- FL
22	1		*BOOT REFLECTOR LAMP LH	Serviceable	493.35 FL	*- FL
23	1		*BOOT REFLECTOR LAMP RH	Serviceable	493.35 FL	*- FL
24	1		*BOOT BADGE RENAULT	Not Necessary	225.36 FL	*- FL
25	1		*BOOT BADGE	Not Necessary	225.36 FL	*- FL
26	1		*BOOT STRUT LH	Serviceable	276.08 FL	*-FL
27	1		*BOOT STRUT RH	Serviceable	276.08 FL	*- FL
28	1		*BOOT HINGE LH	Repair	367.84 FL	*- FL
29	1		*BOOT HINGE RH	Repair	367.84 FL	*- FL
30	1		*BOOT INNER TRIM	Serviceable	586.45 FL	*-FL
31	1		*BOOT SWTICH	Serviceable	168.13 FL	*- FL
32	1		*BOOT LOCK	Repair	202.67 FL	*-FL
33	1		*BOOT LOCK CATCH	Repair	74.40 FL	*-FL
34	1		*EXHAUST REAR	Repair	7,489.05 FL	*-FL
35	1		*EXHAUST CAP REAR	Repair	230.49 FL	*-FL
36	1		*SET PARKING AID	Serviceable	700.00 FS	*-FS
37	1		*SET REAR BUMPER CLIP	Necessary	66.00 FS	*66.00 FS
38	1		*SET BUMPER BRACKET CTR CLIP	Necessary	33.00 FS	*33.00 FS
39	1		*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	10.00 FS	*-FS
40	1		*SET BUMPER RETAINER RH CLIP RR	Not Necessary	20.00 FS	*-FS
41	1		*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	10.00 FS	*-FS
42	1		*SET BUMPER RETAINER CLIP LH RR	Not Necessary	20.00 FS	*-FS
43	1		*SET BUMPER LOWER REAR RIVET	Not Necessary	22.00 FS	*-FS
44	1		*SET BUMPER LOWER REAR CLIP	Not Necessary	66.00 FS	*-FS
45	1		*BOOT STICKER TRANS-CAB	Not Necessary	30.00 FS	*-FS
46	1		*BOOT STICKER 6555-3333	Not Necessary	30.00 FS	*-FS
47	1		*EXHAUST MOUNTING REAR	Not Necessary	17.82 FS	*-FS
48	2		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*-FS
49	1		*WINDSCREEN MOULDING	Not Necessary	100.00 FS	*-FS
50	1		*REAR WINDSCREEN INNER SPONGE SEAL	Not Necessary	100.00 FS	*-FS
51	1		*BOOT INNER TRIM CLIP	Not Necessary	45.00 FS	*-FS
52	1		*SET BOOT FINISHER CLIP	Not Necessary	24.20 FS	*-FS
53	1		*TAILLAMP CLIP LH	Not Necessary	5.00 FS	*-FS
			Report was unsubmitted during thi			

Adjuster Report Page 4 of 5

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
54	1		*TAILLAMP CLIP RH	Not Necessary	5.00 FS	*-FS
F=Fra	nchise	part. S=Spc	Nett. L=ListItemDisc.	'		
				Sub Total (S\$)	25,150.42	1,976.30
			- List Item Discount on L Items 1	0.00/10.00% (S\$)	2,376.64	187.73
				Total Parts (S\$)	22,773.78	1,788.57
			Report was unsubmitted during this	print-out.		

Adjuster Report Page 5 of 5

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount				
Labo	<u>Labour Items</u>							
1	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	0.00				
2	TO TRANSFER OF BOOTLID FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00				
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	0.00				
4	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	0.00				
5	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING	New	170.00	0.00				
6	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	60.00				
7	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.	New	4,500.00	200.00				
8	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	4,500.00	220.00				
9	TO REPAIR AND REALIGN REAR EXHAUST PIPE	New	170.00	0.00				
10	TO DROP REAR EXHAUST BOX ,RENEW THE SAME ,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE	New	170.00	0.00				
11	TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00				
12	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.	New	170.00	0.00				
13	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00				
14	TO TRANSFER OF REAR BUMPER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00				
15	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH ,TO FACILITATE REPAIR	New	380.00	0.00				
	Gross Labour Cost (S\$)		11,890.00	480.00				

Report was unsubmitted during this print-out.

< END OF ESTIMATES >