



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
NG GHIM CHEW BLK 635 JURONG WEST STREET 65 #13-330 SINGAPORE 640635 Contact No Mobile: 97903107	Cust No/Name	LCV07172/NG GHIM CHEW
	Reg No/Reg Date	SMF3945T*ECB / 08/11/201
	Date In/Mileage	/ 0
	Chassis No	KNAF3416MK5017098
	Engine No	G4FGJH707992
	Make/Model	KIA/CERATO 1.6 A SR SX G335
	Colour/Trim	BBL HORIZON BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
CSM00081	Cash	29/06/2019/ 15:03	QUD	247 / DonBong	52964		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000							825 1650.00
RENEW ACCIDENT DAMAGED PARTS ON FRONT BUMPER FACE, RH HEADLAMP, REPAIR RH FRONT FENDER							
E PNT88000							100.00
REMOVE AND INSTALL PARKING ASSIST							
E PNT98000							840 1260.00
PAINT WORK SPRAY FRONT BUMPER FACE, RH FRONT FENDER AND AFFECTED PORTION							
M SUNDRY							60 80.00
PERFORM RUST PREVENTION							
A 54900099							50.00
CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM							
M SUNDRY							X 50.00
SUPPLY FRONT NUMBER PLATE WITH FRAME							
A 10028901							200.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST							
M SUNDRY							20 50.00
SUNDRIES							
M	LAMP ASSY-HEAD, RH	SCR	1.00	2210.00	00.00		2210.00
M	BRACKET-FR BUMPER UPR SIDE MTG	N	1.00	22.00	00.00		22.00
M	BRACKET-FR BUMPER UPR SIDE MTG	X	1.00	22.00	00.00		22.00
M	ABSORBER-FRONT BUMPER ENERGY	?	1.00	84.00	00.00		84.00
M	GRILLE ASSY-RADIATOR	?	1.00	328.00	00.00		328.00
M	GARNISH-RADIATOR GRILLE	?	1.00	38.00	00.00		38.00
M	COVER-FR BUMPER	de	1.00	633.00	00.00		633.00
M	GRILLE-FRONT BUMPER	de	1.00	411.00	00.00		411.00
M	RETAINER-BUMPER SIDE MTG	u	2.00	1.00	00.00		2.00
M	LAMP ASSY-FRONT FOG, RH	?	1.00	303.00	00.00		303.00
M	MOULDING-FRONT BUMPER, RH	scr	1.00	90.00	00.00		90.00
M	ULTRASONIC SENSOR ASSY-P.A.S.	?	1.00	163.00	00.00		163.00
M	LAMP ASSY-SIDE REPEATER, RH	?	1.00	143.00	00.00		143.00
M	AIR DUCT-FR BUMPER, RH	?	1.00	14.00	00.00		14.00

Estimate

SURVEYOR NAME: Hasul-Ho 900100/100

SURVEYOR SIGNATURE: [Signature]

SURVEYOR NAME: Paul - 4p 900/00/0SURVEYOR SIGNATURE: [Signature]

Confirm & accepted by

DATE: 29/07/19 @ 1106hrREMARKS: 4 days

7% GST on

Nett

7,903.00

7903.00

553.21

Total Payable

8,456.21

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.