



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19011720/Ntd3e2

73 BRAS BASAH ROAD

Date: 27-05-2020

#05-01 NTUC TRADE UNION HOUSESINGAPORE

189556



ATTN: AZHARI

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

| | | | |
|--------------|----------------|----------------|------------|
| Insured Veh. | FBB 8612Y | Veh. Inspected | GBD 7327S |
| Policy No. | | Coverage (\$) | 0.00 |
| Claim No. | MT/1051435-001 | Excess (\$) | 0.00 |
| Assign From | THERESA VIMALA | Assign Date | 02/07/2019 |

2. Vehicle Particulars & Condition

| | | | |
|--------------|------------------------|--------------|--------------------|
| Make & Model | TOYOTA DYNA 150 MANUAL | c.c | 2982 |
| Engine No. | HIDDEN | Year of Reg. | 2015 |
| Chassis No. | JTFAT35Y70K204219 | Colour | SILVER |
| Odometer | 128788 KM | Steering | IN ORDER |
| Brakes | IN ORDER | Modification | STANDARD ALLOY RIM |
| General | FAIR | | |

3. Conditions of Tyres

| | Size | Make | Balance |
|----------------|----------|-------|---------|
| R/H Front Tyre | 195 R15C | TOYO | 6 mm |
| L/H Front Tyre | 195 R15C | TOYO | 6 mm |
| R/H Rear Tyre | 155 R12C | LASSA | 5 mm |
| L/H Rear Tyre | 155 R12C | LASSA | 5 mm |

4. Description of Damages

| |
|---|
| THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS. |
|---|

5. General Information

| | | | |
|----------------|--|---------------------|-------------------------|
| Accident Date | 18/12/2018 | Inspect Date / Time | 02/07/2019 (05:08 PM) |
| Survey held at | XINYA AUTO SERVICES PTE LTD BLK 1002 BUKIT MERAH LANE 3 #01-75 SINGAPORE 159719 | | |

5a. Remarks

| |
|--|
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|--|

5b. Estimate Days of Repair

| | |
|-------------------------------------|----------------|
| ESTIMATED NORMAL PERIOD FOR REPAIR: | 6 Working Days |
|-------------------------------------|----------------|