

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19011727/KDA3Q2

Date: 08/09/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant
Vehicle No : SLF2280X **Insured Vehicle No :** SKZ6464M

Date of Loss: 29/06/2019 **Nature of Claim:** TP **Claim No:** 0617204908SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLF2280X

Make & Model: TOYOTA HARRIER, 2.0 Premium (A)

Engine No: 3ZRB720823

Reg. Date: 08/07/2016 (Man. Year: 2016)

Chassis No: ZSU600071279

Colour: Metallic Black

Odometer: 57355 km

Engine Capacity: 1986 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes **Footbrake (Serviceable):** Yes

Handbrake (Serviceable): Yes **Engine Modification:** No **Pre-accident Condition:**

CONDITION OF TYRES

Front Tyre Size: 235/55 R18

Rear Tyre Size: 235/55 R18

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 7 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,112.35	4,405.47	1,706.88	27.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,015.00	1,190.00	825.00	40.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	8,127.35	5,595.47	2,531.88	31.15
Approved Total (Overridden) (\$\$)		4,400.00		
Nett Amount (\$\$)	8,127.35	4,400.00	3,727.35	45.86
+ Car Rental (5.0 x S\$110.00/day + 7.00% GST) (\$\$)		588.50		
+ Doc/Search Fee (\$\$)		2.00		
Nett Liability (\$\$)		4,990.50		

INSPECTION

Date of Assignment: 02/07/2019

Date Inspected: 03/07/2019 **Inspected At:**

Autoworx House - Sin Ming (HQ)
176 SIN MING DRIVE #02-01
Singapore 575721

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG

Manager: CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR LH	Bent / Warped	1,865.40 FL	*1,266.30 FL
2	1		*FRONT DOOR CHROME MOULDING LH	Dented	367.10 FL	*236.00 FL
3	1		*FRONT FENDER LH	Bent	764.50 FL	*764.50 FL
4	1		*FRONT FENDER DUST COVER LH	Distorted	291.10 FL	*291.10 FL
5	1		*FRONT KNUCKLE LH	Bent	577.40 FL	*539.00 FL
6	1		*FRONT LOWER ARM LH	Distorted	434.10 FL	*411.20 FL
7	1		*FRONT WHEEL BEARING LH	Necessary	365.70 FL	*365.70 FL
8	1		*FRONT WHEEL HUB LH	Bent	306.10 FL	*306.10 FL
9	1		*FRONT STEERING TIE ROD LH	Serviceable	246.40 FL	*- FL
10	1		*FRONT STEERING TIE ROD JOINT LH	Serviceable	195.60 FL	*- FL
11	1		*FRONT SIDE MIRROR ASSY	Dented / Cracked	876.40 FL	*587.40 FL
12	1		*SET DOOR VISOR	Necessary	400.00 FS	*150.00 FS
13	1		*ALLOY RIM	Dented	950.00 FS	*680.00 FS
14	1		*LITRE TRANSMISSION FLUID ATF	Not Necessary	45.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,684.80	5,597.30
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,572.45	1,191.83
Total Parts (\$\$)	6,112.35	4,405.47

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND REPLACE THE PARTS MENTIONED ABOVE ,PANEL BEAT AND REALIGN THE NECESSARY AFFECTED AREAS	New	800.00	450.00
2	TO CHECK WIRING SYSTEM	New	40.00	20.00
3	TO REMOVE AND INSTALL FRONT UNDERCARRIAGE PARTS TO ENABLE REPAIR	New	260.00	180.00
4	TO MACHINE PRESS WHEEL BEARING	New	40.00	20.00
5	TO PERFORM 4 WHEELS COMPUTERISED ALIGNMENT	New	85.00	60.00
6	TO APPLY PUTTY AND SPRAY PAINTING ON AFFECTED AREAS	New	750.00	440.00
7	TO REPLACE ALLOY RIM AND PERFORM WHEEL BALANCING	New	40.00	20.00
Gross Labour Cost (\$)			2,015.00	1,190.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >