



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKA 9310K

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
2	REAR BOOT LOWER STOPPER GARNISH @\$46.00	SERVICEABLE	92.00	-
2	REAR BOOT REFLECTOR @\$405.00	SERVICEABLE	810.00	-
1	REAR TAIL-LAMP (RH)	SERVICEABLE	756.00	-
2	REAR TAIL-LAMP LOWER BRACKETS @\$111.00	SERVICEABLE	222.00	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	1,673.00	-
1	REAR BUMPER	CRACKED	2,239.00	2,239.00
2	REAR BUMPER CHROME MOULDING (SIDE) @\$143.00	NECESSARY	286.00	286.00
1	REAR BUMPER CHROME MOULDING (CENTRE)	NECESSARY	189.00	189.00
4	REAR BUMPER PARKTRONIC SENSORS @\$311.00	SCRATCHED (1 PCS ONLY)	1,244.00	311.00
4	REAR BUMPER PARKTRONIC SENSOR SEAL RINGS @\$13.00	NOT NECESSARY	52.00	-
1	REAR BUMPER TOWING COVER	SERVICEABLE	87.00	-
2	REAR BUMPER LOWER BRACKETS @\$27.00	SERVICEABLE	54.00	-
1	REAR BUMPER LOWER SPOILER	DISTORTED / DENTED	702.00	702.00
2	REAR BUMPER SIDE BRACKETS @\$60.00	SERVICEABLE	120.00	-
1	REAR BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	950.00	-
1	REAR SILENCER BOX	TO REPAIR SEE LABOUR	2,266.00	-
2	REAR SILENCER BOX CHROME RINGS @\$243.00	SERVICEABLE	486.00	-
	LESS 10% DISCOUNT		-1,222.80	-372.70
			11,005.20	3,354.30

Report Ref No. CC4/LPC19011730/Kha3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	REMOVE AND REFIT REAR BOOT LOWER STOPPER GARNISH ,REAR BOOT REFLECTOR ,REAR TAIL-LAMP (RH),REAR TAIL-LAMP LOWER BRACKETS ,REAR BUMPER ,REAR BUMPER CHROME MOULDINGS (SIDE),REAR BUMPER CHROME MOULDING (CENTRE) ,REAR BUMPER PARKTRONIC SENSORS ,REAR BUMPER PARKTRONIC SENSOR SEAL RINGS,REAR BUMPER TOWING COVER,REAR BUMPER LOWER BRACKETS ,REAR BUMPER LOWER SPOILER ,REAR BUMPER SIDE BRACKETS ,REAR BUMPER REINFORCEMENT ,REAR SILENCER BOX ,REAR SILENCER BOX CHROME RINGS.INCLUSIVE OF THE REPAIR OF REAR BU		1,400.00	300.00
	REMOVE AND TRANSFER REAR BUMPER & NECESSARY ATTACHMENT SPARE PARTS ITEMS.}		-	-
	HEAT/WELD/CUT /RENEW REAR END PANEL,HEAT/WELD /BEARING/PULL/STRAIGHTEN/ALIGN REAR CHASSIS FRAME BY CHASSIS ALIGNMENT JACK.}		-	-
	TO CHECK AND REFIT REAR TAIL LAMP WIRING HARNESS.		40.00	20.00
	TUFF KOTE REAR DAMAGED PORTION .	NOT NECESSARY	150.00	-
	PUTTY/PRIMER APPLICATION,SPRAY PAINTING REAR END PANEL,REAR BUMPER,REAR BUMPER PARKTRONIC SENSORS,REAR BUMPER TOWING COVER.		1,200.00	450.00
			2,790.00	770.00
	GRAND TOTAL		13,795.20	4,124.30
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,300.00

Report Ref No. CC4/LPC19011730/Kha3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.