



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBG 1135C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	SIDE MIRROR LH	REPLACED	105.30	105.30
1	HANDLE BAR	REPLACED	185.00	185.00
2	HANDLE BAR GRIP L/R	REPLACED	104.00	104.00
2	HANDLE BAR BALANCER L/R	REPLACED	106.00	106.00
2	HANDLE BAR UPPER CLAMP L/R	REPLACED	96.00	96.00
1	HEAD LAMP	CAN'T SEE DAMAGE	520.00	-
1	HEAD LAMP STAY	CAN'T SEE DAMAGE	120.00	-
1	CLUTCH LEVER	REPLACED	65.00	65.00
1	FRONT SIGN LAMP LH	REPLACED	72.90	72.90
1	STEERING STEM ASSY	CAN'T SEE DAMAGE	280.00	-
1	STEERING STEM RACE BEARING	CAN'T SEE DAMAGE	110.00	-
1	FRONT FORK ASSY	CAN'T SEE DAMAGE	720.00	-
1	FRONT WHEEL SHAFT	REPLACED	48.00	48.00
1	FRONT WHEEL RIM	REPLACED	850.00	850.00
1	FUEL TANK	CAN'T SEE DAMAGE	670.00	-
1	SIDE BODY COWLING LH	REPLACED	280.00	280.00
1	FRONT MUDGUARD	REPLACED	245.00	245.00
1	ENGINE LOWER COWLING	REPLACED	320.00	320.00
1	REAR SEAT COWLING	REPLACED	420.00	420.00
1	SIDE FRAME RUBBER PROTECTOR	REPLACED	40.00	40.00
1	TAIL LAMP	CAN'T SEE DAMAGE	154.00	-
1	TAIL LAMP TOP GARNISH	CAN'T SEE DAMAGE	28.00	-
1	REAR MUDGUARD	REPLACED	180.00	180.00
1	REAR SIGNAL LAMP LH	REPLACED	75.20	75.20
1	TAIL BOX BRACKET	REPLACED	210.00	210.00

Report Ref No. CS/LAW19011739/Usd3e2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	TAIL BOX L/R	REPLACED	650.00	650.00
1	REAR FOOT REST PADDAL LH	REPLACED	78.00	78.00
1	REAR FOOT REST BRACKET LH	REPLACED	190.00	190.00
1	FOOT GEAR SELECTOR LEVER	REPLACED	132.00	132.00
1	FRONT FOOT REST PADDAL LH	REPLACED	79.00	79.00
1	FRONT FOOT REST BRACKET LH	REPLACED	210.00	210.00
	LESS 15% DISCOUNT		-1,101.51	-711.21
			6,241.89	4,030.19
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	FRONT FORK OIL (SN)	NOT NECESSARY	18.00	-
1	SET FRONT FORK OIL SEAL AND DUST COVER (SN)	NOT NECESSARY	60.00	-
1	FRONT TYRE (SN) (70%)	REPLACED	180.00	126.00
1	ARROW EXHAUST PIPE ASSY (SN)	NOT CHANGED	750.00	-
1	REAR NUMBER PLATE (SN)	REPLACED	25.00	25.00
			1,033.00	151.00
	<b><u>LABOUR</u></b>			
	CHECK WIRING SYSTEM AND LIGHT.	NOT NECESSARY	150.00	-
	TO CHECK, ALIGN AND BALANCE CHASSIS MAIN FRAME. }		500.00	300.00
	LABOUR CHARGES.}		550.00	-
	RE-PAINTING.		300.00	250.00
			1,500.00	550.00
	<b>GRAND TOTAL</b>		<b>8,774.89</b>	<b>4,731.19</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>3,800.00</b>

Report Ref No. CS/LAW19011739/Usd3e2

CHUA KANG SENG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.