


Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was stationary at Busar Cras, follow the front cars to line up for waiting traffic light to turn green. Suddenly, I felt an impact. Few second later, I notice that the vehicle B hit onto my rear portion.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

TAN BROS GAS SUPPLY

Policyholder's Signature

Date & Time: 1/7/19

12:55pm

GIARMC SketchPlanForm_V3

Driver's Signature

(If driver is not the policyholder)

Date & Time: 1/7/19

12:55pm

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:



松 利 摩 哆
SIONG LEE MOTOR

Sin Ming AutoCity
160 Sin Ming Drive #02-07 Singapore 575722
Tel: 6457 0410, 6453 1255 Fax: 6552 0692

Company Reg No: 100838/00J

We specialise in repairing all kinds of vehicles and pre-inspection servicing.
We also undertake accident insurance claims for our customers.

2 July 2019

ATTN: MOTOR CLAIM DEPARTMENT

ATTN: TAN BROS GAS SUPPLY

H/P: 9105 5622

Dear Sirs / Madam,

**Accident Claim for Vehicle No.GBJ 64 P , Involving Vehicle No.SKL 2487 Y.
Accident on 28 JUNE 2019, AT EUNOS CRESCENT.**

With reference to the above vehicle. We hereby submit a list of parts required to be changed and append below the charges for changing and repairing ;

NO	PARTS REPLACEMENT	QTY	LIST PRICE
1	TAILGATE	1PC	\$ 1,487.70
2	TAILLAMP	2PCS	\$ 550.00
3	TAILLAMP PANEL	2PCS	\$ 440.00
4	REAR STEP BARCKET	1PC	\$ 195.00
5	REAR NUMBER PLATE PANEL	1PC	\$ 182.20
6	REAR NUMBER PLATE LAMP	2PCS	\$ 168.66
7	REAR CROSS MEMBER	1PC	\$ 632.10
8	REAR SPARE TYRE REGULATOR	1PC	\$ 388.40
	TOTAL LIST PRICE		\$ 4,044.06
	LESS 20%	25%	\$ (808.81)
	TOTAL AMOUNT		\$ 3,235.25

NO	PARTS REPLACEMENT	QTY	SPECIAL NETT PRICE
1	TAILGATE STICKER 'DANGER HIGHLY FLAMMABLE'	1PC	\$ 100.00
2	TAILGATE STICKER ' FLAMMABLE GAS'	1PC	\$ 50.00
3	TAILGATE STICKER '70/KM'	1PC	\$ 10.00
4	TAILGATE STICKER 'DYNA'	1PC	\$ 88.90
5	REAR NUMBER PLATE	1PC	\$ 30.00
6	REAR REVERSE SENSOR	1SET	\$ 240.00
	TOTAL SPECIAL NETT PRICE		\$ 518.90

Not Authorised
Pharm & After Sales
3 days
11/12/19 @ 1600h

LABOUR :		
1	LABOUR TO SPRAY PAINT	\$ 3601 600.00
2	LABOUR TO PANEL BEATING	\$ 3001 500.00
3	LABOUR TO TRANSFER AND REFIX TAILGATE WOOD.	\$ 200.00
TOTAL LABOUR		\$ 1,300.00
TOTAL AMOUNT		\$ 5,054.15

THANK YOU

FROM:

SIONG LEE MOTOR

Mr Tan Leng Huat

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before commencing
- To display damaged parts for survey
- Parts prices are subject to survey
- Third party survey is to be conducted on "No Fault" basis
- No illegal modifications to be carried out
- Supplementary items to be covered and is subject to final approval of Insurance Company

Authorised by Repairer

Signature

Date:



松 利 摩 哆
SIONG LEE MOTOR

Sin Ming AutoCity
160 Sin Ming Drive #02-07 Singapore 575722
Tel: 6457 0410, 6453 1255 Fax: 6552 0692

We specialise in repairing all kinds of vehicles and pre-inspection servicing
We also undertake accident insurance claims for our customers.

Company Reg No: 10083800J

2 July 2019

ATTN: MOTOR CLAIM DEPARTMENT

ATTN: TAN BROS GAS SUPPLY

H/P: 9105 5622

Dear Sirs / Madam,

Accident Claim for Vehicle No.GBJ 64 P , Involving Vehicle No.SKL 2487 Y.
Accident on 28 JUNE 2019, AT EUNOS CRESCENT.

With reference to the above vehicle. We hereby submit a list of parts required to be changed and append below the charges for changing and repairing ;

NO	PARTS REPLACEMENT	QTY	LIST PRICE
1	TAILGATE	1PC	\$ 1,487.70
2	TAILLAMP	2PCS	\$ 550.00
3	TAILLAMP PANEL	2PCS	\$ 440.00
4	REAR STEP BARCKET	1PC	\$ 195.00
5	REAR NUMBER PLATE PANEL	1PC	\$ 182.20
6	REAR NUMBER PLATE LAMP	2PCS	\$ 168.66
7	REAR CROSS MEMBER	1PC	\$ 632.10
8	REAR SPARE TYRE REGULATOR	1PC	\$ 388.40
TOTAL LIST PRICE			\$ 4,044.06
LESS 20%			\$ (808.81)
TOTAL AMOUNT			\$ 3,235.25

NO	PARTS REPLACEMENT	QTY	SPECIAL NETT PRICE
1	TAILGATE STICKER 'DANGER HIGHLY FLAMMABLE'	1PC	\$ 100.00
2	TAILGATE STICKER 'FLAMMABLE GAS'	1PC	\$ 50.00
3	TAILGATE STICKER '70/KM'	1PC	\$ 10.00
4	TAILGATE STICKER 'DYNA'	1PC	\$ 88.90
5	REAR NUMBER PLATE	1PC	\$ 30.00
6	REAR REVERSE SENSOR	1SET	\$ 240.00
TOTAL SPECIAL NETT PRICE			\$ 518.90

Not Authorised
Pharm & After Sales
3 days
11 days & 16 days ✓ ok



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ERGO INSURANCE PTE LTD

Ref : CS/EGI19011758/Kqd3s2

5 TEMASEK BOULEVARD
#04-05 SUNTEC TOWER FIVE
SINGAPORE 038985

Date : 06-09-2019



Code : EGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKL 2487Y	Veh. Inspected	GBJ 64P
Policy No.		Coverage (\$)	0.00
Claim No.	CDMPG19001245/PX/jc	Excess (\$)	0.00
Assign From	JEANNIE CHENG	Assign Date	02/07/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA DYNA (M)	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	JTFAT35Y50K211766	Colour	BLUE
Odometer	19550	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/75 R15	BRIDGESTONE	7 mm
L/H Front Tyre	195/75 R15	BRIDGESTONE	7 mm
R/H Rear Tyre	155 R12X8 (D)	BRIDGESTONE	2/2 mm
L/H Rear Tyre	155 R12X8 (D)	BRIDGESTONE	2/2 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	28/06/2019	Inspection Date	03/07/2019
Survey held at	SIONG LEE MOTOR 160 SIN MING DRIVE #02-07 AUTOCITY SINGAPORE 575722		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBJ 64P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	TAILGATE	TO REPAIR SEE LABOUR	1,487.70	-
2	TAILLAMP	CRACKED	550.00	550.00
2	TAILLAMP PANEL	TO REPAIR SEE LABOUR	440.00	-
1	REAR STEP BRACKET	TO REPAIR SEE LABOUR	195.00	-
1	REAR NUMBER PLATE PANEL	DISTORTED	182.20	182.20
2	REAR NUMBER PLATE LAMP	CRACKED	168.66	168.66
1	REAR CROSS MEMBER	TO REPAIR SEE LABOUR	632.10	-
1	REAR SPARE TYRE REGULATOR	DISTORTED / JAMMED	388.40	388.40
	LESS 20% DISCOUNT		-808.81	-
	LESS 25% DISCOUNT		-	-322.32
			3,235.25	966.94
SPECIAL NETT ITEMS				
1	TAILGATE STICKER DANGER HIGHLY FLAMMABLE (SN)	NECESSARY	100.00	60.00
1	TAILGATE STICKER "FLAMMABLE GAS" (SN)	NECESSARY	50.00	30.00
1	TAILGATE STICKER "70/KM" (SN)	NECESSARY	10.00	10.00
1	TAILGATE STICKER "DYNA" (SN)	NECESSARY	88.90	88.90
1	REAR NUMBER PLATE (SN)	BENT	30.00	20.00
1	SET REAR REVERSE SENSOR (SN)	SCRATCHED	240.00	200.00
			518.90	408.90
LABOUR				
	LABOUR TO SPRAY PAINT.		600.00	360.00
	LABOUR TO PANEL BEATING.INCLUSIVE OF THE REPAIR OF TAIL GATE,TAILLAMP PANEL ,REAR STEP BRACKET AND REAR CROSS MEMBER.		500.00	300.00
	LABOUR TO TRANSFER AND REFIX TAILGATE WOOD.	NOT NECESSARY	200.00	-
			1,300.00	660.00
GRAND TOTAL			5,054.15	2,035.84

Report Ref No. CS/EGI19011758/Kqd3s2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,600.00
---	--	--	----------

Report Ref No. CS/EG19011758/Kqd3s2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.