

ASS. REC. BY:

REF: CSI MSG 19011469 / Dtd 302

Special Instruction:

Surveyor: Bryan

ASSIGNMENT (Office)

From (Person): Ng Chen How

of

MSG

Date/Time: 3.7.19 10.32 a.m.

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHA 30915

Insured:

SL2 8678 m

at Workshop m/s Soon Hock Motor

Tel:

65425119

of BIK 10 Amk Industrial Park 2A A01-05106

Policy No: 29114756 MCF

Claim No:

598532

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 29.6.2019

CA / REV / REP. / REV 24 HRS

Date/Time: 3.7.19 11.22 a.m.

Person Contacted:

Lynn

H.O.D. Endorsement:

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SHA 30915 - CC3 / LCR 1800560 / k1 pa 392

D.O.A. - 29/04/2018

SL2 8678 m - x

917@16:40 - revised via preliaduse menmen

ASS. REC. BY:

## ASSIGNMENT

COE Dec 2020

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_


Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_

Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_

Consistent? : Yes or No

Est. Repairs: 108 days Res.: Yes or No

Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SHA 30918

Yr Regn: 2012, Dec

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi Prime Mover /

Truck / Trailer or

Make: Hyundai Sonata C.C. 1991

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 74953 T/Radio: Insured / Std / NI / NA

Eng/No: D4EAD274887

C/No: KMHET41VMCA831656

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60 R16

R: — 11 —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Hankook

Front

Rear

R/Bal. 5 mm

R/Bal. 5 mm

L/Bal. 5 mm

L/Bal. 5 mm

D.O.A. 29/06/2019

D.O.I. 03/07/2019

Survey held at Chunni AMK

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rev N/S y Burnt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

MSG 8LZ 8678M

\* To split survey rpt front y rear \*

Vehicle balance 17 mtrs at time of loss

(Red: 11498.10; 51%)

BV 20.1K

PAR at end of life span 7.1K

LTA 19.4K

08/08/19 final L/S 11000/- with 10 days

check consistency of frontal damage as OI say 2 vehicle. TP say not sure.

Date/Time, File Pass to?



Preli. Report

Days Of Repair: 10

1) 14/8 TUPST



Final Report

Resurvey No. of Trip: 2

Date/Time, File Return to?

2)

RECEIVED 15 AUG 2019

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Weekend (\$)

Survey Fee: 200

Transportation:

S + RS, SI

Photos

Others

TOTAL

21

Report Format: TP

Lump Sum / I.B.I. (\$) 11000/-

## ...CLAIM SUBFOLDER...(New Assignment)

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 Jul 2019 15:48		03 Jul 2019 10:32 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

## CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	GRAB RENTALS PTE LTD, Co. Reg. No.: 201617200G		
Main Claimant:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R		
Vehicle Reg. No.:	SHA3091S	Date of Loss:	29/06/2019 00:00 - :59 [78 Months and 16 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP	Policy/Cover Note No.:	29114756MKF Coverage: 01/02/2019 - 31/01/2020
Vehicle Reg. No. (Insured):	SLZ8678M	Policy No. (Claimant):	
		Excess:	
Repairer:	Soon Hock Motor Pte Ltd (HQ) Blk 10 Ang Mo Kio Industrial Park 2A, #01-05/06 AMK Autopoint, 568047 Ang Mo Kio - Tel: 64836016		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by NG CHEN HOW - 6643 1391]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 04/07/2019]		
Driver/Custodian (Insured):	TAN SZE BOON (), NRIC: S7616870I Email:		
Adj Asg. Remarks:	on WP. Please contact us ASAP if you cannot attend this assignment. Assign to LKK.		

## ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.



## ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: NG CHEN HOW

Date: 09 Jul 2019

## Preliminary Advice

Insured Vehicle No	: SLZ8678M	Accident Date	: 29/06/2019
TP Vehicle No	: SHA3091S	Assignment Date	: 03/07/2019
Make	: HYUNDAI SONATA NF	Est. Duration of Repair	: 8.00
Date of Inspection	: 03/07/2019		
Inspection At	: SOON HOCK MOTOR PTE LTD (HQ) BLK 10 ANG MO KIO INDUSTRIAL PARK 2A, #01-05/06 AMK AUTOPOINT SINGAPORE 568047		

### Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear n/s and front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	22,498.10
Revised Amount	:S\$	11,906.62
Check Items (Estimated)	:S\$	0.00
Total	:S\$	11,906.62
Lump Sum Repair	:S\$	

### Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

### Remarks

- ( ) The vehicle is economical/not economical for repair.
- ( x ) The above survey was conducted on a 'without prejudice' basis.

MCD619065064 / ComfortDelGro Engineering Pte Ltd - Layan  
ENTRY DATE & TIME: 01/07/2019 11:45  
SUBMITTED BY: Huang XiaoYan

**SINGAPORE ACCIDENT STATEMENT****IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**ACCIDENT STATEMENT**

Date Of Report	01/07/2019 11:45
Date Of Accident	29/06/2019 20:00
Exact Location Of Accident	HAVELOCK RD TWDS GANGES AVE
Country/State of Loss	SINGAPORE

**DETAILS OF OWN VEHICLE**

Vehicle Registration Number	SHA3091S
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768
Vehicle Particulars	
Manufacturer	HYUNDAI
Model	SONATA
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	MCOM0015
Cover Note Number	
Driver	
Name of Driver	LIM CHENG HAI
NRIC No	S0724555F
Date Of Birth	09/07/1946
Occupation	OUTDOOR
Date Of Driving Pass	28/04/1966
Driving Experience	53 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91097496
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 288 BISHAN STREET 24 #24-01
Postcode	570288
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

**General Information of the Accident**

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

**Other Information**

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) Involved in the accident	3
Was any body injured in the Accident?	YES
Was any Injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

**Details of Police Action**

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

**Circumstances of Accident**

PLS REFER TO ATTACHED

**Attachment(s)**

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number	SLZ8678M
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	TAN SZE BOON
NRIC/Passport Number	S7516870I
Contact Number	
Address	
Postcode	
Insurance Company Name	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Nature Of Damage	FRT RIGHT
No. Of Passenger (Including Driver)	

**DETAILS OF OTHER VEHICLE PROPERTY 2**

Vehicle Registration Number	SJM1933P
Vehicle Make/Model/Colour	.
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	NOT SURE
No. Of Passenger (Including Driver)	

**DETAILS OF INJURED PERSON 1**

Name	LIM CHENG HAI
Approximate Age	
Injuries Sustain	PAIN ON NECK AND BACK
Injured person in which vehicle?	SHA3091S
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD  
CO. REG. NO. 199303821R


Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name: **Loke Vwei Tieng**  
NRIC/FIN No.:



## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

As per attached

## DECLARATION

I/We declare the foregoing information to be true in every respect.  
COMFORT TRANSPORTATION PTE LTD  
CO. REG. NO. 199303821R

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name: Loke Wei Yieng  
NRIC/FIN No.:

30/6/19

**Describe Circumstances of the Accident.**

On 29/06/2019 @ abt 20:00 hrs, my taxi Veh A was stop at above said location wanted

turn right to Four points Sheraton.

Sunddenly Veh B came from behind It front right portion collided onto the rear left portion

of my taxi and caused my taxi surged forward. I might have a collision with the Veh C infront

of my taxi, but the driver didn't stop at the scene.

Scene photo taken to support my claim. No passenger in my taxi.


I felt pain on neck and back, will consult doctor later on.


**Declaration**

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD  
CO. REG. NO. 199303821R

\_\_\_\_\_  
Policyholder's Signature/Date &  
Time

  
\_\_\_\_\_  
Driver's Signature(If driver is not the policyholder)/Date  
& Time

  
\_\_\_\_\_  
Witnessed by Reporting  
Centre Personnel

Loke Wei Yieng

30/6/19.

## SHA 3091S

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid BT Dented			\$ 1,349.50
	Boot Lid Rubber deformed			\$ 110.90
	Boot Lid Hinge (LH/RH) NW		\$ 170.60	\$ 341.20
	Boot Lid Lock Upper NW			\$ 132.10
	Boot Lid Lock Lower NW			\$ 30.30
	Boot Lid Sonata Plate Nec			\$ 43.60
	Boot Lid Hyundai Plate Nec			\$ 24.20
	Boot Lid 'H' Emblem Nec			\$ 26.10
	Boot Lid CRDI Plate Nec			\$ 22.70
	Boot Lid Lamp (LH) Cwt			\$ 230.20
	Boot Lid Trimboard NW			\$ 165.40
	Boot Lid Trimboard Clips (11pcs) NW			\$ 11.00
	Rear Bumper Dented			\$ 578.40
	Rear Bumper Reinforcement NE NW			\$ 483.30
	Rear Bumper Clip Nec			\$ 22.00
	Rear Bumper Bracket BT			\$ 49.00
	Rear Bumper Sponge NE NW			\$ 137.40
	Rear Bumper Under Cover NW			\$ 185.80
	Rear Bumper Protector (LH) BT			\$ 38.00
	Tail Lamp (LH) broken			\$ 344.00
	Tail Lamp Quarter Panel (LH) Dented			\$ 93.80
	Rear Panel Dented			\$ 391.80
	Rear Panel Garnish NW			\$ 95.80
	Spare Tyre Holder NW			\$ 27.60
	Tail Lamp Panel Top (LH) NW			\$ 217.40
	Spare Tyre Panel Dented			\$ 863.00
	Spare Tyre Panel Cushion NW			\$ 200.30
	Rear Towing Hook NW			\$ 135.30
	Member Assy- Rear Floor Centre NW			\$ 163.60
	Panel Assy-Rear Floor Side (LH) Bnc			\$ 88.55
	Rear Floor Chassis Member (LH) Bnc			\$ 1,280.50
	Rear Fender (LH) Dented			\$ 1,935.90
	Rear Fender Inner Panel (LH) NW			\$ 1,255.00
	Rear Fender Inner Lining (LH) NW			\$ 74.10
	Rear Fender Corner Hardboard Cover (LH) BT			\$ 204.30
	Rear Fender Air-Duct S/C			\$ 49.40
	Rear Fender Mudflap (LH) NW			\$ 15.50
	Rear Fender Trim Board (LH) BT			\$ 180.90
	Rear Windscreen Moulding Nec			\$ 60.00
	Fuel Tank Sub Hose NW			\$ 78.20
	Fuel Tank Upper Neck NW			\$ 221.60
<b>SUB TOTAL</b>				<b>\$ 11,957.65</b>
<b>LESS 20%</b>				<b>\$ 2,391.53</b>
<b>DISCOUNTED TOTAL</b>				<b>\$ 9,566.12</b>

CHUNNI MOTOR WORKS PTE LTD

**REPAIR ESTIMATE\***

VEHICLE NO : SHA 3091S

DATE : 1.07.2019

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI SONATA

FAX : 6542 6039

MSIG

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Radiator Grille <i>NN</i>			\$ 282.10
	Radiator Grille U Moulding <i>NN</i>			\$ 108.90
	Front Bumper Cover <i>ray</i>			\$ 538.80
	Front Bumper Sponge <i>NN</i>			\$ 136.30
	Front Bumper Reinforcement <i>NN</i>			\$ 504.10
	Front Bumper Bracket Top (LH/RH) <i>NN</i>	\$	22.40	\$ 44.80
	Front Bumper Protector (LH/RH) <i>NN</i>	\$	29.20	\$ 58.40
	Front Bumper Bracket (LH/RH) <i>NN</i>	\$	20.10	\$ 40.20
	Front Bumper Clips 10 pcs <i>NN</i>			\$ 22.00
	Headlamp Support Panel Assy <i>bt</i>			\$ 1,023.00
	Headlamp (LH/RH) <i>check cover</i>	\$	797.90	\$ 1,595.80
	Radiator <i>bt / punctured</i>			\$ 814.80
	Radiator Fan Blade, Cowling, Motor Assy <i>NN</i>			\$ 651.30
	Radiator Bracket <i>NN</i>	\$	6.20	\$ 12.40
	Aircon Condenser <i>bt</i>			\$ 1,089.90
	Inter Cooler <i>bt</i>			\$ 771.50
	Inter Cooler Mounting (2 PCS) <i>NN</i>			\$ 24.80
			5295.00	
			4236.00	
	SUB TOTAL			\$ 7,719.10
	LESS 20%			\$ 1,543.82
	DISCOUNTED TOTAL			\$ 6,175.28
	Front Number Plate <i>NN</i>			\$ 25.00
	Front No Plate Trim Cover <i>NN</i>			\$ 30.00
				\$ 55.00
	Labour Charge			
	Panel Beating			\$ 1,000.00
	Spray Painting Charge			\$ 250.00
	Wiring Charge			\$ 50.00
	Towing Charge			\$ 50.00
	Remove/Refix Aircon & Refill Gas			\$ 150.00
			710.00	
	TOTAL LABOUR			\$ 1,500.00



### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 Jul 2019 15:48		03 Jul 2019 10:32 <a href="#">Edit Adj Rpt</a>	<b>S\$11,000.00</b> <a href="#">Edit Estimates</a>	<b>S\$11,000.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>


















































Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	<b>GRAB RENTALS PTE LTD</b> , Co. Reg. No.: 201617200G								
Main Claimant:	<b>COMFORT TRANSPORTATION PTE LTD</b> , Co. Reg. No.: 199303821R								
Vehicle Reg. No.:	<b>SHA3091S</b>	Date of Loss:	29/06/2019 20:00 - :59 [78 Months and 16 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / 598532</b>	Policy/Cover Note No.:	29114756 (Comprehensive) Coverage: 01/02/2019 - 31/01/2020						
Vehicle Reg. No. (Insured):	<b>SLZ8678M</b>	Policy No. (Claimant):							
		Excess:							
Repairer:	<b>Soon Hock Motor Pte Ltd (HQ)</b> Blk 10 Ang Mo Kio Industrial Park 2A, #01-05/06 AMK Autopoint, 568047 Ang Mo Kio - Tel: 64836016								
Handling Insurer:	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>NG CHEN HOW</b> - 6643 1391]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>BRYAN TANI</b> ] ... [Final Rpt due 02/08/2019]								
Driver/Custodian (Insured):	TAN SZE BOON (), NRIC: S76168701 Email:								
Adj Asg. Remarks:	on WP. Please contact us ASAP if you cannot attend this assignment. Assign to LKK.								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents
















































\*SHA3091S (598532)  
[SLZ8678M]  
TP  
COMFORT TRANSPORTATION PTE LTD  
Jun 29 2019 8:00PM  
[GRAB RENTALS PTE LTD]  
Soon Hock Motor Pte Ltd


Upload Documents			Upload Photos		Compose New Letter		View		View in Browser		
Assessment Reports							1 per page		<input checked="" type="checkbox"/>		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	09/07/19 16:40	Adjuster Immediate Advice					1	Load HTM			
Photos/Images							3 per page		<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	08/08/19 12:03	Rear View Right					1	Load JPG	<input checked="" type="checkbox"/>		
2	08/08/19 12:03	Rear View Left					1	Load JPG	<input checked="" type="checkbox"/>		
3	08/08/19 12:06	General View					1	Load JPG	<input checked="" type="checkbox"/>		
4	08/08/19 12:06	General View					1	Load JPG	<input checked="" type="checkbox"/>		
5	08/08/19 12:06	General View					1	Load JPG	<input checked="" type="checkbox"/>		
6	08/08/19 12:06	General View					1	Load JPG	<input checked="" type="checkbox"/>		
7	08/08/19 12:06	General View					1	Load JPG	<input checked="" type="checkbox"/>		
8	08/08/19 12:06	General View					1	Load JPG	<input checked="" type="checkbox"/>		
9	08/08/19 12:06	General View					1	Load JPG	<input checked="" type="checkbox"/>		
10	08/08/19 12:06	General View					1	Load JPG	<input checked="" type="checkbox"/>		
11	08/08/19 12:06	General View					1	Load JPG	<input checked="" type="checkbox"/>		
12	08/08/19 12:06	General View					1	Load JPG	<input checked="" type="checkbox"/>		
13	08/08/19 12:06	General View					1	Load JPG	<input checked="" type="checkbox"/>		
14	08/08/19 12:06	General View					1	Load JPG	<input checked="" type="checkbox"/>		
15	08/08/19 12:06	General View					1	Load JPG	<input checked="" type="checkbox"/>		
16	08/08/19 12:06	General View					1	Load JPG	<input checked="" type="checkbox"/>		
17	08/08/19 12:06	General View					1	Load JPG	<input checked="" type="checkbox"/>		
18	08/08/19 12:06	General View					1	Load JPG	<input checked="" type="checkbox"/>		
19	08/08/19 12:06	General View					1	Load JPG	<input checked="" type="checkbox"/>		
20	08/08/19 12:06	General View					1	Load JPG	<input checked="" type="checkbox"/>		
21	08/08/19 12:06	General View					1	Load JPG	<input checked="" type="checkbox"/>		
22	08/08/19 12:06	General View					1	Load JPG	<input checked="" type="checkbox"/>		
23	08/08/19 12:06	General View					1	Load JPG	<input checked="" type="checkbox"/>		
24	08/08/19 12:06	General View					1	Load JPG	<input checked="" type="checkbox"/>		
25	08/08/19 12:06	General View					1	Load JPG	<input checked="" type="checkbox"/>		
26	08/08/19 12:06	General View					1	Load JPG	<input checked="" type="checkbox"/>		
27	08/08/19 12:06	General View					1	Load JPG	<input checked="" type="checkbox"/>		
28	08/08/19 12:06	General View					1	Load JPG	<input checked="" type="checkbox"/>		
29	08/08/19 12:06	General View					1	Load JPG	<input checked="" type="checkbox"/>		
30	08/08/19 12:06	General View					1	Load JPG	<input checked="" type="checkbox"/>		
31	08/08/19 12:06	General View					1	Load JPG	<input checked="" type="checkbox"/>		
32	08/08/19 12:06	General View					1	Load JPG	<input checked="" type="checkbox"/>		
33	08/08/19 12:06	General View					1	Load JPG	<input checked="" type="checkbox"/>		
34	08/08/19 12:06	General View					1	Load JPG	<input checked="" type="checkbox"/>		



Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	08/08/19 12:06	General View	 Load JPG	<input checked="" type="checkbox"/>
36	08/08/19 12:06	General View	 Load JPG	<input checked="" type="checkbox"/>
37	08/08/19 12:06	General View	 Load JPG	<input checked="" type="checkbox"/>
38	08/08/19 12:06	General View	 Load JPG	<input checked="" type="checkbox"/>
39	08/08/19 12:06	General View	 Load JPG	<input checked="" type="checkbox"/>
40	08/08/19 12:06	General View	 Load JPG	<input checked="" type="checkbox"/>
41	08/08/19 12:06	General View	 Load JPG	<input checked="" type="checkbox"/>
42	08/08/19 12:06	General View	 Load JPG	<input checked="" type="checkbox"/>
43	08/08/19 12:06	General View	 Load JPG	<input checked="" type="checkbox"/>
44	08/08/19 12:06	General View	 Load JPG	<input checked="" type="checkbox"/>
45	08/08/19 12:06	General View	 Load JPG	<input checked="" type="checkbox"/>
46	08/08/19 12:06	General View	 Load JPG	<input checked="" type="checkbox"/>
47	08/08/19 12:06	General View	 Load JPG	<input checked="" type="checkbox"/>
48	08/08/19 12:06	General View	 Load JPG	<input checked="" type="checkbox"/>
49	08/08/19 12:06	General View	 Load JPG	<input checked="" type="checkbox"/>
50	08/08/19 12:06	General View	 Load JPG	<input checked="" type="checkbox"/>
51	08/08/19 12:06	General View	 Load JPG	<input checked="" type="checkbox"/>
52	08/08/19 12:06	General View	 Load JPG	<input checked="" type="checkbox"/>
53	08/08/19 12:06	General View	 Load JPG	<input checked="" type="checkbox"/>
54	08/08/19 12:06	General View	 Load JPG	<input checked="" type="checkbox"/>
55	08/08/19 12:06	General View	 Load JPG	<input checked="" type="checkbox"/>
56	08/08/19 12:06	General View	 Load JPG	<input checked="" type="checkbox"/>
57	08/08/19 12:06	General View	 Load JPG	<input checked="" type="checkbox"/>
58	08/08/19 12:06	General View	 Load JPG	<input checked="" type="checkbox"/>
59	08/08/19 12:06	General View	 Load JPG	<input checked="" type="checkbox"/>
60	08/08/19 12:06	General View	 Load JPG	<input checked="" type="checkbox"/>
61	08/08/19 12:06	General View	 Load JPG	<input checked="" type="checkbox"/>
62	08/08/19 12:06	General View	 Load JPG	<input checked="" type="checkbox"/>
63	08/08/19 12:06	General View	 Load JPG	<input checked="" type="checkbox"/>
64	08/08/19 12:06	General View	 Load JPG	<input checked="" type="checkbox"/>
65	08/08/19 12:06	General View	 Load JPG	<input checked="" type="checkbox"/>
66	08/08/19 12:06	General View	 Load JPG	<input checked="" type="checkbox"/>
67	08/08/19 12:06	General View	 Load JPG	<input checked="" type="checkbox"/>
68	08/08/19 12:06	General View	 Load JPG	<input checked="" type="checkbox"/>
69	08/08/19 12:06	General View	 Load JPG	<input checked="" type="checkbox"/>
70	08/08/19 12:06	General View	 Load JPG	<input checked="" type="checkbox"/>
71	08/08/19 12:06	General View	 Load JPG	<input checked="" type="checkbox"/>
72	08/08/19 12:06	General View	 Load JPG	<input checked="" type="checkbox"/>
73	08/08/19 12:06	General View	 Load JPG	<input checked="" type="checkbox"/>
74	08/08/19 12:06	General View	 Load JPG	<input checked="" type="checkbox"/>
75	08/08/19 12:06	General View	 Load JPG	<input checked="" type="checkbox"/>
76	08/08/19 12:06	General View	 Load JPG	<input checked="" type="checkbox"/>
77	08/08/19 12:06	General View	 Load JPG	<input checked="" type="checkbox"/>
78	08/08/19 12:06	General View	 Load JPG	<input checked="" type="checkbox"/>
79	08/08/19 12:06	General View	 Load JPG	<input checked="" type="checkbox"/>
80	08/08/19 12:06	General View	 Load JPG	<input checked="" type="checkbox"/>
81	08/08/19 12:06	General View	 Load JPG	<input checked="" type="checkbox"/>
82	08/08/19 12:06	General View	 Load JPG	<input checked="" type="checkbox"/>
83	08/08/19 12:06	General View	 Load JPG	<input checked="" type="checkbox"/>



Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
84	08/08/19 12:06	General View		Load JPG <input checked="" type="checkbox"/>
85	08/08/19 12:06	Odometer Reading		Load JPG <input checked="" type="checkbox"/>
86	08/08/19 12:06	Chassis Number		Load JPG <input checked="" type="checkbox"/>
87	08/08/19 12:08	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
88	08/08/19 12:08	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
89	08/08/19 12:08	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
90	08/08/19 12:08	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
91	08/08/19 12:08	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
92	08/08/19 12:08	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
93	08/08/19 12:08	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
94	08/08/19 12:08	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
95	08/08/19 12:08	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
96	08/08/19 12:08	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
97	08/08/19 12:08	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
98	08/08/19 12:08	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
99	08/08/19 12:08	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
100	08/08/19 12:08	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
101	08/08/19 12:08	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
102	08/08/19 12:08	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
103	08/08/19 12:08	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
104	08/08/19 12:08	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
105	08/08/19 12:08	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
106	08/08/19 12:08	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
107	08/08/19 12:09	Finishing Photo		Load JPG <input checked="" type="checkbox"/>
108	08/08/19 12:09	Finishing Photo		Load JPG <input checked="" type="checkbox"/>
109	08/08/19 12:09	Finishing Photo		Load JPG <input checked="" type="checkbox"/>
110	08/08/19 12:09	Finishing Photo		Load JPG <input checked="" type="checkbox"/>
111	08/08/19 12:09	Finishing Photo		Load JPG <input checked="" type="checkbox"/>
112	08/08/19 12:09	Finishing Photo		Load JPG <input checked="" type="checkbox"/>
113	08/08/19 12:09	Finishing Photo		Load JPG <input checked="" type="checkbox"/>
114	08/08/19 12:09	Finishing Photo		Load JPG <input checked="" type="checkbox"/>
115	08/08/19 12:09	Finishing Photo		Load JPG <input checked="" type="checkbox"/>
116	08/08/19 12:09	Finishing Photo		Load JPG <input checked="" type="checkbox"/>
117	08/08/19 12:09	Finishing Photo		Load JPG <input checked="" type="checkbox"/>
118	08/08/19 12:09	Finishing Photo		Load JPG <input checked="" type="checkbox"/>
119	08/08/19 12:09	Finishing Photo		Load JPG <input checked="" type="checkbox"/>
120	08/08/19 12:09	Finishing Photo		Load JPG <input checked="" type="checkbox"/>
121	08/08/19 12:09	Finishing Photo		Load JPG <input checked="" type="checkbox"/>
122	08/08/19 12:09	Finishing Photo		Load JPG <input checked="" type="checkbox"/>
123	08/08/19 12:09	Finishing Photo		Load JPG <input checked="" type="checkbox"/>
124	08/08/19 12:09	Finishing Photo		Load JPG <input checked="" type="checkbox"/>
125	08/08/19 12:09	Finishing Photo		Load JPG <input checked="" type="checkbox"/>
126	08/08/19 12:09	Finishing Photo		Load JPG <input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail Print
1	02/07/19 15:49	Email - PRI		Load PDF
2	02/07/19 15:51	Estimate		Load PDF
3	02/07/19 15:51	SHA3091S GIA Rpt		Load PDF
4	02/07/19 15:52	SLZ8678M GIA Rpt		Load PDF
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor)		Thumbnail Print

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print
1	03/07/19 10:26	LKK Auto Consultants Pte Ltd (HQ) email from workshop	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>
<div></div>
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19011769/DTD3E2

Date: 16/08/2019

### REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29114756

Claimant Vehicle No : SHA3091S

Insured Vehicle No : SLZ8678M

Date of Loss: 29/06/2019

Nature of Claim: TP

Claim No: 598532

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHA3091S**Make & Model: HYUNDAI SONATA NF, 2.0 CRDI AT ABS 2WD  
4DR TURBO (A)

Engine No: D4EAD274887

Reg. Date: 13/12/2012 (Man. Year: 2012)

Chassis No: KMHET41VMCA831656

Colour: Blue

Odometer: 74953 km

Engine Capacity: 1991 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size: 215/60 R16

Front Left Side: Hankook 5 mm

Rear Left Side: Hankook 5 mm

Front Right Side: Hankook 5 mm

Rear Right Side: Hankook 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	16,408.10	11,197.58	5,210.52	31.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,090.00	2,930.00	3,160.00	51.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>22,498.10</b>	<b>14,127.58</b>	<b>8,370.52</b>	<b>37.21</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>11,000.00</b>		
<b>(S\$)</b>	22,498.10	11,000.00	11,498.10	51.11
<b>+ GST 7.00/7.00% (S\$)</b>	1,574.87	770.00	804.87	51.11
<b>Nett Amount (S\$)</b>	<b>24,072.97</b>	<b>11,770.00</b>	<b>12,302.97</b>	<b>51.11</b>

### INSPECTION

Date of Assignment: 03/07/2019

Date Inspected: 03/07/2019 Inspected At:

Blk 10 Ang Mo Kio Industrial Park 2A, #01-

05/06 AMK Autopoint

Singapore 568047

Repairer : Chunni Motor Work Pte Ltd

Estimated Period of Repair: 10.0 days

---

**Adjuster:** BRYAN TANI**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 16 Aug 2019)
<b>Parts:</b>	143	HYUNDAI SONATA NF 2.0 CRDI AT ABS 2WD 4DR TURBO (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHA3091S)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		FRONT PORTION *RADIATOR GRILLE	Not Necessary	282.10 FL	*- FL
2	1		FRONT PORTION *RADIATOR GRILLE U MOULDING	Not Necessary	108.90 FL	*- FL
3	1		FRONT PORTION *FRONT BUMPER COVER	Repair	538.80 FL	*- FL
4	1		FRONT PORTION *FRONT BUMPER SPONGE	Not Necessary	136.30 FL	*- FL
5	1		FRONT PORTION *FRONT BUMPER REINFORCEMENT	Not Necessary	504.10 FL	*- FL
6	2		FRONT PORTION *FRONT BUMPER BRACKET TOP (LH/RH)	Not Necessary	44.80 FL	*- FL
7	2		FRONT PORTION *FRONT BUMPER PROTECTOR (LH/RH)	Not Necessary	58.40 FL	*- FL
8	2		FRONT PORTION *FRONT BUMPER BRACKET (LH/RH)	Not Necessary	40.20 FL	*- FL
9	10		FRONT PORTION *FRONT BUMPER CLIPS	Not Necessary	22.00 FL	*- FL
10	1		FRONT PORTION *HEADLAMP SUPPORT PANEL ASSY	Bent	1,023.00 FL	*1,023.00 FL
11	2		FRONT PORTION *HEADLAMP (LH/RH)	Cover Cracked	1,595.80 FL	*1,595.80 FL
12	1		FRONT PORTION *RADIATOR	Bent/Punctured	814.80 FL	*814.80 FL
13	1		FRONT PORTION *RADIATOR FAN BLADE,COWLING,MOTOR ASSY	Not Necessary	651.30 FL	*- FL
14	2		FRONT PORTION *RADIATOR BRACKET	Not Necessary	12.40 FL	*- FL
15	1		FRONT PORTION *AIRCON CONDENSER	Bent	1,089.90 FL	*1,089.90 FL
16	1		FRONT PORTION *INTER COOLER	Bent	771.50 FL	*771.50 FL
17	1		FRONT PORTION *INTER COOLER MOUNTING (2 PCS)	Not Necessary	24.80 FL	*- FL
18	1		FRONT PORTION *FRONT NUMBER PLATE	Not Necessary	25.00 FS	*- FS
19	1		FRONT PORTION *FRONT NO PLATE TRIM COVER	Not Necessary	30.00 FS	*- FS
20	1		REAR PORTION *BOOT LID LOCK UPPER	Not Necessary	132.10 FL	*- FL
21	1		REAR PORTION *BOOT LID LOCK LOWER	Not Necessary	30.30 FL	*- FL
22	1		REAR PORTION *BOOT LID SONATA PLATE	Necessary	43.60 FL	*43.60 FL
23	1		REAR PORTION *BOOT LID HYUNDAI PLATE	Necessary	24.20 FL	*24.20 FL
24	1		REAR PORTION *BOOT LID H EMBLEM	Necessary	26.10 FL	*26.10 FL
25	1		REAR PORTION *BOOT LID CRDI PLATE	Necessary	22.70 FL	*22.70 FL
26	1		REAR PORTION *BOOT LID LAMP (LH)	Cut	230.20 FL	*230.20 FL
27	1		REAR PORTION *BOOT LID TRIMBOARD	Not Necessary	165.40 FL	*- FL
28	1		REAR PORTION *BOOT LID TRIMBOARD CLIPS (11 PCS)	Not Necessary	11.00 FL	*- FL
29	1		REAR PORTION *REAR BUMPER	Dented	578.40 FL	*578.40 FL
30	1		REAR PORTION *REAR BUMPER REINFORCEMENT	Not Necessary	483.30 FL	*- FL
31	10		REAR PORTION *REAR BUMPER CLIP	Necessary	22.00 FL	*22.00 FL
32	1		REAR PORTION *REAR BUMPER BRACKET	Bent	49.00 FL	*49.00 FL
33	1		REAR PORTION *REAR BUMPER SPONGE	Not Necessary	137.40 FL	*- FL
34	1		REAR PORTION *REAR BUMPER UNDER COVER	Not Necessary	185.80 FL	*- FL
35	1		REAR PORTION *REAR BUMPER PROTECTOR (LH)	Bent	38.00 FL	*38.00 FL
36	1		REAR PORTION *TAIL LAMP LH	Broken	344.00 FL	*344.00 FL
37	1		REAR PORTION *TAIL LAMP QUARTER PANEL LH	Dented	93.80 FL	*93.80 FL
38	1		REAR PORTION *REAR PANEL	Dented	391.80 FL	*391.80 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
39	1	REAR PORTION	*REAR PANEL GARNISH	Not Necessary	95.80 FL	*- FL
40	1	REAR PORTION	*SPARE TYRE HOLDER	Not Necessary	27.60 FL	*- FL
41	1	REAR PORTION	*TAIL LAMP PANEL TOP (LH)	Not Necessary	217.40 FL	*- FL
42	1	REAR PORTION	*SPARE TYRE PANEL	Dented	863.00 FL	*863.00 FL
43	1	REAR PORTION	*SPARE TYRE PANEL CUSHION	Not Necessary	200.30 FL	*- FL
44	1	REAR PORTION	*REAR TOWING HOOK	Not Necessary	135.30 FL	*- FL
45	1	REAR PORTION	*MEMBER ASSY-REAR FLOOR CENTRE	Not Necessary	163.60 FL	*- FL
46	1	REAR PORTION	*PANEL ASSY-REAR FLOOR SIDE (LH)	Buckled	88.55 FL	*88.55 FL
47	1	REAR PORTION	*REAR FLOOR CHASSIS MEMBER (LH)	Buckled	1,280.50 FL	*1,280.50 FL
48	1	REAR PORTION	*REAR FENDER (LH)	Dented	1,935.90 FL	*1,935.90 FL
49	1	REAR PORTION	*REAR FENDER INNER PANEL (LH)	Not Necessary	1,255.00 FL	*- FL
50	1	REAR PORTION	*REAR FENDER INNER LINING (LH)	Not Necessary	74.10 FL	*- FL
51	1	REAR PORTION	*REAR FENDER CORNER HARDBOARD COVER (LH)	Bent	204.30 FL	*204.30 FL
52	1	REAR PORTION	*REAR FENDER AIR-DUCT	Serviceable	49.40 FL	*- FL
53	1	REAR PORTION	*REAR FENDER MUDFLAP (LH)	Not Necessary	15.50 FL	*- FL
54	1	REAR PORTION	*REAR FENDER TRIM BOARD (LH)	Bent	180.90 FL	*180.90 FL
55	1	REAR PORTION	*REAR WINDSCREEN MOULDING	Necessary	60.00 FL	*60.00 FL
56	1	REAR PORTION	*FUEL TANK SUB HOSE	Not Necessary	78.20 FL	*- FL
57	1	REAR PORTION	*FUEL TANK UPPER NECK	Not Necessary	221.60 FL	*- FL
58	1	REAR PORTION	*BOOT LID	Bent/Dented	1,349.50 FL	*1,349.50 FL
59	1	REAR PORTION	*BOOT LID RUBBER	Deformed	110.90 FL	*110.90 FL
60	1	REAR PORTION	*BOOT LID HINGE (LH/RH)	Not Necessary	341.20 FL	*- FL
61	1	REAR PORTION	*BOOT LID COMFORT LOGO & TEL NO STICKER	Necessary	30.00 FS	*30.00 FS
62	1	REAR PORTION	*BOOT LID ADVERTISEMENT LOGO	Necessary	100.00 FS	*100.00 FS
63	1	REAR PORTION	*REAR BUMPER REVERSE SENSOR	Damaged	135.70 FS	*135.70 FS
64	1	REAR PORTION	*REAR BUMPER ADVERTISEMENT LOGO	Necessary	50.00 FS	*50.00 FS
65	1	REAR PORTION	*REAR BUMPER RUBBER MAT	Deformed	50.00 FS	*50.00 FS
66	2	REAR PORTION	*REAR FENDER ADVERTISEMENT LOGO (LH/RH)	Necessary	200.00 FS	*200.00 FS
67	1	REAR PORTION	*REAR WINDSCREEN SEALANT	Necessary	46.00 FS	*46.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 20,343.45 13,844.05  
 - List Item Discount on L Items 20.00/20.00% (\$\$) 3,935.35 2,646.47

Total Parts (\$\$) 16,408.10 11,197.58

Report was unsubmitted during this print-out.
---

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING (FRONT)	New	1,000.00	400.00
2	SPRAY PAINTING CHARGE (FRONT)	New	250.00	200.00
3	WIRING CHARGE (FRONT)	New	50.00	30.00
4	TOWING CHARGE (FRONT)	New	50.00	0.00
5	REMOVE/REFIX AIRCON & REFILL GAS (FRONT)	New	150.00	80.00
6	PANEL BEATING (REAR)	New	2,000.00	1,000.00
7	SPRAY PAINTING CHARGE (REAR)	New	1,500.00	800.00
8	WIRING CHARGE (REAR)	New	50.00	30.00
9	TUFF KOTE (REAR)	New	100.00	40.00
10	REAR CHASSIS ALIGNMENT CHARGE (REAR)	New	400.00	150.00
11	REMOVE/REFIX CUSHION & UPHOLSTERY REAR (REAR)	New	150.00	80.00
12	REMOVE/REFIX REAR WINDSCREEN GLASS (REAR)	New	120.00	80.00
13	REMOVE/REFIX REVERSE SENSOR (REAR)	New	120.00	40.00
14	REMOVE/REFIX FUEL TANK (REAR)	New	150.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>6,090.00</b>	<b>2,930.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >