

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793J . Tel: 6741-1730 / 731 . Fax: 6744-5746. Email: liusbro@gmail.com

Invoice/Ref No: GBE7663R190620

**Estimate****Customer**

Page 01 - 03

Name: AIG Asia Pacific Insurance Pte Ltd

Date: 02-07-19

Address: Motor Claims Department

Vehicle No: GBE7663R

78 Shenton Way #07-16

Model/Make: Toyota Hiace

AIG Building

Singapore 079120

3.0 DX Diesel Turbo MT 2WD

| Item No. | Descriptions Of Parts                                              | Original Quotation / Estimation | Revised Quotation / Cost Of Repair |
|----------|--------------------------------------------------------------------|---------------------------------|------------------------------------|
| 1        | Rear Tailgate <i>body</i>                                          | \$ 1,950.90                     |                                    |
| 2        | Tailgate Inner Lock <i>10/1m</i>                                   | \$ 359.00                       |                                    |
| 3        | Tailgate Outer Handle <i>8m</i>                                    | \$ 137.60                       | <i>X</i>                           |
| 4        | Tailgate Rubber <i>7m</i>                                          | \$ 426.70                       |                                    |
| 5        | Tailgate Inner Trim Board <i>re/repair</i>                         | \$ 165.30                       |                                    |
| 6        | Tailgate Inner Trim Board Clips 1 set <i>re</i>                    | \$ 50.00                        | <i>re</i>                          |
| 7        | Tailgate "Corporate" Advertisement & Artwork <i>re</i>             | \$ 180.00                       | SN 1505.~                          |
| 8        | Tailgate Windscreen Glass Moulding <i>re</i>                       | \$ 219.00                       | <i>X</i>                           |
| 9        | Tailgate Windscreen Glass Sealant <i>re</i>                        | \$ 50.00                        | SN 405.~                           |
| 10       | Tailgate "70 KM/H" Sticker <i>re</i>                               | \$ 15.00                        | SN 105.~                           |
| 11       | Tailgate "8 PAX" Sticker <i>re</i>                                 | \$ 15.00                        | SN 105.~                           |
| 12       | Tailgate "Toyota" Motif <i>re</i>                                  | \$ 68.10                        | <i>X</i>                           |
| 13       | Tail Lamp 02 pcs (@ \$365.10) <i>n/s one</i>                       | \$ 730.20                       | <i>1 pc</i>                        |
| 14       | Tail Lamp Lower Garnish <i>1/5 one 185</i>                         | \$ 435.20                       |                                    |
| 15       | Bumper <i>1/5</i>                                                  | \$ 465.00                       | <i>X</i>                           |
| 16       | Bumper Clips 1 set <i>re</i>                                       | \$ 48.00                        | <i>re</i>                          |
| 17       | <i>1 set</i> Bumper Reverse Sensor <i>shaded</i>                   | \$ 220.00                       | SN 2005.~                          |
| 18       | Bumper Inner Bracket <i>4 pcs</i> ( @ 35.80 X 4 = 143.20 <i>6m</i> | \$ 760.80                       | <i>X</i>                           |
| 19       | Bumper Side Holder 02 pcs (@ \$139.00) <i>1/1</i>                  | \$ 278.00                       | <i>X</i>                           |
| 20       | Exhaust Silencer <i>1/1</i>                                        | \$ 917.60                       | <i>X</i>                           |
| 21       | Number Plate Outer Garnish <i>1/1</i>                              | \$ 397.00                       | <i>X</i>                           |
| 22       | Number Plate and Base <i>1/1</i>                                   | \$ 48.00                        | SN <i>X</i>                        |
| 23       | End Panel Inner <i>body</i>                                        | \$ 936.20                       |                                    |
| 24       | End Panel Outer <i>body</i>                                        | \$ 566.10                       |                                    |
| 25       | End Panel Top Plate <i>re</i>                                      | \$ 299.50                       |                                    |
| 26       | End Panel Sealant <i>re</i>                                        | \$ 50.00                        | SN <i>✓</i>                        |
| 27       | Fender (Body Panel) <i>re</i>                                      | \$ 1,308.10                     | <i>X</i>                           |
| 28       | Fender Inner Panel <i>re</i>                                       | \$ 1,069.10                     | <i>X</i>                           |
| 29       | Fender "Corporate" Advertisement & Artwork <i>re</i>               | \$ 180.00                       | SN 1505.~                          |
|          | Floor Panel Top Wooden Board <i>one</i>                            | \$ 650.00                       | SN 4005.~                          |
|          | C/F Balance --->                                                   | \$ 12,995.40                    |                                    |

Not Authorized  
Date1/5 10,800/  
927.  
3/7/19

M/s Liu's Brother Auto Engrg Wks

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793 | Tel: 6741-1730 / 731 | Fax: 6744-5746. Email: liusbros@gmail.com

Invoice/Ref No: GBE7663R190620

**Estimate**

|                                                 |                                 |
|-------------------------------------------------|---------------------------------|
| <b>Customer</b>                                 | <b>Page 02 - 03</b>             |
| <b>Name:</b> AIG Asia Pacific Insurance Pte Ltd | <b>Date:</b> 02-07-19           |
| <b>Address:</b> Motor Claims Department         | <b>Vehicle No:</b> GBE7663R     |
| 78 Shenton Way #07-16                           | <b>Model/Make:</b> Toyota Hiace |
| AIG Building Singapore 079120                   | 3.0 DX Diesel Turbo MT 2WD      |

| Item No. | Descriptions Of Parts                           | Original Quotation / Estimation | Revised Quotation / Cost Of Repair |
|----------|-------------------------------------------------|---------------------------------|------------------------------------|
|          | <b>B/F Balance ---&gt;</b>                      | \$ 12,995.40                    |                                    |
| 31       | Front Bumper <i>de</i> <i>485.60</i>            | \$ 796.80                       | <i>X</i>                           |
| 32       | Bumper Beam Center <i>R</i>                     | \$ 217.50                       | <i>X</i>                           |
| 33       | Bumper Clips 1 set <i>nu</i>                    | \$ 50.00                        | <i>SN</i> <i>✓</i>                 |
| 34       | Bumper Bracket <i>11</i>                        | \$ 178.00                       | <i>X</i>                           |
| 35       | Bumper Side Holders (@ \$137.20) <i>11</i>      | \$ 274.40                       | <i>X</i>                           |
| 36       | Bumper Centre Grille <i>11</i>                  | \$ 155.80                       | <i>X</i>                           |
| 37       | Bumper Top Beam <i>11</i>                       | \$ 189.60                       | <i>X</i>                           |
| 38       | Bumper Carbon "Sticker" Lower <i>nu</i>         | \$ 180.00                       | <i>SN</i> <i>1505.~</i>            |
| 39       | Grille <i>70.11</i>                             | \$ 487.70                       | <i>✓</i>                           |
| 40       | Grille Clip 1 set <i>11</i>                     | \$ 35.00                        | <i>SN</i> <i>X</i>                 |
| 41       | Grille Chrome <i>(re)</i>                       | \$ 287.50                       | <i>✓</i>                           |
| 42       | Grille Inner <i>11</i>                          | \$ 675.10                       | <i>X</i>                           |
| 43       | Head Lamp 02 pcs (@ \$930.70) <i>holder era</i> | \$ 1,861.40                     | <i>✓</i>                           |
| 44       | Head Lamp clips 1 set <i>11</i>                 | \$ 65.00                        | <i>X</i>                           |
| 45       | Head Lamp Bracket 02 pcs (@ \$19.70) <i>11</i>  | \$ 39.40                        | <i>SN</i> <i>X</i>                 |
| 46       | Radiator <i>pu1</i>                             | \$ 2,372.30                     | <i>✓</i>                           |
| 47       | Radiator Fan Motor <i>11</i>                    | \$ 624.30                       | <i>X</i>                           |
| 48       | Radiator Fan Blade <i>11</i>                    | \$ 290.20                       | <i>X</i>                           |
| 49       | Radiator Fan Cowling <i>11</i>                  | \$ 587.30                       | <i>X</i>                           |
| 50       | Radiator Coolant 1 bottles <i>11</i>            | \$ 50.00                        | <i>SN</i> <i>X</i>                 |
| 51       | Aircon Condenser <i>best pu1</i>                | \$ 1,448.00                     | <i>✓</i>                           |
| 52       | Number Plate and Base <i>sent</i>               | \$ 48.00                        | <i>SN</i> <i>405.~</i>             |
| 53       | Support Panel <i>11</i>                         | \$ 766.30                       | <i>X</i>                           |
| 54       | Brace Panel <i>11</i>                           | \$ 434.80                       | <i>X</i>                           |
| 55       | Aircon Condenser <i>Repaired</i>                | \$ 1,448.00                     | <i>X</i>                           |
| 56       | Windscreen Glass Moulding <i>11</i>             | \$ 303.60                       | <i>X</i>                           |
| 57       | Windscreen Glass Sealant <i>11</i>              | \$ 50.00                        | <i>SN</i> <i>X</i>                 |
|          | <b>C/F Balance ---&gt;</b>                      | \$ 26,911.40                    |                                    |

Liu's Brother Auto Engineering Workshop

(The resurvey of the following:

- To resurvey on any after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



M/s Liu's Brother Auto Engrg Wks

13020.6  
252  
9765.45  
S.N 1150  
C.N 2630  
13545.45  
10836

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793J . Tel: 6741-1730 / 731 . Fax: 6744-5746. Email: liusbros@gmail.com

Invoice/Ref No: GBE7663R190620

**Estimate**

|                                                 |                                 |
|-------------------------------------------------|---------------------------------|
| <b>Customer</b>                                 | <b>Page 03 - 03</b>             |
| <b>Name:</b> AIG Asia Pacific Insurance Pte Ltd | <b>Date:</b> 02-07-19           |
| <b>Address:</b> Motor Claims Department         | <b>Vehicle No:</b> GBE7663R     |
| 78 Shenton Way #07-16                           | <b>Model/Make:</b> Toyota Hiace |
| AIG Building Singapore 079120                   | 3.0 DX Diesel Turbo MT 2WD      |

| Item No. | Descriptions Of Parts                                                     | Original Quotation / Estimation | Revised Quotation / Cost Of Repair |
|----------|---------------------------------------------------------------------------|---------------------------------|------------------------------------|
|          | B/F Balance --->                                                          | \$ 26,911.40                    |                                    |
| 31       | Front Bumper <i>Repld</i>                                                 | \$ 796.80                       | X                                  |
|          | Remove and refix rear tailgate components & wiper mechanism               | \$ 80.00                        | 50                                 |
|          | To check all wiring & electrical component for proper function            | \$ 80.00                        | 30                                 |
|          | Remove and refix rear bumper reverse sensor                               | \$ 100.00                       | 50                                 |
|          | Remove & reinstall Rear Windscreen Glass to facilitate repairs            | \$ 120.00                       | 120                                |
|          | Remove & reinstall Front Windscreen Glass to facilitate repairs           | \$ 120.00                       | X                                  |
|          | To remove & refix air con, re-fill air con gas & test for leakages        | \$ 180.00                       | 100                                |
|          | Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc      | \$ 1,500.00                     | 1100                               |
|          | To putty & spray painting & including touch up paint on accident affected | \$ 1,800.00                     | 1100                               |
|          | To apply Rust Proofing , reseal tuff-coating treatment on accident area   | \$ 80.00                        | ✓                                  |

Total Parts &amp; Labour of estimate for damaged vehicle

\$ 31,768.20

Total amount in Lump Sum Basis for repaired vehicle

SDLS: \_\_\_\_\_



M/s Liu's Brother Auto Engrg Wks