



Case Details

Case Reference Number: TAX/06/19/2118

Type of Repair : Accident Repair

Vehicle Registration Number : SHC4357J

Company Type : SMRT Taxis Pte Ltd

Estimation ID: EST-7534-ID

Assigned By: Taxi Claims Manager Team

Insurance Company Name : AIG Asia Pacific

Insurance Pte Ltd

Accident Date and Time: 29/06/2019 07:55

AM

Vehicle Age(In Months): 67

Documents / Photographs

View Documents / Photographs

Total Documents: 0

Estimation Details

Spare Part's Cost Detail

				SMRT R	ecomi	mendation						Surve	yor Approval	
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			MIRROR ASSY, LH	1	1,224.90	1,224.90	25.00	918.68	Replace	1	918.68	Replace *	BR/
One Time Key In	Main			MIRROR LAMP LH	1	65.30	65.30	10.00	58.77	Replace	0	0	Not Give *	X XIM
One Time Key In	Main			COVER, OUTER MIRROR, LH	1	107.40	107.40	25.00	80.55	Replace	1	80.55	Replace *	/ BK
						То	tal Spare P	art Cost	1,058.00		Su	rveyor Total	999.23	
						Lump	Sum Disc	ount (%)	20.00		Lump	Sum Dis (%)	20.00	
						Fir	nal Spare P	art Cost	846.40		Fir	nal Sur Total	799.38	

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
Total:			0.00	0.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY VIEW MIRROR	180.00	100.00	
Total:			180.00	100.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REMOVE AND REFIX WING MIRROR	120.00	60.00	
2	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20.00	

Recommendation(\$) Adjustment(\$)

3 Main

TO REMOVE AND REFIT WIRE HARDESS

400.00

80.00

Summary

Total Spare Part Detail

Estimator Assesment(\$)

Total Labour Cost

Total Spray Painting

Other 400.00

Lump Sum Repair Option

1,450.00 Lump Sum Total

Surveyor Approved Amount

No of Repair Days*

Surveyor Name

Signature

Survey Date

846.40

0.00

180.00

1,426.40

02/07/2019

Surveyor Assesment(\$)

799.38

0.00

80.00

979.38 1,179:23

1000 1,200.00

1,200.00

US repair, take after spray. Finalize sent to

stevechen@lkkauto.com

STEVE CHEN

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number: 63685592
Estimator Telephone Number: 68662623
Abbident Reporting Number: 68662672

Date Generated: 08/07/2019
User ID: PohSuan

	Section A - Accident Details
Registration Number	SHC4357J
Case Reference Number	TAX/06/19/2118
Registration Date	22/11/2013
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	TAN SEOW PENG
Type of Accident	Side Swipe
Accident Date and Time	29/6/2019 3:55 PM
Accident Reported Date and Time	1/7/2019 11:50 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24102226
Special Instruction to ARC, if any	LEFT HAND FRONT PORTION
Prepared Date and Time	2/7/2019 3:24 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and	

Summary of Repair Estimate		
STATE OF THE STATE	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$0.00	\$0.00
Total Spray Cost	\$180.00	\$100.00
Total Spare Part Cost	\$846.40	\$799.38
Total Other Cost	\$400.00	\$80.00
TOTAL COST	\$1,426.40	\$979.38
Lump Sum Total	\$1,450.00	\$1,000.00 (L/S)
Number of Repair Days	2.0	1.0
Prepared / Adjusted By	Tuck Foo Kok	STEVE CHEN (LKK) / AIG
ARC / Surveyor Sign Off Date	02/07/2019 4:53 PM	02/07/2019 4:20 PM
Signature	A A	~
Remarks	1	L/S repair, take after spray. Finalize sen to stevechen@lkkauto.com



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd 63 Woodlands Industrial Park E4, Singapore 767705 FAX Number: 63865592 Estimator Talephone Number: 68662623 Accident Repairing Number: 68662672

Osta Generated: 08/07/2019
User ID: PohSuan

	Section C - Quota	tion and Accident Invoice Details	
Quotation Number	QN-1907-0121	Invoice Number	
Quotation Date	08.07.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - D	etails of Repair Estimates	
Part 1 - Labour Works		
Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
Total Labour		

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY VIEW MIRROR	\$180.00	\$100.00
Total Spray Painting & Panel Beating	\$180.00	\$100.00

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REMOVE AND REFIX WING MIRROR	\$120.00	\$60.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO REMOVE AND REFIT WIRE HARDESS	\$200.00	\$0.00
Total Other Costs	\$400.00	\$80.00

Part Number	Portion	Stock	Part Name		List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved	
14111001	20 100000000000000000000000000000000000	87940- 47310	MIRROR ASSY, LH	1.00	\$1,224.90	25.00	\$918.68	Replace	Replace	/
		81740- 52040	MIRROR LAMP LH	0.00	\$65,30	0.00	\$0.00	Replace	Not Given	X
		87945- 74010	COVER, OUTER MIRROR,	1.00	\$107.40	25.00	\$80.55	Replace	Replace	/
Total	-				\$1,397.60		\$999.23			

200			ge After Surveyor Signed of					Alega Stille III	
art Iumber	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check

799.23 -202 799.38 + 180.00 + 180.00 - 4 180.00