

Rear Tail gate Pented.

1055.30

" " " Lock LH/RT e \$ 189 mm

378.00

X

" " " Emblem - 'Toyota' Nec

175.00

" " " " 70km } Nec

30.00

15(SN)

" " " " 30 13 Pax } Nec

30.00

15(SN),

" " " " Dyna Nec

38.00

Rear Tail Gate Aluminium Panel ^{MM}

164.00

X

" " " End Panel Dented.

384.00

Tail Lamp LH Smashed.

169.70

Tail Lamp panel LH Bent.

56.10

Rear LH side gate LH Repair

1555.10

X

" side gate Lock LH Bent. ^{LH Bent}

128.00

Rear Tail gate Retainer \$38x2 LH

76.00

38

" " " stop rubber \$34x2 ^{LH Missing}

68.00

Rear Number Plate Panel Bent.

159.10

Rear Spare Tyre Carrier Assy Damaged

312.00

Rear LH chassis member Repair

924.00

X

Rear Step Bracket (Stair Case) Bent.

122.00

Rear side gate panel Repair

188.00

X

Rear Floor Centre panel Repair

945.00

X

Reverse sensor - Damaged

350.00

200(SN)

Radiator - Dented.

1637.00

Fan Blade LH

192.70

Engine Mounting 2x e \$ 123 torn

246.00

Gear Box Mounting torn

117.00

Rear Number Plate Bent

50.00

30(SN)

9550.00

Less 25%

2387.50

4897.90

S.N: 260.

7162.50

Ln 25%: 3673.42

EUNOS MOTOR SERVICE

BLK 1 KAKI BUKIT AVE 6
#01-064 SINGAPORE 417883
TEL: 6747 2033, 6748 0107
FAX: 6741 5497

GBC 8828S T/Dyna

To ~~repair~~ chassis

~~1200~~

800

Dismantle Tail Gate

800

X.

To remove Reverse Sensor -

~~80.00~~

50

To dismantle Radiator -

~~180.00~~

120.

To repair undercarriage

180.00

X.

To adjust alignment

180.00

X.

To check wiring

~~120.00~~

30.

To spray painting affected accident parts

~~650~~

400.

To knock, straighten all necessary parts, including changing & repairing of all damaged parts.

~~800~~

600

11,352.50

To remove rear deck to facilitate

650

450

repairs to rear chassis member Lump Sum: \$ 9082/-

2450

total: 6383.42

H/S: 5.1K.

06 Days.

5.1K