

SK Automobile Pte Ltd
(Co Reg. No. 201500047H)
23 Kaki Bukit Ave 4, #03-01
Vicom Inspection Centre (S415933)
Tel: 6789 5155 Fax : 6783 5155

TO	: AXA	DATE	: 3-Jul-19
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>OWNER'S PARTICULAR</u>		<u>VEHICLE DETAILS</u>	
NAME	: <i>Xiao Tony</i>	VEHICLE NO	: XD9058U
ADDRESS	:	MODEL	: MITSUBISHI FUSO
TEL. NO.	:	CHASSIS NO	: <i>FVS155A10009</i>
OWNER'S INSURANCE	:		
POLICY NO.	:		
<u>ACCIDENT DETAILS</u>	DATE :		
	TIME :		
THIRD PARTY REQUESTOR / CONTACT : XIONG / 8121 0478			

QUOTATION SUMMARY

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>Bent</i>	1	\$ 4,986.00	\$ 4,986.00
2	FRONT BUMPER END GARNISH LH <i>cracked</i>	1	\$ 154.00	\$ 154.00
3	FRONT BUMPER BRACKET LH <i>Not on</i>	1	\$ 598.00	\$ 598.00
4	HEAD LAMP LH <i>cut</i>	1	\$ 3,412.00	\$ 3,412.00
5	HEAD LAMP RING LH <i>cracked</i>	1	\$ 69.00	\$ 69.00
6	BUMPER FOG LAMP LH <i>Not on cracked</i>	1	\$ 689.00	\$ 689.00
7	BUMPER FOG LAMP RING LH <i>cracked</i>	1	\$ 69.00	\$ 69.00
8	FRONT STEP PANEL GARNISH TOP LH <i>By is</i>	1	\$ 697.00	\$ 697.00
9	FRONT STEP PANEL LOWER GARNISH LH <i>cracked</i>	1	\$ 890.00	\$ 890.00
10	FRONT STEP LOWER REFLECTOR LH <i>cracked</i>	1	\$ 156.00	\$ 156.00
11	FRONT STEP PANEL TOP PAD LH <i>Not on</i>	1	\$ 320.00	\$ 320.00
12	FRONT STEP PANEL LOWER PAD LH <i>cut</i>	1	\$ 320.00	\$ 320.00
13	FRONT FENDER WHEEL ARCH LH <i>Not on</i>	1	\$ 417.00	\$ 417.00

TOTAL PRICE \$ 12,777.00
LESS 15% \$ 1,916.55

5711
less 25%: 4283.25

- 2830
x
1286.
312
x
415.
x

SUB TOTAL PRICE \$ 10,860.45

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	CORNER PANEL CLIPS <i>MC New</i>	1	\$ 60.00	\$ 60.00
2	FRONT FENDER COWLING LOWER MUDFLAP <i>MC New</i>	1	\$ 100.00	\$ 100.00
TOTAL				<u>\$ 180.00</u>

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST	APPROVED
1	TO PANEL BEAT, WELD, CUT, ADJUST, KNOCK ON DAMAGE PANEL.	\$ 1,500.00	400	
2	TO PUTTY, SPRAY PAINT, POLISH WAX ON AFFECTED AREA.	\$ 800.00	600	
3	WIRING, BULB CHECKING.	\$ 150.00	30	
TOTAL		<u>\$ 2,450.00</u>		

1030.

ESTIMATE REPORT

TOTAL PARTS COST : \$ 11,040.45
TOTAL LABOUR COST : \$ 2,450.00
TOTAL REPAIR COST : \$ 13,490.45

APPROVED DETAILS

EXCESS :
NO. OF WORKING DAYS :
RE-SURVEY :

PART BY PART OR LUMP SUM :

DATE & TIME OF SURVEY :
SURVEYED BY :
CONTACT NUMBER :
FAX NUMBER :

Adrian Lij
4/s 03/07/15.

LKK Auto-Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: