
































































Report No: 0258-17-N51

09 October 2017

ACCIDENT VEHICLE SURVEY REPORT

Lucky Construction Pte Ltd
c/o N-51 Automotive Pte Ltd
2 Kaki Bukit Ave 2 #01-18
Kaki Bukit Auto Hub
Singapore 417921

VEHICLE INFORMATION:

<i>Vehicle Reg No.:</i>	YL7011M	<i>Odometer:</i>	167445km
<i>Make & Model:</i>	Isuzu FSR33P	<i>Colour:</i>	Yellow/Green
<i>Chassis number:</i>	JALFSR33P47000012	<i>Date of accident:</i>	01/04/2016
<i>Year of Regn.:</i>	18/05/2004	<i>Date inspected:</i>	05/04/2016
<i>Repairer at:</i>	N-51 Automotive Pte Ltd 2 Kaki Bukit Ave 2 #01-18 Kaki Bukit Auto Hub Singapore 417921	<i>Date inspected (After Repair):</i>	20/06/2016

RE-INSPECTION

We had carried out re-inspection during works in progress and post repair inspection on the above vehicle. Attached in Annex B are the re-inspection photos, showing the work in progress and our re-inspection to the hidden part that were damaged.

REMARKS:

We have inspected the above-mentioned vehicle on a "Without Prejudice" basis.



