

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/TMI19011818/K1VD3S2**Date:** 10/07/2019REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MX000877
<b>Claimant Vehicle No :</b>	SHA7379L	<b>Insured Vehicle No :</b>	YN3393B
Date of Loss:	26/06/2019	Nature of Claim:	TP
		Claim No:	M1904914

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SHA7379L</b>	Engine No:	D4FDDU353219
Make & Model:	HYUNDAI I40, 1.7 D CRDi (A)	Chassis No:	KMHLB41UMFU067839
Reg. Date:	02/04/2015 (Man. Year: 2015)	Odometer:	662213 km
Colour:	Blue		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	West Lake 7 mm	Rear Left Side:	West Lake 7 mm
Front Right Side:	West Lake 7 mm	Rear Right Side:	West Lake 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,566.88	625.68	1,941.20	75.62
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,830.00	880.00	950.00	51.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>4,407.88</b>	<b>1,516.68</b>	<b>2,891.20</b>	<b>65.59</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,200.00</b>		
<b>(S\$)</b>	4,407.88	1,200.00	3,207.88	72.78
<b>+ GST 7.00/7.00% (S\$)</b>	308.55	84.00	224.55	72.78
<b>Nett Amount (S\$)</b>	<b>4,716.43</b>	<b>1,284.00</b>	<b>3,432.43</b>	<b>72.78</b>

INSPECTION

Date of Assignment:	03/07/2019	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	03/07/2019	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	3.0 days		

**Adjuster:** KALVIN ANG WEI KUN**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 09 Jul 2019)
<b>Parts:</b>	143	HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHA7379L)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	553.00 FL	*553.00 FL
2	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
3	1		*REAR FENDER LH	Repair	2,171.40 FL	*- FL
4	1		*REAR FENDER INNER LINING LH	Serviceable	169.30 FL	*- FL
5	1		*REAR WINDSCREEN MOULDING	Not Necessary	28.30 FL	*- FL
6	1		*REAR WHEEL HUP-CAP LH	Grazed	107.10 FL	*107.10 FL
7	2		*REAR WINDSCREEN SEALANT	Not Necessary	46.00 F	*- FS
8	1		*REAR DOOR COMFORTDELGRO & APPS STICKER LH	Necessary	80.00 F	*80.00 FS
9	1		*ROCKER PANEL GARNISH (LH)(NPA)	Repair	-	*- FL
						F=Franchise part. S=SpcNett. L=ListItemDisc.
					<b>Sub Total (\$)</b>	<b>3,177.10</b>
					<b>- List Item Discount on L Items 20.00/20.00% (\$)</b>	<b>610.22</b>
					<b>Total Parts (\$)</b>	<b>2,566.88</b>
						<b>625.68</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<b>Miscellaneous Items</b>				
1	1	OD/TP Case (Insurer)	11.00	11.00
<b>Sub Total (\$\$)</b>			<b>11.00</b>	<b>11.00</b>

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	400.00	200.00
2	SPRAY PAINTING CHARGE	New	900.00	600.00
3	WIRING CHARGE	New	50.00	0.00
4	TUFF KOTE	New	50.00	0.00
5	REMOVE/REFIX CUSHION & UPHOLSTERY REAR	New	150.00	50.00
6	REMOVE/REFIX REAR WINDSCREEN GLASS	New	120.00	0.00
7	REMOVE/REFIX REVERSE SENSOR	New	80.00	30.00
8	REAR WHEEL ALIGNMENT	New	80.00	0.00
9	TOWING FEE	New	-	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,830.00</b>	<b>880.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >