

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00

SPRINGLEAF TOWER SINGAPORE 079909

INV No. AC2003878

INV Date 14/05/2020

Reference CC3/CTI19011819/K1ea3n2

Code CT

PROFESSIONAL SERVICE FEE

Vehicle No. SHC 8896T

Insured Veh. XE 3606Y

Claim No. SNM19D203109

Policy No. DMCVSN1764071801

Accident Date 02/07/2019

Inspection Date 03/07/2019

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

HYN



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

	Affiliated to Federation Internationale Des Experts En Automobile					
CHIN	IA TAIPING INSUI	G INSURANCE (S) PTE LTD Ref: CC3/CTI19011819/K1ea3n2				
3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Date: 14-05-2020 Code: CTI				
1.		Policy Particulars	:- THIRD PARTY CLAIM			
	Insured Veh.	XE 3606Y	Veh. Inspected	SHC 8896T		
	Policy No.	DMCVSN1764071801	Coverage (\$)	0.00		
	Claim No.	SNM19D203109	Excess (\$)	0.00		
	Assign From		Assign Date	03/07/2019		
2.		Vehicle Partic	culars & Condition			
	Make & Model	HYUNDAI 140	c.c	1685		
	Engine No.	HIDDEN	Year of Reg.	2016		
	Chassis No.	KMHLB41UMGU087387	Colour	BLUE		
	Odometer	467267	Steering	IN ORDER		
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM		
	General	FAIR				
3.			ons of Tyres			
		Size	Make	Balance		
	R/H Front Tyre	205/60 R16	HANKOOK	7 mm		
	L/H Front Tyre	205/60 R16	HANKOOK	7 mm		
	R/H Rear Tyre	205/60 R16	HANKOOK	7 mm		
	L/H Rear Tyre	205/60 R16	HANKOOK	7 mm		
4.		•	on of Damages			
	THE VEHICLE SU	STAINED DAMAGES AT THE N/S	REAR PORTION.			
	DAMAGES SEE D					
5.		General	Information			
	Accident Date	02/07/2019	Inspection Date	03/07/2019		
	Survey held at	COMFORTDELGRO ENGINEER	RING PTE LTD			
		59 LOYANG DRIVE SINGAPORE 508969				
5a.		Re	emarks			
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NOR	MAL PERIOD FOR REPAIR:	3 Working Days			



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 8896T

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR FENDER -LH	TO REPAIR SEE LABOUR	2,020.10	-
1	REAR WHEEL COVER -LH	GRAZED	107.10	107.10
1	REAR WHEEL RIM -LH	SERVICEABLE	325.30	-
1	REAR BUMPER	TO REPAIR SEE LABOUR	553.00	-
10	REAR BUMPER CLIPS @\$2.20	NOT NECESSARY	22.00	-
1	REAR DOOR -LH	BUCKLED	1,351.10	1,351.10
1	ROCKER COVER GARNISH -LH	TO REPAIR SEE LABOUR	341.40	-
	LESS 20% DISCOUNT		-944.00	-291.64
			3,776.00	1,166.56
	SPECIAL NETT ITEMS			
1	ADVERTISEMENT-LHR DOOR (SN)	NECESSARY	100.00	100.00
1	ADVERTISEMENT-LHR FENDER (SN)	NECESSARY	100.00	100.00
1	LHR DOOR APP STICKER (SN)	NECESSARY	80.00	80.00
			280.00	280.00
	<u>LABOUR</u>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR FENDER -LH ,REAR BUMPER AND ROCKER COVER GARNISH -LH.		750.00	400.00
	SPRAY PAINTING CHARGE.		800.00	600.00
	WIRING CHARGE.	NOT NECESSARY	50.00	-
	REMOVE/REFIX REVERSE SENSOR .	NOT NECESSARY	100.00	-
	TUFF KOTE.		80.00	30.00
	-		-	-
	-		-	-
	-		-	-
			1,780.00	1,030.00
	GRAND TOTAL		5,836.00	2,476.56

Report Ref No. CC3/CTI19011819/K1ea3n2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		2,000.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CC3/CTI19011819/K1ea3n2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

Amonto

HO LEONG CHUAN

Automotive Assessor



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHC 8896T

INSPECTION

















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315







51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHC 8896T

RE-INSPECTION









