

733 BURTT HMAH ROAD 2ND AVE JUNCTION #01-01 S(269748) TEL: 64625158 EMAIL: info@tayjunction.com.sg

Customer: KENNY WONG

Contact: 992258053

Bike Model: 2018 TCR ADV 0

Colour: CARBON

Size: XS

Based on our assessment on Mr Kenny Wong bike, the frame/body of the bike is a total lost (carbon cracked on the seat tube of the frame). Wheelset will also be a total lost as the damage is beyond repair (Wheels come in a set or a pair only). Rear derailleur and shifter are electronic items are not functioning properly due to the impact, other items such as bar tape, brake caliper (jammed due to impact) and saddle need to be replaced. Attached photos will show the damages to these items.

We have viewed the bike and observed that the below-mentioned are required for

| change. | |
|-----------------------------------|--------|
| GIANT TOR ADV FRAME | \$1800 |
| SHIMANO REAR DERAILLEUR DI2 R8050 | \$300 |
| SHIMANO SHIFTER DI2 R8050 | \$450 |
| GIANT SADDLE | \$95 |
| WHEELSET (PAIR) | \$450 |
| SHIMANO BRAKE CALIPER | \$200 |
| LABOUR CHARGES | \$250 |
| BAR TAPE | \$55 |
| TOTAL | \$3600 |

With carbon as a fiber material, once an uneven surface and/or cracks are discovered, the product is no longer fit for use as the raw materials lay-up is disrupted internally, reducing the strength of the whole structure to none. Given further pressure under a damaged structure, it will eventually give way and break apart (into pieces), posing potential death threats and danger to the user