Kw



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Klo, Ind Park 2 #01-251/259, 569536. Tel: +65-6484 1221 Fax: +65-6484 7829 Webelte: www.esteemperf.com.sg

Repair Estimates	SLK 3415 S Finalised	Not Norhanie
rts (a) Cost / List Price Items	\$ 6771-31 11,665.22 6491.31	Not Norharies Resney Bapairy
Plus/Less 25%	\$ (64)-83 2,916.31	
Total of Cost / List	\$ 4427-47 8,748.92 4868.4	48
(b) Nett Price Items		
Less		
Total of Nett Item		LKK Auto Consultants hence notify the Repairer of the following:
(c) Special Nett Items	\$) (5-U) 245.00 325	To display demand part(s) demands
tal Parts Cost	\$ 5173 48 8,993.92	Third party survey is on a "Without Prejudice" basis No literal modifications of the control of the co
bour	\$ 2050 00 3,550.00	is subject to final approval from Insurance Common in the common
DOUL	4 4 4 6	2 C. U. Amendada
otal	\$7)3.48 12,543.92 7 568	Acknowledged by Repairer Signature; Dete:
otal	7% G.S.T.	Date:
ne above total will be subjected to Name of Surveyor	7% G.S.T.	
otal ne above total will be subjected to	7% G.S.T.	Henreth LICK
ne above total will be subjected to Name of Surveyor Company	7% G.S.T.	Henneth LICIC
Name of Surveyor Company Survey conducted on Remarks By Surveyor	7% G.S.T.	Henneth UCIC 9 at
Name of Surveyor Company Survey conducted on Remarks By Surveyor	7% G.S.T. :	Henneth UCIC 9 at
Name of Surveyor Company Survey conducted on Remarks By Surveyor (a) The repair of this vehicle is	7% G.S.T. :	Menneth Ick at notice.
Name of Surveyor Company Survey conducted on Remarks By Surveyor (a) The repair of this vehicle is	7% G.S.T. :	Menneth Ick at notice.



ESTEEM PERFORMANCE PTE LTD

Bik 5033 Ang Mo Klo, Ind Park 2 #01-251/ 259, 569536. Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.estcemperf.com.sg

Spare Parts

Vehicle No.

Make & Model : Chassis No : **SLK 3415 S**

TOYOTA PRIUS

JTDKB3FU003544009

Submit By

Year Manufacture

Engine No.

Carmen Lim

2016

Cost / List

S/N	0.	Part Description		Qty	Unit Price	Price	Disposition by Surveyor
	1	Rear windscreen moulding	m	1	\$97.70		-
	2	Rear windscreen sealant	M	1	\$50.00		401n
	3	Rear number plate	Ru	1	\$45.00	S.N	
	4	Reverse sensor	Show	4	\$200.00	S.N	-
5	5	Rear bumper	Bn	1	\$497.50		
	6	Rear bumper clip	Nen	10	\$40.00		-
	7	Rear bumper side retainer LH	Su	1	\$112.70		2
	8	Rear bumper side retainer RH	m	1	\$112.70		*
	9	Rear bumper reinforcement	By	1	\$398.90		(3)
9	10	Rear bumper lower garnish centre	12,	1	\$582.60		
_	11	Rear bumper lower garnish LH	PL	1	\$149.70		X
_	12	Rear bumper lower garnish RH	1ºcn	1	\$149.70		7X
_	13	Rear bumper tow cover	Pa	1	\$31.70		X
_	14	Rear bumper under cover	Sen	1	\$355.20		7
	15	Rear bumper under cover LH	9-	1	\$187.60		X
	16	Rear bumper under cover RH	1	- 1	\$187.60		X
5	17	Tail door	12	1	\$1,122.50		
_	18	Tail door lock	R	1	\$487.70		X
_	19	Tail door emblem	nec	1	\$61.70		
	20	Wording "PRIUS"	na	1	\$51.90		-
	21	Wording "HYBRID"	na	1	\$55,47		
	22	Tail door hinge LH	n	1	\$87.60		X
1	23	Tail door hinge RH	1	1	\$87.60		X

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge

will be charged accordingly under supplementary.

Blk 5033 Ang Mo Kio Industrial Park 2 #01-259 Singapore 569536 Tel: 64841221 Fax: 64847829 Company Reg No. 200005485N / GST No. 20-0005485-N

2908.27

947.77)45 cr Spare Parts

Vehicle No.

Vake & Model:

SLK 3415 S

TOYOTA PRIUS

JTDKB3FU003544009 Chassis No :

Submit By

Carmon Lim

2016

Year Manufacture

Engine No.

Cost / List

S/No.	Part Description		Qty	Unit Price	Price	Disposition by Surveyor
F- 24	Tail door plate garnish	CM	1	\$782.50		~
25	Tail door inner trim	Pm	1	\$278.90		Z
26	Tail door inner trim clip	NN	10	\$28.00		7
27	Taildoor spoiler	Si	1	\$1,567.83		X
(28)	Tail end panel	124	1	\$596.60		_
R 29	Tail end panel garnish	0	1	\$151.60		_
30	Tail end panel garnish clip	Na	10	\$35.00		
31	Boot weatherstrip	01	1	\$353.10		
32	Spare tyre well panel	n	1	\$793.15		X
33	Spare tyre board	neton	1	\$566.79		
34	Spare tyre compartment sponge LH	In	1	\$297.67		3
35	Spare tyre compartment sponge RH	5-	. 1	\$297.67		X
(36)	Taildoor glass	Bru	1	\$598.70		
37	Taildoor glass sealant	ne	. 1	\$50.00		40sn
38	Third brake light	Sim	1	\$359.64		- X
39					-	
40					-	
41						
42						
43					-	
44					-	
45					-	
46	the wated nexts are recommended to be repo					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

ESTEEM PERFORMANCE PTE LTD

BLK 5033 ANG MO KIO INDUSTRIAL PARK 2 #01-259 SINGAPORE 569536

Tel:64841221 Fax:64847829

Spare Parts Vehicle No.

SLK 3415 S

TOYOTA PRIUS

Submit By Year Manufacture : CARMEN LIM 2016

Make & Model: Chassis No :

JTDKB3FU003544009

Engine No.

Cost / List

Supplementary

	Part Description			Delec	Disposition by
S/No.		Qty	Unit Price	Price	Disposition by Surveyor
1	Tail lamp RH -Upper ay	1	\$498.75		
2		1			
3		1			
4		1			
5		1			
6		1			
7		1			
8		1			
9		1			
10		1			
11		1			
12		1			
13		1			
14		1			
15		1			
16		1			
17		1			
18		1			
19		- 1			
20		4			
21		1			
22		1			
23		1			

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge



ESTEEM PERFORMANCE PTE LTD

Bik 5033 Ang Mo Klo, Ind Park 2 #01-251/ 259, 569536. Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No.	SLK 3415 S	Submit By	7	:	Carmen Lim
Venicle No.	0.00				2016
Victor & Model	TOYOTA PRILIS	Year of Manufactur	LB :		2010

/No	Labour Description	Esimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT		
	REPAIR AREA. (REAR BUMPER, TAILDOOR, END PANEL,	-	7
	SPARE TYRE WELL PANEL, TAILDOOR SPOILER)	\$1,400.00	7001
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT		
	REPAIR AREA. (REAR BUMPER, TAILDOOR, END PANEL,		00
	SPARE TYRE WELL PANEL, TAILDOOR SPOILER)	\$1,200.00	8801
3	To check wiring	\$50.00	201
4	To remove & refit spare tyre, spare tyre board, carpet trim		
	to assist work load.	\$150.00	601
5	To remove & refit rear windscreen.	\$120.00	~
6	To tuff coat.	\$150.00	601
7	To transfer boot mechanism to new boot	\$120.00	601
8	To remove & refit Taildoor glass to assist work load	\$120.00	801
9	To remove & refit reverse sensor	\$120.00	501
10	To conduct water leakage tests to ensure proper air and	\$120.00	201
10	sealing		

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary,