

ASS. REC. BY:

REF:

CS/FC119011890/Ked3n2

Special Instructions:

Surveyor: KennethASSIGNMENT (Office)From (Person): Henry Kao of FCI Date/Time: 4/7/2019

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHC 5695BInsured: SHB 3029Tat Workshop m/s Prane-cabTel: 62876666of No. 2 AMK ST 83

Policy No: _____

Claim No: D19004379MFSH

Sum Insured: _____

Excess: _____

Make of Veh: _____

(Client's Record)

D.O.A. 2/7/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: _____

Date/Time: _____

Person Contacted: _____

Vehicle IN / OUT

Date/Time Action/Instruction (✓) Estimate

SHC 5695B-X

SHB 3029T-X

10/07/19 @ 17:05 pm revised PA to Henry Kao via email.

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SHC 5695B

at Workshop in/s: Trans-cab

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 14 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHC 5695B

yr Regn: 11 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Perault Lotus c.c. 1995

Colour: M. White / Red A/C: Insured / Std / NI / NA

Sp. Reading: 523682 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: V1-1ABCL15AUC 280280

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60R16
R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Giti

Front

Rear

R/Bal. 8 mm R/Bal. 9 mm

L/Bal. 8 mm L/Bal. 9 mm

D.O.A. 2/7/19 D.O.L. 5/7/19

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S & 1st

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>CLIP 813,800</u> <u>(5125, 218 73 Red - 90%)</u> <u>Book Value : \$ 44,997.50</u> <u>LTA : \$ 31,191.00</u> <u>Nett : \$ 13,806.50</u>
RECEIVED 05 SEP 2019	

Date/Time, File Pass by?

05/09/19

Date/Time, File Return to?

Typ. 7

☐ : Preli. Report

☒ : Final Report

Days Of Repair: 14

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

13 + RS. 51

Notes:

Other:

Other:

Other:

Add Fee: ☐ : Site Insp. (\$)

☐ : Interview (\$)

☐ : Tech. Insp. (\$)

☐ : Other (\$)

Report Form 1

Comp. No. 13.800/ 215

350



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19004379MFSH

Date: 10 July 2019

Our Ref: CS/FCI19011890/Ksd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SHC 5695B

Please be informed that we had conducted the inspection of the abovementioned vehicle on 05/07/2019 at the premises of M/s Trans-Cab Auto Services Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$ <u>139,018.73</u>
Revised Estimate Amount	: S\$ <u>28,136.17</u>
"Check" Items Amount	: S\$ _____
Total	: S\$ _____
Market Value	: S\$ _____
LTA Reimbursement Value	: S\$ _____
Nett Value	: S\$ _____

Description of Damage:

The vehicle sustained damages at the rear n/s & front portion.



Comments/ Present Status:

Damages Consistent.

Repair days: 14 days

Yours faithfully,
Kenneth Kong
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	04-07-2019	Our Ref No. D19004379MFSH
Accident Date	02-07-2019	Claim Type. Third Party
Insured Vehicle	SHB3029T	Third Party Vehicle. SHC5695B
Survey Location	NO. 2 ANG MO KIO STREET 63	
Contact Person.	AMANDA TAY	
Contact No.	62876666/ 0	Fax No. 62877764
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TRANS-CAB AUTO SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	HENRY KAO	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

<https://outlook.office.com/mail/inbox/id/AAQkADUxOWNIYmYzLTFhM2QlNDI5Ny05ZWFlLTZlMzA0OTIyM2M5NwAQADWEiBjhmkOdiMsyJDxb0...> 1/2

<BOOK VALUE> SHC5695B DOA 02.07.19 -- AAD1907-044

Ng Wai Yin <waiyin.ng@transcab.com.sg>

Tue 3/9/2019 9:34 AM

To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>

1 attachments (23 KB)

image001.wmz;

Morning Shirley

Refer to our tele-conversation moment ago.

Net Book Value : \$ 44,997.50

Thank You

Best Regards,

Ng Wai Yin

Finance Department

TEL: 6603 1265 Ext.308

***** Please be reminded that all claims correspondence to be send to claims@transcab.com.sg**

TRANS-CAB SERVICES PTE LTD

No. 2 Ang Mo Kio Street 63, Singapore 569111

Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764

Website: www.transcab.com.sg



This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Wednesday, 10 July 2019 5:05 PM
To: 'Henry Kao Cai Jie'; 'CWS Motor Claims'
Cc: SUR
Subject: RE: SURVEY ASSESSMENT - D19004379MFSH/1
Attachments: SHC 5695B - Preli Advise -.pdf

Dear Henry,

Enclosed preliminary revised of vehicle SHC 5695B.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Monday, 8 July 2019 4:21 PM
To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Subject: FW: SURVEY ASSESSMENT - D19004379MFSH/1

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Thursday, 4 July 2019 3:59 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Henry Kao Cai Jie <HenryKao@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19004379MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	3878K

Vehicle Details

Vehicle No.:	SHC5695B
Vehicle to be Exported:	Yes
Intended Deregistration Date:	03 Jul 2019
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2014
Engine No.:	M9R8839C002195
Chassis No.:	VF1ABL15AUC280290
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	28 Nov 2014
First Registration Date:	28 Nov 2014
Transfer Count:	0
Actual ARF Paid:	\$12,498.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Nov 2022
PARF Rebate Amount:	\$9,373.00

Intended COE Rebate Details

COE Expiry Date:	27 Nov 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$51,337.00
COE Rebate Amount:	\$21,818.00
Total Rebate Amount:	\$31,191.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 03 Jul 2019

OK

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5695B**AAD1907-044**

Not Authorised
11 Sep @ 13, 800

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHC 5695B

VF1ABL15AUC280290

RENAULT

LATITUDE

2.7.19

FIRST CAPITAL

28/11/2014

PART

1	1	BUMPER COVER REAR
2	1	BUMPER LOWER REAR
3	1	BUMPER BRACKET CTR REAR
4	1	BUMPER BRACKET SIDE RH REAR
5	1	BUMPER RETAINER RH REAR
6	1	BUMPER REFLECTOR RH
7	1	BUMPER BRACKET SIDE LH REAR
8	1	BUMPER RETAINER LH REAR
9	1	BUMPER REFLECTOR LH
10	1	BUMPER BEAM REAR
11	1	BUMPER BEAM BRACKET LH REAR
12	1	BUMPER BEAM BRACKET RH REAR
13	1	BOOT REAR
14	1	BOOT FINISHER
15	1	BOOT WHEATERSTRIP
16	1	BOOT REFLECTOR LAMP LH
17	1	BOOT REFLECTOR LAMP RH
18	1	BOOT BADGE 'RENAULT'
19	1	BOOT BADGE
20	1	BOOT STRUT LH
21	1	BOOT STRUT RH
22	1	BOOT HINGE LH
23	1	BOOT HINGE RH
24	1	BOOT INNER TRIM
25	1	BOOT SWITCH
26	1	BOOT LOCK
27	1	BOOT LOCK CATCH
28	2	LICENCE PLATE LAMP
29	2	BOOT RUBBER PLUG

LIST

\$	<i>R</i>	1,108.46	✓
\$	<i>Dis/cm</i>	768.84	✓
\$	<i>Dir</i>	113.47	✓
\$	<i>SL</i>	135.97	X
\$	<i>SL</i>	44.99	X
\$	<i>SL</i>	43.61	X
\$	<i>CM</i>	135.97	✓
\$	<i>Dir</i>	44.99	✓
\$	<i>Bo</i>	43.61	✓
\$	<i>R</i>	777.52	✓
\$	<i>R</i>	225.95	✓
\$	<i>R</i>	225.95	X
\$	<i>R</i>	2,872.68	✓
\$	<i>SL</i>	470.06	X
\$	<i>Dis/Ru</i>	323.05	<i>50% in</i>
\$	<i>CM</i>	493.35	✓
\$	<i>SL</i>	493.35	X
\$	<i>ru</i>	225.36	✓
\$	<i>ru</i>	225.36	✓
\$	<i>SL</i>	276.08	X
\$	<i>SL</i>	276.08	X
\$	<i>R</i>	367.84	X
\$	<i>R</i>	367.84	X
\$	<i>Return</i>	586.45	✓
\$	<i>SL</i>	168.13	X
\$	<i>R</i>	202.67	X
\$	<i>R</i>	74.40	X
\$	<i>SL</i>	50.52	X
\$	<i>SL</i>	221.81	X

Trans-cab Auto Services Pte Ltd**AAD1907-044**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5695B

30	1	FENDER PANEL INNER TRIM REAR LH	\$	<i>Deform</i>	671.45	✓
31	1	FENDER PANEL REAR LH	\$	<i>Bu</i>	3,299.13	✓
32	1	WHEELARCH REAR LH	\$	<i>SL</i>	543.47	X
33	1	FENDER PANEL INNER TRIM REAR RH	\$	<i>SL</i>	671.45	X
34	1	FENDER PANEL REAR RH	\$	<i>N</i>	3,299.13	X
35	1	WHEELARCH REAR RH	\$	<i>SL</i>	543.47	X
36	1	WHEEL HOUSING PANEL REAR LH	\$	<i>N</i>	4,682.09	X
37	1	CHASSIS PANEL REAR LH	\$	<i>N</i>	3,766.43	X
38	1	TAILLAMP RH	\$	<i>SL</i>	552.55	X
39	1	TAILLAMP PANEL RH	\$	<i>N</i>	986.70	X
40	1	TAILLAMP LH	\$	<i>CM</i>	552.55	✓
41	1	TAILLAMP PANEL LH	\$	<i>N</i>	986.70	✓
42	1	KNUCKLE ARM REAR LH L70Y	\$	<i>SL</i>	736.67	} X
43	1	BRAKE DISC REAR L70Y	\$	<i>SL</i>	525.91	
44	1	WHEEL HUB NUT L70Y	\$	<i>SL</i>	51.11	
45	1	WHEEL HUB CAP L70Y	\$	<i>SL</i>	57.82	
46	1	ABS SENSOR REAR LH L70Y	\$	<i>SL</i>	255.75	
47	1	REAR AXLE L70Y	\$	<i>SL</i>	4,167.03	
48	1	AXLE ARM LH L70Y	\$	<i>SL</i>	117.22	
49	1	LOWER ARM REAR LH L70Y	\$	<i>SL</i>	905.99	
50	1	ABSORBER REAR	\$	<i>SL</i>	389.75	}
51	1	STABILIZER BAR REAR LH	\$	<i>SL</i>	604.65	
52	1	BRAKE CALIPER REAR LH	\$	<i>SL</i>	1,300.67	}
53	1	OUTER PANEL REAR (End Panel)	\$	<i>N</i>	1,471.77	
54	1	OUTER PANEL REAR (End Panel)TRIM	\$	<i>N</i>	404.56	✓
55	1	SPARE WHEEL PANEL (Luggage Floor Panel)	\$	<i>N</i>	2,189.88	X
56	1	SPARE WHEEL PANEL TRIM	\$	<i>SL</i>	612.21	X
57	1	EXHAUST REAR	\$	<i>N</i>	7,489.05	X
58	1	EXHAUST CAP REAR	\$	<i>N</i>	230.49	<
59	1	FUEL FLAP L70Y	\$	<i>SL</i>	343.57	X
60	1	BUMPER COVER FRT	\$	<i>Bu</i>	1,259.42	✓
61	1	BUMPER SPOILER FRT	\$	<i>SL</i>	181.75	X
62	1	BUMPER ABSORBER FRT	\$	<i>CM</i>	394.68	✓
63	1	BUMPER RETAINER FRT LH	\$	<i>N</i>	151.41	✓
64	1	BUMPER SUPPORT FRT	\$	<i>SL</i>	123.88	X
65	1	BUMPER RETAINER FRT RH	\$	<i>SL</i>	150.77	X
66	1	BUMPER SUPPORT FRT	\$	<i>SL</i>	123.88	<
67	1	BUMPER UNDERTRAY FRT	\$	<i>SL</i>	472.83	X

Trans-cab Auto Services Pte Ltd**AAD1907-044**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5695B

68	1	BUMPER GRILLE LOWER FRT	\$	<i>SL</i>	266.80	X
69	1	BUMPER FOG LAMP GRILLE LH	\$	<i>SL</i>	207.21	X
70	1	BUMPER FOG LAMP GRILLE RH	\$	<i>SL</i>	207.21	X
71	1	BUMPER BEAM FRT	\$	<i>R</i>	914.08	X
72	1	TOW COVER FRT	\$	<i>SL</i>	28.61	X
73	1	RADIATOR GRILLE	\$	<i>CM</i>	1,707.78	✓
74	1	RADIATOR GRILLE BADGE 'RENAULT'	\$	<i>m</i>	225.36	✓
75	1	RADIATOR GRILLE FRAME	\$	<i>CM</i>	1,353.75	✓
76	1	FRAME FULL SUPPORT PANEL	\$	<i>CM</i>	615.90	✓
77	1	FRAME FULL SUPPORT BRACKET	\$	<i>R</i>	89.79	X
78	1	FRONT BRACE PANEL	\$	<i>R</i>	177.22	✓
79	1	HORN	\$	<i>SL</i>	314.17	X
80	1	HORN BRACKET	\$	<i>R</i>	40.45	X
81	1	HEADLAMP LH	\$	<i>CM</i>	1,184.43	✓
82	1	HEADLAMP RH	\$	<i>SL</i>	1,184.43	X
83	1	HEADLAMP PANEL FRT LH	\$	<i>R</i>	152.15	X
84	1	HEADLAMP PANEL FRT RH	\$	<i>R</i>	152.15	X
85	1	BONNET	\$	<i>R</i>	1,941.63	✓
86	1	BONNET INSULATOR	\$	<i>SL</i>	405.73	X
87	1	BONNET STRUT LH	\$	<i>SL</i>	88.61	X
88	1	BONNET STRUT RH	\$	<i>SL</i>	88.61	X
89	1	BONNET HINGE LH	\$	<i>R</i>	348.31	X
90	1	BONNET HINGE RH	\$	<i>R</i>	348.31	X
91	1	BONNET LOCK	\$	<i>R</i>	305.48	✓
92	1	BONNET CABLE	\$	<i>SL</i>	119.19	X
93	1	BONNET CABLE COVER	\$	<i>SL</i>	161.03	X
94	1	BONNET SEAL OUTER	\$	<i>SL</i>	92.36	X
95	1	BONNET SEAL INNER	\$	<i>SL</i>	157.28	X
96	1	FENDER PANEL FRT LH	\$	<i>R</i>	783.83	✓
97	1	WHEELARCH FRT LH	\$	<i>SL</i>	278.84	X
98	1	FENDER BRACKET LOWER LH	\$	<i>SL</i>	15.79	} X
99	1	FENDER INSULATOR LH	\$	<i>SL</i>	130.84	
100	1	FENDER INSULATOR RH	\$	<i>SL</i>	130.84	
101	1	FENDER PANEL FRT RH	\$	<i>R</i>	783.83	
102	1	WHEELARCH FRT RH	\$	<i>SL</i>	278.84	
103	1	FENDER BRACKET LOWER RH	\$	<i>R</i>	15.79	} X
104	1	WIPER RESERVOIR	\$	<i>SL</i>	348.25	
105	1	WIPER RESERVOIR NECK	\$	<i>SL</i>	136.11	

Trans-cab Auto Services Pte Ltd**AAD1907-044**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5695B

106	1	WIPER RESERVOIR MOTOR	\$	270.06
107	1	AIR CLEANER LOWER	\$	271.26
108	1	AIR CLEANER HOSE	\$	76.14
109	1	BASE BATTERY TRAY	\$	363.40
110	1	AIR CLEANER BOX	\$	464.20
111	1	TURBO DUCT	\$	1,027.80
112	1	A/C HEATER VALVE	\$	484.50
113	1	SUBFRAME OUTER FRT	\$	2,652.45
114	1	SUBFRAME BRACKET OUTER LH	\$	92.36
115	1	SUBFRAME BRACKET OUTER RH	\$	92.36
116	1	ENGINE UNDERTRAY	\$	564.98
117	1	A/C CONDENSER	\$	2,020.37
118	1	A/C CONDENSER GARNISH LH UPPER	\$	39.67
119	1	A/C CONDENSER GARNISH RH UPPER	\$	39.67
120	1	A/C CONDENSER GARNISH LH	\$	58.81
121	1	A/C CONDENSER GARNISH RH	\$	59.60
122	1	A/C PIPE CONDENSER TO COMPRESSOR	\$	208.39
123	1	A/C PIPE CONDENSER TO EXPENSION VALVE	\$	658.72
124	1	A/C PIPE COMPRESSOR	\$	334.29
125	1	A/C PIPE	\$	658.72
127	1	A/C COMRPRESSOR	\$	2,684.61
128	1	AIR COOLER	\$	792.60
129	1	AIR INTERCOOLER HOSE (LONG)	\$	1,014.13
130	1	AIR INTERCOOLER HOSE (Short)	\$	375.14
131	1	TRANSMISSION COOLER	\$	1,219.30
132	1	TRANSMISSION COOLER PAD	\$	17.96
133	1	RADIATOR	\$	1,202.20
134	2	RADIATOR STUD UPPER	\$	14.41
135	2	RADIATOR BUSH UPPER	\$	50.12
136	2	RADIATOR MTG LOWER	\$	55.85
137	1	RADIATOR FAN COWLING	\$	820.54
138	1	RADIATOR FAN MOTOR LH	\$	967.36
139	1	RADIATOR FAN MOTOR RH	\$	1,479.46
140	1	RADIATOR TANK	\$	324.62
141	1	RADIATOR HOSE UPPER	\$	240.56
142	1	RADIATOR HOSE LOWER	\$	491.18
143	1	RADIATOR TANK HOSE	\$	61.18
144	1	AUTO COMPUTER	\$	5,032.17

Per
X

Trans-cab Auto Services Pte Ltd**AAD1907-044**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5695B

145	1	INJECTION COMPUTER	\$	Sn	4,706.30	X
146	1	RHD HYDRAULIC POWER(RQCK&PINION)	\$	Sn	5,154.52	X
147	1	STEERING PUMP ELECTRIC L70Y	\$	Sn	2,306.90	X
148	1	STEERING PINION RACK L70Y	\$	Sn	4,413.11	✓
149	1	DOOR PANEL REAR LH	\$	N	2,844.66	X

TOTAL	\$	119,119.82
10%	\$	11,911.98
	\$	107,207.84

Special Nett

1	1SET	PARKING AID	\$	Shor	700.00	4000
2	1SET	REAR BUMPER CLIP	\$	N	66.00	—
3	1SET	BUMPER BRACKET CTR CLIP	\$	N	33.00	—
4	1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	N	10.00	X
5	1SET	BUMPER RETAINER RH CLIP RR	\$	N	20.00	X
6	1SET	BUMPER BRACKET SIDE CLIP LH RR	\$	N	10.00	X
7	1SET	BUMPER RETAINER CLIP LH RR	\$	N	20.00	X
8	1SET	BUMPER LOWER REAR RIVET	\$	N	22.00	X
9	1SET	BUMPER LOWER REAR CLIP	\$	N	66.00	✓
10	1	EXHAUST MOUNTING REAR	\$	Sn	17.82	X
11	1SET	BOOT FINISHER CLIP	\$	N	24.20	X
12	1	BOOT INNER TRIM CLIP	\$	N	45.00	✓
13	1SET	FENDER WHEELARCH REAR RH CLIP	\$	N	35.00	X
14	1SET	FENDER WHEELARCH REAR LH CLIP	\$	N	35.00	X
15	1	FENDER INNER TRIM CLIP LH	\$	N	28.00	X
16	1	FENDER INNER TRIM CLIP RH	\$	N	28.00	X
17	1	TAILLAMP CLIP RH	\$	N	5.00	X
18	1	TAILLAMP CLIP LH	\$	N	5.00	✓
19	2	REAR WINDSCREEN SEALANT	\$	N	80.00	4000
20	1	WINDSCREEN MOULDING	\$	N	100.00	—
21	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	N	100.00	3000
22	1	SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	Sn	385.00	X
23	1	SPARE TYRE	\$	Sn	330.00	X
24	1SET	RADIATOR GRILLE FRAME CLIP	\$	N	52.00	X
25	1SET	BUMPER CLIP FRT	\$	N	66.00	✓
26	1	BUMPER BRACKET CLIP FRT LH	\$	N	12.00	X
27	1	BUMPER SUPPORT CLIP FRT LH	\$	N	10.50	X

Trans-cab Auto Services Pte Ltd

AAD1907-044

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5695B

28	1	BUMPER BRACKET CLIP FRT RH	\$	nn	12.00	X
29	1	BUMPER SUPPORT CLIP FRT RH	\$	nn	10.50	X
30	1SET	RADIATOR GRILLE SCREW	\$	nn	16.00	X
31	1SET	BUMPER GRILLE LOWER CLIP	\$	nn	69.00	X
32	1SET	FRAME FULL SUPPORT PANEL CLIP	\$	nn	70.00	X
33	2	FRAME FULL SUPPORT PANEL NUT	\$	nn	20.00	X
34	2	FRAME FULL SUPPORT PANEL STUD	\$	nn	30.00	X
35	1	Windscreen moulding	\$	nn	100.00	X
36	1	FRONT WINDSCREEN SEALANT	\$	nn	253.80	X
37	1	FRONT WINDSCREEN INNER SPONGE SEAL	\$	nn	100.00	X
38	1SET	Front licence plate with holder	\$	nn	80.00	X
39	1	WHEELARCH CLIP FRT LH	\$	nn	30.50	X
40	1	WHEELARCH CLIP FRT RH	\$	nn	30.50	
41	2	BONNET STRUT L70Y	\$	nn	88.61	
42	6	BONNET INSULATOR CLIP L70Y	\$	nn	7.30	
43	2	BONNET CABLE COVER SCREW L70Y	\$	nn	10.85	
44	2	BONNET CABLE CLIP L70Y	\$	nn	6.31	
45	1	REAR LH DOOR STICKER '6555-3333'	\$	nn	80.00	X
46	1	REAR LEFT TYRE	\$	nn	300.00	
47	1	REAR LEFT TYRE RIM	\$	nn	380.00	
48	1	BOOT STICKER "Trans-cab"	\$	nn	30.00	✓
49	1	BOOT STICKER "6555-3333"	\$	nn	30.00	✓
50	1	FRONT LEFT TYRE	\$	nn	300.00	X
51	1	FRONT LEFT TYRE RIM	\$	nn	380.00	X

TOTAL	\$	4,740.90
--------------	-----------	-----------------

TOTAL PARTS	\$	111,948.73
--------------------	-----------	-------------------

LABOUR

Putty And Spray Painting Of The Affected Portion.	\$	9,000.00	17601
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	9,000.00	18001
To Rust-Proofing Of The Affected Areas.	\$	170.00	1501
To reinstall rear bumper parking sensor.	\$	170.00	601

Trans-cab Auto Services Pte Ltd**AAD1907-044**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No.: 6287 6666 Fax No.: 6257 1330

CO./GST Reg. No. 201019626G

SHC 5695B

To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00	X
To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing.	\$	380.00	601
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00	X
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	601
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	801
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00	1201
To supply and re-do rear luggage floor panel insulation padding.	\$	380.00	X
To vacuum, replace, retix and recharge air condenser	\$	380.00	1001
To Check Electrical Lighting Concerned.	\$	170.00	401
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00	2501
Towing Fees	\$	150.00	501
To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas.	\$	380.00	X
To repair and realign rear exhaust pipe.	\$	170.00	X
To check steering geometry and computer wheel alignment	\$	220.00	X

Trans-cab Auto Services Pte Ltd**AAD1907-044**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5695B

To apply paint protection system (PPS) maintain and enhancement	\$	na	380.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	na	380.00	X
To replace, refix and top up coolant for radiator.	\$		170.00	501
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	na	340.00	X
To transfer of front bumper fittings, attachment and perform water seepage test.	\$	na	180.00	X
To transfer of front bonnet fittings, attachment and perform water seepage test.	\$	na	180.00	X
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	na	180.00	X
To transfer of front windscreen fittings and conduct water seepage test.	\$	na	170.00	X
To transfer of tire, rim and on wheel balancing.	\$	na	170.00	X
To Transfer Of Rear Fender Fittings, Attachments And Perform Water Seepage Test.	\$	na	340.00	X
To vacuum, replace, refix and recharge Air Intercooler	\$	na	170.00	X
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	Repaired	380.00	X
To check ABS and brake efficiency, final checking and testing.	\$	na	380.00	X

Trans-cab Auto Services Pte Ltd**AAD1907-044**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5695B

To dismantle and refit rear undercarriage parts, final checking and testing. \$ *~* 380.00 X

To dismantle and refit rear axle housing assy, remove and renewal of parts, final checking and testing. \$ 380.00 X

To transfer of rear door fittings, attachment and perform water seepage test. \$ 170.00 X

To remove and renew power steering pump, oil cooler pipe and final checking and testing. \$ 440.00 X

To remove and refit air bag system and reset vehicle warning indicators. \$ 480.00 X

TOTAL \$ 27,070.00**Over All Total \$ 139,018.73****Repair Days (LUMP SUM)****30 DAYS***14 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19011890/Ksd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 06-09-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 3029T	Veh. Inspected	SHC 5695B	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19004379MFSH	Excess (\$)	0.00	
Assign From	HENRY KAO	Assign Date	04/07/2019	
2. Vehicle Particulars & Condition				
Make & Model	RENAULT LATITUDE (A)	c.c	1995	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	VF1ABL15AUC280290	Colour	METALLIC WHITE / RED	
Odometer	523662	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	GITI	8 mm	
L/H Front Tyre	215/60 R16	GITI	8 mm	
R/H Rear Tyre	215/60 R16	GITI	9 mm	
L/H Rear Tyre	215/60 R16	GITI	9 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S AND FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	02/07/2019	Inspection Date	05/07/2019	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		14 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 10

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 5695B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BUMPER COVER REAR	BENT	1,108.46	1,108.46
1	BUMPER LOWER REAR	DISTORTED / CRACKED	768.84	768.84
1	BUMPER BRACKET CTR REAR	DISTORTED	113.47	113.47
1	BUMPER BRACKET SIDE RH REAR	SERVICEABLE	135.97	-
1	BUMPER RETAINER RH REAR	SERVICEABLE	44.99	-
1	BUMPER REFLECTOR RH	SERVICEABLE	43.61	-
1	BUMPER BRACKET SIDE LH REAR	CRACKED	135.97	135.97
1	BUMPER RETAINER LH REAR	DISTORTED	44.99	44.99
1	BUMPER REFLECTOR LH	BROKEN	43.61	43.61
1	BUMPER BEAM REAR	BENT	777.52	777.52
1	BUMPER BEAM BRACKET LH REAR	BENT	225.95	225.95
1	BUMPER BEAM BRACKET RH REAR	TO REPAIR SEE LABOUR	225.95	-
1	BOOT REAR	BENT	2,872.68	2,872.68
1	BOOT FINISHER	SERVICEABLE	470.06	-
1	BOOT REFLECTOR LAMP LH	CRACKED	493.35	493.35
1	BOOT REFLECTOR LAMP RH	SERVICEABLE	493.35	-
1	BOOT BADGE "RENAULT"	NECESSARY	225.36	225.36
1	BOOT BADGE	NECESSARY	225.36	225.36
1	BOOT STRUT LH	SERVICEABLE	276.08	-
1	BOOT STRUT RH	SERVICEABLE	276.08	-
1	BOOT HINGE LH	TO REPAIR SEE LABOUR	367.84	-
1	BOOT HINGE RH	TO REPAIR SEE LABOUR	367.84	-
1	BOOT INNER TRIM	DEFORMED	586.45	586.45
1	BOOT SWITCH	SERVICEABLE	168.13	-
1	BOOT LOCK	TO REPAIR SEE LABOUR	202.67	-
1	BOOT LOCK CATCH	TO REPAIR SEE LABOUR	74.40	-
2	LICENCE PLATE LAMP	SERVICEABLE	50.52	-

Report Ref No. CS/FC119011890/Ksd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 10

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	BOOT RUBBER PLUG	SERVICEABLE	221.81	-
1	FENDER PANEL INNER TRIM REAR LH	DEFORMED	671.45	671.45
1	FENDER PANEL REAR LH	BUCKLED	3,299.13	3,299.13
1	WHEELARCH REAR LH	SERVICEABLE	543.47	-
1	FENDER PANEL INNER TRIM REAR RH	SERVICEABLE	671.45	-
1	FENDER PANEL REAR RH	TO REPAIR SEE LABOUR	3,299.13	-
1	WHEELARCH REAR RH	SERVICEABLE	543.47	-
1	WHEEL HOUSING PANEL REAR LH	TO REPAIR SEE LABOUR	4,682.09	-
1	CHASSIS PANEL REAR LH	TO REPAIR SEE LABOUR	3,766.43	-
1	TAILLAMP RH	SERVICEABLE	552.55	-
1	TAILLAMP PANEL RH	TO REPAIR SEE LABOUR	986.70	-
1	TAILLAMP LH	CRACKED	552.55	552.55
1	TAILLAMP PANEL LH	BENT	986.70	986.70
1	KNUCKLE ARM REAR LH L70Y	SERVICEABLE	736.67	-
1	BRAKE DISC REAR L70Y	SERVICEABLE	525.91	-
1	WHEEL HUB NUT L70Y	SERVICEABLE	51.11	-
1	WHEEL HUB CAP L70Y	SERVICEABLE	57.82	-
1	ABS SENSOR REAR LH L70Y	SERVICEABLE	255.75	-
1	REAR AXLE L70Y	SERVICEABLE	4,167.03	-
1	AXLE ARM LH L70Y	SERVICEABLE	117.22	-
1	LOWER ARM REAR LH L70Y	SERVICEABLE	905.99	-
1	ABSORBER REAR	SERVICEABLE	389.75	-
1	STABILIZER BAR REAR LH	SERVICEABLE	604.65	-
1	BRAKE CALIPER REAR LH	SERVICEABLE	1,300.67	-
1	OUTER PANEL REAR (END PANEL)	BENT	1,471.77	1,471.77
1	OUTER PANEL REAR (END PANEL) TRIM	DENTED	404.56	404.56
1	SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL)	TO REPAIR SEE LABOUR	2,189.88	-
1	SPARE WHEEL PANEL TRIM	SERVICEABLE	612.21	-
1	EXHAUST REAR	TO REPAIR SEE LABOUR	7,489.05	-

Report Ref No. CS/FCI19011890/Ksd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 10

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	EXHAUST CAP REAR	TO REPAIR SEE LABOUR	230.49	-
1	FUEL FLAP L70Y	SERVICEABLE	343.57	-
1	BUMPER COVER FRT	BUCKLED	1,259.42	1,259.42
1	BUMPER SPOILER FRT	SERVICEABLE	181.75	-
1	BUMPER ABSORBER FRT	CRACKED	394.68	394.68
1	BUMPER RETAINER FRT LH	DISTORTED	151.41	151.41
1	BUMPER SUPPORT FRT	SERVICEABLE	123.88	-
1	BUMPER RETAINER FRT RH	SERVICEABLE	150.77	-
1	BUMPER SUPPORT FRT	SERVICEABLE	123.88	-
1	BUMPER UNDERTRAY FRT	SERVICEABLE	472.83	-
1	BUMPER GRILLE LOWER FRT	SERVICEABLE	266.80	-
1	BUMPER FOG LAMP GRILLE LH	SERVICEABLE	207.21	-
1	BUMPER FOG LAMP GRILLE RH	SERVICEABLE	207.21	-
1	BUMPER BEAM FRT	TO REPAIR SEE LABOUR	914.08	-
1	TOW COVER FRT	SERVICEABLE	28.61	-
1	RADIATOR GRILLE	CRACKED	1,707.78	1,707.78
1	RADIATOR GRILLE BADGE "RENAULT"	NECESSARY	225.36	225.36
1	RADIATOR GRILLE FRAME	CRACKED	1,353.75	1,353.75
1	FRAME FULL SUPPORT PANEL	CRACKED	615.90	615.90
1	FRAME FULL SUPPORT BRACKET	TO REPAIR SEE LABOUR	89.79	-
1	FRONT BRACE PANEL	TO REPAIR SEE LABOUR	177.22	-
1	HORN	SERVICEABLE	314.17	-
1	HORN BRACKET	TO REPAIR SEE LABOUR	40.45	-
1	HEADLAMP LH	CRACKED	1,184.43	1,184.43
1	HEADLAMP RH	SERVICEABLE	1,184.43	-
1	HEADLAMP PANEL FRT LH	TO REPAIR SEE LABOUR	152.15	-
1	HEADLAMP PANEL FRT RH	TO REPAIR SEE LABOUR	152.15	-
1	BONNET	BENT	1,941.63	1,941.63

Report Ref No. CS/FCI19011890/Ksd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 10

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BONNET INSULATOR	SERVICEABLE	405.73	-
1	BONNET STRUT LH	SERVICEABLE	88.61	-
1	BONNET STRUT RH	SERVICEABLE	88.61	-
1	BONNET HINGE LH	TO REPAIR SEE LABOUR	348.31	-
1	BONNET HINGE RH	TO REPAIR SEE LABOUR	348.31	-
1	BONNET LOCK	BENT	305.48	305.48
1	BONNET CABLE	SERVICEABLE	119.19	-
1	BONNET CABLE COVER	SERVICEABLE	161.03	-
1	BONNET SEAL OUTER	SERVICEABLE	92.36	-
1	BONNET SEAL INNER	SERVICEABLE	157.28	-
1	FENDER PANEL FRT LH	BENT	783.83	783.83
1	WHEELARCH FRT LH	SERVICEABLE	278.84	-
1	FENDER BRACKET LOWER LH	SERVICEABLE	15.79	-
1	FENDER INSULATOR LH	SERVICEABLE	130.84	-
1	FENDER INSULATOR RH	SERVICEABLE	130.84	-
1	FENDER PANEL FRT RH	TO REPAIR SEE LABOUR	783.83	-
1	WHEELARCH FRT RH	SERVICEABLE	278.84	-
1	FENDER BRACKET LOWER RH	TO REPAIR SEE LABOUR	15.79	-
1	WIPER RESERVOIR	SERVICEABLE	348.25	-
1	WIPER RESERVOIR NECK	SERVICEABLE	136.11	-
1	WIPER RESERVOIR MOTOR	SERVICEABLE	270.06	-
1	AIR CLEANER LOWER	SERVICEABLE	271.26	-
1	AIR CLEANER HOSE	SERVICEABLE	76.14	-
1	BASE BATTERY TRAY	SERVICEABLE	363.40	-
1	AIR CLEANER BOX	SERVICEABLE	464.20	-
1	TURBO DUCT	SERVICEABLE	1,027.80	-
1	A/C HEATER VALVE	SERVICEABLE	484.50	-
1	SUBFRAME OUTER FRT	SERVICEABLE	2,652.45	-
1	SUBFRAME BRACKET OUTER LH	SERVICEABLE	92.36	-
1	SUBFRAME BRACKET OUTER RH	SERVICEABLE	92.36	-

Report Ref No. CS/FCI19011890/Ksd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 10

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	ENGINE UNDERTRAY	SERVICEABLE	564.98	-
1	A/C CONDENSER	SERVICEABLE	2,020.37	-
1	A/C CONDENSER GARNISH LH UPPER	SERVICEABLE	39.67	-
1	A/C CONDENSER GARNISH RH UPPER	SERVICEABLE	39.67	-
1	A/C CONDENSER GARNISH LH	SERVICEABLE	58.81	-
1	A/C CONDENSER GARNISH RH	SERVICEABLE	59.60	-
1	A/C PIPE CONDENSER TO COMPRESSOR	SERVICEABLE	208.39	-
1	A/C PIPE CONDENSER TO EXPENSION VALVE	SERVICEABLE	658.72	-
1	A/C PIPE COMPRESSOR	SERVICEABLE	334.29	-
1	A/C PIPE	SERVICEABLE	658.72	-
1	A/C COMPRESSOR	SERVICEABLE	2,684.61	-
1	AIR COOLER	SERVICEABLE	792.60	-
1	AIR INTERCOOLER HOSE (LONG)	SERVICEABLE	1,014.13	-
1	AIR INTERCOOLER HOSE (SHORT)	SERVICEABLE	375.14	-
1	TRANSMISSION COOLER	SERVICEABLE	1,219.30	-
1	TRANSMISSION COOLER PAD	SERVICEABLE	17.96	-
1	RADIATOR	SERVICEABLE	1,202.20	-
2	RADIATOR STUD UPPER	SERVICEABLE	14.41	-
2	RADIATOR BUSHD UPPER	SERVICEABLE	50.12	-
2	RADIATOR MTG LOWER	SERVICEABLE	55.85	-
1	RADIATOR FAN COWLING	SERVICEABLE	820.54	-
1	RADIATOR FAN MOTOR LH	SERVICEABLE	967.36	-
1	RADIATOR FAN MOTOR RH	SERVICEABLE	1,479.46	-
1	RADIATOR TANK	SERVICEABLE	324.62	-
1	RADIATOR HOSE UPPER	SERVICEABLE	240.56	-
1	RADIATOR HOSE LOWER	SERVICEABLE	491.18	-
1	RADIATOR TANK HOSE	SERVICEABLE	61.18	-
1	AUTO COMPUTER	SERVICEABLE	5,032.17	-
1	INJECTION COMPUTER	SERVICEABLE	4,706.30	-
1	RHD HYDRAULIC POWER (RACK & PINION)	SERVICEABLE	5,154.52	-
1	STEERING PUMP ELECTRIC L70Y	SERVICEABLE	2,306.90	-
1	STEERING PINION RACK L70Y	SERVICEABLE	4,413.11	-

Report Ref No. CS/FCI19011890/Ksd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:6 of 10

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	DOOR PANEL REAR LH	TO REPAIR SEE LABOUR	2,844.66	-
	LESS 10% DISCOUNT		-11,879.68	-2,493.18
			106,917.09	22,438.66
1	BOOT WEATHERSTRIP (50%)(SN)	DISTORTED / DENTED	323.05	161.52
	LESS 10% DISCOUNT		-32.31	-
			290.74	161.52
SPECIAL NETT ITEMS				
1	SET PARKING AID (SN)	SHORTED	700.00	400.00
1	SET REAR BUMPER CLIP (SN)	NECESSARY	66.00	66.00
1	SET BUMPER BRACKET CTR CLIP (SN)	NECESSARY	33.00	33.00
1	SET BUMPER BRACKET SIDE CLIP RH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER RH CLIP RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER BRACKET SIDE CLIP LH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER CLIP LH RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER LOWER REAR RIVET (SN)	NOT NECESSARY	22.00	-
1	SET BUMPER LOWER REAR CLIP (SN)	NECESSARY	66.00	66.00
1	EXHAUST MOUNTING REAR (SN)	SERVICEABLE	17.82	-
1	SET BOOT FINISHER CLIP (SN)	NOT NECESSARY	24.20	-
1	BOOT INNER TRIM CLIP (SN)	NECESSARY	45.00	45.00
1	SET FENDER WHEELARCH REAR RH CLIP (SN)	NOT NECESSARY	35.00	-
1	SET FENDER WHEELARCH REAR LH CLIP (SN)	NOT NECESSARY	35.00	-
1	FENDER INNER TRIM CLIP LH (SN)	NOT NECESSARY	28.00	-
1	FENDER INNER TRIM CLIP RH (SN)	NOT NECESSARY	28.00	-
1	TAILLAMP CLIP RH (SN)	NOT NECESSARY	5.00	-
1	TAILLAMP CLIP LH (SN)	NECESSARY	5.00	5.00
2	REAR WINDSCREEN SEALANT (SN)	NECESSARY	80.00	40.00
1	WINDSCREEN MOULDING (SN)	NECESSARY	100.00	100.00
1	REAR WINDSCREEN INNER SPONGE SEAL (SN)	NECESSARY	100.00	30.00
1	SPARE TYRE RIM (ROUE 7J 16H 2547)(SN)	SERVICEABLE	385.00	-
1	SPARE TYRE (SN)	SERVICEABLE	330.00	-

Report Ref No. CS/FCI19011890/Ksd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:7 of 10

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET RADIATOR GRILLE FRAME CLIP (SN)	NOT NECESSARY	52.00	-
1	SET BUMPER CLIP FRT (SN)	NECESSARY	66.00	66.00
1	BUMPER BRACKET CLIP FRT LH (SN)	NOT NECESSARY	12.00	-
1	BUMPER SUPPORT CLIP FRT LH (SN)	NOT NECESSARY	10.50	-
1	BUMPER BRACKET CLIP FRT RH (SN)	NOT NECESSARY	12.00	-
1	BUMPER SUPPORT CLIP FRT RH (SN)	NOT NECESSARY	10.50	-
1	SET RADIATOR GRILLE SCREW (SN)	NOT NECESSARY	16.00	-
1	SET BUMPER GRILLE LOWER CLIP (SN)	NOT NECESSARY	69.00	-
1	SET FRAME FULL SUPPORT PANEL CLIP (SN)	NOT NECESSARY	70.00	-
2	FRAME FULL SUPPORT PANEL NUT (SN)	NOT NECESSARY	20.00	-
2	FRAME FULL SUPPORT PANEL STUD (SN)	NOT NECESSARY	30.00	-
1	WINDSCREEN MOULDING (SN)	REPEATED	100.00	-
1	FRONT WINDSCREEN SEALANT (SN)	NOT NECESSARY	253.80	-
1	FRONT WINDSCREEN INNER SPONGE SEAL (SN)	NOT NECESSARY	100.00	-
1	SET FRONT LICENCE PLATE WITH HOLDER (SN)	BENT	80.00	45.00
1	WHEELARCH CLIP FRT LH (SN)	NOT NECESSARY	30.50	-
1	WHEELARCH CLIP FRT RH (SN)	NOT NECESSARY	30.50	-
2	BONNET STRUT L70Y (SN)	SERVICEABLE	88.61	-
6	BONNET INSULATOR CLIP L70Y (SN)	NOT NECESSARY	7.30	-
2	BONNET CABLE COVER SCREW L70Y (SN)	SERVICEABLE	10.85	-
2	BONNET CABLE CLIP L70Y (SN)	NOT NECESSARY	6.31	-
1	REAR LH DOOR STICKER "6555-3333" (SN)	NOT NECESSARY	80.00	-
1	REAR LEFT TYRE (SN)	SERVICEABLE	300.00	-
1	REAR LEFT TYRE RIM (SN)	SERVICEABLE	380.00	-
1	BOOT STICKER "TRANS-CAB" (SN)	NECESSARY	30.00	30.00
1	BOOT STICKER "6555-3333" (SN)	NECESSARY	30.00	30.00
1	FRONT LEFT TYRE (SN)	SERVICEABLE	300.00	-
1	FRONT LEFT TYRE RIM (SN)	SERVICEABLE	380.00	-
			4,740.89	956.00
	LABOUR			
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		9,000.00	1,760.00

Report Ref No. CS/FCI19011890/Ksd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:8 of 10

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME. }		9,000.00	1,800.00
	INCLUSIVE OF THE REPAIR OF BUMPER BEAM BRACKET RH REAR,BOOT HINGE LH,BOOT HINGE RH,BOOT LOCK,BOOT LOCK CATCH,FENDER PANEL REAR RH,WHEEL HOUSING PANEL REAR LH,CHASSIS PANEL REAR LH,TAILLAMP PANEL RH,SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL),EXHAUST REAR,EXHAUST CAP REAR,BUMPER BEAM FRT,FRAME FULL SUPPORT BRACKET,FRONT BRACE PANEL,HORN BRACKET,HEADLAMP PANEL FRT LH,HEADLAMP PANEL FRT RH,BONNET HINGE LH,BONNET HINGE RH,FENDER PANEL FRT RH,FENDER BRACKET LOWER RH AND DOOR PANEL REAR LH. }		-	-
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	150.00
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	60.00
	TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO DROP DIESEL TANK,PIPES,HOSES TO FACILITATE BODYWORK REPAIR,FINAL CHECKING AND TESTING.		380.00	60.00
	TO DROP REAR EXHAUST BOX,RENEW THE SAME,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TO TRANSFER OF BOOTLID FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.		170.00	60.00
	TO TRANSFER OF REAR END PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.		170.00	80.00
	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.		170.00	120.00
	TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING.	NOT NECESSARY	380.00	-
	TO VACUUM,REPLACE,REFIX AND RECHARGE AIR CONDENSER.		380.00	100.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	40.00
	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH,TO FACILITATE REPAIR.		380.00	250.00
	TOWING FEES.		150.00	50.00
	TO DISMANTLE AND REFIT AIRCON ASSY AND ATTACHMENT,VACUUM AND CHARGE-IN-GAS.	NOT NECESSARY	380.00	-

Report Ref No. CS/FCI19011890/Ksd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:9 of 10

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REPAIR AND REALIGN REAR EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO APPLY PAINT PROTECTION SYSTEM (PPS) MAINTAIN AND ENHANCEMENT.	NOT NECESSARY	380.00	-
	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	TO REPLACE,REFIX AND TOP UP COOLANT FOR RADIATOR.		170.00	50.00
	TO TRANSFER OF FENDER FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	340.00	-
	TO TRANSFER OF FRONT BUMPER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	180.00	-
	TO TRANSFER OF FRONT BONNET FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	180.00	-
	TO TRANSFER OF REAR BUMPER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	180.00	-
	TO TRANSFER OF FRONT WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR FENDER FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	340.00	-
	TO VACUUM,REPLACE,REFIX AND RECHARGE AIR INTERCOOLER.	NOT NECESSARY	170.00	-
	TO PULL AND JACK OUT CHASSIS FRAME AND CORRECT IT TO SYMMETRICAL POSITION WITH THE AID OF HYDRAULIC PNEUMATIC JACK.	REPEATED	380.00	-
	TO CHECK ABS AND BRAKE EFFICIENCY,FINAL CHECKING AND TESTING.	NOT NECESSARY	380.00	-
	TO DISMANTLE AND REFIT REAR UNDERCARRIAGE PARTS,FINAL CHECKING AND TESTING.	NOT NECESSARY	380.00	-
	TO DISMANTLE AND REFIT REAR AXLE HOUSING ASSY,REMOVE AND RENEWAL OF PARTS,FINAL CHECKING AND TESTING.	NOT NECESSARY	380.00	-

Report Ref No. CS/FCI19011890/Ksd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:10 of 10

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO TRANSFER OF REAR DOOR FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO REMOVE AND RENEW POWER STEERING PUMP, OIL COOLER PIPE AND FINAL CHECKING AND TESTING.	NOT NECESSARY	440.00	-
	TO REMOVE AND REFIT AIR BAG SYSTEM AND RESET VEHICLE WARNING INDICATORS.	NOT NECESSARY	480.00	-
			27,070.00	4,580.00
GRAND TOTAL			139,018.72	28,136.18
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				13,800.00

Report Ref No. CS/FCI19011890/Ksd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.