

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19011912/KPA3Q2

Date: 22/04/2020

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D19MCV0001044
Claimant Vehicle No :	GBH8308U	Insured Vehicle No :	GBE6548Y
Date of Loss:	28/05/2019	Nature of Claim:	TP
		Claim No:	MCV2019D0000646

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBH8308U	Engine No:	1KD2823503
Make & Model:	TOYOTA DYNA 150, 3.0 D 5MT (M)	Chassis No:	JTFAT35Y50K211525
Reg. Date:	11/10/2018 (Man. Year: 2018)	Odometer:	2595 km
Colour:	Silver		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/75 R15	Rear Tyre Size:	155 R12X8 (D)
Front Left Side:	Bridgestone 9 mm	Rear Left Side:	Bridgestone 9/9 mm
Front Right Side:	Bridgestone 9 mm	Rear Right Side:	Bridgestone 9/9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,358.87	1,048.85	8,310.02	88.79
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,900.00	1,010.00	1,890.00	65.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	12,258.87	2,058.85	10,200.02	83.21
+ Loss of Use (4.0 x S\$80.00/day) (S\$)		320.00		
	Nett Liability (S\$)	2,378.85		

INSPECTION

Date of Assignment:	19/07/2019	
Date Inspected:	19/07/2019	Inspected At:
		Autoworx House - Sin Ming (HQ)
		176 SIN MING DRIVE #02-01
		Singapore 575721
Estimated Period of Repair:	3.0 days	

Adjuster: KENNETH KONG

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 01 Aug 2019)	
Parts:	N/A	TOYOTA DYNA 150 3.0 D 5MT (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBH8308U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT GRILLE	Dented / Cut	564.10 FL	*564.10 FL
2	1		*FRONT BUMPER	Repair	768.90 FL	*- FL
3	2		*FRONT BUMPER BRACKET	Repair	348.40 FL	*- FL
4	1		*FRONT HEAD LAMP ASSY	N/S Mtg Cracked	1,527.40 FL	*645.10 FL
5	1		*FRONT PANEL	Repair	1,264.30 FL	*- FL
6	1		*FRONT PANEL TOP GARNISH (BLACK)	Not Such Part	464.10 FL	*- FL
7	1		*FRONT CORNER PANEL	Repair	264.30 FL	*- FL
8	1		*FRONT CORNER PANEL GARNISH	Serviceable	217.80 FL	*- FL
9	1		*FRONT INNER LOWER PANEL	Repair	574.80 FL	*- FL
10	1		*FRONT TOP INNER PANEL	Repair	465.40 FL	*- FL
11	1		*FRONT WIPER CENTRE PANEL	Repair	745.20 FL	*- FL
12	1		*FRONT WIPER SIDE PANEL	Repair	376.40 FL	*- FL
13	1		*FRONT WINDSCREEN GLASS RUBBER	Not Necessary	198.90 FL	*- FL
14	1		*FRONT EMBLEM LOGO	Scratched	84.20 FL	*84.20 FL
15	1		*FRONT DYNA EMBLEM	Necessary	78.40 FL	*78.40 FL
16	1		*FRONT BRAKE MASTER CYLINDER ASSY	Serviceable	445.60 FL	*- FL
17	1		*FRONT BRAKE BOOSTER	Serviceable	784.20 FL	*- FL
18	1		*AIR CON FAN BLOWER ASSY	Serviceable	1,193.00 FL	*- FL
19	1		*AIR CON COOLING COIL HOUSING ASSY	Serviceable	674.00 FL	*- FL
20	1		*FRONT WIPER MOTOR	Serviceable	954.00 FL	*- FL
21	1		*FRONT WIPER MOTOR LINKAGE	Serviceable	345.10 FL	*- FL
22	1		*NUMBER PLATE	Bent	35.00 FS	*20.00 FS
23	1		*FRONT DOOR LABELLED STICKER	Not Necessary	45.00 FS	*- FS
24	1		*ERP IU BRACKET	Not Necessary	25.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	12,443.50	1,391.80
- List Item Discount on L Items 25.00/25.00% (S\$)	3,084.63	342.95

Total Parts (S\$)	9,358.87	1,048.85
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND REPLACE ALL THE PARTS MENTIONED ABOVE, KNOCKING AND STRAIGHTEN UP THE NECESSARY AFFECTED AREAS.	New	1,200.00	450.00
2	TO CHECK WIRING SYSTEM.	New	50.00	20.00
3	TO REMOVE AND INSTALL AIR-CON COMPONENTS AND TOP UP GAS.	New	220.00	0.00
4	TO SPRAY PAINTING ON AFFECTED AREAS.	New	800.00	540.00
5	TO APPLY RUST PROOFING.	New	150.00	0.00
6	TO REMOVE DASHBOARD TO ENABLE REPAIR.	New	300.00	0.00
7	TO REMOVE CABIN TIMMING TO ENABLE REPAIR.	New	180.00	0.00
Gross Labour Cost (\$\$)			2,900.00	1,010.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >