



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19011916/Kpa3q2

8 SHENTON WAY #24-01  
AXA TOWERSINGAPORE 068811  
ATTN:LYNN

Date : 08-07-2020



Code : ASM

#### 1. Policy Particulars :- THIRD PARTY CLAIM

|                     |           |                       |            |
|---------------------|-----------|-----------------------|------------|
| <b>Insured Veh.</b> | SLV 5424U | <b>Veh. Inspected</b> | SDU 8228A  |
| <b>Policy No.</b>   | P2052632  | <b>Coverage (\$)</b>  | 0.00       |
| <b>Claim No.</b>    | S9M01SY0  | <b>Excess (\$)</b>    | 0.00       |
| <b>Assign From</b>  |           | <b>Assign Date</b>    | 05/07/2019 |

#### 2. Vehicle Particulars & Condition

|                         |                   |                     |                    |
|-------------------------|-------------------|---------------------|--------------------|
| <b>Make &amp; Model</b> | NISSAN ALMERA (A) | <b>c.c</b>          | 1498               |
| <b>Engine No.</b>       | HIDDEN            | <b>Year of Reg.</b> | 2016               |
| <b>Chassis No.</b>      | MNTBBAN17Z0005591 | <b>Colour</b>       | METALLIC RED       |
| <b>Odometer</b>         | 102294            | <b>Steering</b>     | IN ORDER           |
| <b>Brakes</b>           | IN ORDER          | <b>Modification</b> | STANDARD ALLOY RIM |
| <b>General</b>          | GOOD              |                     |                    |

#### 3. Conditions of Tyres

|                       |             |             |                |
|-----------------------|-------------|-------------|----------------|
|                       | <b>Size</b> | <b>Make</b> | <b>Balance</b> |
| <b>R/H Front Tyre</b> | 195/55 R15  | FIRENZA     | 8 mm           |
| <b>L/H Front Tyre</b> | 195/55 R15  | FIRENZA     | 8 mm           |
| <b>R/H Rear Tyre</b>  | 195/55 R15  | HANKOOK     | 7 mm           |
| <b>L/H Rear Tyre</b>  | 195/55 R15  | HANKOOK     | 7 mm           |

#### 4. Description of Damages

|                                                                                |
|--------------------------------------------------------------------------------|
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.<br>DAMAGES SEE DETAILS. |
|--------------------------------------------------------------------------------|

#### 5. General Information

|                       |                                                                                      |                        |            |
|-----------------------|--------------------------------------------------------------------------------------|------------------------|------------|
| <b>Accident Date</b>  | 04/07/2019                                                                           | <b>Inspection Date</b> | 15/07/2019 |
| <b>Survey held at</b> | CHENG HOE MOTOR PL<br>BLK 1019 YISHUN IND. PARK A<br>#01-374/382<br>SINGAPORE 768761 |                        |            |

#### 5a. Remarks

|                                                                                                                                        |
|----------------------------------------------------------------------------------------------------------------------------------------|
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|----------------------------------------------------------------------------------------------------------------------------------------|

#### 5b. Estimate Days of Repair

|                                     |                       |
|-------------------------------------|-----------------------|
| ESTIMATED NORMAL PERIOD FOR REPAIR: | <b>6 Working Days</b> |
|-------------------------------------|-----------------------|