

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLH 6305Y

| Qty | Description of Parts | Condition | Estimate By Workshop (\$)) | Our Adjusted (\$) |
|-----|--|---------------|-------------------------------|----------------------|
| | REPLACEMENT OF PARTS | | | |
| 1 | REAR BUMPER (CONSISTENT) | BUCKLED | 497.50 | 497.50 |
| 10 | REAR BUMPER CLIP (CONSISTENT) | NECESSARY | 40.00 | 40.00 |
| 1 | REAR BUMPER SIDE RETAINER LH (CONSISTENT) | SERVICEABLE | 112.70 | - |
| 1 | REAR BUMPER SIDE RETAINER RH (CONSISTENT) | SERVICEABLE | 112.70 | - |
| 1 | REAR BUMPER REINFORCEMENT (CONSISTENT) | BENT | 398.90 | 398.90 |
| 1 | REAR BUMPER LOWER GARNISH CENTRE (CONSISTENT) | DENTED | 582.60 | 582.60 |
| 1 | REAR BUMPER TOW COVER (CONSISTENT) | MISSING | 31.70 | 31.70 |
| | LESS 25% DISCOUNT | | -444.02 | -387.67 |
| | | | 1,332.08 | 1,163.03 |
| | SPECIAL NETT ITEMS | | | |
| 1 | REVERSE SENSOR (SN) (CONSISTENT) | DENTED | 200.00 | 200.00 |
| | | | 200.00 | 200.00 |
| | LABOUR | | | |
| | TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (REAR BUMPER, TAIL DOOR, END PANEL, FRONT BUMPER) | | 1,000.00 | 200.00 |
| | TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (REAR BUMPER, TAIL DOOR, END PANEL, FRONT BUMPER) | | 1,000.00 | 220.00 |
| | TO CHECK WIRING. | | 50.00 | 10.00 |
| | TO REMOVE & REFIT REVERSE SENSOR. | | 120.00 | 50.00 |
| | TO REMOVE & REFIT SPARE TYRE, SPARE TYRE BOARD, CARPET TRIM TOASSIST WORK LOAD. | NOT NECESSARY | 150.00 | - |
| | TO CONDUCT WATER LEAKAGE TESTS TO ENSURE PROPER AIR AND SEALING. | NOT NECESSARY | 120.00 | - |
| | TO TUFF COAT. | NOT NECESSARY | 150.00 | - |
| | | | - | - |
| | | | - | - |
| | | | - | - |
| | | | 2,590.00 | 480.00 |
| | GRAND TOTAL | | 4,122.08 | 1,843.03 |

Report Ref No. CC4/ASM19011920/Kha3s2





| RECOMMENDED COST OF REPAIRS | | | 1,843.03 |
|-----------------------------|--|--|----------|
|-----------------------------|--|--|----------|

Report Ref No. CC4/ASM19011920/Kha3s2

KONG SENG CHEONG

Licensed Appraiser