



友尼摩多公司 UNIMOTOR COMPANY

一號加基武吉六道一樓門牌九十四號 新加坡郵區四一七八八三
AUTOBAY @ KAKI BUKIT
No. 1 KAKI BUKIT AVE 6 #01-94 SINGAPORE 417883
TELEPHONE: 6748 2795 FAX: 6747 2373
Registration No.: 203165/00D

larger case

Alu 2

*Not Approved
Lian*

5/7/19

*2/s \$6000/
521*

LKK

DATE: 11/07/2019 OUR REF: UAPL1275
REPAIR ESTIMATE TO THE KIA CERATO FORTE NO: SKB3813K

- 1 FRONT BONNET ASSY
- 2 FRONT BONNET HINGES
- 1 FRONT BONNET LOCK
- 1 FRONT L/H HEADLAMP ASSY
- 1 FRONT L/H FENDER ASSY
- 1 FRONT L/H FENDER INNER SHIELD
- 8 FRONT L/H INNER SHIELD CLIPS
- 1 FRONT BUMPER FACE
- 1 FRONT BUMPER REINFORCEMENT
- 2 FRONT BUMPER SIDE RETAINER
- 1 FRONT BUMPER SPONGE
- 1 FRONT BUMPER LOWER SPOILER
- 1 FRONT SUPPORT PANEL
- 1 FRONT RADIATOR GRILLE
- 1 FRONT L/H FOG LAMP
- 8 FRONT BUMPER CLIPS
- 1 FRONT L/H DRIVESHAFT
- 1 FRONT L/H SHOCK ABSORBER
- 1 FRONT L/H LOWER ARM
- 1 FRONT L/H WHEEL HUB
- 1 FRONT L/H WHEEL HUB BEARING
- 1 FRONT L/H KNUCKLE ARM

38.00

<i>Surf/Buc</i>	\$	897.00	✓
<i>ru</i>	\$	168.00	X
<i>11</i>	\$	67.00	X
<i>cu</i>	\$	988.00	✓
<i>Dis</i>	\$	354.00	✓
<i>10.1</i>	\$	154.00	✓
<i>ru</i>	\$	40.00	✓
<i>Dis</i>	\$	617.00	✓
<i>11</i>	\$	378.00	X
<i>115</i>	\$	114.00	✓
<i>cu</i>	\$	115.00	X
<i>cu</i>	\$	887.00	✓
<i>cu</i>	\$	1,012.00	✓
<i>11</i>	\$	311.00	X
<i>cu</i>	\$	210.00	✓
<i>ru</i>	\$	40.00	✓
<i>11</i>	\$	988.00	X
<i>11</i>	\$	445.00	X
<i>11</i>	\$	357.00	X
<i>11</i>	\$	313.00	✓
<i>11</i>	\$	166.00	✓
<i>11</i>	\$	411.00	✓

\$ 9,032.00
\$ 903.20
\$ 8,128.80

*6111
5514.30*

LESS 10%.....

SPECIAL NETT:-

- 1 FRONT L/H SPORT WHEEL *11m*
- 1 FRONT TYRE

<i>Surf</i>	\$	550.00	<i>380 s. n</i>
<i>ru</i>	\$	180.00	X

LABOUR CHARGES:-

TO TOW VEHICLE VEHICLE BACK TO WORKSHOP

\$ 11 80.00 X

TO SPRAY UNDERCOATING IN REPAIR

\$ 100.00 60

TO COMPLETE WHEEL ALIGNMENT (BEFORE/AFTER)

\$ 200.00 100

TO DISM/REWIRE FRONT DAMAGED PORTION *to check wiring*

\$ 120.00 20

TO DISM/RENEW FRONT UNDERCARRIER IN REPAIR

\$ 380.00 120

TO PANEL BEAT DAMAGED PORTION

\$ 1,000.00 600

TO PUTTY AND RESPRAY DAMAGED PORTION

\$ 1,000.00 800

\$ 11,738.80

7554.3

Unimotor Consultants hence notify the following:

- Repair work shall follow after painting
- Repair work shall be subject to confirmation
- The repair work shall be on a "Without Prejudice" basis
- No repair work shall be allowed
- Supplier's warranty must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Stamford Tyres International Pte Ltd

23 Kaki Bukit Road 4

#01-12/13 Synergy@KB

Singapore 417801

Phone Number: 6702 3355

Fax Number: 6341 6993

Customer:			Date: 7/5/2019 11:22 AM			
Company:			VIN			
License NO: SKB3813K			Technician:			
Odometer: 236'219KM			Order NO:			
VEHICLE ALIGNMENT REPORT						
KIA, CERATO, 05-08 (Customized)						
Primary Angles			Initial	Specifications		Final
				Min.	Max.	
Front	Caster	Left	----	2°06'	4°06'	----
		Right	----	2°06'	4°06'	----
	Camber	Left	-0°54'	-0°55'	0°55'	-0°42'
		Right	-1°00'	-0°55'	0°55'	-1°00'
	Toe	Left	-2°09'	-0°08'	0°08'	-3°42'
		Right	-2°09'	-0°08'	0°08'	-0°42'
Total		-4°18'	-0°16'	0°16'	-4°24'	
Rear	Camber	Left	-1°30'	-1°25'	-0°25'	-1°30'
		Right	-1°54'	-1°25'	-0°25'	-1°54'
	Toe	Left	0°18'	0°00'	0°23'	0°18'
		Right	0°06'	0°00'	0°23'	0°06'
		Total	0°24'	0°00'	0°47'	0°24'
	Max Thrust Angle			-0°06'	----	
Secondary Angles			Initial	Specifications		Final
				Min.	Max.	
SAI		Left	----	11°40'	12°40'	----
		Right	----	11°40'	12°40'	----
Included Angle		Left	----	----	----	----
		Right	----	----	----	----
Toe Out On Turns		Left	----	----	----	----
		Right	----	----	----	----
Max Turn Inside		Left	----	----	----	----
		Right	----	----	----	----
Toe Curve Change		Left	----	----	----	----
		Right	----	----	----	----
Setback		Front	-2mm	----	----	-2mm
		Rear	-10mm	----	----	-10mm
Track Width Diff.			6mm			6mm
Wheel Base Diff.			8mm			8mm
Front Ride Height		Left	----	----	----	----
		Right	----	----	----	----
Rear Ride Height		Left	----	----	----	----
		Right	----	----	----	----
Frame Angle						----