

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19011978/ECF3E2

Date: 01/08/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No: 0999994322
Claimant Vehicle No : GBF8929M	Insured Vehicle No : SMG4222J
Date of Loss: 25/06/2019	Nature of Claim: TP Claim No: 4207755963SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBF8929M		
Make & Model:	TOYOTA HIACE, 3.0 D DX (A)	Engine No:	1KD2682522
Reg. Date:	31/03/2017 (Man. Year: 2016)	Chassis No:	KDH2010215457
Colour:	Silver	Odometer:	118393 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/70 R15	Rear Tyre Size:	195/70 R15
Front Left Side:	Compasal 5 mm	Rear Left Side:	Compasal 5 mm
Front Right Side:	Compasal 5 mm	Rear Right Side:	Compasal 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	08/07/2019	
Date Inspected:	08/07/2019 Inspected At:	51 DEFU LANE 9 SINGAPORE 539291 Repairer : Gforce Autotech Private Limited (HQ)
Estimated Period of Repair:	4.0 days	

Adjuster: CHEN TSUE YEE

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cut	0.00 F	*- F
2	1		*REAR BUMPER CLIP	Necessary	0.00 F	*- F
3	1		*REAR BUMPER SIDE RETAINER RH	Distorted	0.00 F	*- F
4	1		*REAR RH TAILLAMP	Cut	0.00 F	*- F
5	1		*REAR RH TAILLAMP BELOW GARNISH	* Check	0.00 F	*- F
6	1		*REAR BODY PANEL RH	Repair	0.00 F	*- F
7	1		*SLIDING DOOR RH	Repair	0.00 F	*- F
8	1		*REAR RH WHEEL RIM	Bent	0.00 F	*- F
9	1		*REAR RH WHEEL BEARING	Jammed	0.00 F	*- F
F=Franchise part.						
Total Parts (\$\$)					0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >