Adjuster Report Page 1 of 4

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19011995/R1GA3N2

**Date:** 21/07/2020

**REFERENCE** 

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015

Claimant
PC6031R

Insured Vehicle No: SH9393P

Vehicle No:

Date of Loss: 01/07/2019 Nature of Claim: TP Claim No: MCT19070010

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: PC6031R

 Make & Model:
 YUTONG ZK6118HGA, 6.7 D (A)
 Engine No:
 ISB67E5285B22244826

 Reg. Date:
 15/09/2017 (Man. Year: 2017)
 Chassis No:
 LZYTAGE67H1003990

Colour: Multi-colour Odometer: 233913 km

Engine Capacity: 6690 cc Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 275/70 R22.5 Rear Tyre Size: 275/70 R22.5 (D)
Front Left Side: AUFINE 8 mm Rear Left Side: AUFINE 8/8 mm
Front Right Side: AUFINE 8 mm Rear Right Side: AUFINE 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,200.00	1,700.00	500.00	22.73
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,200.00	1,700.00	500.00	22.73
+ GST 7.00/7.00% (S\$)	154.00	119.00	35.00	22.73
Nett Amount (S\$)	2,354.00	1,819.00	535.00	22.73
	000000000000000000000000000000000000000	4.050.00		

+ Loss of Use (3.0 x S\$350.00/day) (S\$) 1,050.00

(\$\$) 2,869.00 Liable Amount (50.00%) (\$\$) 1,434.50

Global Sum Settlement (S\$) 1,500.00

INSPECTION

Date of Assignment: 05/07/2019

Date Inspected: 09/07/2019 Inspected At: WTS ENGINEERING PTE LTD

8 Gul Circle

Singapore 629564

Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL Manager: Chong Pui Lin

Adjuster Report Page 2 of 4

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

## REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 06 Mar 2020)

Parts: N/A YUTONG ZK6118HGA 6.7 D (A) (Model not available in database)

**Labour:** Repairer's (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for PC6031R)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

### **Recommended Parts**

There are no new parts selected.

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO PANEL BEAT RHS REAR PANEL	New	400.00	300.00
2	TO REMOVE AND REPLACE RHS REAR PANEL STICKER	New	1,200.00	950.00
3	TO PUTTY AND SPRAY PAINTING RHS REAR PANEL	New	600.00	450.00
	Gross Labour Cost (S\$)		2,200.00	1,700.00
	Report was unsubmitted durin	a this print-out.		

< END OF ESTIMATES >