

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG19012002/KBA3Q2

**Date:** 11/11/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

**Claimant**

**Vehicle No :** SKE2911B

**Insured Vehicle No :** SKT2920X

Date of Loss: 02/07/2019

Nature of Claim: TP

Claim No: 5808980611SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKE2911B**

Make & Model: TOYOTA HARRIER, 2.0 Premium (A)

Engine No: 3ZRB703424

Reg. Date: 12/08/2017 (Man. Year: 2015)

Chassis No: ZSU600068907

Colour: Metallic Maroon

Odometer: 30564 km

Engine Capacity: 1986 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 235/55R18

Rear Tyre Size:

235/55R18

Front Left Side: Bridgestone 5 mm

Rear Left Side:

Bridgestone 8 mm

Front Right Side: Bridgestone 5 mm

Rear Right Side:

Bridgestone 8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,930.54	1,862.55	67.99	3.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	930.00	810.00	120.00	12.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>2,860.54</b>	<b>2,672.55</b>	<b>187.99</b>	<b>6.57</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,100.00</b>		
<b>(S\$)</b>	2,860.54	2,100.00	760.54	26.59
<b>+ GST 7.00/7.00% (S\$)</b>	200.24	147.00	53.24	26.59
<b>Nett Amount (S\$)</b>	<b>3,060.78</b>	<b>2,247.00</b>	<b>813.78</b>	<b>26.59</b>
<b>+ Car Rental (4.0 x S\$130.00/day) (S\$)</b>		520.00		
<b>+ Doc/Search Fee (S\$)</b>		8.00		
<b>Nett Liability (S\$)</b>		<b>2,775.00</b>		
<b>Global Sum Settlement (S\$)</b>		<b>2,700.00</b>		

### INSPECTION

Date of Assignment: 08/07/2019

Date Inspected: 15/07/2019 Inspected At:

Cheng Hoe Motor Pte Ltd (Yishun)

Blk 1019 #01-374/382, Yishun

Industrial Park A

Singapore 768761

Estimated Period of Repair: 4.0 days

---

**Adjuster:** KENNETH KONG**Manager:** CHUA ZHEN LI

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled/Cut	1,450.40 FL	*1,450.40 FL
2	1		*FRONT BUMPER LH SIDE RETAINER	Serviceable	90.66 FL	*- FL
3	6		*FRONT BUMPER CLIPS	Necessary	21.00 FL	*21.00 FL
4	1		*FRONT LH FENDER	Buckled	1,012.00 FL	*1,012.00 FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>2,574.06</b>	<b>2,483.40</b>
<b>- List Item Discount on L Items 25.00/25.00% (S\$)</b>	643.52	620.85
<b>Total Parts (S\$)</b>	<b>1,930.54</b>	<b>1,862.55</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	400.00	360.00
2	PUTTY & RESPRAY PAINT	New	500.00	420.00
3	RUSTPROOFING	New	30.00	30.00
<b>Gross Labour Cost (\$\$)</b>			<b>930.00</b>	<b>810.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >